

STS-115 Post-Mission Summary



The Shuttle Atlantis launched from Kennedy Space Center's (KSC) Launch Pad 39B on September 9th, 2006 at 1515 UTC after several delays due to weather and technical issues. While on-orbit, the astronaut crew successfully completed the installation of the P3/P4 truss and deployed solar arrays to provide additional power capability for the International Space Station. A one-day delay for landing gave the crew time to inspect the orbiter following the observation of unidentifiable debris as well as opportunity to avoid unacceptable weather due to a cold front. Atlantis touched down on KSC's Shuttle Landing Facility (SLF) at 1021 UTC on September 21st under nearly ideal weather conditions.

Weather presented several challenges throughout the final preparations for the launch and on launch day. A squall line passed through KSC on August 25th producing numerous lightning strokes in the area. Cameras monitoring the pad imaged a lightning strike to the pad. The Air Force's Cloud-to-Ground Lightning Sensor System (CGLSS) and the National Lightning Detection Network (NLDN) detected five return strokes with the flash, two of which appear to have struck the pad based on lightning location information and current sensors in the catenary wire system used for lightning protection. A launch delay was required to review data to ensure Atlantis's systems did not suffer any damage. During the launch delay, Hurricane Ernesto's forecast track caused a concern for winds greater than 70 knots at the launch pad. NASA decided to roll the Shuttle back to the Vehicle Assembly Building, but forecast updates during the roll back gave managers confidence that the threat of 70 knot winds had diminished. NASA/KSC managers then decided to stop the "roll back" in mid-course and return the vehicle to the pad was then made.

The first launch attempt occurred on 8 September. During tanking for the launch attempt, a problem with one of the external tank fuel sensors occurred. Mission managers allowed the launch countdown to continue while reviewing data. Forecasters were concerned with potential rainshowers developing along the sea breeze at KSC. SMG issued a "GO" forecast for RTLS 50 minutes prior to the planned launch time of 1535 UTC based on trends in the satellite and radar observations, as well as favorable weather reconnaissance reports. The final updates for the TAL sites predicted acceptable conditions at Zaragoza and Moron. Thunderstorms within flight rule limits produced unacceptable conditions at Istres, France. The mission management team then decided to scrub the launch to allow further time to evaluate the fuel sensor.

Atlantis launched successfully on 9 September, but not without some weather challenges in the hour prior to launch. The primary RTLS concerns entering the second launch count were also the potential for small showers developing along the sea breeze. SMG issued an update at 1435 UTC for a "GO" RTLS removing the forecast of a chance for showers developing with the sea breeze. However, the Shuttle Landing Facility observer reported a cloud ceiling of 1,700 feet at 1455 UTC in association with the development of the sea breeze. Astronauts Kent Rominger

