

Authority: 12 U.S.C. 4001–4010, 12 U.S.C. 5001–5018.

■ 2. The Fourth District routing symbol list in appendix A is revised to read as follows:

Appendix A to Part 229—Routing Number Guide to Next-Day Availability Checks and Local Checks

* * * * *

Fourth Federal Reserve District

[Federal Reserve Bank of Cleveland]

Head Office

0220	2220
0223	2223
0410	2410
0412	2412
0420	2420
0421	2421
0422	2422
0423	2423
0430	2430
0432	2432
0433	2433
0434	2434
0440	2440
0441	2441
0442	2442
0515	2515
0519	2519
0720	2720
0724	2724
0740	2740
0749	2749
0813	2813
0830	2830
0839	2839
0863	2863

* * * * *

By order of the Board of Governors of the Federal Reserve System, acting through the Secretary of the Board under delegated authority, August 11, 2008.

Robert deV. Frierson,

Deputy Secretary of the Board.

[FR Doc. E8–18850 Filed 8–14–08; 8:45 am]

BILLING CODE 6210–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 26

[Docket No. FAA–2004–18379; Amendment No. 26–0]

RIN 2120–AI31

Enhanced Airworthiness Program for Airplane Systems/Fuel Tank Safety (EAPAS/FTS); Technical Correction

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; technical correction.

SUMMARY: This final rule corrects a subpart heading in the Code of Federal Regulations. The heading was inadvertently misstated when the FAA published the rule in November 2007.

EFFECTIVE DATE: This final rule is effective August 15, 2008.

FOR FURTHER INFORMATION CONTACT:

Annette K. Kovite, ANM–113, Standardization Branch, Federal Aviation Administration, 1601 Lind Avenue, SW., Renton, WA 98057, telephone: 425–227–1262, facsimile: 425–227–1320, e-mail: Annette.Kovite@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

On November 8, 2007, the FAA published a final rule to establish part 26 in the Code of Federal Regulations (72 FR 63364). The heading for subpart B of that part contained the phrase “aging systems” instead of the intended “airplane systems.” This final rule corrects that error.

Justification for Immediate Adoption

Because this action corrects merely a typographical error, the FAA finds that notice and public comment under 5 U.S.C. 553(b) is unnecessary. For the same reason, the FAA finds that good cause exists under 5 U.S.C. 553(d) for making this rule effective upon publication.

List of Subjects in 14 CFR Part 26

Aircraft, Aviation safety, Continued airworthiness.

■ In consideration of the foregoing, the Federal Aviation Administration amends Chapter I of Title 14, Code of Federal Regulations part 26 as follows:

PART 26—CONTINUED AIRWORTHINESS AND SAFETY IMPROVEMENTS FOR TRANSPORT CATEGORY AIRPLANES

■ 1. The authority citation for part 26 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702 and 44704.

Subpart B—Enhanced Airworthiness Program for Airplane Systems

■ 2. The heading for subpart B is revised to read as set forth above.

Issued in Washington, DC, on August 11, 2008.

Pamela Hamilton-Powell,

Director, Office of Rulemaking, Aviation Safety.

[FR Doc. E8–18859 Filed 8–14–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2008–0864; Directorate Identifier 2008–NM–120–AD; Amendment 39–15644; AD 2008–17–06]

RIN 2120–AA64

Airworthiness Directives; Bombardier Model DHC–8–400 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) that applies to certain Bombardier Model DHC–8–400 series airplanes. The existing AD currently requires revising the Limitations section of the airplane flight manual (AFM) to include procedures for pulling the “HYD PWR XFER” circuit breaker in the event of the loss of all hydraulic fluid in the No. 1 or No. 2 hydraulic system. This AD requires a revision to the AFM to include additional procedures for ensuring that the “PTU CNTRL” switch is Normal, the “PTU CNTRL ON” advisory light is out, and the “HYD PWR XFER” circuit breaker is pulled in the event of the illumination of the “#2 HYD ISO VALVE” caution light. This AD resulted from low No. 2 hydraulic pressure in-flight, which caused the power transfer unit to overspeed, and the fluid flow within the No. 1 hydraulic system to increase. We are issuing this AD to prevent possible loss of both the No. 1 and No. 2 hydraulic systems, resulting in the potential loss of several functions essential for safe flight and landing of the airplane.

DATES: This AD becomes effective September 2, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of September 2, 2008.

On July 10, 2007 (72 FR 30968, June 5, 2007), the Director of the Federal Register approved the incorporation by reference of certain other publications.

We must receive any comments on this AD by September 15, 2008.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: 202–493–2251.
- Mail: U.S. Department of Transportation, Docket Operations, M–