

(e) *Can I comply with this AD in any other way?* To use an alternative method of compliance or adjust the compliance time, use the procedures in 14 CFR 39.19. Send these requests to the Manager, Standards Office, Small Airplane Directorate, For information on any already approved alternative methods of compliance, contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(f) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Pilatus Aircraft Ltd. PC-6 Service Bulletin No. 57-002, dated November 27, 2002, and Pilatus Aircraft Ltd. PC-6 Service Bulletin No. 118, dated December 1972. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland; telephone: +41 41 619 63 19; facsimile: +41 41 619 6224; or from Pilatus Business Aircraft Ltd., Product Support Department, 11755 Airport Way, Broomfield, Colorado 80021; telephone: (303) 465-9099; facsimile: (303) 465-6040. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note: The subject of this AD is addressed in Swiss AD Number HB 2003-092, dated February 17, 2003.

(g) *When does this amendment become effective?* This amendment becomes effective on August 15, 2003.

Issued in Kansas City, Missouri, on June 16, 2003.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-15723 Filed 6-23-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-CE-11-AD; Amendment 39-13206; AD 2003-13-06]

RIN 2120-AA64

Airworthiness Directives; Iniziative Industriali Italiane S.p.A. Models Sky Arrow 650 TC and 650 TCN Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain Iniziative Industriali

Italiane S.p.A. (3I) Models Sky Arrow 650 TC and 650 TCN airplanes. This AD requires you to modify the nose gear support bulkhead (STA600). This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Italy. The actions specified by this AD are intended to prevent failure of the nose gear support bulkhead (STA600). Such failure could lead to loss of control of the airplane during landing or take-off.

DATES: This AD becomes effective on August 11, 2003.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of August 11, 2003.

ADDRESSES: You may get the service information referenced in this AD from Iniziative Industriali Italiane S.p.A., Corso Trieste, n. 150, 00198 Rome, Italy; telephone: 06 84.15.821; facsimile: 06 855.71.62. You may view this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-11-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

What Events Have Caused This AD?

The Ente Nazionale per l'Aviazione Civile (ENAC), which is the airworthiness authority for Italy, recently notified FAA that an unsafe condition may exist on certain Iniziative Industriali Italiane S.p.A. (3I) Models Sky Arrow 650 TC and 650 TCN airplanes. The ENAC reports that data collected on in-service airplanes show that cracks have been detected on the nose gear support bulkhead (STA600) of several airplanes with high operating time on grass airfields and at flight schools where activity of hard landings have occurred.

What Is the Potential Impact if FAA Took No Action?

If not corrected, the nose gear support bulkhead (STA600) could fail. Such failure could lead to loss of control of the airplane during landing or take-off.

Has FAA Taken Any Action to This Point?

We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Iniziative Industriali Italiane S.p.A. (3I) Models Sky Arrow 650 TC and 650 TCN airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on April 3, 2003 (68 FR 16220). The NPRM proposed to require you to modify the nose gear support bulkhead (STA600).

Was the Public Invited to Comment?

The FAA encouraged interested persons to participate in the making of this amendment. We did not receive any comments on the proposed rule or on our determination of the cost to the public.

FAA's Determination

What Is FAA's Final Determination on This Issue?

After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. We have determined that these minor corrections:

- Provide the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

How Does the Revision to 14 CFR Part 39 Affect This AD?

On July 10, 2002, FAA published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA's AD system. This regulation now includes material that relates to special flight permits, alternative methods of compliance, and altered products. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Cost Impact

How Many Airplanes Does This AD Impact?

We estimate that this AD affects 10 airplanes in the U.S. registry.

What Is the Cost Impact of This AD on Owners/Operators of the Affected Airplanes?

We estimate the following costs to accomplish the modification:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
19 workhours × \$60 = \$1,140	\$100	\$1,240	\$12,400

The modification to the nose gear support bulkhead (STA600) requires 39 hours for cure and post cure time.

Regulatory Impact

Does This AD Impact Various Entities?

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

Does This AD Involve a Significant Rule or Regulatory Action?

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. FAA amends § 39.13 by adding a new AD to read as follows:

2003-13-06 Initiative Industriali Italiane S.p.A.: Amendment 39-13206; Docket No. 2003-CE-11-AD.

(a) *What airplanes are affected by this AD?* This AD affects the following airplanes that are certificated in any category:

Model	Serial No.
Sky Arrow 650 TC	C001 through C004, C006 through C008, and C011.
Sky Arrow 650 TCN ..	CN001 through CN006 and CN008.

(b) *Who must comply with this AD?*

Anyone who wishes to operate any of the airplanes identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?*

The actions specified by this AD are intended to prevent failure of the nose gear support bulkhead (STA600). Such failure could lead to loss of control of the airplane during landing or take-off.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following, unless already accomplished:

Actions	Compliance	Procedures
Modify the nose gear support bulkhead (STA600).	Within the next 100 hours time-in-service (TIS) after August 11, 2003 (the effective date of this AD).	In accordance with Iniziative Industriali Italiane S.p.A. 3i Service Bulletin SB-C No. 02/02, dated October 15, 2002.

(e) *Can I comply with this AD in any other way?* To use an alternative method of compliance or adjust the compliance time, use the procedures in 14 CFR 39.19. Send these requests to the Manager, Standards Office, Small Airplane Directorate. For information on any already approved alternative methods of compliance, contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(f) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Iniziative Industriali Italiane S.p.A. 3i Service Bulletin SB-C No. 02/02, dated October 15, 2002. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from Iniziative Industriali Italiane S.p.A., Corso Trieste, n. 150, 00198 Rome, Italy; telephone: 06 84.15.821; facsimile: 06 855.71.62. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the

Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

Note: The subject of this AD is addressed in Italian AD Number 2002-591, dated November 29, 2002.

(g) *When does this amendment become effective?* This amendment becomes effective on August 11, 2003.

Issued in Kansas City, Missouri, on June 17, 2003.

James E. Jackson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-15725 Filed 6-23-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-CE-10-AD; Amendment 39-13205; AD 2003-13-05]

RIN 2120-AA64

Airworthiness Directives; Iniziative Industriali Italiane S.p.A. Models Sky Arrow 650 TC and 650 TCN Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all Iniziative Industriali Italiane S.p.A. (3I) Models Sky Arrow 650 TC and 650 TCN airplanes. This AD requires you to repetitively inspect the engine mount for cracks and modify or replace the engine mount if cracks are