

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Wichita Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Philip Petty, Aerospace Engineer, ACE-119W, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4139; facsimile: (316) 946-4107.

Does This AD Incorporate Any Material by Reference?

(g) You must do the actions required by this AD following the instructions in Raytheon Aircraft Company Mandatory Service Bulletin SB 32-3678, dated June 2004. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get a copy of this service information, contact Raytheon Aircraft Company, P.O. Box 85, Wichita, Kansas 67201-0085; telephone: (800) 625-7043. To review copies of this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html or call (202) 741-6030. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2004-19119.

Issued in Kansas City, Missouri, on December 6, 2004.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-27195 Filed 12-15-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2004-18034; Directorate Identifier 2004-CE-18-AD; Amendment 39-13905; AD 2004-25-17]

RIN 2120-AA64

Airworthiness Directives; LETECKÉ ZÁVODY Model L 23 SUPER—BLANIK Sailplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA adopts a new airworthiness directive (AD) for certain LETECKÉ ZÁVODY Model L 23 SUPER—BLANIK sailplanes. This AD requires you to do a repetitive, non-destructive magnetic test (NDMT) inspection on the elevator rocker lever (part number A 730 201 N) for cracks. If cracks are found, this AD also requires you to return the part to the manufacturer. The manufacturer will send you a replacement part for installation. Installing the improved replacement part terminates the need for the repetitive inspections. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the Czech Republic. We are issuing this AD to prevent failure of the elevator rocker lever caused by cracks that resulted from a defect in prior manufacturing procedures. Such failure could lead to loss of control of the sailplane.

DATES: This AD becomes effective on January 28, 2005.

As of January 28, 2005, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

ADDRESSES: To get the service information identified in this AD, contact LETECKÉ ZÁVODY a.s., 686 04 Kunovice 1177, Czech Republic. To review this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html or call (202) 741-6030.

To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2004-18034.

FOR FURTHER INFORMATION CONTACT:

Gregory A. Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:**Discussion**

What events have caused this AD? The Civil Aviation Authority (CAA), which is the airworthiness authority for the Czech Republic, recently notified FAA that an unsafe condition may exist on certain LETECKÉ ZÁVODY Model L

23 SUPER—BLANIK sailplanes. The CAA reports that, during an accident investigation, cracks were found on the elevator rocker lever.

The manufacturer has identified a problem with its quality control inspection procedures during the production of the original elevator rocker lever part prior to January 2004. Micro-cracks or voids were not detected when the parts left production and were installed on the affected sailplanes. These discrepancies may cause fatigue failure of the elevator rocker lever.

In January 2004, the manufacturer changed its manufacturing process and is currently replacing any existing defective elevator rocker levers within the specified affected sailplanes.

What is the potential impact if FAA took no action? If not detected and corrected, cracks in the elevator rocker lever could cause the lever to fail. Such failure could result in loss of control of the sailplane.

Has FAA taken any action to this point? We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain LETECKÉ ZÁVODY Model L 23 SUPER—BLANIK sailplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on September 2, 2004 (69 FR 53655). The NPRM proposed to require you to do a repetitive, non-destructive magnetic test (NDMT) inspection on the elevator rocker lever (part number A 730 201 N) for cracks. If cracks are found, the NPRM also proposed to require you to return the part to the manufacturer. The manufacturer will send you a replacement part for installation. Installing the improved replacement part would terminate the need for the repetitive inspections.

What is the difference between this AD and the CAA AD? The CAA AD requires doing the initial inspection prior to further flight after the effective date of this AD. We are requiring that you do the initial inspection within the next 25 hours time-in-service (TIS) after the effective date of this AD.

We do not have justification to require this action prior to further flight. We use compliance times such as this when we have identified an urgent safety of flight situation. We believe that 25 hours TIS will give the owners or operators of the affected sailplanes enough time to have the actions required by this AD done without compromising the safety of the sailplanes.

Comments

Was the public invited to comment?
We provided the public the opportunity to participate in developing this AD. We received no comments on the proposal or on the determination of the cost to the public.

Conclusion

What is FAA's final determination on this issue? We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial corrections. We have

determined that these minor corrections:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Changes to 14 CFR Part 39—Effect on the AD

How does the revision to 14 CFR part 39 affect this AD? On July 10, 2002, the FAA published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's AD system. This regulation now includes material

that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Costs of Compliance

How many sailplanes does this AD impact? We estimate that this AD affects 103 sailplanes in the U.S. registry.

What is the cost impact of this AD on owners/operators of the affected sailplanes? We estimate the following costs to accomplish the inspections:

Labor cost	Parts cost	Total cost per sailplane	Total cost on U.S. operators
2 workhours × \$65 per hour = \$130	Not applicable	\$130	\$130 × 103 = \$13,390.

We estimate the following costs to accomplish any necessary replacements that will be required based on the results of the inspections. We have no way of determining the number of sailplanes that may need this replacement:

Labor cost	Parts cost	Total cost per sailplane
2 workhours × \$65 = \$130	Parts provided by the manufacturer at no cost	\$130 × 103 = \$13,390.

Authority for this Rulemaking

What authority does FAA have for issuing this rulemaking action? Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this AD.

Regulatory Findings

Will this AD impact various entities? We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

Will this AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "Docket No. FAA-2004-18034; Directorate Identifier 2004-CE-18-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. FAA amends § 39.13 by adding a new AD to read as follows:

2004-25-17 LETECKÉ ZÁVODY:

Amendment 39-13905; Docket No. FAA-2004-18034; Directorate Identifier 2004-CE-18-AD.

When Does This AD Become Effective?

(a) This AD becomes effective on January 28, 2005.

What Other ADs Are Affected by This Action?

(b) None.

What Sailplanes Are Affected by This AD?

(c) This AD affects Model L 23 SUPER—BLANIK sailplanes, all serial numbers up to and including 039019, that are certificated in any category.

What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the Czech Republic. We are issuing this AD to prevent fatigue failure of the elevator rocker lever. This failure could lead to loss of control of the sailplane.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Do a non-destructive magnetic test (NDMT) inspection on the elevator rocker lever (part number A 730 201 A) for cracks and deficiencies.	Initially inspect within the next 25 hours time-in-service (TIS) after January 28, 2005 (the effective date) of this AD. If no cracks or deficiencies are found, reinstall and repetitively inspect thereafter at intervals not to exceed 100 hours TIS until the replacement in paragraph (e)(2) of this AD is done. The replacement in paragraph (e)(2) of this AD is the terminating action for the repetitive inspection requirements in this AD.	Follow the work procedures in LETECKÉ ZÁVODY Mandatory Bulletin MB No.: L23/48a, not dated.
(2) If cracks are found during any inspection required in paragraph (e)(1) of this AD, send the cracked part and a report of the inspection that contains the information about the position and size of cracks, the serial number of the sailplane, and the total number of hours TIS since new to LETECKÉ ZÁVODY at the address specified in paragraph (h) of this AD. (i) The manufacturer will send you a replacement part for installation. (ii) The Office of Management and Budget (OMB) approved the information collection requirements contained in this regulation under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 <i>et seq.</i>) and assigned OMB Control Number 2120-0056	Return the cracked elevator rocker lever to the manufacturer and install the replacement part prior to further flight after the inspection in which cracks are found. Prior to installing the new part, place a permanent (paint) blue dot approximately 0.25 inches in diameter in an open location on the elevator rocker lever. Installing the replacement part received from the manufacturer is the terminating action for the repetitive inspection requirements in paragraph (e)(1) of this AD.	Follow the work procedures in LETECKÉ ZÁVODY Mandatory Bulletin MB No.: L23/48a, not dated.
(3) You may terminate the repetitive inspections required in paragraph (e)(1) of this AD by: (i) Replacing the elevator rocker lever with one obtained from the manufacturer at the address specified in paragraph (h) of this AD; and (ii) Prior to installing the new part, place a permanent (paint) blue dot approximately 0.25 inches in diameter in an open location on the elevator rocker lever	At any time after the initial inspection required in paragraph (e)(1) of this AD.	Not applicable.
(4) If you have already replaced the defective elevator rocker lever with a manufacturer-approved lever that was produced in January 2004 or later following LETECKÉ ZÁVODY Mandatory Bulletin MB No.: L23/48a, not dated, you may take credit for compliance with this AD by having an appropriately-rated mechanic do the following: (i) Make a log book entry showing compliance with this AD; and (ii) Place a permanent (paint) blue dot approximately 0.25 inches in diameter in an open location on the newly installed elevator rocker lever.	As of January 28, 2005 (the effective date of this AD).	Not applicable.

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Gregory A. Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

Is There Other Information That Relates to This Subject?

(g) Czech Republic AD Number CAA-AD-T-005/2004, dated January 16, 2004, also addresses the subject of this AD.

Does This AD Incorporate Any Material by Reference?

(h) You must do the actions required by this AD following the instructions in LETECKÉ ZÁVODY Mandatory Bulletin MB No.: L23/48a (referenced in Czech Republic AD Number CAA-AD-T-005/2004, dated January 16, 2004). The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR

part 51. To get a copy of this service information, contact LETECKÉ ZÁVODY a.s., 686 04 Kunovice 1177, Czech Republic. To review copies of this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html or call (202) 741-6030. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2004-18034.

Issued in Kansas City, Missouri, on December 6, 2004.

William J. Timberlake,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-27284 Filed 12-15-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19693; Directorate Identifier 2004-CE-40-AD; Amendment 39-13904; AD 2004-25-16]

RIN 2120-AA64

Airworthiness Directives; Kelly Aerospace Power Systems Part Number (P/N) 14D11, A14D11, B14D11, C14D11, 23D04, A23D04, B23D04, C23D04, or P23D04 Fuel Regulator Shutoff Valves (Formerly Owned by ElectroSystems, JanAero Devices, Janitrol, C&D, FL Aerospace, and Midland-Ross Corporation)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) to supersede AD 2001-17-13, which applies to aircraft equipped with a Kelly Aerospace Power Systems (Kelly Aerospace) part number (P/N) 14D11, A14D11, B14D11, C14D11, 23D04, A23D04, B23D04, C23D04, or P23D04 fuel regulator shutoff valve used with Kelly Aerospace B1500, B2030, B2500, B3040, B3500, B4050, or B4500 B-Series combustion heaters. AD 2001-17-13 requires you to visually inspect or pressure test the fuel regulator shutoff valves for leaks and replace the fuel regulator shutoff valve if leaks are found. This AD is the result of continued reports of fuel regulator shutoff valve problems and the manufacturer revising the service information to modify the pressure test procedures and to specify installing improved design replacement parts. This AD retains the actions required in AD 2001-17-13, makes the inspection repetitive, and requires installing improved design replacement parts. We are issuing this AD to prevent failure of the fuel regulator shutoff valve, which could result in fuel leakage in aircraft with these combustion heaters. This failure could result in an aircraft fire.

DATES: This AD becomes effective on January 5, 2005.

As of January 5, 2005, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

We must receive any comments on this AD by February 11, 2005.

ADDRESSES: Use one of the following to submit comments on this AD:

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001.

- *Fax:* 1-202-493-2251.

- *Hand delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

To get the service information identified in this proposed AD, contact Kelly Aerospace Power Systems, P.O. Box 273, Fort Deposit, Alabama 36032; telephone: (334) 227-8306; facsimile: (334) 227-8596; Internet: <http://www.kellyaerospace.com>.

To view the comments to this AD, go to <http://dms.dot.gov>. The docket number is FAA-2004-19618.

FOR FURTHER INFORMATION CONTACT:

Kevin L. Brane, Aerospace Engineer, Atlanta Aircraft Certification Office, FAA, One Crown Center, 1985 Phoenix Boulevard, Suite 450, Atlanta, GA 30349; telephone: (770) 703-6063; facsimile: (770) 703-6097.

SUPPLEMENTARY INFORMATION: *Has FAA taken any action to this point?* Reports of JanAero fuel regulator shutoff valves leaking caused FAA to issue AD 2001-08-01, Amendment 39-12178 (66 FR 19718, April 17, 2001). AD 2001-08-1 required you to do the following on certain JanAero Devices (JanAero) 14D11 and 23D04 series fuel regulator shutoff valves used with certain JanAero combustion heaters that are installed on aircraft:

- Visually inspect and pressure test the fuel regulator shutoff valves for leaks; and
- If leaks are found, replace the fuel regulator shutoff valve.

The affected fuel regulator shutoff valves are part of the JanAero B1500, B2030, B2500, B3040, B3500, B4050, or B4500 combustion heater configuration.

Operators of aircraft with the affected fuel regulator shutoff valves installed and mechanics who did the actions of

AD 2001-08-01 provided suggestions for improvement to the AD. Based on that feedback, FAA superseded AD 2001-08-01 with AD 2001-17-13, Amendment 39-12404 (66 FR 44027, August 22, 2001).

AD 2001-17-13 retained the actions of AD 2001-08-01, except it requires only the visual inspection or the pressure test of the fuel regulator shutoff valves (not both) and lists the affected fuel regulator shutoff valves by part number instead of series. AD 2001-17-13 also includes a provision for disabling the heater as an alternative method of compliance.

Accomplishment of AD 2001-17-13 is required following JanAero Service Bulletin No. A-107, dated January 8, 2001.

What has happened since AD 2001-17-13 to initiate this AD action? The FAA continues to receive reports of problems with these fuel regulator shutoff valves. This service history reflects that the inspections should be repetitive instead of one-time.

Kelly Aerospace has revised the service information to modify the pressure test procedures, to specify installing improved design replacement parts with a manufacture date code of 02/02 or later, and to make the inspection repetitive.

The New Piper Aircraft, Inc. has also issued new service information that specifies replacing part number (P/N) A23D04-7.5 with an improved design replacement part P/N P23D04-7.5.

What is the potential impact if FAA took no action? This condition, if not corrected, could result in fuel leakage in aircraft with these combustion heaters, which could result in an aircraft fire with consequent damage or destruction.

FAA's Determination and Requirements of the AD

What has FAA decided? We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other products of this same type design.

Since the unsafe condition described previously is likely to exist or develop on type design aircraft equipped with a Kelly Aerospace B1500, B2030, B2500, B3040, B3500, B4050, or B4500 combustion heater, we are issuing this AD to prevent failure of the fuel regulator shutoff valve, which could result in fuel leakage in aircraft with these combustion heaters. This failure could result in an aircraft fire.

What does this AD require? This AD supersedes AD 2001-17-13 with a new AD that requires you to: