

**US Army Corps  
of Engineers**

New Orleans District

**LAKE PONTCHARTRAIN, LOUISIANA AND VICINITY**

**CHALMETTE AREA PLAN**

**BAYOU BIENVENUE CONTROL STRUCTURE**

**PERIODIC INSPECTION REPORT NO.7**

**30 MARCH 1994**



rec'd 3/13/95  
Not dated.

CEMRC-PE-G (CELMN-ED-G/25 Jan 95) (1130-2-320b) 1st End  
Mr. Tucker/pt/(601) 634-5900  
SUBJECT: Bayou Bienvenue Control Structure, Report of Periodic  
Inspection No. 7 Under ER 1110-2-100

DA, Mississippi River Commission, Vicksburg, MS 39181-0080

TO MAR '95

FOR Commander, New Orleans District, ATTN: CELMN-ED-G

The enclosed periodic inspection report is approved. No further  
action is required on this correspondence chain.

FOR THE PRESIDENT OF THE COMMISSION:

Encl (6 cys)  
wd 1 cy



JAMES R. TUTTLE  
Acting Director of Planning and Engineering



DEPARTMENT OF THE ARMY  
NEW ORLEANS DISTRICT, CORPS OF ENGINEERS  
P.O. BOX 60267  
NEW ORLEANS, LOUISIANA 70160-0267

REPLY TO  
ATTENTION OF:

CELMN-ED-G

25 January 1995


MEMORANDUM FOR Commander, Lower Mississippi Valley Division,  
ATTN: CELMV-PE-G

SUBJECT: Bayou Bienvenue Control Structure, Periodic  
Inspection Report No. 7

Subject report is submitted for your approval.

FOR THE COMMANDER:

1 Encl (6 cys)  
as

  
W. EUGENE TICKNER  
Chief, Engineering Division

LAKE PONTCHARTRAIN, LOUISIANA AND VICINITY

CHALMETTE AREA PLAN

BAYOU BIENVENUE CONTROL STRUCTURE

PERIODIC INSPECTION REPORT NO. 7

30 MARCH 1994

U.S. ARMY ENGINEER DISTRICT, NEW ORLEANS

CORPS OF ENGINEERS

NEW ORLEANS, LOUISIANA





PHOTO TAKEN 27 SEPTEMBER 1974

BAYOU BIENVENUE CONTROL STRUCTURE



SUMMARY

The Bayou Bienvenue Control Structure was inspected on 30 March 1994 by representatives of the New Orleans District, Mississippi River Commission and Orleans Levee District.

Overall the structure is in good condition. Observations are noted within.

BAYOU BIENVENUE CONTROL STRUCTURE  
TABLE OF CONTENTS

| <u>Para. No.</u>   | <u>Description</u>                           | <u>Page No.</u> |
|--|--|-----------------|
| <u>SECTION I - INTRODUCTION</u>                                      |  |                 |
| 1-01   | Authority                                    | I-1             |
| 1-02   | Purpose and Scope                            | I-1             |
| 1-03   | Safety                                       | I-1             |
| 1-04   | Datum  | I-1             |
| 1-05   | Previous Inspections                         | I-1             |
| <u>SECTION II - PROJECT DESCRIPTION AND BACKGROUND</u>               |  |                 |
| 2-01   | General                                      | II-1            |
| <u>SECTION III - OPERATION AND MAINTENANCE DATA</u>                  |  |                 |
| 3-01   | Operation and Maintenance Problems           | III-1           |
| 3-02   | Actions on Deficiencies from Last Inspection | III-1           |
| <u>SECTION IV - REVIEW OF DESIGN AND ANALYSIS OF INSTRUMENTATION</u> |  |                 |
| 4-01   | Review of Design                             | IV-1            |
| 4-02   | Analysis of Instrumentation Data             | IV-1            |
| <u>SECTION V - INSPECTION</u>  |  |                 |
| 5-01   | Inspection Team                              | V-1             |
| 5-02   | Orientation                                  | V-1             |
| 5-03   | Observations                                 | V-2             |
| PHOTOGRAPHS  |  |                 |
| <u>SECTION VI - CONCLUSIONS AND PROPOSED REMEDIAL ACTIONS</u>        |  |                 |
| 6-01   | Conclusions                                  | VI-1            |
| 6-02   | Remedial Actions                             | VI-1            |
| 6-03   | Next Inspection                              | VI-1            |
| APPENDIX I - MRC TRIP REPORT   |  |                 |
| APPENDIX II - INSTRUMENTATION PLATES                                 |  |                 |



SECTION I - INTRODUCTION

1-01 Authority. Authority is provided by ER 1110-2-100, dated 8 April 1988, subject "Periodic Inspections and Continuing Evaluation of Completed Civil Works Structures".

1-02 Purpose and Scope. The results and conclusions of the inspection and evaluation for assuring the structural integrity and operational adequacy of the structure are presented herein.

1-03 Safety. The inspection was performed in accordance with the pertinent provisions of the "General Safety Requirements", EM 385-1-1, dated 1 April 1981, revised October 1984 and other applicable recognized safe practices.

1-04 Datum. All elevations are in feet and refer to the National Geodetic Vertical Datum (N.G.V.D.), formerly Mean Sea Level (M.S.L.).

1-05 Previous Inspections. Past inspections of the Bayou Bienvenue Control Structure are included in the following reports:

| <u>Report No.</u> | <u>Date of Inspection</u> |
|-------------------|---------------------------|
| 1                 | 31 Oct 73                 |
| 2                 | 27 Jul 79                 |
| 3                 | 31 Mar 83                 |
| 4                 | 7 Mar 85                  |
| 5                 | 29 Mar 88                 |
| 6                 | 25 Jul 91                 |

## SECTION II - PROJECT DESCRIPTION AND BACKGROUND

2-01 General. The Bayou Bienvenue Control Structure is a feature of the Chalmette Area plan of the Lake Pontchartrain, Louisiana, and vicinity hurricane protection project authorized by Public Law 298, 89th Congress, 1st Session, approved 27 October 1965.

The structure is located at the eastern edge of Orleans Parish, Louisiana near the intersection of Bayou Bienvenue and the MR-GO. The structure is located at station 367+60.25 on the MR-GO base line, approximately 400 feet west of the original intersection of Bayou Bienvenue and the MR-GO.

The structure was constructed under contract No. DACW29-72-C-0064, awarded in Jan 1972 to T. L. James & Company. It was completed in Sep 1974 and turned over to local interest for maintenance and operation in accordance with the conditions of local cooperation, as specified by the authorizing law.

The description of the structure, historical and other general background information, are included in report No. 1 which also contains selected construction drawings illustrating typical sections and details. A location map is included in this report (Plate 1). This report is supplementary to previously numbered reports.

SECTION III - OPERATION AND MAINTENANCE DATA

3-01 Operation and Maintenance Problems. There have been no accidents nor major operating problems since the previous periodic inspection of the structure.

3-02 Actions on Deficiencies from Last Inspection. The following proposed remedial work included in the last inspection report had not been accomplished by the Orleans Levee Board at the time of the inspection:

a. Riprap has not been replaced in deficient areas near the banks of the north and south approach channels behind the guidewalls.

b. Rusting steel members, ladders, corner plates and metal pile caps have not been repaired.



## SECTION IV - REVIEW OF DESIGN AND ANALYSIS OF INSTRUMENTATION

4-01 Review of Design. The criteria used in the original design is equal to or more conservative than current design criteria. The present loads on the structure do not exceed design load conditions. Since the criteria and loading conditions have not changed, a detailed review of the original design is not warranted.

### 4-02 Analysis of Instrumentation Data.

a. Settlement Survey. The survey data, dated 2 Nov 93, show that no significant settlement has occurred at the wing-walls, the monoliths or the floodwalls on both sides of the structure.

b. Scour. The surveys show that scour is occurring between stations 17+00 and 19+00 on the south approach channel. This scour is far away and is not migrating toward the structure; therefore it does not represent any danger to the integrity and safety of the structure at this moment. This area will continue to be monitored in future surveys.

SECTION V - INSPECTION

5-01 Inspection Team. The field inspection of the Bayou Bienvenue Control Structure was conducted on 30 March 1994 by the following personnel from the New Orleans District(NOD), Mississippi River Commission(MRC) and the Orleans Levee District:

NOD

|                      |                                 |
|----------------------|---------------------------------|
| Emmanuel Harris      | Inspection Coordinator          |
| Dan Bradley          | Gen & Envir Des Sec(Electrical) |
| Mike Sanchez-Barbudo | Gen & Envir Des Sec(Mechanical) |
| Mohan Desai          | Struc Des Sec                   |
| Soheila Holley       | F & M Br(Materials)             |
| Roberto Estrada      | F & M Br(Structures)            |
| Erika Gomez          | H & H Br                        |
| Robert Bass          | H & H Br                        |
| Brian Keller         | Op Div                          |
| Marcia Demma         | Op Div                          |

MRC

|                |             |
|----------------|-------------|
| Edwin Boren    | Con-Op Div  |
| Lawrence Cook  | Proj Eng Br |
| Patrick Tucker | Proj Eng Br |

ORLEANS LEVEE DISTRICT

Max Rubbins  
Ed Rubbins  
Steve King  
Al Wetheren

5-02 Orientation. Prior to inspecting the structure, the inspection team gave a brief orientation on the following features of the project: Structural, foundation and soils, hydraulic and hydrologic, instrumentation, operations and maintenance and the plan for accomplishing the inspection.

5-03 Observations. The overall condition of the structure was good. Most areas above the water surface were refurbished and painted. The structure was not dewatered; therefore, all observations were limited above the water elevation. The following observations were noted by the inspection team:

- a. The condition of the gate bay structure was excellent.
- b. The existing levee was raised 4 feet and the new sheet piling was tied into the concrete structure wall.
- c. An electrical conduit on top of the west sector gate constitutes a tripping hazard.
- d. The gates were operated through several cycles using the auxiliary generator. Both gates, their operating machinery and the auxiliary generator performed satisfactorily. The cable on both gates, however, was excessively slack and continued to fall off the top sheave during gate actuation. Additionally, the top sheave in the west machinery room appeared to be frozen.
- e. The staff gages need to be refurbished, too hard to read.



f. Safety chains were missing from the structure in **several** locations on top of the sector gates and for the recess ladder.

g. Riprap is deficient along the banks of the north and **south approach** channels behind the guidewalls.

(See Photo 1)

h. Rusting steel members, ladders, corner plates and metal pile caps need repair. (See Photos 2 & 3).

i. Termite infested portions of the timber guidewalls need replacing. Also, timbers were missing from the bottom half of the east sector gate and from the end of the northeast guide wall.

j. There were no significant changes in the condition of the concrete since the last inspection. There were small spalls as shown in **Photos 4 & 5**.

k. A depression, which had been filled with sandbags, was noted behind the wingwall at the northwest corner of the structure. Site personnel stated that this depression was apparently caused by material migrating through the joint at the wingwall/gatebay interface. The sandbags had been placed in the depression about three years ago and no appreciable movement had been noted since. This condition does not apparently pose any immediate threat to the structure. Site personnel will continue to monitor this area for change.

(See Photo 6)



PHOTO 1 - Deficient Rip-Rap along banks of the north and south approach channels (Typical)



PHOTO 2 - Rusting steel members





PHOTO 3 - Rusting Steel Members



PHOTO 4 - Small spall with exposed rebar on the west side by monolith B-2





PHOTO 5 - Typical small spalls at the joints  
on the east side



PHOTO 6 - Depression filled with sandbags  
behind wingwall at northwest corner  
of structure

SECTION VI - CONCLUSIONS AND PROPOSED REMEDIAL ACTIONS

6-01 Conclusions. It is concluded that the Bayou Bienvenue Control Structure is safe, stable and in satisfactory operating condition.

6-02 Remedial Actions. The following remedial actions will be accomplished by the Orleans Levee District in FY-95 under their routine periodic maintenance program:

a. Deficient riprap, rusting steel members, termite infested timbers and missing timbers will be replaced or repaired by contract forces.

b. Missing safety chains, a hazardous electrical conduit, loose cables/frozen sheave in machinery room, and unreadable staff gages will be corrected by site personnel.

c. Small concrete spalls and the depression behind the wingwall at the northwest corner of the structure will be monitored in future periodic inspections for further deterioration.

6-03 Next Inspection. The next inspection of the Bayou Bienvenue Control Structure is scheduled in March 1997.

APPENDIX I - MRC TRIP REPORT

4 May, 1994  
Tucker/pt/5900

fn PE  
JPT  
5/17/94

MEMORANDUM THRU

CEMRC-PE-G *JAO*  
CEMRC-PE-T *WMM*  
CEMRC-PE-W  
CEMRC-~~CO~~ *JRO*  
CEMRC-PE-A  
CEMRC-PE

SUBJECT: Trip Report, Periodic Inspection No. 7, Bayou Bienvenue Control Structure

FOR MAIN FILES

1. On 30 March, 1994, the undersigned participated in the subject periodic inspection along with personnel from the New Orleans District. A list of attendees is enclosed (encl 1). The inspection was conducted in accordance with ER 1110-2-100, Periodic Inspection and Continuing Evaluation of Completed Civil Works Structures, dated 8 April 1988.

2. Project Description.

a. General. The Bayou Bienvenue Control Structure is located on the eastern edge of Orleans Parish, Louisiana, near the intersection of Bayou Bienvenue and the Mississippi River - Gulf Outlet (MRGO) channel. The control structure consists of a reinforced concrete sector gate bay supported on untreated timber piles, welded steel sector gates, treated timber guidewalls, pile-supported inverted T walls, and sheet pile I walls connecting the structure to the earthen levees on each side. The gate bay is 76 feet in length and has a channel width of 56 feet. The elevation of the top of the gates and floodwalls is 17.5 feet. The sector gates are operated by electric motors with provisions for manual operation.

3. Observations and Recommendations.

a. General. At the time of the inspection the structure was not unwatered. Therefore the inspection was limited to visual observation of those features above the water surface.

b. Operation and Maintenance Observations. The following deficiencies were noted:

(1). Riprap has not been replaced along the banks of the north and south approach channels behind the guidewalls.



(2). Rusting steel members, ladder, corner plates and metal pile caps need repair.

(3). Termite infested portions of the timber guidewalls need replacing. Also, timbers were missing from the bottom half of east sector gate and from the end of northeast guide wall.

(4). One or two safety chains were missing on top of the sector gates/sector gate bays.

(5). An electrical conduit on top of west sector gate constitutes a tripping hazard.

c. **Geotechnical Observations.** A depression which had been filled with sandbags was noted behind the wingwall at the northwest corner of the structure (see photo). Site personnel informed us that this depression was apparently caused by material migrating through the joint at the wingwall/gatebay interface. The sandbags had been placed in the depression about three years ago and no appreciable movement had been noted since. This condition does not apparently pose any immediate threat to the structure. Site personnel will continue to monitor this area for change.

4. Action Required. No action is required by the Commander at this time. CELMN will prepare an inspection report and submit the report to this office for review and approval.

5. The next periodic inspection of this project is scheduled for 1999.

2 Encl  
as

  
Edwin L. Boren

  
Lawrence F. Cook

  
Patrick G. Tucker

TEAM MEMBERS  
PERIODIC INSPECTION NO. 7  
OF  
BAYOU BIENVENUE CONTROL STRUCTURE

30 MARCH 1994

MISSISSIPPI RIVER COMMISSION

|                   |            |
|-------------------|------------|
| Edwin L. Boren    | CEMRC-CO-O |
| Lawrence F. Cook  | CEMRC-PE-W |
| Patrick G. Tucker | CEMRC-PE-G |

NEW ORLEANS DISTRICT

|                      |             |
|----------------------|-------------|
| Emmanuel Harris      | CELMN-ED-DG |
| Mike Sanchez-Barbudo | CELMN-ED-DG |
| Daniel Bradley       | CELMN-ED-DG |
| Mohan Desai          | CELMN-ED-DD |
| Erika Gomez          | CELMN-ED-HC |
| Robert Bass          | CELMN-ED-HC |
| Roberto Estrada      | CELMN-ED-FS |
| Soheila Holley       | CELMN-ED-FM |
| Brian Keller         | CELMN-OD-R  |
| Marcia Demma         | CELMN-OD-SE |

ORLEANS LEVEE DISTRICT

Max Rubbins  
Ed Rubbins  
Steve King  
Al Wetheren




Enclosure 1

APPENDIX II - INSTRUMENTATION PLATES


BAYOU BIENVENUE CONTROL STRUCTURE

INSTRUMENTATION PLATES

| <u>Plate No.</u> | <u>Title</u>  |
|------------------|---|
| 1                | Location Map  |
| 2                | Settlement Reference Marks<br>Plan and Profile                        |
| 3                | Settlement Reference Marks<br>Differential Settlement Chart           |
| 4                | Wing-Wall Settlement Reference Marks<br>Plan and Tabulation           |
| 5                | Wing-Wall Settlement Reference Marks<br>Differential Settlement Chart |
| 6                | Scour and Overbank Survey   |
| 7                | Northwest Wingwall  |
| 8                | Northeast Wingwall  |
| 9                | Southwest Wingwall  |
| 10               | Southeast Wingwall  |
| 11               | Profile Survey  |
| 12               | Profile Survey  |
| 13               | Scour Survey  |
| 14               | Scour Survey  |
| 15               | Scour Survey  |
| 16               | Scour Survey  |
| 17               | Scour Survey  |
| 18               | Scour Survey  |
| 19               | Scour Survey  |
| 20               | Scour Survey  |
| 21               | Scour Survey  |
| 22               | Scour Survey  |






LAKE PONTCHARTRAIN AND VICINITY  
 BAYOU BIENVENUE  
 PERIODIC INSPECTION  
 LOCATION MAP  
 U. S. ARMY ENGINEER DISTRICT, NEW ORLEANS  
 CORPS OF ENGINEERS  
 FILE NO.



PLAN

SCALE IN FEET

| SETTLEMENT REFERENCE MARKS |             |         |         |         |         |         |         |         |         |         |         |         |         | TEMP    | GAGE 1 | GAGE 2 |    |     |
|----------------------------|-------------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|--------|--------|----|-----|
| NO. OF REFERENCE MARKS     | B-1         | B-2     | B-3     | B-4     | B-5     | B-6     | B-7     | B-8     | B-9     | B-10    | B-11    | B-12    | B-13    | B-14    |        |        |    |     |
| INITIAL DATE               | 6-25-74     | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 | 6-25-74 |        |        |    |     |
| ORIGINAL READINGS          | 16.85       | 16.88   | 16.87   | 16.87   | 16.89   | 16.86   | 16.84   | 16.80   | 16.81   | 16.75   | 16.87   | 16.86   | 16.91   | 16.88   | 79°    | L9     | L9 |     |
| DATE OF OBSERVATIONS       | 10 NOV 1991 | 16.28   | 16.64   | 16.64   | 16.78   | 16.82   | 16.87   | 16.81   | 16.88   | 16.72   | 16.81   | 16.87   | 16.89   | 16.90   | 16.90  | 88°    | L9 | L9  |
|                            | 17 DEC 1992 | 16.23   | 16.59   | 16.49   | 16.74   | 16.79   | 16.84   | 16.78   | 16.65   | 16.68   | 16.37   | 16.83   | 16.85   | 16.86   | 16.87  | 63°    | -  | -   |
|                            | 02 NOV 1993 | 16.20   | 16.80   | 16.60   | 16.80   | 16.80   | 16.88   | 16.82   | 16.69   | 16.72   | 16.40   | 16.87   | 16.89   | 16.90   | 16.90  | 72°    | L4 | 2.2 |



LEGEND

- 10 NOV. 1991
- 17 DEC. 1992
- ▲
- △
- 
- 


COMPUTER  
AIDED  
DESIGN  
DRAFTING

LAKE PONTCHARTRAIN AND VICINITY  
BAYOU BENVENUE  
PERIODIC INSPECTION


SETTLEMENT REFERENCE MARKS  
PLAN AND PROFILE

U.S. ARMY ENGINEER DISTRICT, NEW ORLEANS  
CORPS OF ENGINEERS  
NEW ORLEANS, LOUISIANA


WEST MONOLITH




WEST FLOODWALL



EAST MONOLITH



EAST FLOODWALL




| NO. OF REFERENCE MARKS  | DISTANCE BETWEEN REFERENCE MARKS |         |         |         |         |         |         |
|-------------------------|----------------------------------|---------|---------|---------|---------|---------|---------|
|                         | B2TOB3                           | B4TOB5  | B5TOB6  | B1TOB2  | B3TOB4  | B6TOB7  | B8TOB9  |
| INITIAL DATE            | 4-11-74                          | 4-11-74 | 4-11-74 | 4-11-74 | 4-11-74 | 4-11-74 | 4-11-74 |
| ORIGINAL READINGS (ft.) | 4.97                             | 3.98    | 13.135  | 64.7    | 64.9    | 2.48    | 5.00    |
| 03 MAR. 1987            | 5.02                             | 4.03    | —       | —       | —       | 2.55    | 5.08    |
| 25 FEB. 1988            | 5.04                             | 4.03    | —       | —       | —       | 2.56    | 5.08    |
| 01 DEC. 1988            | 5.15                             | 4.04    | —       | —       | —       | 2.57    | 5.09    |
| 04 DEC. 1989            | 5.05                             | 4.05    | —       | —       | —       | 2.55    | 5.08    |
| 01 NOV. 1990            | 5.07                             | 4.04    | —       | —       | —       | 3.57    | 5.09    |
| 18 NOV. 1991            | 5.05                             | 4.03    | —       | —       | —       | 2.57    | 5.08    |
| 17 DEC. 1992            | 5.05                             | 4.03    | —       | —       | —       | 2.57    | 5.09    |
| 02 NOV. 1993            | 5.05                             | 4.05    | —       | —       | —       | 2.58    | 5.08    |

NOTE:  
For location and tabulation of settlement reference marks see plate



LAKE PONTCHARTRAIN AND VICINITY  
BAYOU BIENVILLE  
PERIODIC INSPECTION

**SETTLEMENT REFERENCE MARKS  
DIFFERENTIAL SETTLEMENT CHART**



U.S. ARMY ENGINEER DISTRICT, NEW ORLEANS  
CORPS OF ENGINEERS  
NEW ORLEANS, LOUISIANA






| NO. OF REFERENCE MARKS | SETTLEMENT REFERENCE MARKS |         |         |         |         |         |         |         |         |         |         |         | TEMP    | GAGE 1 | GAGE 2 | B.M. | ELEV. |       |
|------------------------|----------------------------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|--------|--------|------|-------|-------|
|                        | 3-29-78                    | NW-1    | NW-2    | NW-3    | NE-1    | NE-2    | NE-3    | SW-1    | SW-2    | SW-3    | SE-1    | SE-2    |         |        |        |      |       | SE-3  |
| INITIAL DATE           | 3-29-78                    | 3-29-78 | 3-29-78 | 3-29-78 | 3-29-78 | 3-29-78 | 3-29-78 | 3-29-78 | 3-29-78 | 3-29-78 | 3-29-78 | 3-29-78 | 3-29-78 |        |        |      |       |       |
| ORIGINAL READINGS      | 5.02                       | 5.17    | 5.32    | 4.83    | 5.00    | 5.23    | 5.02    | 5.12    | 5.26    | 4.86    | 4.99    | 5.32    |         | 61°    | 0.4    | 0.3  | BB 2  | 6.279 |
| 29 FEB. 1980           | 4.87                       | 5.04    | 5.18    | 4.68    | 4.86    | 5.11    | 4.89    | 5.02    | 5.16    | 4.71    | 4.85    | 5.21    |         | 58°    | -0.3   | 0.1  | BB2   | 6.279 |
| 11 NOV. 1980           | 4.86                       | 5.02    | 5.22    | 4.67    | 4.84    | 5.13    | 4.86    | 4.98    | 5.13    | 4.70    | 4.85    | 5.19    |         | 69°    | 1.5    | 1.4  | BB2   | 6.278 |
| 31 MAY 1982            | 4.81                       | 4.99    | 5.16    | 4.62    | 4.80    | 5.07    | 4.81    | 4.84    | 5.09    | 4.66    | 4.80    | 5.17    |         | 85°    | 1.8    | 1.9  | BB2   | 6.278 |
| 29 NOV. 1982           | 4.85                       | 5.02    | 5.17    | 4.65    | 4.84    | 5.13    | 4.84    | 4.98    | 5.14    | 4.68    | 4.83    | 5.21    |         | 66°    | 1.1    | 1.6  | BB3   | 6.270 |
| 13 APR. 1984           | 4.84                       | 5.02    | 5.21    | 4.65    | 4.84    | 5.12    | 4.84    | 4.98    | 5.15    | 4.68    | 4.83    | 5.22    |         | 67°    | -      | 1.0  | BB3   | 6.270 |
| 22 OCT. 1984           | 4.84                       | 5.03    | 5.21    | 4.64    | 4.83    | 5.11    | 4.84    | 4.97    | 5.15    | 4.68    | 4.83    | 5.21    |         | 80°    | 2.5    | 2.5  | BB3   | 6.270 |
| 11 AUG. 1986           | 4.81                       | 5.03    | 5.20    | 4.62    | 4.83    | 5.07    | 4.82    | 4.97    | 5.15    | 4.65    | 4.75    | 5.19    |         | 78°    | 1.1    | 1.0  | BB3   | 6.270 |
| 03 MAR. 1987           | 4.81                       | 5.00    | 5.20    | 4.59    | 4.79    | 5.08    | 4.80    | 4.94    | 5.12    | 4.62    | 4.78    | 5.18    |         | 60°    | 1.9    | 1.7  | BB3   | 6.270 |
| 25 FEB. 1988           | 4.82                       | 5.00    | 5.21    | 4.64    | 4.85    | 5.14    | 4.80    | 4.95    | 5.13    | 4.64    | 4.82    | 5.22    |         | 50°    | -0.3   | 0.0  | BB3   | 6.270 |
| 01 DEC. 1988           | 4.81                       | 5.00    | 5.20    | 4.63    | 4.84    | 5.13    | 4.80    | 4.94    | 5.13    | 4.67    | 4.83    | 5.23    |         | 52°    | 0.8    | 0.8  | BB3   | 6.270 |
| 04 DEC. 1989           | 4.79                       | 4.99    | 5.18    | 4.60    | 4.80    | 5.09    | 4.78    | 4.93    | 5.13    | 4.63    | 4.79    | 5.19    |         | 52°    | -      | -    | BB3   | 6.270 |
| 01 NOV. 1990           | 4.79                       | 4.98    | 5.20    | 4.60    | 4.80    | 5.09    | 4.78    | 4.93    | 5.13    | 4.62    | 4.79    | 5.18    |         | 80°    | 1.8    | 1.4  | BB3   | 6.270 |
| 18 NOV. 1991           | 4.80                       | 4.99    | 5.20    | 4.62    | 4.83    | 5.11    | 4.79    | 4.94    | 5.14    | 4.63    | 4.80    | 5.23    |         | 86°    | 1.9    | 1.9  | BB3   | 6.278 |
| 17 DEC. 1992           | 4.74                       | 4.94    | 5.16    | 4.57    | 4.75    | 5.08    | 4.74    | 4.90    | 5.10    | 4.60    | 4.77    | 5.19    |         | 63°    | -      | -    | BB3   | 6.270 |
| 02 NOV. 1993           | 4.80                       | 5.00    | 5.19    | 4.58    | 4.79    | 5.09    | 4.70    | 4.90    | *       | 4.61    | 4.78    | 5.20    |         | 72°    | 1.4    | 2.2  | BB3   | 6.270 |

\* TOP OF BRASS BOLT BENT OVER.


COMPUTER  
AIDED  
DESIGN  
DRAFTING

LAKE PONTCHARTRAIN AND VICINITY  
BAYOU BIENVILLE  
PERIODIC INSPECTION  
WING-WALL  
SETTLEMENT REFERENCE MARKS  
PLAN AND TABULATION



U.S. ARMY ENGINEER DISTRICT, NEW ORLEANS  
CORPS OF ENGINEERS  
NEW ORLEANS, LOUISIANA


NORTHWEST WING-WALL




LEGEND

|      |   |      |   |
|------|---|------|---|
| NW-1 | ○ | NE-1 | ○ |
| NW-2 | □ | NE-2 | □ |
| NW-3 | △ | NE-3 | △ |

NORTHEAST WING-WALL




SOUTHWEST WING-WALL



LEGEND

|      |   |      |   |
|------|---|------|---|
| SW-1 | ○ | SE-1 | ○ |
| SW-2 | □ | SE-2 | □ |
| SW-3 | △ | SE-3 | △ |

SOUTHEAST WING-WALL









NOTE:  
For location and tabulation of  
settlement reference marks see  
plate

LAKE PONTCHARTRAIN AND VICINITY  
BAYOU BIENVENUE  
PERIODIC INSPECTION  
**WING-WALL  
SETTLEMENT REFERENCE MARKS  
DIFFERENTIAL SETTLEMENT CHART**



U.S. ARMY ENGINEER DISTRICT, NEW ORLEANS  
CORPS OF ENGINEERS  
NEW ORLEANS, LOUISIANA




**NOTE:**  
For location and tabulation of settlement reference marks see plate

LAKE PONTCHARTRAIN AND VICINITY  
BAYOU BIENVENUE  
PERIODIC INSPECTION  
**WING-WALL**  
SETTLEMENT REFERENCE MARKS  
DIFFERENTIAL SETTLEMENT CHART



U.S. ARMY ENGINEER DISTRICT, NEW ORLEANS  
CORPS OF ENGINEERS  
NEW ORLEANS, LOUISIANA



NORTHWEST WING WALL

FLOOD SIDE

NORTHEAST WING WALL

NW-1  
NW-2  
NW-3

CONTROL HOUSES

NE-1  
NE-2  
NE-3

GATE WALL

ROUND HEAD BRASS BOLT OR RODS (1/2" DIA. x 3" LONG)  
CENTER PUNCHES

WING WALL CAP

SW-3  
SW-2  
SW-1

SOUTHWEST WING WALL

SE-3  
SE-2  
SE-1

DETAIL "A"

DETAIL "B"


SOUTHEAST WING WALL

PROTECTED SIDE


LEVEE


STRUCTURE





LAKE PONTCHARTRAIN LA. AND VICINITY  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 PERIODIC INSPECTIONS  
**NORTHWEST WINGWALL (FY 94)**  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS






**LEGEND:**  
 ——— 16-APR-1984  
 - - - 01-NOV-1990  
 - - - 18-NOV-1991  
 - - - 17-DEC-1992  
 - - - 02-NOV-1993


NOTES:

STATION:  
 1+00.00  
 2+00.00  
 3+00.00

LAKE PONTCHARTRAIN LA. AND VICINITY  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 PERIODIC INSPECTIONS  
**SOUTHWEST WINGWALL (FY 94)**  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS







STA. 12+00 (STRUCTURE) =  
STA. 358+30 (LEVEE) 170' BASELINE

P.B.M.-BB-3

P.B.M.-BB-2

BRASS DISK STA. 33+00  
170' OFFSET

BRASS DISK STA. 6+00  
170' OFFSET

220' BASELINE

STA. 22+00  
STA. 21+00  
STA. 20+00  
STA. 19+00  
STA. 18+00  
STA. 17+50  
STA. 17+00  
STA. 16+50  
STA. 16+00  
STA. 15+50  
STA. 15+00  
STA. 14+50

MR-GO (R/W LINE)

SOUTH APPROACH CHANNEL

STRUCTURE

NORTH APPROACH CHANNEL

MISSISSIPPI RIVER GULF OUTLET  
MILE 59.0

PLAN

SCALE IN FEET  
100 50 0 100 200 300


LOADING DOCK @  
STA. 14+80

P.B.M.-BB-1


BAYOU BIENVENUE

| REVISION  | DATE | DESCRIPTION | BY |
|---|------|-------------|----|
| LAKE PONTCHARTRAIN LA. AND VICINITY<br>CHALMETTE AREA                             |      |             |    |
| BAYOU BIENVENUE CONTROL STRUCTURE<br>PERIODIC INSPECTION                          |      |             |    |
| <b>SCOUR AND OVERBANK SURVEY<br/>APPROACH CHANNELS<br/>CLOSURE DAM AND LEVEES</b> |      |             |    |
| U.S. ARMY ENGINEER DISTRICT, NEW ORLEANS<br>CORPS OF ENGINEERS                    |      |             |    |

REV. 14 MAR 83







**LEGEND:**  
 - - - - - 17-APR-1984  
 - - - - - 01-NOV-1990  
 . . . . . 17-DEC-1991  
 - . - . - 04-NOV-1993

NOTES:

STATION:


- 6+00.00
- 6+50.00
- 7+00.00

LAKE PONTCHARTRAIN LA. AND VICINITY  
 CHALMETTE AREA  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 SCOUR SURVEY (FY 94)  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS




DISTANCE IN FEET


-50    -30    -10    10    30    50    70    90    110    130    150    170    190    210    230    250    270    290    310    330    350    370    390    410    430    450



7+50.00



8+00.00



8+50.00

**LEGEND:**  
 - - - - - 17-APR-1984  
 - - - - - 01-NOV-1990  
 - - - - - 17-DEC-1991  
 - - - - - 17-DEC-1992  
 - - - - - 04-NOV-1993


NOTES:


STATION:

- 7+50.00
- 8+00.00
- 8+50.00

LAKE PONTCHARTRAIN LA. AND VICINITY  
 CHALMETTE AREA  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 SCOUR SURVEY (FY 94)  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS







LEGEND:  
 - - - - - 17-APR-1984  
 - - - - - 01-NOV-1990  
 - - - - - 17-DEC-1991  
 - - - - - 17-DEC-1992  
 - - - - - 04-NOV-1993


NOTES:


STATION:

- 10+62.00
- 11+12.00
- 11+62.00

LAKE PONTCHARTRAIN L.A. AND VICINITY  
 CHALMETTE AREA  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 SCOUR SURVEY (FY 94)  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS








**LEGEND:**  
 — 17-APR-1984  
 - - - 01-NOV-1990  
 . . . 17-DEC-1991  
 - . - 04-NOV-1993

NOTES:

STATION:  
 13+88.00  
 14+50.00  
 15+00.00

LAKE PONTCHARTRAIN LA. AND VICINITY  
 CHALMETTE AREA  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 SCOUR SURVEY (FY 94)  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS






LEGEND:  
 - - - - - 17-APR-1984  
 - - - - - 01-NOV-1990  
 - - - - - 17-DEC-1991  
 - - - - - 17-DEC-1992  
 - - - - - 04-NOV-1993

NOTES:

STATION:  
 15+50.00  
 16+00.00  
 16+50.00

LAKE PONTCHARTRAIN L.A. AND VICINITY  
 CHALMETTE AREA  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 SCOUR SURVEY (FY 94)  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS






LEGEND:  
 — 17-APR-1984  
 - - - 01-NOV-1990  
 . . . 17-DEC-1991  
 - . - . 17-DEC-1992  
 - - - - 04-NOV-1993

NOTES:

STATION:  
 17+00.00  
 17+50.00  
 18+00.00

LAKE PONTCHARTRAIN LA. AND VICINITY  
 CHALMETTE AREA  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 SCOUR SURVEY (FY 94)  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS






**LEGEND:**  
 - - - - - 17-APR-1984  
 - - - - - 01-NOV-1990  
 . . . . . 17-DEC-1991  
 - . - . - 04-NOV-1993

NOTES:

**STATION:**  
 19+00.00  
 20+00.00  
 21+00.00

LAKE PONTCHARTRAIN LA. AND VICINITY  
 CHALMETTE AREA  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 SCOUR SURVEY (FY 94)  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS



LEGEND:  
 — 17-APR-1984  
 - - - 01-NOV-1990  
 . . . 17-DEC-1991  
 - . - . 04-MAY-1993

NOTES:

STATION:

22+00.00

LAKE PONTCHARTRAIN LA. AND VICINITY  
 CHALMETTE AREA  
 BAYOU BIENVENUE CONTROL STRUCTURE  
 SCOUR SURVEY (FY 94)  
 U.S. ARMY ENGINEERS, NEW ORLEANS CORPS OF ENGINEERS