ARM Nauru Research Station
Site Visit 0407N Report

Visit Duration: 5 July to 12 July

Nauru Island, Republic of Nauru

SV0407N					
Site:Nauru	Proposed Dates on Site: July 05-16				
Team Members: • Rex Pearson • Troy Culgan David Kratzman	Ship or hand carry prior to SV: Loggers and associated parts.				
	Safety: Major Hazards: AC electricity.				
	Hazard Controls: BOM Electrolyser Handbook, BM Electrolyzer Operations/Maintenance Training, ASNZS 4836/2001-Safe Working on LV Electrical Installations, 2 man rule.				

Site Tasks

Pr		Date	Service Time	Tasks/Assoc Hazards-Controls	
Priority	System	Completed	in Hours	For each priority item insert new line(row) for each date/time entry	
ity		(dd/Month)			
				Install new Campbell Logger for SkyRAD/ Electrical- ASNZS	
1	LOGGERS			4836/2001	
				Skyrad ingest turned off at 2230z 5July. Skyrad old logger removed	
				and installation of campbell logger commenced. Campbell logger	
				installation completed at 0500z 6July and data collection turned on	
				on logger net PC. Problems experienced with the NL100	
				serial/ethernet converter. We used the unit from the Smet system	
				and reprogrammed the IP via telent to the correct IP address for the	
		6 Jul 04	12	skyrad. Will investigate the NL100 problem tomorrow.	
				Install new Campbell Logger for GndRAD/ Electrical- ASNZS	
2	LOGGERS			4836/2001	
				Removed old gndrad logger at ~1020z. Commenced installation of	
		5 Jul 04	4	new campbell logger on to gndrad stand.	
				Gndrad logger connected to the Loggernet PC and cal coefficients	
		5 Jul 04	2	loaded into .csi program and downloaded to the logger	
		0 1.1 04	0	Completed loggernet view screen and initialised data collection of	
		6 Jul 04	2	loggernet at 2202Z 5 July Install new Campbell Logger for SMET/ Electrical- ASNZS	
2	LOGGERS			Install new Campbell Logger for SME1/ Electrical- ASNZS 4836/2001	
3	LOGGENS			4030/2001	
				Smet ingest and collection system turned off at 2030z 6July. Zeno	
				logger system removed from service. Replacement mounting	
				system constructed to take Hoffman Smet logger case on the Smet	
				stand. Commenced installation of the Smet logger system. NL100	
				communications problems sorted out - forced the NL100 back to	
				factory defaults and reprogrammed. Campbell logger installed and	
				communications tested. TRH probe and wind heads installed and	
		7 Jul 04	20	tested.	
		33.		Replaced ORG cable to allow sufficient length to connect to new	
				logger. Completed installation of Smet logger. Water was sprayed	
		8 Jul 04	7	across the org to confirm it was functioning.	
				Rewired ORG connection to include the carrier signal so it can be	
				remotely monitored for fault analysis. New smet.csi file loaded into	
		10 Jul 04	2	logger.	
4	LOGGERS			Install LoggerNet System/ Electrical- ASNZS 4836/2001	
		5 Jul 04	2	Continued installation of logger net PC in D Van.	
				Replicated loggernet monitoring screen to match Darwin overview	
		6 Jul 04		screen for all 3 systems	
\vdash		7 Jul 04		Added Smet data to loggernet PC	
		8 Jul 04	2	Added additional screen monitoring facilities	
		40 1 04	4	Added new smet.csi file to allow monitoring of the ORG carrier	
		10 Jul 04	1	signal.	
		44 1		Made a disk image of the Neurolana at DO for harden	
		11 Jul 04	1	Made a disk image of the Nauru loggernet PC for backup purposes	

5	UVB			Remove UVB, Pack and Ship/ Electrical- ASNZS 4836/2001
Priority	System	Date Completed (dd/Month)	Service Time in Hours	Tasks/Assoc Hazards-Controls For each priority item insert new line(row) for each date/time entry
Υ		6 Jul 04	0.5	UVB removed at 2230z 5July.
		0 00. 0 1	0.0	H2Gen maintenance/ KOH,H2,Electrical- BOM Handbook, ASNZS
6	H2GEN			4836/2001, 2 man rule
		9 Jul 04		H2 gen maintenance commenced
		10 Jul 04		H2 gen maintenance completec
	AEDI	11 Jul 04	4	Spares inventory checked spare compressor cleaner
- /	AERI	11 Jul 04	0.5	Change out Fine Particle Filters/None Filter changed
8	AWS	11 Jul 04	0.5	Change out fan in Sat Phone/None
	71110	10 Jul 04	1	Fan changed out
9	CEIL			Change out internal battery/None
				Internal battery changed out. Status screen indicates the battery is
		10 Jul 04		low, will monitor or charge it externally then refit.
- 10	E0011	11 Jul 04	1	Ceil battery has come up ok after charging.
10	ES&H	40 11 04	2	Change out Smoke Alarms/None
		10 Jul 04 10 Jul 04		Change out smoke alarms in D& E Vans Smoke alarm in U & I van changed out
11	ES&H	10 Jul 04	_	Lock Out/Tag Out Procedure Training/None
	Loui	8/9/10 Jul04	2	Proceedure reinforcedwith observers during A/C installation
12	IRT	0,0,1000.	_	Change out Skyrad IRT Gold Mirror/None
		5 Jul 04	0.5	Mirror changed out
13	HVAC			AE Smith replace Bard units with split units in E & U vans.
				Equipment arrived from Brisbane and Dave has commenced
		8 Jul 04	6	installation of the split A/C unit in the U Van.
		0 1 104	40	U Van A/C installation completed. Commenced installation of units
		9 Jul 04 10 Jul 04		in the E Van. Continued installation of E Van units
		10 Jul 04	10	Completed installation of A/C units and inventory of equipment on
		11 Jul 04	8	site
14	HVAC	11 301 04	0	AE Smith perform general maintenance on all ac units
				gordon gordon de antico
		5 Jul 04	3	Baird unit in E Van is now working in a temp fashion. Awaiting for the equipment to arrive from Brisbane to install the split units.
		6 Jul 04	10	Continued maintenance of existing A/C units. Drains connected to existing A/C units to prevent water flowing under the vans.
				Completed general maintenance. Robroy (using his old Air Nauru
				contacts) has tried to ensure Air Nauru will ship tools and 1 A/C
		7 Jul 04	6	tomorrow as a minimum.
15	GENSET	0.1.104		Hastings Deering to perform normal genset maintenance
16	VANS	9 Jul 04		Had confirmation HD will not be on site with us Change out the white van door locks
10	VAINS	5 Jul 04	1.5	Locks changed out on white vans – observers given keys.
		0 001 04	1.0	Work on possible balloon proceedures to allow use of 40mm
17	BBSS			balloons
				Initial tests of possible proceedure to attach bungs to 40mm
		8 Jul 04	3	balloons. 1 test flight to be done to see if system works
				Test flight completed balloon went for 89 minutes and got to
		8 Jul 04	2	24370ft.
		0 101 04	2	Additional tests on night time launch and lunchtime launch indicate the proceedure is repeatable. 2 launches today were successful proceedure appears to be repeatable.
18	I Van UPS	9 Jul 04		Prevent accidental use of UPS power in I Var
10	. van or o			UPS in I van was tripped because the ups power was used to run
				power saw. The UPS locked its self out due to the high overload. A proceedure will be written on how to reset the unit if this happen again, and we will investigate means of preventing this happening
		8 Jul 04		again.
		9 Jul 04		Commenced documentation for UPS reset procedure
		10 Jul 04	2	Completed UPS documentation
		40.1.16		Require piece of perspex 19¾ x 16 inches. This will prevent acce to the 110v UPS protected outlets. Will purchase in Darwin and
		12 Jul 04	1	ship to Nauru.
19	SAM	8 Jul 04	1	Check I Van monitoring - Monty Apple reported TRH readings high Checked and replaced TRH sensor in I Var
	!	5 50i 07	<u>'</u>	

Maintneance to be per 15-Jul-04

20	SDS			Impliment BCR796		
		Date	Service Time	Tasks/Assoc Hazards-Controls		
Priority	System	Completed (dd/Month)	in Hours	For each priority item insert new line(row) for each date/time entry		
_		,		Confirm installation and operation of Aboutime on Win98 machines		
		9 Jul 04	2	and that both time sources are installed		
21	EH&S			Install eyewash station		
		10 Jul 04	2	Eyewash station installed and filled		
				Note: Solution has to be changed every 6 months - this no		
				to be put on the maintenance schedule		
				Check and replace sun sensor if necessary - check settings as per		
22	Skyrad			email from C. Long		
		11 Jul 04	3	Checked sun sensor on skyrad tracker. Moisture was evident on the inside of the lens. The sun sensor was dismantled and a reasonable quantity of water darined from the unit. There was evidence of corrosion on the printed circuit board terminals. We decided to change the unit as it's reliability would be questionable. The replacement unit also appeared to have a droplet of moisture on the lens assembly (we are not sure if this was moisture or glue). The new unit was installed and alignment values updated, time checked and sunsonsor tracking value adjusted. As a precaution we put vulcanising tape on the upper and lower joints of the sensor to help prevent water getting in.		
23	Housekeepi			General cleanup		
				·		
				Removed old cables etc in storage van, general cleanup of shelves		
		11 Jul 04		stored spare satellite equipment on lower shelf of storage van		
		12 Jul 04	l 8	Redied equipment for shipping		
0.4				11 11 5		
24	Emwin			Check and repair Emwin system		
24	Emwin	11 Jul 04		11 11 5		
24	Emwin		4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file.		
		12 Jul 04	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software		
	Emwin Observer Po	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc		
25	Observer Po	12 Jul 04	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated		
25		12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None		
25	Observer Po	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror		
25	Observer Po	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866		
25	Observer Po	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans, cables and spare parts		
25	Observer Post	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866		
25	Observer Po	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans,cables and spare parts K&Z sun sensor List items needed for future visits (spares, etc)/ None		
25	Observer POSHIPPING	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans,cables and spare parts K&Z sun sensor List items needed for future visits (spares, etc)/ None DB9 female plugs and sockets - solder type		
25	Observer POSHIPPING	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans,cables and spare parts K&Z sun sensor List items needed for future visits (spares, etc)/ None DB9 female plugs and sockets - solder type 100mm shifting spanner		
25	Observer POSHIPPING	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans,cables and spare parts K&Z sun sensor List items needed for future visits (spares, etc)/ None DB9 female plugs and sockets - solder type 100mm shifting spanner		
25	Observer POSHIPPING	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans,cables and spare parts K&Z sun sensor List items needed for future visits (spares, etc)/ None DB9 female plugs and sockets - solder type 100mm shifting spanner 150mm shifting spanner		
25	Observer POSHIPPING	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans,cables and spare parts K&Z sun sensor List items needed for future visits (spares, etc)/ None DB9 female plugs and sockets - solder type 100mm shifting spanner 150mm shifting spanner		
25	Observer POSHIPPING	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans,cables and spare parts K&Z sun sensor List items needed for future visits (spares, etc)/ None DB9 female plugs and sockets - solder type 100mm shifting spanner 150mm shifting spanner 174 inch ss full nuts Metric drill set Imperial allen key set		
25	Observer POSHIPPING	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans,cables and spare parts K&Z sun sensor List items needed for future visits (spares, etc)/ None DB9 female plugs and sockets - solder type 100mm shifting spanner 150mm shifting spanner 174 inch ss full nuts Metric drill set Imperial allen key set 12 volt 17AH battery for UPS - 140mm x 48mm x 48mm size		
25	Observer POSHIPPING	12 Jul 04 C's etc	4	Check and repair Emwin system Emwin computer was not booting. It appears the file system has become corrupted. A repair was done on the hard disk which allowed the computer to boot to Windows, but the Emwin software would not load. Found missing dll and vbx files. Was able to find most of them on the net and have most of the system now running except for what appears to be one file. Additional checks unsuccessful, may need a reload of the software Update software as required (windows updates etc Software updated List items to be shipped following visit/ None IRT gold mirror UVB serial number 2866 Zeno loggers, cans,cables and spare parts K&Z sun sensor List items needed for future visits (spares, etc)/ None DB9 female plugs and sockets - solder type 100mm shifting spanner 150mm shifting spanner 174 inch ss full nuts Metric drill set Imperial allen key set		

