

NEW ORLEANS TO VENICE, LOUISIANA

HURRICANE PROTECTION


REACH B-1 - TROPICAL BEND TO FORT JACKSON

## EMPIRE FLOODGATE

### PERIODIC INSPECTION REPORT NO. 4

RETURN TO Structures Inspection Unit

PERIODIC INSPECTION  
31 JANUARY 1984



**United States Army  
Corps of Engineers**

*...Serving the Army  
...Serving the Nation*

**New Orleans District**

LMVED-GS (NOD 6 Jul 84) 5th Ind

SUBJECT: New Orleans to Venice, Louisiana (Hurricane Protection);  
Reach B-1 - Tropical Bend to Fort Jackson, Empire Floodgate,  
Periodic Inspection Report No. 4, 31 January 1984

DA, Lower Mississippi Valley Division, Corps of Engineers, Vicksburg, MS 39180-0080

04 JAN '85

TO: Commander, New Orleans District, ATTN: LMNED-G

The disposition of comments in the preceding 4th Ind is satisfactory. No further action is required on this correspondence chain.

FOR THE COMMANDER:



R. H. RESTA, P.E.  
Chief, Engineering Division

wd incl



DEPARTMENT OF THE ARMY  
NEW ORLEANS DISTRICT, CORPS OF ENGINEERS  
P. O. BOX 60267  
NEW ORLEANS, LOUISIANA 70160

REPLY TO  
ATTENTION OF:

LMNED-DG

6 July 1984

SUBJECT: New Orleans to Venice, Louisiana (Hurricane Protection);  
Reach B-1 - Tropical Bend to Fort Jackson, Empire Floodgate,  
Periodic Inspection Report No. 4, 31 January 1984

Commander, Lower Mississippi Valley Division  
ATTN: LMVED-G

Subject report is submitted herewith for your approval.

FOR THE COMMANDER:

1 Incl (6 copies)  
as

FREDERIC M. CHATRY  
Chief, Engineering Division

S: 19 Oct 84

LMVED-GS (NOD 6 Jul 84) 1st Ind

SUBJECT: New Orleans to Venice, Louisiana (Hurricane Protection);  
Reach B-1 - Tropical Bend to Fort Jackson, Empire Floodgate,  
Periodic Inspection Report No. 4, 31 January 1984

DA, Lower Mississippi Valley Division, Corps of Engineers, Vicksburg, MS 39180

20 SEP '84

TO: Commander, New Orleans District, ATTN: LMNED-DG

1. The inclosed periodic inspection report is approved subject to the following comments:

a. Para 3-02b. It was understood by LMVD personnel who participated in the third periodic inspection of this project that the joint between the sheet pile I-wall and the concrete T-wall will be modified and made watertight when the I-wall is capped with concrete. This procedure was documented in the 1st and 2d Inds to LMNED-DG letter, 23 Nov 81, subject: New Orleans to Venice, Louisiana (Hurricane Protection); Reach B-1 - Tropical Bend to Fort Jackson, Empire Floodgate, Periodic Inspection Report No. 3, 29 Jul 81. We still concur in this plan of action.

b. Para 4-02d.

(1) This paragraph should contain a complete discussion on all settlement reference marks. In this regard, the discussion on settlement data for the sheet pile I-walls should be included in this paragraph in lieu of para 5-03.C.1. In the discussion of settlement data for the T-walls, it should be indicated that the settlement data on Plates I-3 and I-4 show that settlement of the T-walls is essentially complete with the exception of settlement mark 20 which indicates that the east end of the east T-wall is continuing to settle.

(2) This report should include time-settlement plots for the I-wall settlement reference marks. Note that this was discussed in para g(2) of the 1st Ind to the LMNED-DG letter of 23 Nov 81 referenced in para 1a above.

c. Para 5-03A.1.b and 5-03C.3.

(1) There appears to be a conflict between these two paragraphs. Paragraph 5.03A.1.b indicates that there is no substantial change in recent joint measurements between reference marks RM-18 and RM-19 and concludes that the wall foundation seems to have stabilized. However, paragraph 5-03C.3 indicates that the joint between T-wall monoliths T-4R and T-3R is continuing to widen as seen from the measurement of distances between RM-18 and RM-19. This discrepancy should be reconciled. In this regard, settlement data for RM-20 indicate that the east end of monolith T-4R is continuing to settle, as discussed in para 1b above, therefore, the joint between monolith T-4R and T-3R will likely continue to widen until settlement is complete.

S: 19 Oct 84

LMVED-GS (NOD 6 Jul 84) 1st Ind 20 SEP '84

SUBJECT: New Orleans to Venice, Louisiana (Hurricane Protection);  
Reach B-1 - Tropical Bend to Fort Jackson, Empire Floodgate,  
Periodic Inspection Report No. 4, 31 January 1984

(2) These paragraphs should discuss the condition of the waterstop at the joint between monoliths T-4R and T-3R. If the waterstop is ruptured or if it becomes ruptured due to increased widening of the joint, this joint will have to be resealed.

d. Para 5-03A.1.d. The decayed timbers addressed in this paragraph should be replaced prior to any future dewatering operation.

e. See additional comments in red on pages III-1 and V-1 through V-4. These corrections may be made in your file copies of the report.

2. The report should be revised in accordance with above comments in paras 1a through 1d and revised pages of the report should be furnished to this office by 19 Oct 84.

FOR THE COMMANDER:

1 Incl (dupe)  
wd 4 cy

*for Robert J Kaufman, P.E.*  
*R. H. RESTA, P.E.*  
*Chief, Engineering Division*

LMNED-DG (6 July 1984) 2d Ind

SUBJECT: New Orleans to Venice, Louisiana (Hurricane Protection);  
Reach B-1-Tropical Bend to Fort Jackson, Empire Floodgate,  
Periodic Inspection Report No. 4, 31 January 1984

DA, New Orleans District, Corps of Engineers, P. O. Box 60267, New Orleans,  
Louisiana 70160-0267 23 Oct 84

TO: Commander, Lower Mississippi Valley Division, ATTN: LMVED-DG

1. The disposition of comments presented in the 1st Ind follows. Paragraph numbers refer to like numbered paragraphs in the indorsement. Duplicate copies of inclosures are submitted for your files.

a. Para 3-02b. The sheet pile I-wall will be capped with concrete upon completion of primary consolidation, at which time the joint between the I-wall and T-wall will be modified and made watertight. Monitoring of the sheet piling will continue until primary consolidation has leveled off.

b. Para 4-02d.

(1) Concur. See Inclosure 2.

(2) Concur. Time settlement plots for the I-wall settlement reference marks for 1984 data are being completed by our drafting personnel. They will be distributed to your office upon completion within 45 days.

c. Para 5-03 A1.b and 5-03C.3.

(1) Reference to RM-18 and RM-19 has been deleted in paragraph 5-03A.1.b. Inclosure 3.

(2) The waterstop at the joint between monoliths T-4R and T-3R was in good condition at the time of inspection. If it becomes ruptured due to increased widening of the joint, this joint will be resealed as indicated. See Inclosures 2 and 3.

d. Para 5-03A.1.d.. Concur. See Inclosure 3.

e. The additional comments in red on Pages III-1, V-1 and V-4 have been made in our file copy.

FOR THE COMMANDER:



2 Incls  
wd Incl 1  
Added 2 Incls (dupe)  
2 & 3  
as

FREDERIC M. CHATRY  
Chief, Engineering Division

S: 21 Dec 84

LMVED-GS (NOD 6 Jul 84) 3d Ind

SUBJECT: New Orleans to Venice, Louisiana (Hurricane Protection);  
Reach B-1 - Tropical Bend to Fort Jackson, Empire Floodgate,  
Periodic Inspection Report No. 4, 31 January 1984


DA, Lower Mississippi Valley Division, Corps of Engineers, Vicksburg, MS 39180-0080

14 NOV '84  
TO: Commander, New Orleans District, ATTN: LMNED-G

The disposition of comments in the preceding 2d Ind is satisfactory subject  
to the following comment:

Para 1b(2). The time-settlement plots discussed in this paragraph should  
be submitted by 4th Ind to this correspondence chain NLT 21 Dec 84.

FOR THE COMMANDER:



wd incl

R. H. RESTA, P.E.  
Chief, Engineering Division

LMNED-DG (6 July 1984) 4th End Mr. Drummond/ds/2711  
SUBJECT: New Orleans to Venice, Louisiana (Hurricane Protection); Reach B-1-Tropical Bend to Fort Jackson, Empire Floodgate, Periodic Inspection Report No. 4, 31 January 1984

DA, New Orleans District, Corps of Engineers, P. O. Box 60267, New Orleans, Louisiana 70160-0267, 13 Dec 84

TO: Commander, Lower Mississippi Valley Division,  
ATTN: LMVED-DG

The disposition of comments presented in the 3d End follows. Paragraph numbers refer to like numbered paragraphs in the endorsement. Duplicate copies of enclosures are submitted for your files.

Para 1b(2). The time settlement plots for the I-wall settlement reference marks for 1984 data are submitted for your files. See Encl 4.

FOR THE COMMANDER:

1 Encl (Dupe)

*William B. Doak*  
FREDERIC M. CHATRY  
Chief, Engineering Division

NEW ORLEANS TO VENICE, LOUISIANA  
HURRICANE PROTECTION  
REACH B-1 - TROPICAL BEND TO FORT JACKSON  
EMPIRE FLOODGATE  
PERIODIC INSPECTION REPORT NO. 4

31 JANUARY 1984

U.S. ARMY ENGINEER DISTRICT  
CORPS OF ENGINEERS  
NEW ORLEANS, LOUISIANA

S U M M A R Y

The Empire Floodgate was inspected on 31 January 1984 by representatives of NOD and the Plaquemines Parish Commission Council and found to be stable and structurally sound. Minor discrepancies are noted within.




PHOTO TAKEN 28 JULY 1976

EMPIRE FLOODGATE

EMPIRE FLOODGATE

PERIODIC INSPECTION NO. 4

TABLE OF CONTENTS

<u>Para. No.</u>	<u>Description</u>	<u>Page No.</u>
<u>SECTION I - INTRODUCTION</u>		
1-01	Authority	I-1
1-02	Purpose and Scope	I-1
1-03	Datum	I-1
1-04	Previous Inspections	I-1
<u>SECTION II - PROJECT DESCRIPTION AND BACKGROUND</u>		
2-01	General	II-1
<u>SECTION III - CURRENT OPERATION &amp; MAINTENANCE DATA</u>		
3-01	Operating Statistics	III-1
3-02	Maintenance & Operating Problems	III-1
3-03	Actions of Deficiencies From Last Inspection	III-1
<u>SECTION IV - REVIEW OF DESIGN &amp; ANALYSIS OF INSTRUMENTATION</u>		
4-01	Review of Design	IV-1
4-02	Analysis of Instrumentation Data	IV-1
	Instrumentation Plates	IV-3
<u>SECTION V - INSPECTION</u>		
5-01	Inspection Team	V-1
5-02	Orientation	V-1
5-03	Observations	V-1
<u>SECTION VI - CONCLUSIONS AND REMEDIAL ACTION</u>		
6-01	Conclusions	VI-1
6-02	Remedial Actions	VI-1
6-03	Next Inspection	VI-2

## SECTION I - INTRODUCTION

1-01 Authority. Authority is provided by ER 1110-2-100, subject, "Periodic Inspection and Continuing Evaluation of Completed Civil Works Structures."

1-02 Purpose and Scope. The results and conclusions of the inspection and evaluation for assuring the structural integrity and operational adequacy of the structure are presented herein.

1-03 Datum. All elevations, except where otherwise indicated, are in feet and refer to the National Geodetic Vertical Datum (NGVD), formerly Mean Sea Level (m.s.l.).

### 1-04 Previous Inspections.

<u>Report No.</u>	<u>Date of Inspection</u>	<u>Date Report Approved</u>
1	4 Sep 75	7 Apr 76
2	4 Oct 78	13 Aug 79
3	29 Jul 81	20 Oct 82

## SECTION II - PROJECT DESCRIPTION AND BACKGROUND

2-01 General. The description of the structure, historical and other general background information, are included in report no. 1 which also contains selected construction drawings illustrating typical sections and details. A location map for this project is included in this report (plate I-1). This report is supplementary to previously numbered reports.

SECTION III - OPERATING AND MAINTENANCE DATA

3-01 Operation and Maintenance Problems. The following work was done at the structure since the last inspection.

- a. May 1982 - dredged gate area.
- b. June 1982 - replaced lights & shutters, dredged gate area.
- c. December 1982 - shelled bank.
- d. January 1983 - maintenance work on handrails, miscellaneous cleaning and painting.

3-02 Action on Deficiencies From Last Inspection. Refer to Periodic Inspection Report No. 3, Section VI - Conclusions and Remedial Actions.

- a. Item 6-02(a), monitor T-wall monoliths for further signs of movement, is being accomplished by Government hired labor forces.
- b. Item 6-02(b), openings between the sheetpiling and T-wall monolith interfaces, has not been repaired at the time of this inspection but will be monitored by Government hired labor forces for further movement.
- c. All other remedial actions, Items 6-02(c) thru (k), have been accomplished by the Plaquemines Parish Commission Council during regular scheduled maintenance periods.

## SECTION IV - REVIEW OF DESIGN & ANALYSIS OF INSTRUMENTATION

4-01 Review of Design. A detailed comparison of the original design criteria to current design criteria was recorded in Periodic Inspection Report No. 1, dated September 1975. A review of this comparison shows that the original design is equal to or is more conservative than current design criteria. The allowable working stresses for concrete and structural steel are in accordance with those recommended in "Working Stresses for Structural Design," EM 1110-1-2101, dated November 1963, through change 2 dated 17 January 1972, which is still current. The actual conditions experienced at the floodgate since design and construction have not exceeded the conditions investigated in the design review. There have been no appreciable changes in design criteria, assumptions or function of this structure; therefore, a detailed design analysis is not required.

### 4-02 Analysis of Instrumentation Data.

a. General. The following chart indicates the type, location and schedule for reading of each type of instrumentation:

<u>Instrumentation Devices</u>	<u>Observation Schedule</u>
1. <u>Settlement</u>	
20 reference marks on structure & floodwall	Annually
18 reference marks on steel sheet pile walls	Annually

2. <u>Scour Survey</u>	Annually
20 ranges in approach channels	
3. <u>Floodwall Alinement</u>	Annually
16 measurements on floodwalls	
4. <u>Distance Across Chamber</u>	Annually
2 measurements across chamber	
5. <u>Joint Measurement</u>	Annually
12 measurements across joints	

The concrete T-walls are instrumented with reference marks in order to measure settlement, changes in alignment, and movement at the joints while the sheetpile I-walls are instrumented with settlement reference marks to determine when settlement of the levee is essentially completed.

b. Scour Survey. Recent scour surveys indicate no appreciable scouring has occurred since the last inspection.

c. Alinement. The alinement surveys indicate an apparent movement to the north.

\* d. Settlement. Plates I-4 and I-4A indicate rather excessive settlement at reference mark 20 and the steel sheet piling at both ends of the structure. Settlement of the T-walls is essentially complete with the exception of settlement mark 20 which indicates that the east end of the east T-wall is continuing to settle. All settlement reference marks indicate that the levee supporting the sheet piling sections on each end of the structure is undergoing consolidation.

However, the resulting settlements have been anticipated and will continue until the completion of primary consolidation, at which time the sheet pile will be capped. Monitoring of the sheet piling should be continued until primary consolidation has leveled off.

2. <u>Scour Survey</u>		
20 ranges in approach channels		Annually
3. <u>Floodwall Alinement</u>		
16 measurements on floodwalls		Annually
4. <u>Distance Across Chamber</u>		
2 measurements across chamber		Annually
5. <u>Joint Measurement</u>		
12 measurements across joints		Annually

The concrete T-walls are instrumented with reference marks in order to measure settlement, changes in alignment, and movement at the joints while the sheetpile I-walls are instrumented with settlement reference marks to determine when settlement of the levee is essentially completed.



b. Scour Survey. Recent scour surveys indicate no appreciable scouring has occurred since the last inspection.

c. Alinement. The alinement surveys indicate an apparent movement to the north.

d. Settlement. Plates I-4 and I-4A indicate rather excessive settlement at reference mark 20 and the steel sheet piling at both ends of the structure.

4-03 Instrumentation Plates.

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
1	Location Map	H-4-26081
I-1	Location of Instrumentation	H-4-27323
I-2	Alinement and Settlement Reference Marks - Tabulation	H-4-27323
I-2A	Alinement Differential Chart	H-4-27323
I-3	Settlement and Reference Marks Differential Movement	H-4-27323
I-4	Settlement and Reference Marks Differential Movement	H-4-27323
I-4A	Differential Chart	
I-5	Profile Survey N. App. Channel	H-4-27323
I-5A	Profile Survey S. App. Channel	
I-6	Scour Survey	
I-7	Scour Survey	
I-8	Scour Survey	
I-9	Scour Survey	
I-10	Scour Survey	
I-11	Scour Survey	



---

**INDEX TO DRAWINGS**

Note: See dwg. 2 for tabulation of bench marks.

U.S. ENGINEER DISTRICT NEW ORLEANS  
CORPS OF ENGINEERS

NEW ORLEANS TO VENICE, LOUISIANA  
ICANIC PROTECTION, REACH B-1  
**EMPIRE FLOODGATE**  
PLAQUEMINES PARISH, LA.  
**LOCATION MAP VICINITY**  
**MAP AND INDEX**

H-4-26081

64








PLATE I-1





NOTE: FOR LOCATION OF SETTLEMENT REFERENCE  
MARKS SEE PLATE.  
FOR TABULATION OF ELEVATIONS SEE PLATE.

LEGEND

○ RM-9  
△ RM-9A  
□ RM-11

NOTE: ALL POINTS PLOTTED AFTER 1979 ARE  
USING THE EQUATION  $(R-R_0) - 1.51 = \text{DIFF.}$ ;  
SEE TABULATION CHART FOR FURTHER  
INFORMATION.

NEW ORLEANS TO VENICE, LA.

HURRICANE PROTECTION REACH B-1

PERIODIC INSPECTION





EMPIRE FLOODGATE

#### SETTLEMENT AND REFERENCE MARKS DIFFERENTIAL'S MOVEMENT

U.S. ARMY ENGINEER DISTRICT, NEW ORLEANS  
CORPS OF ENGINEERS

FILE NO H-4-27323

PLATE I-3



NOTE: FOR LOCATION OF SETTLEMENT REFERENCE MARKS  
SEE PLATE.  
FOR TABULATION OF ELEVATIONS SEE PLATE.

NOTE: ALL POINTS PLOTTED AFTER 1979 ARE USING  
THE EQUATION  $(R-R_1) \cdot 15 = \text{DIFF}$ ; SEE TABULATION  
CHART FOR FURTHER INFORMATION.

LEGEND

- —○— RM-17
- △ —△— RM-18
- —□— RM-19
- —●— RM-20


NEW ORLEANS TO VENICE, LA.  
HURRICANE PROTECTION REACH B-1  
PERIODIC INSPECTION  
EMPIRE FLOODGATE

SETTLEMENT AND REFERENCE MARKS  
DIFFERENTIAL'S MOVEMENT

U. S. ARMY ENGINEER DISTRICT, NEW ORLEANS  
CORPS OF ENGINEERS

FILE NO H-4-27323


PLATE I-4






NEW ORLEANS TO VENICE, LA.  
HURRICANE PROTECTION REACH B-I  
PERIODIC INSPECTION  
EMPIRE FLOODGATE

**REFERENCE MARKS  
DIFFERENTIAL CHART**

U.S. ARMY ENGINEER DISTRICT, NEW ORLEANS  
CORPS OF ENGINEERS






FOOTING	ANCHOR	DOOR	STAIR
01	02	03	04
05	06	07	08
09	10	11	12
13	14	15	16
17	18	19	20


NOTE:  
VERTICAL PLOTTED LOOKING NORTH


N.O. TO VENICE  
HURR PROT REACH


EMPIRE FLOODED S.J. APP. CHANN  
PROFILE SURVEY (77-03)


U.S. ARMY ENGINEER NEW ORLEANS CORPS OF ENGINEERS  
SHEET OF APR. 1985 FILE NO.  
PLATE I-5A














## SECTION V- INSPECTION

5-01 Inspection Team. The inspection of the structure was conducted on 31 January 1984 by the following personnel:

### NOD

Johnny Drummond  
Harvey Sims  
Angel Misland  
Kevin Healy  
Richard Baldini  
Mohan Desai

General Engineering Section  
General Engineering Section  
Hydraulics & Hydrologic Branch  
Foundations & Materials Branch  
Operation Division  
Structural Design Section

### PLAQUEMINES PARISH COMMISSION COUNCIL

Henry Urban

5-02 Orientation. Prior to the inspection, the team members were given a brief orientation of the following features of the structure: Hydraulic and hydrology, structural considerations, foundations, operating machinery and construction history.

5-03 Observations. The floodgate was not dewatered at the time of the inspection, therefore, the following observations were limited to those visible above the water surface.

#### A. Structure.

1. Reinforced Concrete. The overall appearance of the concrete was good. With the exception of a few minor flaws, no unusual deterioration was noticed.

a. Floodwall. There were some temperature and shrinkage cracks on the stem and walkway area of T-wall monolith T-4R. Some of

these cracks were noted in previous inspection reports and showed no signs of activity.

b. Joints. The recent joint measurements between \*reference marks RM2-RM3 and RM4-RM5 show no substantial change from the previous ones. The wall foundation seems to have stabilized but these measurements will continue to be monitored. The waterstop at the joint between monoliths T-4R and T-3R was in good condition.\*

c. Gatebay Monolith. A minor concrete popout was noticed on the top surface of the west side wall (Photo 1). Some handrail post anchors and a safety chain at a bulkhead recess were missing. To avoid further deterioration of the concrete, the spall should be repaired with epoxy concrete. Also, the missing post anchors and chain should be installed to avoid hazardous conditions.

d. Needle Storage Rack. The steel girders are well painted and the concrete needles are in very good condition. Some timbers are decayed but have no significant effect on structure. They \*should be replaced prior to any future dewatering operation.

2. The gate seems to be in good condition except for damage to the gate skin plate due to an accidental impact by a vessel (Photo 2). This damage is not effecting the operational condition of the gate.

3. Timber Guidewalls. Timber guidewalls are in good condition.

B. Hydraulic & Hydrology.

1. The breakwater dike on the west bank of the south approach channel has lost practically all the riprap. The embankment seems to be lower than the design elevation which is +3.0 feet MSL.

2. The staff gage on the guidewall should be painted again. It is difficult to read the elevations. The lowest elevation that can be read is 4 feet.

C. Foundations & Materials.

\* 1. All banks are in good condition.

2. Reference mark No. 20 shows excessive settlement at the east edge of the outer T-wall monolith T-4R. It was observed that the joint between monolith T-4R and the adjoining T-3R is widening at the top as can also be seen from the measurements of distance between marks 18 and 19 (Photo 3) presented on Plate I-2. It appears from these observations that monolith T-4R is rotating due to settlement under its outermost edge. Minor cracks were also observed at the top of monolith T-4R, one of which continued down each side of the monolith. It is recommended that monolith T-4R be monitored closely in the future to determine if the rate of settlement of the monolith and its pile foundation will decrease as primary consolidation of the surrounding soils levels off. The waterstop at the joint between monoliths T-4R and T-3R was in good condition. If it becomes ruptured due to increased widening of the joint, this joint will be resealed.\*

## SECTION V - INSPECTION

5-01 Inspection Team. The inspection of the structure was conducted on 31 January 1984 by the following personnel:

### NOD

Johnny Drummond	General Engineering Section
Harvey Sims	General Engineering Section
Angel Mislan	Hydraulics & Hydrologic Branch
Kevin Healy	Foundations & Materials Branch
Richard Baldini	Operations Division
Mohan Desai	Structural Design Section

### PLAQUEMINES PARISH COMMISSION COUNCIL

Henry Urban

5-02 Orientation. Prior to the inspection, the team members were given a brief orientation of the following features of the structure: Hydraulic and hydrology, structural considerations, foundations, operating machinery and construction history.

5-03 Observations. The floodgate was not dewatered at the time of the inspection, therefore, the following observations were limited to those visible above the water surface.

#### A. Structure.

1. Reinforced Concrete. The overall appearance of the concrete was good. Excluding few minor flaws, no unusual deterioration was noticed.

a. Floodwall. There were some temperature and shrinkage cracks on the stem and walkway area of the T-wall

monolith T-4R. Some of these cracks were noted in previous inspection reports and showed no signs of activity.

b. Joints. The recent joint measurements between reference marks RM2-RM3, RM4-RM5 and RM18-RM19 show no substantial change from the previous ones. The wall foundation seems to have stabilized but these measurements will continue to be monitored.

c. Gatebay Monolith. A minor concrete popout was noticed on the top surface of the west side wall (Photo 1). Some handrail post anchors and a safety chain at bulkhead recess were missing. To avoid further deterioration of the concrete, pot hole should be repaired with epoxy concrete. Also, the missing post anchors and chain should be installed to avoid hazardous conditions.

d. Needle Storage Rack. The steel girders are well painted and the concrete needle is in very good condition. Some timbers are decayed but have no significant effect to structure.

2. The gate seems to be in good condition except for damage to the gate skin plate due to an accidental hit by a vessel (Photo 2). This damage is not effecting the operational condition of the gate.

3. Timber Guidewalls. Timber guidewalls are in good condition.

B. Hydraulic & Hydrology.

1. The breakwater dike on the west bank of the south approach channel has lost practically all the riprap. The embankment seems to be lower than the design elevation which is +3.0 feet MSL.

2. The staff gage on the guidewall should be painted again. It is difficult to read the elevations. The lowest elevation that can be read is 4 feet.

C. Foundations & Materials.

1. Instrumentation has shown that the levee supporting the sheet piling sections on each end of the structure is undergoing consolidation. However, the resulting settlements have been anticipated in the GDM and will continue until the completion of primary consolidation, at which time the sheet pile will be capped. Monitoring of the sheet piling should be continued until primary consolidation has leveled off.

2. All banks are in good condition.

3. Reference mark No. 20 shows excessive settlement at the east edge of the outer T-wall monolith T-4R. It was observed that the joint between monolith T-4R and the adjoining T-3R is widening at the top as can also be seen from the measurements of distance between marks 18 and 19 (Photo 3) presented on Plate I-2. It appears from these observations that monolith T-4R is rotating due to settlement under its outermost edge. Minor

cracks were also observed at the top of monolith T-4R, one of which continued down each side of the monolith. It is recommended that close attention be paid to monolith T-4R in the future to determine if the rate of settlement of the monolith and its pile foundation will decrease as primary consolidation of the surrounding soils levels off.



Photo 1: Concrete Popout on Top of West Side Wall




Photo 2: Damage to Gate Skin Plate



Photo 3: Excessive Gap Between RM 19 and RM **18**

## SECTION VI - CONCLUSIONS AND REMEDIAL ACTIONS

6-01 Conclusion. It is concluded that Empire Floodgate is a stable, safe, well maintained structure in satisfactory operating condition.

6-02 Remedial Action. The following remedial actions will be accomplished by the local interest (Plaquemines Parish Commission Council) in FY 85.

- a. The gate skin plate will be repaired.
- b. Riprap will be replaced at the breakwater dike on the west bank of the south approach channel.
- c. The staff gage on the guidewall will be repainted.

The following remedial actions will be accomplished by Government hired labor forces at scheduled periodic surveys and inspections:

- d. The temperature and shrinkage cracks on the stem and walkway area of the T-wall monolith T-4R will continue to be monitored for signs of activity.
- e. The measurements for RM2-RM3, RM4-RM5, RM18-RM19 and RM20 will be monitored for substantial changes.
- f. Monitoring of the sheet piling will be continued until primary consolidation has leveled off.
- g. Monolith T-4R will be monitored in the future for settlement as primary consolidation of the surrounding soils levels off.

6-03 Next Inspection. The next inspection of Empire  
Floodgate ~~is~~<sup>S</sup> scheduled for Jan 1987. The structure will not be  
dewatered at that time.