



**UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-4005**

March 31, 2005

Gregory M. Rueger, Senior Vice
President, Generation and
Chief Nuclear Officer
Pacific Gas and Electric Company
Diablo Canyon Power Plant
P.O. Box 3
Avila Beach, CA 93424

**SUBJECT: DIABLO CANYON POWER PLANT, UNITS 1 AND 2 - NRC PILOT ENGINEERING
INSPECTION REPORT 05000275/2005006; 05000323/2005006**

Dear Mr. Rueger:

On February 15, 2005, the NRC completed an engineering team inspection at your facility. The inspection was conducted using Temporary Instruction 2515/158, "Functional Review of Low Margin/Risk Significant Components and Operator Actions," and examined activities conducted under your license as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your license. In conducting the inspection, the team examined the adequacy of the facility's design and design implementation for selected risk significant components and operator actions. The enclosed inspection report documents the inspection findings, which were discussed on February 15, 2005, with you and other members of your staff during a public exit meeting in San Luis Obispo, California. Following completion of additional review in the Region IV office, a final exit was held by telephone with you and other members of your staff on March 24, 2005, to provide an update on changes to the preliminary inspection findings.

The team concluded that, in general, the components and systems reviewed would be capable of performing their intended safety functions and that for the most part, sufficient design controls had been implemented for engineering work performed at your Diablo Canyon Nuclear Power Plant, Units 1 and 2. However, the team did identify a number of deficiencies during the course of the inspection which are discussed in the enclosed report.

The team found that your design basis is meticulously documented in most cases. Our reviews indicated that appropriate surveillance tests were well-coordinated with the design basis to appropriately demonstrate that equipment continued to perform as it was intended. Your engineering documents generally showed a clear policy of conservatism in your approach to engineering. The team also found that your staff is experienced, proficient, and knowledgeable of your design basis and practices.

Based on the results of this inspection, the NRC has identified eight issues that were evaluated under the risk significance determination process as having very low safety significance (Green). The NRC has also determined that violations are associated with six of these issues. These violations are being treated as noncited violations, consistent with Section VI.A of the Enforcement Policy. These noncited violations are described in the subject inspection report. If you contest the violation or significance of these noncited violations, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001, with copies to the Regional Administrator, U.S. Nuclear Regulatory Commission, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011; the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector at the Diablo Canyon Nuclear Power Plant, Units 1 and 2 facility.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Dwight D. Chamberlain, Director
Division of Reactor Safety

Dockets: 50-275; 50-323
Licenses: DPR-80; DPR-82

Enclosures:
Inspection Report 05000275/2005-006; 05000323/2005-006
w/Attachment Supplemental Information

cc w/enclosures:
David H. Oatley, Vice President
and General Manager
Diablo Canyon Power Plant
P.O. Box 56
Avila Beach, CA 93424

Lawrence F. Womack
Vice President, Nuclear Services
Diablo Canyon Power Plant
P.O. Box 56
Avila Beach, CA 93424

James R. Becker, Vice President
Diablo Canyon Operations and
Station Director, Pacific Gas and
Electric Company
Diablo Canyon Power Plant
P.O. Box 3
Avila Beach, CA 93424

Sierra Club San Lucia Chapter
ATTN: Andrew Christie
P.O. Box 15755
San Luis Obispo, CA 93406

Nancy Culver
San Luis Obispo Mothers for Peace
P.O. Box 164
Pismo Beach, CA 93448

Chairman
San Luis Obispo County Board of
Supervisors
Room 370
County Government Center
San Luis Obispo, CA 93408

Truman Burns\Robert Kinosian
California Public Utilities Commission
505 Van Ness Ave., Rm. 4102
San Francisco, CA 94102-3298

Diablo Canyon Independent Safety Committee
Robert R. Wellington, Esq.
Legal Counsel
857 Cass Street, Suite D
Monterey, CA 93940

Ed Bailey, Chief
Radiologic Health Branch
State Department of Health Services
P.O. Box 997414 (MS 7610)
Sacramento, CA 95899-7414

Richard F. Locke, Esq.
Pacific Gas and Electric Company
P.O. Box 7442
San Francisco, CA 94120

Pacific Gas and Electric Company

-4-

City Editor
The Tribune
3825 South Higuera Street
P.O. Box 112
San Luis Obispo, CA 93406-0112

James D. Boyd, Commissioner
California Energy Commission
1516 Ninth Street (MS 34)
Sacramento, CA 95814

Electronic distribution by RIV:
 Regional Administrator (**BSM1**)
 DRP Director (**ATH**)
 DRS Director (**DDC**)
 DRS Deputy Director (**vacant**)
 Senior Resident Inspector (**DLP**)
 Branch Chief, DRP/E (**WBJ**)
 Senior Project Engineer, DRP/E (**VGG**)
 Team Leader, DRP/TSS (**RLN1**)
 RITS Coordinator (**KEG**)
 DRS STA (**DAP**)
 J. Dixon-Herrity, OEDO RIV Coordinator (**JLD**)
 DC Site Secretary (**AWC1**)

SISP Review Completed: Yes ADAMS: : Yes No Initials: JAC
 : Publicly Available Non-Publicly Available Sensitive : Non-Sensitive

RI:DRS/EB	SRI:DRP/PBB	SOE:DRS/OB	TL:DRS/EB	C:/DRP/PBE
G. George	J. Hanna	T. McKernon	N. OKeefe	W. Jones
/RA/	/RA/	/RA/	/RA/	/RA/
3/15/2005	3/15/2005	3/15/2005	3/15/2005	3/30/2005
C:DRS/EB	DD:DRS			
J. Clark	D. Chamberlain			
/RA/	/RA/			
3/31/2005	3/31/2005			

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

ENCLOSURE

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

Dockets: 50-275; 50-323
Licenses: DPR-80; DPR-82
Report No.: 05000275/2005006; 05000323/2005006
Licensee: Pacific Gas and Electric Company
Facility: Diablo Canyon Nuclear Power Plant, Units 1 and 2
Location: 7 1/2 miles NW of Avila Beach
Avila Beach, California
Dates: January 3 through February 15, 2005
Team Leader: N. O'Keefe, Senior Reactor Inspector - Team Leader
Inspectors: J. Hanna, Senior Resident Inspector, Project Branch C
T. McKernon, Senior Operations Engineer
G. George, Reactor Inspector
Accompanying Personnel: J. Leivo, NRC Contract Inspector
W. Sherbin, NRC Contract Inspector
G. Skinner, NRC Contract Inspector
Approved By: Dwight D. Chamberlain, Director
Division of Reactor Safety

TABLE OF CONTENTS

ENCLOSURE	i
SUMMARY OF FINDINGS	iv
REPORT DETAILS	1
1. REACTOR SAFETY	1
1R04 Equipment Alignment	1
.1 Partial System Walkdown	1
1R15 Operability Evaluations	1
4. OTHER ACTIVITIES	2
.1 Cross-Reference to Problem Identification and Resolution Findings Documented Elsewhere in this Report	2
4OA5 Other Activities	3
.1 Inspection Sample Selection Process	3
.2 Results of Detailed Reviews	3
.2.1 Detailed Component and System Reviews	4
.2.1.2 Single Train Component Cooling Water Capabilities	4
.2.1.3 Emergency Core Cooling System (ECCS) Gas Voiding	5
.2.1.4 Diesel Fuel Oil Transfer System Normal and Backup Capabilities	8
.2.1.5 Diesel Fuel Oil Storage Tank Capacity and Modification	10
.2.1.6 Design of Condensate Storage Tank	12
.2.1.7 Pressurizer Power Operated Relief Valve Modification and Manual Actions to Respond to Inadvertent Safety Injection Event	14
.2.1.8 Component Cooling Water Modification to Prevent Water-Hammer in Containment Air Coolers	17
.2.1.9 Manual Actions to Respond to a Steam Generator Tube Rupture	17
.2.1.10 Auxiliary Feedwater Response to High Energy Line Break in the Auxiliary Feedwater	18
.2.1.11 Electrical and Control Design for Auxiliary Feedwater Level Control Valves	18
.2.1.12 Alternate Water Supplies to the Auxiliary Feedwater System	20
.2.1.13 Setpoint Methodology for Selected Safety-Significant Setpoints	20
.2.1.14 Design and Testing of Auto-Transfer Features for Offsite Power System	21
.2.1.15 Electrical Bus Work Connector Torquing in High Voltage Electrical	21

.2.1.16	Battery 12 Sizing Calculations and Manual Actions to Ensure Design Load Life	22
.2.1.17	Margin Review for engineered safety feature Bus Load, Load Shed, Load Sequencing, and Breaker Coordination/Fault Protection	22
.2.1.18	Control and Protection for Components that Supply Offsite Power to Engineered Safety Features Buses	24
.2.1.19	Capabilities for Restoring Offsite Power Following Prolonged Loss of Offsite Power	24
.2.1.20	Review Modification that Replaced Startup Transformers and Installed New Load Tap Changers	25
.2.1.21	Electrical Cables Potentially Degraded due to Submergence in Underground Cable Vaults	25
.2.1.22	Analysis and Design Features to Withstand Tsunami Effects	26
.3	Industry Operating Experience	27
.3.1	Review of Licensee Response to Industry Operating Experience	27
40A6	Meetings, Including Exit	31
ATTACHMENT	1-A

SUMMARY OF FINDINGS

IR 05000275/2005-006; 05000-323/2005-006; January 3 through February 15, 2005; Diablo Canyon Nuclear Power Plant, Units 1 and 2: Temporary Instruction 2515/158, Functional Review of Low Margin/Risk Significant Components and Operator Actions.

This inspection was conducted by a team of four NRC inspectors and three NRC contract inspectors. The team identified eight findings. The significance of most findings is indicated by its color (Green, White, Yellow, Red) using Inspection Manual Chapter 0609, "Significance Determination Process." Findings for which the significance determination process does not apply may be green or be assigned a severity level after NRC management review. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 3, dated July 2000.

A. Integrated Assessment

- The team concluded that, in general, components and systems were capable of performing their intended safety functions. Design controls were sufficient in areas examined by the team. The design basis was well documented and coordinated with surveillance tests used to demonstrate that equipment continued to perform as it was intended. Engineering documents showed a clear policy of conservatism and the addition of adequate margins. The team also found that your staff is experienced, proficient, and knowledgeable of your design basis and practices. Also, several examples were noted where calculations relied upon data which did not have adequate technical basis, although none of these examples resulted in any findings of more than very low safety significance.

B. NRC-Identified and Self Revealing Findings

Cornerstone: Mitigating Systems Cornerstone

- Green. A noncited violation was identified for inadequate corrective action to address an on-going problem with emergency core cooling system gas voiding in the common suction crossover line. The licensee had a sustained history of gas voiding in emergency core cooling system piping, which had the potential to lead to failure of the centrifugal charging pumps or safety injection pumps during the switchover from cold-leg recirculation to hot-leg recirculation during a loss-of-coolant accident. The team concluded that the corrective actions taken by the licensee focused on managing the symptom of the problem rather than finding and eliminating the cause of the voiding.

This finding constituted a performance deficiency because the licensee's corrective actions did not determine the cause nor prevent recurrence of gas voiding in the emergency core cooling system. Consequently, the licensee had operated the plant for years with the potential for gas voiding, which could affect one or more redundant trains of the emergency core cooling system. This issue was more than minor because it affected the Mitigating System cornerstone objective of equipment reliability, in that, voiding of the piping could cause mitigating equipment to fail. This finding was determined to be of very low safety significance (Green) during a Phase 1 significance determination process, since the finding was a design or qualification deficiency that

was confirmed to not have resulted in a loss of function in accordance with Generic Letter 91-18. This finding is being treated as an additional example of Noncited Violation 05000275/2004005-05, since the corrective actions for that violation are not yet complete and were expected to correct this issue. (Section 4OA5.2.1.3)

- Green. A finding was identified associated with the minimum flow settings for the auxiliary feedwater pumps. NRC Bulletin 88-04 identified that many pump minimum flow values were too low because they did not account for flow instability concerns. The team identified that when the licensee addressed this operating experience item, they did not properly verify the minimum flow settings with the pump manufacturer in accordance with the bulletin. A new analysis performed during the inspection by the manufacturer concluded that the existing minimum flow settings did not allow continuous operation. The manufacturer recommended an increased monitoring and maintenance schedule for the existing minimum flow values in order to promptly detect degradation. This issue was entered into the licensee's corrective action program under Action Request A0631659.

This finding represented a performance deficiency because the licensee did not verify with the manufacturer that the minimum flow settings for the auxiliary feedwater pumps were acceptable. As a result, the auxiliary feedwater pumps were operated since 1988 with an increased potential for unusual wear and aging without establishing increased monitoring and maintenance, or other compensating actions. This issue was more than minor because it affected the equipment reliability objective of the Mitigating Systems cornerstone. This finding was determined to be of very low safety significance (Green) during a Phase 1 significance determination process, since the performance deficiency was confirmed not to result in a loss of function in accordance with Generic Letter 91-18. (Section 4OA5.3.1)

- Green. A noncited violation was identified for inadequately translating design requirements into calculations used to demonstrate the capabilities of the pressurizer power operated relief valve backup accumulators. The calculation was found to contain a number of non-conservative errors and did not contain the most current acceptance criteria from accident analyses. As a result, this calculation failed to demonstrate that the backup nitrogen accumulators could operate the pressurizer power operated relief valves for the required number of cycles. Failure to properly demonstrate that design requirements for the number of power operated relief valve cycles needed to respond to an inadvertent safety injection actuation were satisfied through a design calculation was a violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control." This issue was entered into the licensee's corrective action program under Action Requests A0631420, A0630719 and A0630740.

The failure to adequately assess and document the capability of the backup accumulators to provide enough gas to operate the power operated relief valves through the required number of cycles was a performance deficiency. This issue was greater than minor because it was similar to Example 3.i in Manual Chapter 0612, Appendix E,

in that, calculations had to be performed to demonstrate that the system could satisfy the accident analyses. This finding affected the Mitigating System cornerstone. This finding screened as having very low safety significance (Green) during a Phase 1 significance determination process, since the issue was confirmed to not have resulted in a loss of function in accordance with Generic Letter 91-18. (Section 4OA5.2.1.7)

- Green. A finding was identified for modifying the diesel fuel oil transfer system without properly assessing the resulting net affect on reliability from introducing a new failure potential associated with new active components. As a result, the licensee rejected a small design change, which would have eliminated the failure mode when it was recognized that failure of the new pressure control valves could fail the train. Because the failure potential was not fully assessed, the licensee decided not to implement a change that would have eliminated the impact of the failure, nor were the pressure control valves subject to any preventive maintenance to ensure their reliability. This issue was entered into the licensee's corrective action program under Action Request A0630383.

The failure to properly assess the net effect on system reliability and risk due to the positive and negative effects of this modification, or to mitigate or eliminate a new failure mode created by the modification was a performance deficiency. This issue is more than minor because it affected the design control attribute of the Mitigating Systems cornerstone objective to assure the reliability and capability of equipment needed for accident mitigation. This finding was determined to be of very low safety significance (Green) during a Phase 1 significance determination process, since the performance deficiency was confirmed not to result in a loss of function in accordance with Generic Letter 91-18 based on test results. (Section 4OA5.2.1.4.b.1)

- Green. A noncited violation was identified for failure to demonstrate that load sequencing would satisfy regulatory requirements. The team identified that a single postulated fault occurring during load sequencing with offsite power available could restart load sequencing timers in all three engineered safety features buses and result in a more limiting scenario than previously analyzed by the licensee. This could result in overlapping starting transients for motors that were intended to start separately, which was not evaluated in existing calculations. The combined effects of this could cause later starting times for safety-related loads, potentially affecting system performance assumed in accident analyses. Failure to demonstrate that the system could perform as required considering a single fault was a violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control." This issue was entered into the licensee's corrective action program under Action Request 0630036.

This failure to demonstrate through analyses that the electrical distribution system was capable of performing its required function following a single postulated fault was a performance deficiency. This issue was more than minor because it affected the Mitigating System cornerstone objective of ensuring availability, reliability, and capability of systems needed to respond to a design basis accident. The licensee was subsequently able to demonstrate that there would be no loss of safety function even considering the effects of a fault as described above. Therefore, this finding was determined to be of very low safety significance (Green) in Phase I of the significance determination process. (Section 4OA5.2.1.17)

- Green. A noncited violation was identified for not having a procedure to cross-tie fuel oil transfer trains in response to certain failures, contrary to the design and licensing basis of the system. The design and license basis of the diesel fuel oil transfer system credited the capability to cross-tie trains in order to meet requirements to maintain the system function and be able to withstand a worst-case single failure. The team identified that the licensee did not have a procedure or training to accomplish this task. Failure to incorporate design and licensing requirements into plant procedures was a violation of 10 CFR Part 50, Appendix B, Criterion III. This issue was entered into the licensee's corrective action program under Action Requests A0630010 and A0630015.

The failure to have a procedure needed to meet the design and license basis of the fuel oil transfer system was a performance deficiency. This finding was more than minor because it impacted the Mitigating Systems cornerstone objective of procedure quality to ensure the capability of the system, in that, the system would not be capable of supplying the emergency diesel generators for the required 7-day mission time in the event of a single failure. The team concluded that this would not result in a loss of function in accordance with Generic Letter 91-18; since procedures direct monitoring of fuel capacity, operators would be aware of the need for action for the following reasons: 1) there should be a relatively long time available to detect and correct the problem (in excess of 24 hours), 2) the expected actions are not complex, and 3) existing procedures require monitoring of the remaining fuel oil capacity during extended diesel runs. Therefore, this finding was determined to be of very low safety significance (Green) in Phase 1 of the significance determination process. The licensee took prompt compensatory measures to ensure the full mission time could be met. (Section 4OA5.2.1.4.b.1)

- Green. A noncited violation was identified for inadequate design control because the licensee did not properly account for vortex prevention in the calculation used to determine the usable volume in the diesel fuel oil storage tank, which could cause the pump to ingest air. The licensee was unable to locate a technical basis for this part of the calculation. The team independently calculated that 4.1 inches was necessary, compared to the 2.0 inches used in the calculation. The licensee performed a similar calculation and reached the same conclusion, which reduced the tanks' unusable volumes by a little less than 1,000 gallons in this 50,000 gallon tank. Failure to properly account for the unusable fuel oil storage tank volume necessary to prevent vortexing was a violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control." This issue was entered into the licensee's corrective action program under Action Request A0629779.

The failure to properly evaluate and document the unusable volume of the diesel fuel oil storage tank needed to prevent vortexing and ingesting air into the transfer pump was a performance deficiency. Through calculations, the licensee was able to demonstrate that there was sufficient available margin in both the tank capacity and the existing technical specification requirement to account for this without affecting operability or necessitating a technical specification change. This finding affected the Mitigating Systems cornerstone. The issue is more than minor because it was similar to Example 3.i of Appendix E to Manual Chapter 0609, since it was necessary to

re-perform a calculation to determine whether the existing condition was acceptable. The finding was determined to be of very low safety significance (Green) during Phase 1 of the significance determination process, since there was available margin in the tank capacity and technical specification minimum required volume and it was confirmed not to involve a loss of function of the system in accordance with Generic Letter 91-18. (Section 4OA5.2.1.5)

- Green. A noncited violation was identified for inadequate design control, because Calculation STA-135, "Auxiliary Feedwater System," Revision 2, which was intended to demonstrate that the auxiliary feedwater pumps have adequate capacity to meet their design basis, did not correctly identify the highest pressure under which the pumps needed to function. Specifically, the calculation did not account for the dynamic pressure loss between the feedwater inlet ring and the main steam safety valves. The licensee was able to perform an analysis that concluded the pumps had sufficient flow margin at the new pressure. Failure to properly translate the peak pressure against which the auxiliary feedwater pumps must deliver the required flow rate was a violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control." This issue was entered into the licensee's corrective action program under Action Request A0630804.

The failure to document the capability of the auxiliary feedwater pumps to deliver the required flow at the maximum possible pressure was a performance deficiency. The issue is more than minor because a calculation was needed to determine whether the existing condition was acceptable, consistent with Example 3.i of Appendix E to Manual Chapter 0609. This issue affected the Mitigating Systems cornerstone. Because there was available margin in the pump capacity, this issue was confirmed not to involve a loss of function of the system in accordance with Generic Letter 91-18. Therefore, the finding was determined to be of very low safety significance (Green) during Phase 1 of the significance determination process. (Section 4OA5.2.1.6)

C. Licensee-Identified Findings

None.

REPORT DETAILS

1. REACTOR SAFETY

1R04 Equipment Alignment (71111.04)

.1 Partial System Walkdown

a. Inspection Scope

The inspectors conducted partial walkdowns of the following five risk-significant systems to verify that they were in their proper standby alignment as defined by system operating procedures and system drawings. During the walkdowns, inspectors examined system components for material conditions that could degrade system performance. In addition, the inspectors evaluated the effectiveness of the licensee's problem identification and resolution program in resolving issues, which could increase event initiation frequency or impact mitigating system availability.

- On January 5, 2005, the team performed a partial system walkdown of the Units 1 and 2 auxiliary feedwater systems. This walkdown included the majority of the raw water system, since it is designated as an alternate source of water to auxiliary feedwater.
- On January 6, 2005, the team performed a partial system walkdown of the Units 1 and 2 diesel fuel oil transfer system. Subsequently, a timed walkthrough and inspection was conducted for connecting the emergency fuel oil transfer pump to the Unit 1 system.
- On January 6, 2005, the team performed a partial system walkdown of the Units 1 and 2 auxiliary salt water system.
- On January 12, 2005, the team performed a partial system walkdown of the Units 1 and 2 component cooling water system.
- On January 27, 2005, the team performed a partial system walkdown of Centrifugal Charging Pump 1-1 in conjunction with a timed walkthrough for connecting the alternate cooling source to the pump.

b. Findings

No findings of significance were identified.

1R15 Operability Evaluations (71111.15)

a. Inspection Scope

The inspectors reviewed six inspection samples of operability evaluations. In each case, these were operability assessments made in response to issues the team raised

during this inspection. These reviews of operability evaluations and/or prompt operability assessments and supporting documents were performed to determine if the associated systems could meet their intended safety functions despite the potentially degraded or non-conforming status. The inspectors reviewed the applicable technical specification, Codes/Standards, and Updated Final Safety Analysis Report sections in support of this inspection. The inspectors reviewed the following action requests and operability evaluations:

- (Units 1 and 2) diesel fuel oil storage tank capacity calculation did not adequately account for vortex prevention (Action Request A0629779) (further discussed in Section 4OA5.2.1.5)
- (Units 1 and 2) auxiliary feedwater pump net-positive suction head available is less than required in several cases (Action Request A0630009) (further discussed in Section 4OA5.2.1.6)
- (Units 1 and 2) calculations demonstrating that the backup accumulators will provide enough nitrogen to meet pressurizer power operated relief valves missions include errors and non-conservatism (Action Requests A0630719, A0630780) (further discussed in Section 4OA5.2.1.7)
- (Units 1 and 2) manual actions needed for auxiliary feedwater system single failure qualification (Action Request A0629860) (further discussed in Section 4OA5.2.1.10)
- (Unit 1 and 2) engineering safety feature timing relays subject to resetting during certain faults (Action Request A0630036) (further discussed in Section 4OA5.2.1.17)
- (Units 1 and 2) lack of documentation on tsunami hydraulic effects (Action Request A0630734) (further discussed in Section 4OA5.2.1.22)

b. Findings

No findings of significance were identified.

4. OTHER ACTIVITIES

4OA2 Problem Identification and Resolution

.1 Cross-Reference to Problem Identification and Resolution Findings Documented Elsewhere in this Report

Section 4OA5.2.1.3 describes a noncited violation for inadequate corrective actions to address on-going problems with gas voiding in emergency core cooling system piping over a number of years.

4OA5 Other Activities

Temporary Instruction 2515/158, "Functional Review of Low Margin/Risk Significant Components and Operator Actions."

.1 Inspection Sample Selection Process

In selecting samples for review, the team focused on the most risk significant components and operator actions. The team selected these components and operator actions by using the risk information contained in the licensee's probabilistic risk assessment. An initial sample was chosen from these components and operator actions that had a risk achievement worth factor greater than two. These components and operator actions are important to safety since their failure would result in at least a doubling in the plant's baseline core damage frequency.

Many of the samples selected were located within the component cooling water, auxiliary salt water, auxiliary feedwater, diesel fuel oil transfer, and off-site power systems. In addition, inspection samples were added based upon operational experience reviews.

A total of 52 samples were chosen for the team's initial review. These samples were assessed to determine whether any low margin concerns existed. For the purpose of this inspection, low margin concerns included original design issues, margin reductions due to modification, or margin reductions identified as a result of material condition issues. Consideration was also given to the uniqueness and complexity of the design, operating experience, and the available defense in-depth margins. Based on the above considerations, 27 of the original samples were selected for a detailed review. An overall summary of the detailed reviews performed and the specific inspection findings identified is included in the following sections of this report.

.2 Results of Detailed Reviews

The team performed detailed reviews of the components, operator actions, and operating experience issues selected. For components, the team reviewed the adequacy of the original design, modifications to the original design, maintenance and corrective action program histories, and all associated operating and surveillance procedures. As practical, the team also performed walkdowns of the selected components to assess material condition and conformance to design. For operator actions, the team reviewed the adequacy of the operating procedures and compared design basis time requirements against actual demonstrated time lines. For the operating experience issues, the team assessed the applicability of the issue to the Diablo Canyon Power Plant and the licensee's disposition of the issue. The following sections of the report provide a summary of the detailed reviews, including any findings identified by the inspection team.

This inspection met the intent of, and took credit for, the following inspection procedures. The specific samples reviewed during this inspection are listed in the documents reviewed section at the back of this report.

- 71111.02, Evaluation of Changes, Tests, or Experiments
- 71111.17B, Permanent Plant Modifications
- 71111.21, Safety System Design and Performance Capability

.2.1 Detailed Component and System Reviews

.2.1.1 Alternate Supply of Cooling to Centrifugal Charging Pumps

a. Inspection Scope

The team reviewed the capability to provide an alternate cooling supply to a centrifugal charging pump. This risk-significant manual action allowed restoring makeup to the reactor coolant system and seal cooling to the reactor coolant pumps in the event of a loss of the component cooling water or auxiliary salt water systems. This capability was implemented under Design Change Package M-410009. The team reviewed the modification, and 50.59 evaluation and supporting documentation, including the system's design change memorandum, and performed a walkdown of the centrifugal charging pumps to assess the material condition.

The team observed operators performing a walkthrough of the abnormal operating procedure for establishing backup cooling to the centrifugal charging pumps, Appendix C of Procedure OP AP-11, "Backup Cooling to a Centrifugal Charging Pump," Revision 21. The team verified that operators were able to acquire the necessary tools and hoses and complete the in-plant hookups within the 1-hour time limit established in the design documentation.

b. Findings

No findings of significance were identified.

.2.1.2 Single Train Component Cooling Water Capabilities

a. Inspection Scope

The inspectors reviewed mechanical design calculations, piping and instrumentation drawings, and design basis documents associated with establishing or demonstrating heat load capabilities for the component cooling water system when operating with a single train. The calculations that were reviewed included accident analyses performed with single train component cooling water alignment, and interface auxiliary salt water heat load calculations. The team also performed a partial system walkdown of the component cooling water system in order to assess the material condition, operational alignment, and conformance to design.

Additionally, operating procedures, abnormal operating and emergency procedures, which implement steps to reduce or shed heat loads from the component cooling water system during degraded system operation or accidents were reviewed to assess the complexity of manual actions and the time available versus allowable system temperatures.

b. Findings

No findings of significance were identified.

2.1.3 Emergency Core Cooling System (ECCS) Gas Voiding

a. Inspection Scope

The team reviewed the history of ECCS gas voiding at Diablo Canyon Power Plant. Specifically, the team inspected previous instances of such gas voiding, the corrective actions taken, and whether they had been effective. The team selected this sample for review based on Diablo Canyon Power Plant's historical problems with gas voiding, (including several instances in 2004). The team assessed the potential of large gas bubbles making multiple trains of ECCS equipment inoperable, and the relevance of industry operating experience with ECCS gas voiding. The team also reviewed the modification of the centrifugal charging pump recirculation line orifices performed in 1999 in response to gas voiding.

b. Findings

Introduction. A Green noncited violation was identified for inadequate corrective action to address an on-going problem with ECCS gas voiding in the common suction crossover line. The licensee had a sustained history of gas voiding in ECCS piping, which had the potential to lead to failure of the centrifugal charging pumps or safety injection pumps during the switchover from cold-leg recirculation to hot-leg recirculation during a loss-of-coolant accident. The team concluded that the corrective actions taken by the licensee focused on managing the symptom of the problem rather than finding and eliminating the cause of the voiding. This finding is being treated as an additional example of a corrective action finding assessed in NRC Inspection Report 50-275/2004-005.

Description. The team noted that the licensee had a sustained history of gas voiding in ECCS piping. The piping of concern was a high point where gas has accumulated. Valves 8807A and 8807B were normally closed within this horizontal run of piping, causing it to be stagnant. During a postulated loss-of-coolant accident, the centrifugal charging pumps and safety injection pumps start. During the switchover from cold-leg recirculation to hot-leg recirculation, these valves are opened and flow would rapidly sweep gas voids into the suction of either the centrifugal charging pumps or safety injection pumps, possibly resulting in gas binding or damage to these components.

The team noted that both units had experienced gas voiding problems periodically during the past several years. Please refer to NRC Inspection Report 50-275/99-07 for a previously assessed violation written to address ECCS voiding. The team noted the following recent history of gas voiding:

- February 5, 1998 - voids occurred in cross-over piping, but were incorrectly determined to be acceptable

- March 27, 1998 - voids occurred in cross-over piping, but were incorrectly determined to be acceptable
- September 10, 1998 - small voids occurred in cross-over piping, and were determined to be acceptable
- November 16, 1998 - voids occurred, which “exceed design assumptions” making either both safety injection pumps or both centrifugal charging pump’s inoperable
- October 26, 1999 - two instances occurred of voids in excess of the allowable size; system declared inoperable, Technical Specification 3.0.3 entered while system was vented (Licensee Event Report 99-03)
- September 3, 2000 - small voids occurred in crossover piping, and were determined to be acceptable
- May 14, 2004 - voids occurred in excess of the allowable size; system was declared inoperable, Technical Specification 3.0.3 entered while system was vented
- October 21, 2004 - two occurrences of a void in excess of the allowable size; system declared inoperable, Technical Specification 3.0.3 entered while system was vented
- December 1-2, 2004 - voids of allowable size occurred; system was vented
- December 17, 2004 - voids of allowable size occurred; system was vented

The licensee’s efforts have been directed at managing the size of the bubble and venting it prior to its size increasing to the point where it affected system operability. The team concluded that the corrective actions taken by the licensee focused on managing the symptom of the problem rather than finding and eliminating the cause of the voiding. This was evident by the following licensee actions:

- Proceduralizing when to check for gas bubble buildup,
- Installing “temporary” instruments to assist in detecting voids, and
- Installing a permanent hard pipe vent line to vent gas from affected piping to outside the building.

Following the gas voiding events in 1998, the licensee concluded that one of the causes of gas voiding was the piping design. Though this conclusion was reached, no modifications to the piping (other than adding vent valves) were performed. The team noted that the licensee believed the gas was hydrogen from the volume control tank, although they had never taken samples of the void gas to determine the type of gas present. The team noted that for gas voiding events prior to 1998, the licensee had concluded the source of gas was nitrogen from outage-related sources, also without

verifying this assumption. Without firm evidence of the type of gas involved, the team was not able to conclude the validity of the licensee's cause analyses. The team noted that in response to the most recent gas voiding problems, the licensee was planning sampling to determine the source of the gas.

The team concluded that this gas voiding represented a significant condition adverse to quality because of the potential effect on multiple trains of safety-related equipment. The team also reviewed both the internal and external operational experience relevant to this condition. Please refer to Section 4OA5.3.1 of this report for a discussion of relevant industry operational experience.

During discussions with the licensee, the team clarified the situations listed above where the licensee had declared the system inoperable. In each case, operators followed their procedure in declaring the system inoperable. However, the licensee had established an administrative limit which required this action well before calculations would indicate that a pump could be rendered inoperable. Therefore, despite administratively declaring pumps inoperable, the voids observed would not have resulted in a loss-of-safety function. In assessing the impact of a void, the NRC conservatively assumed that the full volume of a void would go to a single pump, since that would have the greatest chance of rendering the pump inoperable.

Analysis. The team determined that this finding constituted a performance deficiency because the licensee's corrective actions did not determine the cause nor prevent recurrence of gas voiding in the ECCS. Consequently, the licensee had operated the plant for years with the potential for gas voiding causing a common mode failure of redundant trains of ECCS equipment. This issue was more than minor because it affected the Mitigating System cornerstone objective of equipment reliability, in that, voiding of the piping could cause mitigating equipment (i.e., pumps) to fail. Using the NRC Inspection Manual Chapter 0609, Phase 1 Screening Worksheet, the finding was determined to be of very low safety significance (Green) since it was a design or qualification deficiency that was confirmed to not have resulted in a loss of function in accordance with Generic Letter 91-18.

Enforcement. 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action," requires that conditions adverse to quality are promptly identified and corrected. Further, the requirement states that in the case of significant conditions adverse to quality, the measures shall assure that the cause of the condition is determined and corrective action taken to preclude repetition. Contrary to this requirement, from 1998 to present, the licensee did not prevent repeated occurrences of a significant condition adverse to quality wherein gas voiding of piping could challenge the functionality/operability of multiple trains of emergency core cooling equipment.

This violation is being treated as another example of a violation documented in NRC Inspection Report 05000275/2004-005. That violation included specific examples of this larger pattern of inadequate corrective action. Corrective actions for the violation are expected to cover this example, and insufficient time has passed for the licensee to be able to complete those corrective actions. Therefore, this will be treated as an additional example of Noncited Violation 50-275/04-05-05, "Failure to Adequately Correct ECCS Voiding Following Operation of the Positive Displacement Pump."

.2.1.4 Diesel Fuel Oil Transfer System Normal and Backup Capabilities

a. Inspection Scope

The team reviewed design basis documentation, the Final Safety Analysis Report, system drawings, and a failure modes analysis for the diesel fuel oil transfer system. In concert with the review, the team completed a walkdown of the diesel fuel oil transfer system to assess the material condition, operational alignment, and conformance with the design configuration. This included an inspection of the portable, emergency diesel-driven transfer pump and its support equipment. The team also reviewed procedures for operation, surveillance testing, and annunciator response for the diesel fuel oil transfer system. The team also reviewed calculations establishing the minimum capabilities of the diesel fuel oil transfer system and its backup pump. In addition, the team observed operators perform a walkthrough of the operating procedure to install the portable emergency diesel-driven pump to the diesel fuel oil transfer system. The team verified that all the required fittings and hoses were available, that the procedure worked as written, and that the pump could be installed within the 1 hour time established by the licensee for this risk-significant manual action.

The team reviewed permanent plant modification Design Change Package M-39858, "Addition of Diesel Fuel Oil Recirculation System and Emergency Fuel Oil Transfer System," Revision 5, and the associated safety evaluation. The team also reviewed Calculation M-805, "EDG Fuel Oil Transfer - PCV 410/411 Failure," Revision 3, which addressed a new failure potential introduced as a result of this modification.

The team reviewed the design, maintenance history, and material condition of several passive components in this system. These included the foot valves (backflow prevention valves) in the suction line, suction strainers and discharge filters, and the transfer pump vault sump drain check valves.

b. Findings

b.1 Modification Review Did Not Balance New Failure Potential With Improved Reliability

Introduction. A Green finding was identified for modifying the diesel fuel oil transfer system with the intent of improving reliability, but not properly assessing the resulting affect on reliability from introducing a new failure potential associated with new active components. As a result, the licensee rejected a small design change that would have eliminated the failure mode when it was recognized that failure of the new pressure control valves could fail the train.

Background. The team reviewed a modification to the diesel fuel oil transfer system installed in 1990, which was intended to improve its reliability. The modification added recirculation lines to allow the system to be operated continuously during a long-term run of diesel emergency generators, rather than starting and stopping the transfer pump repeatedly. In evaluating whether this change would also introduce a new potential for failure, a calculation concluded that the new pressure control valve could fail open and disable one train. This failure mode did not previously exist, although other existing failure modes could have resulted in loss of function for one train. The 50.59 safety

evaluation associated with this modification concluded that a new failure mode was not created on the basis of the latter point. The calculation went on to design a flow orifice, which would eliminate the failure mode by assuring adequate flow to diesel emergency generators even if the pressure control valve failed open. However, this simple change was not implemented based on a narrow position that failure of one train would not fail the function.

As a result, the plant was modified, a new failure potential was introduced, and an attempt to eliminate the problem was rejected, all without assessing the relative safety implications of the choices. As a result, the team concluded that the licensee did not determine whether the net effect of the modification met the goal of improving the reliability of the system.

The team determined that the pressure control valves were not subject to any preventive maintenance. The performance of the valves was demonstrated during in-service testing, and no pressure control valve failures had been experienced since the valves were originally installed.

Assessment. The performance deficiency was failure to properly assess the net effect on system reliability or risk due to this modification (positive affect on pump reliability, negative affect of introducing a new failure mode), and choosing not to eliminate a new failure mode when it involved relatively little effort. The team reviewed test results and concluded that the system reliability had not been reduced because no pressure control valve failures had been experienced. This issue will be treated as a finding: FIN 05000275, 323/2005006-01, Diesel Fuel Oil Transfer Modification Did Not Adequately Assess the Net Reliability Impact.

This issue is more than minor because it affected the design control attribute of the Mitigating Systems cornerstone objective to assure the reliability and capability of equipment needed for accident mitigation. This finding was determined to be of very low safety significance (Green) during a Phase 1 significance determination process, since the performance deficiency was been confirmed not to result in a loss of function in accordance with Generic Letter 91-18. This issue was entered into the licensee's corrective action program under Action Request A0630383.

Enforcement. No violations of NRC requirements were identified.

b.2 No Procedure for Cross-Tying Fuel Oil Transfer Trains

Introduction. A Green noncited violation was identified for not having a procedure to cross-tie fuel oil transfer trains in response to certain failures, contrary to the design and license basis of the system.

Description. The design and license basis of the diesel fuel oil transfer system credited the capability to cross-tie trains. This was necessary in some cases in order to meet requirements to maintain the system function and be able to withstand a worst-case single failure. The team identified that the licensee did not have a procedure or training to accomplish this task.

Each unit had one storage tank and one train of fuel oil transfer equipment. Each train was the primary source of fuel to the day tanks associated with the diesel engine generators in the same unit, and the backup supply to the diesel engine generators in the opposite unit. In order to establish the required redundancy, the licensee credited the capability to cross-tie the trains.

Analysis. The performance deficiency associated with this finding was that the licensee did not have a procedure to cross-tie trains of diesel fuel oil transfer system, consistent with the design and license basis.

The way the system is designed, it will automatically compensate for failures for several days. The remaining train can supply all diesel engine generators to the limit if its storage tank capacity. However, the mission time for the emergency diesel generators was 7 days, so action may be needed to cross-tie to access fuel from the storage tank associated with a failed train. This issue is more than minor because it affected the mitigating system cornerstone objective of procedure quality to ensure the capability of the system.

The team concluded that this would not result in a loss of function in accordance with Generic Letter 91-18; since procedures direct monitoring of fuel capacity, operators would be aware of the need for action for the following reasons: 1) there should be a relatively long time available to detect and correct the problem (in excess of 24 hours), 2) the expected actions are not complex, and 3) existing procedures require monitoring of the remaining fuel oil capacity during extended diesel runs. Therefore, this finding screened as having very low safety significance (Green) in a Phase 1 significance determination process. The licensee entered this issue into their corrective action program under Action Requests A0630010 and A0630015 and took prompt compensatory measures when this issue was raised, so there was no current safety concern.

Enforcement. Failure to incorporate design and licensing requirements into plant procedures was a violation of 10 CFR Part 50, Appendix B, Criterion III. Because this issue was of very low safety significance (Green) and it was entered into the licensee's corrective action program (Action Requests A0630010 and A0630015), this violation is being treated as a noncited violation, consistent with Section VI.A.1 of the NRC Enforcement Policy: NCV 05000275; 323/2005006-02, No Procedure for Cross-Tying Trains of the Diesel Fuel Oil Transfer System.

.2.1.5 Diesel Fuel Oil Storage Tank Capacity and Modification

a. Inspection Scope

The team reviewed the design basis and license basis documents associated with diesel generator loading, mission time, fuel consumption rates, and fuel oil storage requirements. This included a review of the calculation used to establish the fuel oil storage volume required and available. The team reviewed the technical basis for calibration of the tank level/capacity indication.

The team reviewed the program for maintaining chemistry control in the fuel oil storage and transfer system, including sample results, historical problems and corrective actions. The team also reviewed procedures used for filling, draining, recirculating, sampling, or removing water or sediment from the fuel oil storage tanks.

The team reviewed permanent plant modifications to the system and their associated safety evaluations, Design Change Packages M-049160 and M-49268, "Upgrade DFO Tanks," Revision 0.

b. Findings

Introduction. A Green noncited violation was identified for inadequate design control because the licensee did not properly account for vortex prevention in the calculation used to determine the usable volume in the diesel fuel oil storage tank.

Discussion. The team identified that the calculation for diesel fuel oil storage tank capacity did not adequately account for vortexing in the suction line, which could cause the pump to ingest air. The licensee was unable to locate a technical basis for the 2.0 inches of unusable tank volume assigned for preventing vortexing. The team independently calculated that 4.1 inches was necessary, using the methodology recommended by the Hydraulics Institute. The licensee performed a similar calculation and reached the same conclusion.

In response, the licensee wrote Action Request A0629779 to increase the unusable volume at the bottom of the tank by 2.1 inches, or a little less than 1,000 gallons in this 50,000 gallon tank. The usable capacity was correspondingly reduced.

Additionally, the team noted that in 1994, the licensee upgraded the system by installing larger, more leak-resistant storage tanks via Design Change Packages M-049160 and M-49268, "Upgrade DFO Tanks," Revision 0. However, configuration changes made during this modification were not reflected in a calculation that was impacted by the modification. Calculation M-821, "Determine If Sufficient Net Positive Suction Head Is Available For Operation Of The Diesel Fuel Oil Transfer Pumps," Revision 3, required the correct elevations and pipe sizes to calculate whether there was adequate net-positive suction head. The team identified that this calculation used the old configuration to calculate the values of available net-positive suction head, and added a qualitative assessment that the tank replacement would have a net improvement. However, this involved an improvement in net-positive suction head due to larger pipe diameter and a loss of net-positive suction head due to an elevation change. The team concluded that when engineering judgement was used to qualitatively address the change rather than updating the calculation to reflect the new configuration, the calculation no longer had a valid basis. In response, the licensee wrote Action Request A0629779 to correct the calculation. The team determined that there was no safety concern, since the engineering judgement appeared to be correct. However, this was a weak engineering practice, since changes to the design documents were supposed to involve the same quality as the original work.

Analysis. The performance deficiency associated with this finding was that the licensee had not properly evaluated and documented the unusable volume of the diesel fuel oil storage tank needed to prevent vortexing and ingesting air into the transfer pump. Through calculations, the licensee was able to demonstrate that there was sufficient available margin in both the tank capacity and the existing technical specification requirement to account for this without affecting operability or necessitating a technical specification change.

The issue is more than minor because it was similar to Example 3.i of Appendix E to Manual Chapter 0609, since it was necessary to re-perform a calculation to determine whether the existing condition was acceptable. Because there was available margin in the tank capacity and technical specification minimum required volume, this issue was confirmed not to involve a loss of function of the system in accordance with Generic Letter 91-18. Therefore, the issue screens as Green during Phase 1 of the significance determination process.

Enforcement. Failure to properly account for the unusable fuel oil storage tank volume necessary to prevent was a violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," for not translating design requirements into a design calculation. Because this issue was of very low safety significance and it was entered into the licensee's corrective action program (Action Request A0629779), this violation is being treated as a noncited violation, consistent with Section VI.A.1 of the NRC Enforcement Policy: NCV 05000275, 323/2005006-03, Diesel Fuel Oil Storage Tank Calculation Did Not Adequately Account for Vortexing.

.2.1.6 Design of Condensate Storage Tank

a. Inspection Scope

During the inspection, the team reviewed the adequacy of the design of the condensate storage tank and its ability to meet the various functions. In particular, the team reviewed the design and licensing basis information used to size the condensate storage tank, the design temperature of the condensate storage tank, along with procedures, surveillance tests, and inspections performed on the condensate storage tanks to verify their condition. Also, since the auxiliary feedwater pumps suction source is normally aligned to the condensate storage tank, the team reviewed the technical bases used to demonstrate that adequate net-positive suction head was available for the auxiliary feedwater pumps.

When the team identified a small number of cases where auxiliary feedwater pump runout was possible for a short period of time, the team reviewed the relay calculation and drawings for overcurrent protection of the auxiliary feedwater pump motors. This was to determine whether pumps were protected and whether auxiliary feedwater pumps would be expected to trip under the postulated conditions.

b. Findings

Auxiliary Feedwater System Calculation Issue With Steam Generator Backpressure

Introduction. A Green noncited violation was identified for inadequate design control, because the calculation demonstrating that the auxiliary feedwater pumps have adequate capacity to meet their design basis did not correctly identify the highest pressure under which the pumps needed to function. Specifically, the calculation did not account for the dynamic pressure loss between the feedwater inlet ring and the main steam safety valves.

Description. The team reviewed Calculation STA-135, "Auxiliary Feedwater System," Revision 2. The purpose of this calculation was to determine acceptance curves for auxiliary feedwater pump tests, based on flow resistance of the system. These curves were intended to verify that the auxiliary feedwater system test performance is within that assumed in accident analyses. When determining the hydraulic system resistance, the team noted that the calculation did not account for the flow resistance from the steam generator auxiliary feedwater feed ring to the main steam safety valves. Since the safety valves controlled the maximum system pressure during certain transients, the pressure at the auxiliary feedwater pumps would be correspondingly higher.

In response, the licensee performed an analysis that indicated that approximately 5 psi additional backpressure needed to be considered in auxiliary feedwater system hydraulic analyses.

Additionally, the team noted problems with the technical basis and conclusions in Calculation M-826, "Auxiliary Feedwater Pumps NPSH," Revision 1. The calculation showed that auxiliary feedwater pumps did not always have adequate net-positive suction head during a specific event. It was further noted that pump performance data curves were extrapolated beyond what was provided by the vendor for both flow and net-positive suction head. Extrapolated data points were used to form conclusions that pump operation without adequate net-positive suction head was satisfactory for up to 10 minutes without any supporting technical basis or verification from the pump manufacturer. The licensee documented this concern in Action Request A0630009. The licensee was subsequently able to show that adequate net-positive suction head was available, although the calculation needed to be revised to properly demonstrate this. The team considered that determining safety-related pump operability without adequate net-positive suction head, using unverified data extrapolated from vendor-supplied data was a weak engineering practice.

Analysis. The performance deficiency associated with this finding was that the calculation did not account for the dynamic pressure loss in part of the system, so the calculation did not show that the auxiliary feedwater pumps could deliver the required flow at the maximum possible pressure. The licensee was able to demonstrate by revising the calculation that there was sufficient available margin in the calculation to account for the increased backpressure.

The issue is more than minor because a calculation was needed to determine whether the existing condition was acceptable, consistent with Example 3.1 of Appendix B to Manual Chapter 0609. This issue affected the Mitigating Systems cornerstone. Because there was available margin in the pump capacity, this issue was confirmed not to involve a loss of function of the system in accordance with Generic Letter 91-18. Therefore, the issue screens as Green during Phase 1 of the significance determination process.

Enforcement. Failure to properly translate the peak pressure against which the auxiliary feedwater pumps must deliver the required flow rate was a violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control." Because this issue was of very low safety significance and it was entered into the licensee's corrective action program (Action Request A0630804), this violation is being treated as a noncited violation, consistent with Section VI.A.1 of the NRC Enforcement Policy: NCV 05000275; 323/2005006-04, Failure to Use the Highest Pressure In Calculation to Verify Adequate Auxiliary Feedwater Flow.

.2.1.7 Pressurizer Power Operated Relief Valve Modification and Manual Actions to Respond to Inadvertent Safety Injection Event

a. Inspection Scope

The team reviewed the licensee's modification packages, 50.59 evaluation, and supporting license amendment request for the pressurizer power operated relief valves performed in 2004. This modification upgraded two power operated relief valves in each unit and their associated actuation instruments to safety-related in order to credit the valves to respond to an inadvertent safety injection actuation while at power. The licensee wanted to credit these values to increase the margin for operator response time in the accident. The team selected this item based on the risk significance of these components and the apparent low margin between the required number of cycles specified in the Final Safety Analysis Report and the calculated number of cycles, which could be provided by the backup accumulators.

The team reviewed surveillance test procedures to verify that they properly determined operational leakage and that the acceptance criteria were consistent with supporting calculations.

The team also reviewed simulator response data for a scenario that mimicked the design basis time line for an inadvertent safety injection actuation.

b. Findings

Introduction. The team identified a Green noncited violation for inadequately translating design requirements into calculations used to demonstrate the capabilities of the pressurizer power operated relief valve backup accumulators. The calculation was

found to contain a number of non-conservative errors, and the licensee had revised analyses for an inadvertent safety injection actuation in a way that changed the number of required power operated relief valve cycles without updating this calculation. As a result, this calculation failed to demonstrate that the backup nitrogen accumulators could operate the pressurizer power operated relief valves for the required number of cycles.

Description. The pressurizer was equipped with safety valves and power operated relief valves for over-pressure protection and control. The licensee performed an accident analysis to assess the acceptability of plant response for an inadvertent safety injection actuation. During this event, the safety injection pumps inject water into the reactor coolant system, filling up the pressurizer until manual action is taken to control makeup. At the same time, a Phase A containment isolation occurs, removing the normal air source to operate pressurizer power operated relief valves and requiring the backup nitrogen accumulators to fill this function. The licensee recognized that the pressurizer fill rate during this event could be higher than calculated in the original analysis if the positive displacement charging pump was initially running, and that the pressurizer might be filled solid before operators controlled makeup. Once solid, pressure would rapidly rise until a relief valve opened. Since the pressurizer power operated relief valves were not safety-related at that time, they could not be credited to mitigate the resulting pressure rise, so safety valves might be challenged. However, the safety valves installed were not rated for water challenges, and may fail after a limited number of cycles. Therefore, to negate the potential problem with operator response, the licensee modified the system to make the power operated relief valves safety related so they could be credited for relieving pressure and avoiding a challenge to the safety valves.

The design basis specified that the accumulators would allow up to 150 power operated relief valve cycles over a 30-minute period. The team reviewed Calculations J-002 and M-009 (used to calculate and verify the required size and capability of the accumulators) to determine whether the power operated relief valves could adequately perform their design function. The team identified a number of problems with the backup accumulator sizing calculations. These calculations used a non-conservatively low minimum operating pressure, which did not account for the proper operation of the two regulators and pressure losses between the accumulator and the power operated relief valve. This had the effect of improperly increasing the number of available open-close cycles. It was also non-conservative in calculating the number of available cycles by not accounting for work done by the gas and in using a volume of the valve actuator, which was less than the actual volume; the calculation used the usable piston volume but did not count the unusable volume in the dome.

Based on these findings, the team concluded that Calculation J-002 did not demonstrate that the power operated relief valves could be operated by the backup accumulators for the postulated number of cycles in response to an inadvertent safety injection actuation. In response to the team's concerns, the licensee determined that the accumulators were not capable of meeting this design basis number of cycles.

The licensee subsequently provided an analysis (Calculation STA-119), which was used to support a technical specification change to make two power operated relief valves

safety related. This analysis conservatively showed that up to 93 power operated relief valve cycles were possible during this event using the NRC-approved RETRAN computer code. In July 2004, the NRC approved Amendment Request 171 and 172 (for Units 1 and 2 respectively), based in part on this analysis and the fact that the backup nitrogen accumulators were designed to support 150 power operated relief valve cycles.

The licensee subsequently revised Calculation J-002 to correct the problems discussed above, and were able to demonstrate that the backup accumulators were capable of operating the power operated relief valves through 106 cycles, which exceeded the maximum number of cycles required of 93 cycles.

Based on the above concerns and prior to re-performing the calculation, the team requested that the licensee perform simulator scenarios to demonstrate the number of cycles expected during an inadvertent safety injection event during the first 30 minutes of the event. The simulation mimicked the time line used in accident analysis. The simulator results, which are considered best-estimate rather than worst-case, indicated that far fewer power operated relief valve cycles would occur than predicted in the analysis. This provided the team some assurance that the analysis specifying 93 cycles was conservatively high.

Analysis. The team determined that the above calculation deficiencies constituted a performance deficiency. This was because the calculations were intended to demonstrate that the backup nitrogen accumulators could support operation of the pressurizer power operated relief valves for the number of cycles needed to prevent challenging a safety valve in the event of an inadvertent safety injection actuation. However, the calculations did not adequately demonstrate that this capability existed. This issue was greater than minor because it was similar to Example 3.i in Manual Chapter 0612, Appendix E, in that calculations had to be performed to demonstrate that the system could satisfy the accident analyses. This finding screened as having very low safety significance during a Phase 1 significance determination process, since the issue was confirmed to not have resulted in a loss of function in accordance with Generic Letter 91-18.

Enforcement. Failure to properly demonstrate that design requirements for the number of power operated relief valve cycles needed to respond to an inadvertent safety injection actuation were satisfied through a design calculation was a violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control." Because this issue was of very low safety significance and it was entered into the licensee's corrective action program (Action Requests A0631420, A0630719 and A0630740), this violation is being treated as a noncited violation, consistent with Section VI.A.1 of the NRC Enforcement Policy: NCV 05000275, 323/2005006-05, Inadequate Power Operated Relief Valve Accumulator Calculation.

.2.1.8 Component Cooling Water Modification to Prevent Water-Hammer in Containment Air Coolers

a. Scope

The scope of this inspection was to review the addition of the nitrogen pressurization system to the component cooling water system surge tank. The team verified that the modification to add the nitrogen overpressure addressed the concerns in NRC Generic Letter 96-06, "Assurance of Equipment Operability and Containment Integrity During Design Basis Accident." The team reviewed design change packages and the associated 50.59 evaluation. The team also conducted a partial system walkdown of the nitrogen pressurization system and the component cooling water system. The team verified the operability of the nitrogen pressurization system through review of post modification test results and subsequent surveillance test results. The team reviewed calculations and vendor documents to evaluate the limiting capabilities of the nitrogen pressurization system and the system's effects on the component cooling water system.

The team assessed the licensee's response to NRC Generic Letter 96-06, "Assurance of Equipment Operability and Containment Integrity during Design Basis Accident." As a response to Generic Letter 96-06, the licensee evaluated the susceptibility for water-hammer and two-phase flow in the containment air cooler cooling water system and over-pressurization of piping in containment penetrations. During this review, the team verified the licensee's commitments were completed.

b. Findings

No findings of significance were identified.

.2.1.9 Manual Actions to Respond to a Steam Generator Tube Rupture

a. Scope

The team selected manual actions in response to a steam generator tube rupture as a risk-significant, time-critical manual action sample that presented low margin between time required and time available to complete the actions. The team reviewed design margins presented in calculations and accident analyses. The team used the plant reference simulator to run specific scenarios to compare the calculated design margins to actual performance of operators under simulated conditions, accounting for times to perform in-plant local equipment manipulations. For example, the team ran a steam generator tube rupture scenario utilizing the assumptions used in the engineering analysis to assess the actual margin for steam generator overfill. During the scenario, the team recorded manual operator action times for actions outside the simulator. These times were then validated during walkthroughs of the actions by operators in the plant observed by the team.

The scenario started with the plant at 100 percent power with a maximum decay heat load. A steam generator tube rupture was initiated that rapidly increased to 700 gpm primary to secondary flowrate. The flow control valves for the auxiliary feedwater Pump 1-2 were simulated to fail open upon safety injection signal initiation, such that,

the auxiliary feedwater flow to the ruptured steam generator could not be remotely controlled, necessitating operator action to prevent overfilling of the associated steam generators.

b. Findings

No findings of significance were identified.

.2.1.10 Auxiliary Feedwater Response to High Energy Line Break in the Auxiliary Feedwater

a. Scope

The team performed an integrated review of plant response, manual operator actions, and auxiliary feedwater equipment capabilities for a high energy line break in the main feedwater and main steam penetration room (Area GE/GW). The integrated event issues will be discussed in this section. Some details are covered in Section 4OA5.2.1.11.

The team selected this topic for inspection because multiple high energy line break sources were available in this area, a high energy line break would create a harsh (high temperature) environment in this relatively small area, and because portions of the auxiliary feedwater system that were needed to mitigate this high energy line break would be exposed to that harsh environment.

The team examined the design and license basis analyses for high energy line breaks in this area. The team reviewed the requirements for environmental qualification for specific components, then reviewed the environmental qualification design files for these components. The team reviewed non-conformance reports and action requests, which documented plant changes and corrective action when compliance with environmental qualification requirements was questioned.

The team evaluated the results of a simulator scenario for a steam line break outside containment in the feedwater and steam line penetration room (Area GE/GW) run with a full compliment shift crew in support of the inspection issues. The scenario involved a specific steam break in the steam supply line to the turbine driven auxiliary feedwater pump with a loss of power to engineered safety feature Bus H. The ability of the crew to implement feed and bleed core cooling was also evaluated, since this was the backup decay heat removal method if all auxiliary feedwater was lost.

b. Findings

No findings of significance were identified.

.2.1.11 Electrical and Control Design for Auxiliary Feedwater Level Control Valves

a. Inspection Scope

The team reviewed the electrical and control design, environmental qualification basis, installation, testing, and corrective action history for the auxiliary feedwater electro-

hydraulic level control valves. The team reviewed the appropriateness of using pump discharge pressure signals to control the level control valves to provide runout protection for the motor driven pumps, the manual control features, and the failure modes.

The purpose of this review was to confirm that these valves were capable of performing their safety functions in accordance with the design and licensing basis for loss of feedwater, loss of offsite power, loss-of-coolant accident, main steam line break, or high energy line break.

The team reviewed the calculations for the environmental conditions during a high energy line break and assessed the environmental qualification files for the auxiliary feedwater components in Area GE/GW. This was because some components that could be exposed to a harsh environment as a result of a main steam line break or high energy line break event must also function to mitigate this accident. The team also reviewed the basis for exemption of certain auxiliary feedwater components from qualification to a harsh environment, and the assumptions regarding operator action.

The team reviewed selected failure modes and effects that could be associated with these events, including consideration of electrical power dependencies and applicable environmental effects, to determine if the consequences were consistent with the licensing and design basis. The team coordinated this part of the review with the review of simulator scenarios to confirm that the simulator, the applicable emergency operating procedures, and operator training were consistent with the expected plant response, control capabilities, and operator actions for the selected failure scenarios.

The documents reviewed included the Final Safety Analysis Report, auxiliary feedwater design criteria memorandum, vendor manuals, schematic diagrams, and calculations. The team also performed a partial system walkdown of the auxiliary feedwater system and Area GE/GW, to assess installation configuration, potential hazards to auxiliary feedwater equipment, and material condition. The review also included a sample of data and selected installations associated with "hot spot" temperature monitoring, which the licensee had implemented to support the basis for component operating temperatures assumed in the environmental qualification program.

The team reviewed non-conformance reports and action requests initiated within the previous 3 years associated with the auxiliary feedwater level control valves in order to assess the material condition and reliability, and corrective actions. The team also reviewed electrical power sources for auxiliary feedwater components to assess whether motive and control power schemes were susceptible to single failure vulnerabilities.

b. Findings

No significant findings were identified.

.2.1.12 Alternate Water Supplies to the Auxiliary Feedwater System

a. Inspection Scope

The team reviewed the two principle alternate sources of water to the auxiliary feedwater system. The function of this system was risk-significant for removing core decay heat, and the system mission time exceeded the amount of time the normal source (condensate storage tank) would be able to supply water. Therefore, the NRC had previously approved alternate sources of water which were to be maintained available onsite in sufficient quantity. The team reviewed design and license basis documentation and drawings for the function and equipment. Team members walked down the accessible portions of the systems with the system engineers to assess material condition, equipment alignment, and accessibility of components required to be realigned when shifting to an alternate supply. The team also reviewed procedures used to align two of the alternate water sources. The team also reviewed water purity records, strainer design and maintenance records, and surveillance test procedures for using emergency pumps.

The team reviewed calculations and surveillance tests to determine whether the pumps could be supplied with an adequate supply of water to meet regulatory requirements with sufficient net-positive suction head for the required flow rates.

b. Findings

No findings of significance were identified.

.2.1.13 Setpoint Methodology for Selected Safety-Significant Setpoints

a. Inspection Scope

The team reviewed the assumptions, design inputs, and methodology used in the licensee's calculations that established the scaling, instrument uncertainty, setpoints, and setpoint margins for the following instrument channels:

- Condensate storage tank low-low level indication/alarm used by operators in determining when to switch to an alternate source of auxiliary feedwater.
- Refueling water storage tank low-low level, used to trip the residual heat removal pumps when aligning the ECCS from the injection phase to recirculation phase of a loss-of-coolant accident.
- Containment narrow and wide range level indication, used by operators, together with refueling water storage tank level, to determine when to manually align the ECCS for post-loss-of-coolant accident recirculation.

The team also reviewed installation details for these instruments, to confirm that the configuration was consistent with the basis of the calculations. For instruments located in containment, the team also reviewed the installation detail drawings to confirm that the instruments would not be vulnerable to post-accident debris or process conditions.

In addition, for a sample of motor operated valves in the auxiliary feedwater system, the team reviewed the adequacy of actuator motor overload protection and the licensee's use of thermal overload bypass circuits used to preclude nuisance tripping while the valve is performing its safety function.

b. Findings

No findings of significance were identified.

.2.1.14 Design and Testing of Auto-Transfer Features for Offsite Power System

a. Inspection Scope

The team reviewed elementary and logic diagrams, test reports, and calculations for circuits that control the automatic transfer of offsite power sources for the engineered safety feature buses during required events such as a unit trip or accidents. Elementary and logic diagrams were reviewed to determine whether the transfer from station auxiliary power to offsite startup power would occur immediately for unit trip scenarios, and after main generator trip for accident scenarios. The setpoints, time delays and the associated tolerances for voltage relays were reviewed to determine whether the slow transfer scheme would allow sufficient voltage decay to preclude damage to motors, but still avoid spurious transfer to the onsite emergency source. The team also reviewed elementary and logic diagrams, and calculations for the fast transfer of non-engineered safety feature buses to the offsite source to determine whether it would result in spurious actuation of engineered safety feature bus undervoltage protection, or disrupt load sequencing on the engineered safety feature buses.

b. Findings

No findings of significance were identified.

.2.1.15 Electrical Bus Work Connector Torquing in High Voltage Electrical Buses

a. Inspection Scope

The team reviewed calculations, procedures, and drawings to determine whether the appropriate corrective actions had been taken for a 12 kV electrical bus failure that occurred at Diablo Canyon Power Plant in May, 2000. This issue had been selected for review by the team due to the on-site electrical distribution bus work being categorized as a Maintenance Rule Category (a)(1) system as a result of failures.

The licensee attributed the May 2000 failure to thermal runaway in the connection due to long-term degradation; however, since components critical to identifying any cause were destroyed when the electrical bus failed, the inspectors verified that the corrective actions were broad and comprehensive to address the relative uncertainty of the presumed cause. Specifically the team reviewed: 1) the scope of the licensee's inspections following the event to ensure that potential degradation in other electrical bus work was identified, 2) the inspection results to verify that possible failure mechanisms (e.g., inadequate torquing of bus work connection bolts) were addressed

and findings documented, and 3) that appropriate corrective actions were taken when degraded bus work connections were identified. The inspection team also reviewed other actions taken by the licensee including the increased monitoring of bus work temperatures.

The inspection team also performed a review of the operational experience available at the time of the failure to assess the licensee's actions and prior opportunities to identify and prevent similar failures.

b. Findings

No findings of significance were identified.

.2.1.16 Battery 12 Sizing Calculations and Manual Actions to Ensure Design Load Life

a. Inspection Scope

The team reviewed the battery calculation for the loss of three diesel generators prepared for probabilistic risk assessment scenario evaluation, and interviewed the site probabilistic risk assessment specialist. The scenario considered in the calculation was beyond the design basis in that it considered the failure of all three diesels. The battery capacity was analyzed for 7 hours of operation. The team verified that substantial margin was available in battery capacity over the station blackout coping time.

b. Findings

No findings of significance were identified.

.2.1.17 Margin Review for engineered safety feature Bus Load, Load Shed, Load Sequencing, and Breaker Coordination/Fault Protection

a. Inspection Scope

The team reviewed calculations and drawings to determine whether engineered safety feature Bus G loading was within equipment ratings. The team also reviewed calculations, drawings, relay setting sheets and test reports to determine whether engineered safety feature load shed schemes, load sequencing, and bus protection were adequate to assure availability of engineered safety feature loads within the times assumed in the safety analysis, and to prevent spurious tripping of buses. The team reviewed the setpoints and time delays for undervoltage relays used in the load shed scheme, as well as power supplies and setpoints for the discrete timing relays used in motor starting circuits. The team also reviewed surveillance procedures and test reports for time delay relays to determine whether actual setpoints were consistent with the intended design.

b. Findings

Motor Starting Analyses did not Consider Out of Sequence Starting of Motors During Load Sequencing Caused By Fault on the 4160V System

Introduction. The team identified a Green noncited violation for inadequate design control associated with a failure to demonstrate that postulated limiting load sequencing would satisfy regulatory requirements. The team identified that a single fault occurring during load sequencing with offsite power available could restart load sequencing timers in all three engineered safety feature buses and result in a more limiting scenario than previously analyzed by the licensee.

Description. The licensee did not analyze the simultaneous starting of multiple large motors during load sequencing, which could result from maloperation of timing relays following a fault. The load sequencing scheme utilized individual timing relays in the circuit breaker control circuits for sequenced loads. The team identified that these timing relays received power from their associated 4160 V buses. Because of this, the timers associated with all three 4160V emergency feedwater system buses are vulnerable to simultaneous maloperation caused by voltage perturbations when these buses are all connected to offsite power. As a result, a fault that causes a large enough voltage dip of sufficient duration (prior to clearing) could re-initiate some or all of the sequence timing relays. The team determined that individual relays had dropout voltages in the range of 5 to 50 percent of rated voltage and that dropout times were slightly shorter than the design total clearing time for a fault of this type. Thus, the team concluded that some relays could re-initiate and some could be unaffected. This could result in overlapping starting transients for motors that were intended to start separately. Existing calculations did not evaluate the simultaneous starting of multiple motors on a single bus. Overlap of starting transients because of the postulated fault could result in lower voltages at the terminals of the starting motors and longer acceleration times than previously analyzed, potentially affecting system performance assumed in accident analyses.

Since a single fault could adversely affect redundant trains of equipment, an analysis was necessary to demonstrate that a single fault would not prevent satisfactory performance of the minimum Class 1E load required for the safety function.

In response to the team's concerns, the licensee wrote Action Request 0630036 to evaluate the condition described above. A subsequent evaluation concluded that there would be no loss-of-safety function even considering the effects of a fault as described above. Specifically, the action request documented that the limiting times for starting loads was greater than twice the scheduled times, so even if the timer went through two complete cycles, the loads would start in time to accomplish the safety function. Also, the licensee performed preliminary calculations that demonstrated that the electrical distribution system was capable of starting and accelerating multiple motors simultaneously. The team independently reviewed relay calculations and concluded that starting multiple motors would not trip overcurrent relays.

Analysis. The team concluded that this was a performance deficiency because the licensee failed to demonstrate through analyses that the electrical distribution system was capable of performing its required function following the failure (fault) of a single component. This issue was more than minor because it affected the Mitigating System cornerstone objective of ensuring availability, reliability, and capability of systems needed to respond to a design basis accident. The issue screened as having very low safety significance in Phase I of the significance determination process, because it involved a design deficiency that was determined not to involve a loss of function in accordance with Generic Letter 91-18.

Enforcement. 10 CFR Part 50, Appendix B, Criterion III, "Design Control," requires that measures be established to assure that applicable regulatory requirements and the design basis are correctly translated into specifications, drawings, procedures, and instructions. Contrary to the above, the licensee failed to analyze the effects of an limiting, non-standard load sequencing schedule on redundant safety buses caused by a single failure. Since this finding is of very low safety significance and has been entered into the licensee's corrective action program (Action Request A0630036), it will be treated as a noncited violation, consistent with Section VI.A.1 of the NRC Enforcement Policy: NCV 05000275; 323/2005006-06, Analyses Did Not Demonstrate Proper Load Sequencing With Timer Anomalies.

.2.1.18 Control and Protection for Components that Supply Offsite Power to Engineered Safety Features Buses

a. Inspection Scope

The team reviewed calculations, drawings, modification packages, maintenance procedures, and vendor data to determine whether buses and transformers that supply power from offsite to engineered safety feature buses were adequately designed and maintained. Specifically, the team reviewed load flow calculations to determine whether loading of buses and transformers were applied within their ratings. The team also reviewed the design of protective relaying for buses and transformers to determine whether equipment was properly protected, and also immune from spurious tripping under expected transient and steady state loading conditions. Particular attention was given to the differential protection scheme for the new startup transformers, which were modified to accommodate new transformer switching schemes.

b. Findings

No findings of significance were identified.

.2.1.19 Capabilities for Restoring Offsite Power Following Prolonged Loss of Offsite Power

a. Inspection Scope

The team performed a tour of 500kV switchyard and its associated control center to determine whether the physical condition and arrangement of switchyard, its controls, and power sources, including standby batteries and breaker air supplies, were adequate for restoration activities during station blackout events. The team interviewed

switchyard control center operators to determine whether they were familiar with power restoration procedures and whether communication systems and protocols would facilitate coordination of activities with station operators during station blackout events. The team reviewed procedures governing restoration of power and reviewed electrical one line drawings to ascertain that there was a reliable source of power for the 500kV switchyard control center. The team also reviewed the probabilistic risk assessment analyses relating to restoration of offsite power to assess whether the assumptions and time limits were valid.

b. Findings

No findings of significance were identified.

.2.1.20 Review Modification that Replaced Startup Transformers and Installed New Load Tap Changers

a. Inspection Scope

The team reviewed the modification for replacement of the startup transformers to determine whether the objective of the modification was correctly translated into the final design. Specifically, the team reviewed load flow calculations, drawings, and setting sheets, to determine whether the new design was properly analyzed and implemented to meet the design objective. The team reviewed operating procedures to determine whether new contingencies, such as transformer tap changers out of service, were properly considered. The team reviewed power supplies for the new load tap changers to determine whether motive and control power would be available during low grid voltage conditions when the tap changers would be required to operate, and assessed the failure modes of the modified system. The team also reviewed maintenance and calibration procedures and results for the load tap changer and controllers to determine whether the design basis for the load tap changers was being properly maintained.

b. Findings

No findings of significance were identified.

.2.1.21 Electrical Cables Potentially Degraded due to Submergence in Underground Cable Vaults

a. Inspection Scope

The team reviewed Diablo Canyon Power Plant's corrective action program documentation for underground electrical cables in order to determine whether any risk-significant medium and high voltage cables were potentially degraded due to submergence problems in cable vaults and conduits. This issue was selected for a detailed review by the team because of multiple failures that had occurred in the 1990's at Diablo Canyon Power Plant, as well as some recent cable problems that might have been related. The team reviewed the appropriateness of the design specifications and

ratings of the cables, the corrective actions taken to address past problems, and use of operating experience reviews by the licensee.

The team assessed the licensee's routine monitoring and inspection program for underground and/or potentially submerged cables. The team also reviewed the effectiveness of the electrical pullbox inspection and dewatering preventative maintenance program for 4kV and 12kV underground electrical cables.

The team also inspected the material condition of underground vaults and cable pull boxes to look for evidence of wetting and water intrusion. This review was performed during the week of January 24, 2005, following unusually heavy and sustained rainfall. Cables within the inspected vaults were found to be either dry or had acceptably small quantities of water, which did not affect the cables.

The team reviewed the effectiveness of the licensee's corrective actions. The team noted that the licensee had not had any failures on medium voltage cables due to water submergence since the corrective actions were taken.

The team also reviewed industry operating experience that was related to submerged cable issues and how the licensee evaluated and addressed those issues.

b. Findings

No findings of significance were identified.

.2.1.22 Analysis and Design Features to Withstand Tsunami Effects

a. Inspection Scope

The team reviewed the plant's ability to withstand the effects of a tsunami. Team members reviewed design basis and license basis documents, interviewed cognizant engineers about areas of the plant that were potentially susceptible to the effects of a tsunami and the design features intended to address the effects. The team reviewed the procedure used for responding to tsunami warnings to verify that it was practicable and consistent with the plant design basis. Team members conducted a walkdown of the susceptible areas to verify that design features were in good material condition and the related administrative controls were effective.

b. Findings

Diablo Canyon Power Plant's design conservatively assumes a tsunami occurs during a combination of the worst tide and storm-induced wave conditions, and uses the worst tsunami ever documented on the California coast. The plant's ability to withstand large waves and the maximum wave height at the intake structure were determined through extensive and detailed scale model wave testing.

However, the team raised a question, which was not documented in the licensee's analysis of record. The licensee did not determine what the peak pressure could be in the a cooling water system as a result of the dynamic wave effects.

In response, the licensee performed an operability evaluation, documented in Action Request A0630734, which concluded that the expected dynamic effects should be within the capability of the system. The licensee planned to complete their analysis of record for the design capability of the plant to withstand tsunami effects under Action Request A0630734.

Analysis. The safety significance of any issues identified upon review of the licensee's analysis update will be determined at that time.

Enforcement. This issue remains unresolved pending NRC review of further documented analyses by the licensee: URI 05000275/2005006-07; 05000323/2005006-07; Assess Peak Pressure Effects Due to Tsunami.

.3 Industry Operating Experience

.3.1 Review of Licensee Response to Industry Operating Experience

a. Inspection Scope

The team reviewed selected operating experience issues that had occurred at other facilities for their possible applicability to Diablo Canyon Power Plant. Five issues that appeared to be applicable to Diablo Canyon Power Plant were selected for a more in-depth review. The issues that received a detailed review by the team included:

- NRC Generic Letter 96-06, Assurance of Equipment Operability and Containment Integrity During Design Basis Accident Conditions.
- NRC Information Notice 88-23, Potential for Gas-Binding High Pressure Safety Injection Pumps During a loss-of-coolant accidents. The team also reviewed other Operational Experience related to and referenced by this document. Refer to Section 4OA5.2.1.3 of this inspection report for a discussion of gas voiding issues at Diablo Canyon Power Plant.
- NRC Generic Letter 90-06, Resolution of Generic Issues 70, "PORV and Block Valve Reliability," and Generic Issue 94, "Additional LTOP Protection for PWRs." Refer to Section 4OA5.2.1.7 of this inspection report for a discussion of power operated relief valve operability issues at Diablo Canyon Power Plant.
- Westinghouse Nuclear Service Advisory Letter 93-13 and Supplements.
- NRC Bulletin 88-04 and Information Notice 87-59, both addressing pump to pump interactions and minimum flow.

b. Findings

b.1 Inadequate Response to Operating Experience for Minimum Pump Flow Settings

Introduction. The team identified a Green finding for inadequate response to industry operating experience regarding establishing minimum flow for the auxiliary feedwater

pumps. The team concluded that the licensee recognized that the conditions reported in NRC Bulletin 88-04 were present in auxiliary feedwater pumps because of low settings in the minimum flow lines, but failed to take appropriate actions to minimize and manage, or to eliminate, the potential for pump damage.

Discussion. The team reviewed the licensee's response to NRC Bulletin 88-04, "Potential Safety-Related Pump Loss." This Bulletin, in part, identified a concern regarding the adequacy of minimum flow capacities for safety-related centrifugal pumps. The bulletin requested licensees to evaluate the capability of safety related pumps to run long term at minimum recirculation flow rates. The bulletin stated that many licensees had accounted for thermal considerations in setting the minimum recirculation flow rates, but had failed to consider flow instability effects. The latter consideration could necessitate a considerable increase in minimum flow settings.

The team identified no concerns with most safety-related pumps at Diablo Canyon Power Plant. However, the team identified concerns with the auxiliary feedwater pumps. The licensee had concluded that the original, manufacturer-supplied minimum recirculation flows (circa 1974) were adequate to meet the issues discussed in Bulletin 88-04. The motor-driven pumps had a 490 gpm capacity and a 50 gpm minimum flow setting, while the turbine-driven pumps had an 930 gpm capacity with a 50 gpm minimum flow setting. However, Pacific Gas and Electric Company's May 9, 1989, updated response to Bulletin 88-04 indicated that the turbine-driven auxiliary feedwater pumps did not have adequate minimum flow, and that the consequence was potential for unusual wear and aging because of the hydraulic effects during surveillance testing and plant startup and shutdown evolutions. However, no action was taken to adjust maintenance frequencies, or operating or surveillance procedures to minimize or compensate for this.

The team requested documentation to establish the technical basis for the minimum flow settings for the auxiliary feedwater pumps, particularly how they accounted for flow instability, and the licensee was not able to provide any documentation that addressed this issue during the inspection.

The team questioned whether the current settings were reviewed and approved by the pump manufacturer (originally Byron-Jackson, currently owner by Flowserve), as specified in Bulletin 88-04. Westinghouse was able to show that Flowserve had approved a slight increase in the minimum flow setting for the motor-driven auxiliary feedwater pumps in 2001, but could not show documentation for motor-driven or turbine-driven pumps at the time of the Bulletin 88-04 evaluation.

The team reviewed the available documentation and concluded that the existing minimum flow settings for the motor-driven auxiliary feedwater pumps accounted only for thermal effects. Similar documentation was not available for the turbine-driven pumps, but since they were double the capacity of the motor-driven pumps but had the same minimum flow setting, and had been assigned that setting well prior to Bulletin 88-04, it was likely that this setting also did not account for flow instability considerations.

In response to the lack of documentation and the team's concerns, the licensee had Flowserve and Westinghouse perform a new analysis of the auxiliary feedwater pump minimum flow settings in response to NRC Bulletin 88-04. On February 25, 2005, Flowserve concluded the pumps were not currently degraded, but the minimum flow being used did not allow continuous operation. Specifically, Flowserve stated that for the motor-driven pumps (turbine-driven pumps), the minimum flow rate for continuous unrestricted operation was 250 gpm (484 gpm). For intermittent operation with a recommended total accumulation of not more than 1500 hours between overhauls, the minimum flow rate was given as 175 gpm (339 gpm). For short periods of operation with a recommended total accumulation of not more than 60 hours between overhauls, the minimum flow rate was given as 50 gpm (50 gpm). Flowserve went on to state that their review of several years' of test data for the Diablo Canyon Power Plant auxiliary feedwater pumps indicated that there was no adverse trend in performance indicative of degradation, so continued operation was acceptable. However, Flowserve recommended that should the pumps exceed the alert levels in vibration or differential pressure, the pump should be inspected at the next convenient time. The team noted that this action would normally occur when pumps are more degraded, at the required-action level.

Based upon the above, the team made the following conclusions:

- The existing auxiliary feedwater minimum flow settings did not account for the flow instability issues; they were based on thermal considerations only.
- The existing minimum flow settings in the auxiliary feedwater system were not supported by adequate technical documentation.
- The licensee had not contacted the auxiliary feedwater pump supplier to get their minimum flow settings verified, as specified in Bulletin 88-04. When Pacific Gas and Electric Company contacted the supplier during this inspection, restrictive administrative limits were recommended based on the existing minimum flow settings.
- The licensee had assessed the adequacy of the minimum flow settings for auxiliary feedwater pumps with Westinghouse in response to Bulletin 88-04, and concluded that no changes were needed except for residual heat removal and turbine-driven auxiliary feedwater pumps. However, for auxiliary feedwater, no action was taken to ensure that degradation would be monitored and controlled in ways that ensured the reliability of the auxiliary feedwater pumps. The conclusion that the motor-driven auxiliary feedwater pumps had adequate minimum flow was inappropriate.
- The licensee had missed an important opportunity to identify and correct an important operating experience issue in 1988.

Analysis. This finding represented a performance deficiency because the licensee did not adequately address a degradation mechanism identified in NRC Bulletin 88-04, as required by the station's operating experience program. As a result, the auxiliary feedwater pumps continued to be operated with insufficient minimum flow to avoid

unusual wear and aging without establishing increased monitoring and maintenance, or other compensating actions.

This issue was more than minor because it affected the equipment reliability objective of the Mitigating Systems cornerstone. This issue screened as Green during a Phase 1 significance determination process, since the performance deficiency was confirmed not to result in a loss of function in accordance with Generic Letter 91-18. This issue will be treated as a finding in accordance with Manual Chapter 0612: FIN 05000275, 323/2005006-08, Inadequate Response to Operating Experience for Auxiliary Feedwater Minimum Flow.

Enforcement. No violation of NRC requirements was identified.

b.2 Observations on Operating Experience Weaknesses

In reviewing the licensee's response to industry operating experience associated with ECCS gas voiding, the team noted the following issues:

- Information Notice 88-23, Supplement 3, regarding events at Sequoyah stated that "Further investigation and analysis by the licensee revealed that hydrogen gas was accumulating in the suction piping of the "B" pump and in the residual heat removal crossover piping to the charging header." The operating experience also stated that "The gas came out of solution (in part) due to localized reductions in pressure because of piping elevation differences and eccentric pipe reducers. . . ." which closely relates to the licensee's current theory of the 2004 events. The information notice also stated that "It is important to consider all potential sources of gas intrusion to the ECCS suction piping." The corrective actions the licensee took, as specified in Action Request 214415 and Nonconformance Report DCO-91-TN-N004, focused on volume control tank (VCT) pressure variations and not on the "piping elevation differences and eccentric pipe reducers."
- Information Notice 88-23, Supplement 0 regarding an issue at Farley, stated "If the local pressure in the piping at some point between the VCT and HPSI pump suction nozzles is less than VCT pressure, the dissolved hydrogen will come out of solution and will not immediately go back into solution even if the pressure downstream from that point is greater than VCT pressure. The licensee believes that the pressure distribution in some elbows and tees downstream from the VCT is such that some hydrogen comes out of solution in those fittings and that these hydrogen bubbles are swept through the pumps without damaging them. In the suction piping of pump A, however, some of the bubbles are trapped in the vertical section of line that runs to the high point vent." In accordance with a May 17, 1991, letter, "PG&E determined that the gas binding problem was not a concern for DCPD since DCPD did not have a similar piping configuration where the bubbles could collect. Where high point did exist in the ECCS piping, venting of the piping using STP M89, . . . was already being done." This response did not address the concern or prevent problems.

- A similar gas intrusion problem in the charging pumps suction at Catawba was analyzed by Diablo Canyon Power Plant in early March 2004, and deemed not to be an issue “because numerous barriers have been implemented to minimize the probability of a void impacting the operability of the ECCS, *especially at the suction of charging pumps.*” {Emphasis added.} Refer to Action Request 0601949. This evaluation, performed in April 2004, concluded that the condition was not a “quality problem.” The team noted that the licensee came to this conclusion one month prior to gas voiding at Diablo Canyon Power Plant that made both trains of ECCS inoperable.
- As discussed in Section 4OA5.2.1.3, the symptoms and causes discussed in these operating experience reports appear to closely correspond to problems being experienced at Diablo Canyon Power Plant. The licensee missed prior opportunities to address these issues when they did not properly assess the relevance of the issues to their plant.

4OA6 Meetings, Including Exit

Exit Meeting Summary

The lead inspector presented the inspection results to Mr. G. Rueger, Senior Vice President, Generation and Chief Nuclear Officer, and other members of the licensee staff on February 15, 2005, at a public exit meeting in San Luis Obispo, California. The team confirmed that proprietary information provided to the team was handled in accordance with NRC policy. Following completion of additional review in the Region IV office, a final exit was held by telephone with Mr. Parker and other members of the licensee staff on March 24, 2005, to provide an update on the inspection findings as discussed at the February 15, 2005, meeting.

ATTACHMENT: Supplemental Information

ATTACHMENT

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee personnel

A. Afzali, Supervisor, Probabilistic Risk Assessment Group
T. Baldwin, Manager, Engineering
C. Belmont, Director, Nuclear Quality, Analysis, and Licensing
M. Burgess, Supervisor, Component Engineering
K. Bush, Supervisor, Engineering
S. Chesnut, Director, Engineering Services
C. Dougherty, Senior Engineer, Regulatory Services
D. Jacobs, Vice President, Nuclear Services
C. Joyce, Engineer, Nuclear Quality Assurance and Licensing
S. Ketelsen, Manager, Regulatory Services
J. Knisley, Shift Manager, Operations
D. Miklush, Director, Strategic Projects
D. Oatley, Vice President and General Manager, Diablo Canyon Power Plant
L. Parker, Supervisor, Regulatory Services
G. Reimers, Engineer, Electrical Design
P. Roller, Director, Operations Services
G. Rueger, Senior Vice President, Generation and Chief Nuclear Officer
B. Terrell, Supervisor, Corrective Action Program
J. Tompkins, Director, Site Services
D. Vosberg, Project Manager, Strategic Projects
L. Walter, Manager, Engineering
R. West, Supervisor, Engineering Services

NRC personnel

H. Chernoff, Project Manager, Office of Nuclear Reactor Regulation
T. Jackson, Resident Inspector, Diablo Canyon Power Plant
S. Jones, Acting Section Chief, Plant Systems Branch, Office of Nuclear Reactor Regulation
D. Loveless, Senior Reactor Analyst, Region IV
D. Proulx, Senior Resident Inspector, Diablo Canyon Power Plant
G. Sanborn, Allegation Coordinator Enforcement Staff, Region IV
G. Shukla, Project Manager, Office of Nuclear Reactor Regulation

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

Opened

05000275, 323/2005006-07 URI Assess peak pressure effects due to tsunami
(Section 40A5.2.22)

Opened and Closed

05000275, 323/2005006-01	FIN	diesel fuel oil transfer modification did not adequately assess reliability impact (Section 4OA.2.1.4.b.1)
05000275, 323/2005006-02	NCV	No procedure for cross-tying trains of the diesel fuel oil transfer system (Section 4OA5.2.1.4.b.2)
05000275, 323/2005006-03	NCV	diesel fuel oil storage tank calculation did not adequately account for vortexing (Section 4OA5.2.1.5)
05000275, 323/2005006-04	NCV	Failure to use the highest pressure in calculation to verify adequate auxiliary feedwater flow (Section 4OA5.2.1.6)
05000275, 323/2005006-05	NCV	Inadequate power operated relief valve accumulator calculation (Section 4OA5.2.1.7)
05000275, 323/2005006-06	NCV	Analyses did not demonstrate proper load sequencing with timer anomalies (Section 4OA5.2.1.17)
05000275, 323/2005006-08	FIN	In complete action for setting auxiliary feedwater pump minimum flow values (Section 4OA5.3.1)

Discussed

50-275/04-05-05	NCV	Failure to adequately correct ECCS voiding following operation of the positive displacement pump (Section 4OA5.2.1.3)
-----------------	-----	-----------------------------------------------------------------------------------------------------------------------

LIST OF DOCUMENTS REVIEWED

Section 4OA5.1.2, Results of Detailed Reviews

Modification Packages: (also listed in other sections below)

DCP J-49461, Qualification of FCV-38, Revision 0

DCP-M-41009, Install Emergency Tie-Ins for Alternate Cooling to CCPs, Revision 0

DCP M-39858, Addition of Diesel Fuel Oil Recirculation System and Emergency Fuel Oil Transfer System, Revision 5

DCP M-049160 Upgrade Diesel Fuel Oil Tanks (Unit 1), Revision 0

DCP M-49268, Upgrade Diesel Fuel Oil Tanks (Unit 2), Revision 0

DCP M-049284, Addition of Nitrogen Pressurization to CCW Surge Tank, Revision 0

DCP P-049371, Unit 1-Replace Existing Balls in FCV-253 and FCV-500 with Modified Balls during 1R9, Revision 0

DCP P-050371, Unit 2-Replace Existing Balls in FCV-253 and FCV-500 with Modified Balls during 2R8, Revision 0

DCP E-050490, Replace Starter, Overload Relay, and Overload Auxiliary Relay, Revision 0.

DCP E-049322, Replace Startup Transformer 11 with New Transformer Equipped with Load Tap Changer, Revision 0

50.59 Safety Evaluations:

The following examples of full 50.59 safety evaluations were reviewed as part of this inspection. The intent of Inspection Procedure 71111.02 was met, although the specific guidance of that procedure was not used. Multiple 50.59 screenings were reviewed but not recorded.

DCP M-39858, Addition of Diesel Fuel Oil Recirculation System and Emergency Fuel Oil Transfer System, Revision 5

DCP M-049160 Upgrade Diesel Fuel Oil Tanks (Unit 1), Revision 0

DCP M-49268, Upgrade Diesel Fuel Oil Tanks (Unit 2), Revision 0

50.59 Review for SGTR Dose Increase Due to Analysis Error

DCP E-050490, Replace starter, overload relay, and overload auxiliary relay, Revision 0.

DCP J-49461, Qualification of FCV-38, Revision 0 (LBIE 98-158)

Supplemental Safety Evaluation of PG & E Response to Station Blackout Rule (10 CFR 50.63) for Diablo Canyon (TAC Nos. M68537 and M69538), dated May 25, 1992

Safety Evaluation number SECL-94-188, Revision 1, Diablo Canyon Units 1 and 2, Reduction in the Auxiliary Feedwater Flow Evaluation, dated March 17, 1995.

Safety Evaluation SECL-89-509, Adequacy of Safety Related Auxiliary Pumps Minimum Flow Requirements, Revision 1, dated October 7, 1989.

Safety Evaluation related to License Amendments 171 and 172

Supplemental Safety Evaluation of PG & E Response to Station Blackout Rule for Diablo Canyon, dated May 25, 1992

Section 4OA5.2.1.1 Alternate Cooling Supply to Centrifugal Charging Pumps

OP AP-11, Backup Cooling to a Centrifugal Charging Pump, Revision 21

STP M-120, Firewater Availability to CCP Coolers, Revision 4

Job Performance Measure LJP-130, Establish Backup Cooling to a Centrifugal Charging Pump, Revision 9

Westinghouse Letter PGE-96-605, Evaluation of Auxiliary Pumps for Elevated Component Cooling Water Temperatures, dated September 3, 1996

Westinghouse Letter PGE-96-608, Review Comments on CCP Replacement Gear Oil Cooler Performance, dated September 23, 1996

DCM S-08, Chemical and Volume Control System, Revision x

DCP-M-41009, Install Emergency Tie-Ins for Alternate Cooling to CCPs, Revision 0

Section 4OA5.2.1.2 Single Train CCW Capabilities

Design Criteria Memoranda:

DCM S-14, Component Cooling Water System, Revision 15D.

DCM S-17-B, Auxiliary Salt Water System, Revision 17B.

Calculations:

STA-163, Estimation of Heat Removal Capacity of a Water Flow, Revision 1.

M-938, CCW Data Input for 1993 Containment Analysis Program (CAP), Revision 3.

M-1024, Backup Fire Water Supply to CCP Coolers During Periods of Total Loss of CCW, Revision 0.

Drawings:

106714, Operating Valve Identification Diagram (OVID), Component Cooling Water, Revision 55.

106717, Operating Valve Identification Diagram (OVID), Salt Water, Revision 137.

102014, Component Cooling Water Pumps, Sheet 5, Revision 56

Maintenance, Surveillance, and Test Procedures:

OP AP-11, Malfunction of Component Cooling Water System, Revision 21.

AR PK01-14, CCW Surge Tank Pressure, Revision 4A.

Other documents:

WCAP-14282, Evaluation of Peak CCW Temperature Scenarios for Diablo Canyon Units 1 and 2, Revision 1.

PG&E Letter from Michael R. Tresler to Scott A. McHugh of Westinghouse, Subject: Input Data for New Containment Analysis, dated June 28, 1993.

PG&E Letter from Tien P. Lee to Scott A. McHugh of Westinghouse, Subject: Input Data for New Containment Analysis, dated October 15, 1993.

ECG 17.1, Auxiliary Salt Water Cross-Tie Valve FCV-601, Revision 2.

File 116.30, Record of Telephone Call dated March 29, 1993, from Kelley, of PG&E to Allan Dohrer of Yuba Heat Transfer, Subject: Allowable Tube Plugging of the CCW Heat Exchanger.

PG&E Letter number DCL-97-151, from Gregory M. Rueger to USNRC, dated August 28, 1997, Response to NRC Staff's Concerns Regarding Installation of the Component Cooling Water Surge Tank Pressurization System-DCPP, Units 1 and 2.

UFSAR, Revision 15.

Technical Specifications, Unit 1-Amendment No. 135, Unit 2-Amendment No. 135.

Section 4OA5.2.1.3, Electrical Bus Work Connector Torquing Issue

Good Bolting Practices: A Reference Manual for Nuclear Power Plant Maintenance Personnel, Volume 2, December 1990

Electrical Connectors Application Guidelines, Final Report, December 2002

Altran Root Cause Evaluation Report, 12kV Bus Failure Root Cause, June 6, 2000

Electrical Single Line Diagram 500/230/12/4.16kV Systems, Revision 12

Work Order C00187799, 2R12 Bus Duct Inspection

NRC Information Notice 89-64, Electrical Bus Bar Failures September 7, 1989

NRC Information Notice 00-14, Non-Vital Bus Fault Leads to Fire and Loss of Offsite Power

Procedure MP E-63.3C, Maintenance of 4 and 12 kV Switchgear, August 5, 2004

Action Requests: A0512317, A0301721, A0313919, A0410818

Non-Conformance Reports: N002005, N002112

Section 4OA5.2.1.4, Diesel Fuel Oil Transfer System Normal and Backup Capabilities

AR DG13-3-4, High-Low Fuel Oil Level, Revision 1

DCM S-21, Diesel Engine System, Revision 19

OP J-6C,, Diesel Fuel Oil Transfer System, Revision 7A

OP J-6C:I, Diesel Fuel Oil Transfer System – Make Available and Place in Service, Revision 11

OP J-6C:II, Diesel Fuel Oil Transfer System – Alignment Verification for Plant Startup, Revision 14

OP J-6C:III, Diesel Fuel Oil Transfer System Recirculation, Revision 6

OP J-6C:IV, Diesel Fuel Oil Transfer System – Receiving Fuel Oil, Revision 8A

OP J-6C:V, Diesel Fuel Oil Transfer System – Use of Portable Fuel Oil Transfer Pump and DFO Day Tank LCVs, Revision 11,

STP P-PDFOTP-01, Routine Surveillance of Portable Diesel Fuel Oil Transfer Pump 0-1

STP P-DFO-01, Revision 5, Routine Surveillance Test of Diesel Fuel Oil Transfer Pump 0-1

Technical Specifications 3/4.8.1

Equipment Control Guidelines 21.1, 21.2

DCM S-21, Diesel Engine System, Revision 19

NCR DCO-89-TN-N022

Action Requests: A0141683, A0145835, A0142619, A0142738, A0141690, A0142156

UFSAR section 9.5.4

Licensee Event Report 50-275/89-002-00.

Preventive maintenance item MP M-51.14

Alarm Response Procedures:

AR PK15-01, CONT/TB SUMP/DSL FO VAULT LVL/DSL FO FLTR dP, Revision 18
AR PK17-07, Diesel 12 Fuel Oil System, Revision 12A
AR PK16-07, Diesel 11 Fuel Oil System, Revision 10A

Surveillance Test Procedures:

P-DFO-01, Routine Surveillance Test of Diesel Fuel Oil Transfer Pump 0-1, Revision 5

M-9A, Diesel Engine Routine Surveillance Test, Revision 68A

M-10B3, New Fuel Oil Shipment Analysis, Revision 4A

Calculation M-821, Determine If Sufficient Net Positive Suction Head Is Available For Operation Of The Diesel Fuel Oil Transfer Pumps, Revision 3

Calculation M-203, Determine the Required Pressure Setpoint for Diesel Generator Fuel Transfer Safety Relief Valve, Revision 4

Calculation M-805, Emergency Diesel Generator Fuel Oil Transfer System - PCV-410/411 Failure, Revision 3.

Calculation M-786, Determine the Required Diesel Fuel Oil Storage to Meet DCPD Licensing Bases for Operating Minimum ESF Loads, Revision 13.

Replacement Part Evaluation P-8403, APCO Valve, DC 1, 4"-125# Cast Iron Single Poppet Foot Valve, Revision 00

Design Change Packages M-049160 and M-49268, Upgrade DFO Tanks, Revision 0
Quality Evaluation Q0011662, AR A0367845

Drawing 501135, Electrical Schematic Diagram Main Annunciator, Revision 37

Drawing 106721, Diesel Fuel Oil System, Revision 38

Drawing 463667, Civil Structural Modifications Diesel Fuel Oil Pump Vaults, Revision 8

Drawing 102027, Turbine Building Sump, Revision 45

2004 Diesel Generator Safety System Functional Audit and Review - Audit Report 040080101

Standard Review Plan (NUREG 0800), Section 9.5.4

IEEE Standard 387-1995, "IEEE Standard Criteria for Diesel Generator Units Applied as Standby Power Supplies for Nuclear Power Generating Stations,"

Regulatory Guide 1.9, "Selection, Design, Qualification, and Testing of Emergency Diesel Generator Units Used as Class 1E Onsite Electric Power Systems at Nuclear Power Plants," Revision 3

Regulatory Guide 1.137, "Fuel Oil Systems for Standby Diesel Generators," Revision 1

Section 40A5.2.1.5 Diesel Fuel Oil Storage Tank Capacity and Modification

Modification Packages:

DCP M-39858, Addition of Diesel Fuel Oil Recirculation System and Emergency Fuel Oil Transfer System, Revision 5 and associated 50.59 safety evaluation

DCP M-049160 and M-49268, Upgrade Diesel Fuel Oil Tanks (Units 1 and 2), Revision 0

Non-Conformance Reports:

DCO-89-TN-N022

DCO-88-TN-N058

Alarm Response Procedures:

AR PK15-01, CONT/TB SUMP/DSL FO VAULT LVL/DSL FO FLTR dP, Revision 18

AR PK17-07, Diesel 12 Fuel Oil System, Revision 12A

AR PK16-07, Diesel 11 Fuel Oil System, Revision 10A

Surveillance Test Procedures:

P-DFO-01, Routine Surveillance Test of Diesel Fuel Oil Transfer Pump 0-1, Revision 5

M-9A, Diesel Engine Routine Surveillance Test, Revision 68A

M-10B3, New Fuel Oil Shipment Analysis, Revision 4A

Design Criteria Memoranda:

DCM No. S-21, Diesel Engine System, Revision 19.

Calculations:

SC-L-21-37, Instrument Scaling Calculation Diesel FOST 0-1 Level Alarms., Revision 1

SC-L-21-38, Instrument Scaling Calculation Diesel FOST 0-2 Level Alarms, Revision 0

70-DC, Overcurrent Relay Setting for Class 1E, 4 kV Motors, Revision 15

M-821, Determine If Sufficient Net Positive Suction Head Is Available For Operation Of The Diesel Fuel Oil Transfer Pumps, Revision 3

M-786, Determine the Required Diesel Fuel Oil Storage to Meet DCPD Licensing Bases for Operating Minimum ESF Loads, Revision 13.

Drawings:

Contained in DCP Number 49160, Diesel Fuel Oil Storage Tanks Upgrades, January, 1997.
437583, Electrical Schematic Diagram Auxiliary Feedwater Pumps, Revision 24
106721, Diesel Fuel Oil System, Revision 38

Action Requests:

A0529714, A0581761, A0367845, A0141683, A0145835, A0142619, A0142738, A0141690,
A0142156, A0109011, A0110905

Operating Procedures:

OP J-6C:IV, Diesel Fuel Oil Transfer System-Receiving Fuel Oil, Revision 8A.

Maintenance Procedures:

MP M-51.14, Generic Check Valve Inspection, Revision 10.
MP M-21.3, Diesel Fuel Oil Transfer Filter Element Replacement, Revision 2

Test Procedures:

STP M-10B, Diesel Fuel Oil Testing Program, Revision 17.
STP M-10B1, Emergency Diesel Fuel Oil Storage Tanks Analyses, Revision 6.
STP M-10B2, Diesel Generator Day Tanks Fuel Oil Analyses, Revision 3.
STP M-10B3, New Fuel Oil Shipments Analyses, Revision 4A.
CAP C-71, Total Particulate Contaminant of Fuel Oil, Revision 6A.
STP P-DFO-01, Routine Surveillance Test of Diesel Fuel Oil Transfer Pump 0-1, Revision 5.
STP P-DFO-02, Routine Surveillance Test of Diesel Fuel Oil Transfer Pump 0-2, Revision 5.

Work Orders:

R0150582 01; component 49-1230, Record No. 0000113542

Other documents:

Diablo Canyon Power Plant Operations Data, Storage Tank Volume Data, System 21, Diesel Generators Fuel Oil Storage Tanks 0-1 and 0-2.

PG&E Letter No. DCL-92-036, dated February 14, 1992, to USNRC; License Amendment Request 92-03.

PG&E Letter No. DCL-92-131, dated June 5, 1992, to USNRC; Response to NRC Questions on License Amendment Request 92-03.

USNRC Letter from Harry Rood to Gregory M. Rueger, dated August 12, 1992, Subject; Issuance of Amendments for Diablo Canyon Nuclear Power Plant, Unit No. 1 and Unit No. 2.

PG&E Letter DCL-04-118, dated September 23, 2004, to USNRC, LAR 04-04, Revision to Technical Specification 3.8.3, Diesel Fuel Oil, Lube Oil, Starting Air, and Turbocharger Air Assist.

PG&E Letter DCL-04-162, dated December 21, 2004, to USNRC, Response to Request for Additional Information Regarding LAR 04-04, Revision to Technical Specification 3.8.3, Diesel Fuel Oil, Lube Oil, Starting Air, and Turbocharger Air Assist.

Replacement Part Evaluation P-8403, APCO Valve, DC 1, 4"-125# Cast Iron Single Poppet Foot Valve, Revision 00

Quality Evaluation Q0011662

UFSAR Section 9.5.4

Licensee Event Report 50-275/89-002-00.

Technical Specifications 3/4.8.1

Equipment Control Guidelines 21.1, 21.2

2004 Diesel Generator Safety System Functional Audit and Review - Audit Report 040080101

System Check Valve Basis Documents for Inservice Testing Program, 12/11/01, Revision 0.

Section 4OA5.2.1.6, Design of Condensate Storage Tank

Design Criteria Memoranda:

DCM No. S-3B, Auxiliary Feedwater System, Revision 14A.

DCM No. T-12, Pipe Break (HELB/MELB), Flooding, and Missiles, Figure 4-23B, Area GE/GW Temperature vs Time Response, MSLB at El 115', 0.1 sq ft Break without BIT, Revision 14A.

Calculations:

M-405, AFWS Pressure and Temperature for DCM-M71, Revision 5.

STA-135, AFW Pump Acceptance Curves, Revision 2.

M-826, Auxiliary Feedwater Pump Net Positive Suction Head, Revision 2.

M-791, Maximum Steam Generator Pressure Following a Plant Trip, Revision 1.

M-831, CST Bases Requirements, Revision 0.

TV 16-4, Scaling Calculations for CST Level 1-1.

Summary of Draft Calculation STA-208, RETRAN Evaluation of MSLB at FCV-95.

Drawings:

102003 Sheet 4, Unit 1 Piping Schematic, Auxiliary Feedwater System, Revision 70

102009 Sheet 4, flow diagram showing refueling water storage tank, Revision 69.

102016 Sheet 7, flow diagram showing Unit 1 condensate storage tank, Revision 101.

106713 Sheet 3, flow diagram showing AFW Pumps, Revision 68.

464831, Sheet 1, Vortex Suppression Cages, Revision 3.

CST Construction Drawings numbered 1, 1A, 3, 8, 9, 12, 13 by PDM Steel Company for Contract number 13903.

Operating Procedures:

OP D-1:V, Auxiliary Feedwater System-Alternate Auxiliary Feedwater Supplies, Revision 16.

Test Procedures/results:

STP-P-AFW-11, Routine Surveillance Test of Motor-Driven Auxiliary Feedwater Pump 1-2, Revision 20.

STP-P-AFW-12, Routine Surveillance Test of Motor-Driven Auxiliary Feedwater Pump 1-2, Revision 11.

STP-P-AFW-13, Routine Surveillance Test of Motor-Driven Auxiliary Feedwater Pump 1-3, Revision 11A.

STP-I-16-L40, CST 1-1 Water Level Channel LT-40 Calibration, Revision 6.

STP-I-16-L44, CST 1-1 Water Level Channel LT-44 Calibration, Revision 0.

STP P-AFW-AT, Performance Test of Turbine-Driven Auxiliary Feedwater Pump, Revision 5A (Includes results of 5-28-01 test).

STP P-AFW-AM, Performance Test of Motor-Driven Auxiliary Feedwater Pump, Revision 6.

MP I-2.5-1, PME Plant Pressure Gauge (PPG) Calibration Record-Direct Calibration for: FI-207 on 12-1-03; PI-428 on 3-27-03 and 3-27-01; PI-422 on 10-7-03 and 10-12-01; and FI-207 on 1-4-02.

B-STP P-AFWT, Bases Document for STP P-AFW-11 and 21, Routine Surveillance Tests of Steam Driven Auxiliary Feedwater Pump, Revision 1.

B-STP P-AFWM, Bases Document for STP P-AFW-12, 13, 22, and 23, Routine Surveillance Tests of Motor Driven Auxiliary Feedwater Pump, Revision 1.

Work Orders:

R0263791, R0260133, R0240280 for P-AFW-11
R0263055, R0259475, R0240278 for P-AFW-12
R0264518, R0261599, R0259476 for P-AFW-13
R0245031, R0261747, R0257553 for P-AFW-21
R0264143, R0260677, R0256887 for P-AFW-22

R0268494, R0265522, R0262799 for P-AFW-23
R0249085 01 for FWT1 Inspection
R0230339 01 for FWT1 Inspection
C0178311 for FWT1 Inspection
R0198748 for FWT1 Inspection
R0119999 for CST 1 Inspection
R0193934 for CST 1 Inspection
R0193935 for CST 2 Inspection
R0222485 for CST 1 Inspection
R0225646 for CST 2 Inspection

Action Requests:

A0558271, A0515666, A0413813, A0507478, A0630009 , A0629991, A0630804

Other documents:

Record Number DC 663216-66-1, Vortex Suppression and Vortex Potential of the Refueling, Condensate, and Fire Water Storage Tanks, by Western Canada Hydraulic Laboratories Ltd., Port Coquitlam, B. C., dated April, 1980

System Training Guide D-1, Auxiliary Feedwater System, Revision 9.

Report of Outdoor Water Storage Tanks Visual Inspection Structural Monitoring Program, dated February 26, 1993.

Catalog Sheet for Hamondflote II Internal Floating Cover (No document number, or date, was provided).

Steam Driven AFW Pump and Turbine Vendor Curves, number 663056-27 and 663056-45.

PG&E Letter number DCL-95-217, from Gregory M. Rueger to USNRC, dated September 29, 1995, Revision of Technical Specification 3/4.7.1.2 Bases-Auxiliary Feedwater Flow Reduction.

Westinghouse Safety Evaluation number SECL-94-188, Revision 1, Diablo Canyon Units 1 and 2, Reduction in the Auxiliary Feedwater Flow Evaluation, dated March 17, 1995.

System Check Valve Basis Documents for Inservice Testing Program, 12/11/01, Revision 0.

System Manually Operated Valve Basis Documents for Inservice Testing Program, June 30, 1999, Revision 1.

PG&E Company Purchase Order number 4R-28960, for Level Control Valves (LCVs) 106, 107, 108, 109, 110, 111, 113, 115, dated April 5, 1971.

PG&E UFSAR, Revision 15.

PG&E Technical Specifications, Unit 1-Amendment No. 135, Unit 2-Amendment No. 135.

Section 4OA5.2.1.7, Potentially Degraded Electrical Cables due to Submergence in Underground Cable Vaults

NRC Information Notice 98-21, Potential Deficiency of Electrical Cable/Connection Systems
June 4, 1998

NRC Information Notice 84-01, Excess Lubricant in Electrical Cable Sheaths, January 10, 1998

NRC Information Notice 93-33, Potential Deficiency of Certain Class 1E Instrumentation and Control Cables, April 28, 1993

NRC Information Notice 92-81, Potential Deficiency of Electrical Cables with Bonded Hypalon Jackets, December 11, 1992

NRC Information Notice 02-12, Submerged Safety Related Cables, March 21, 2002

NRC Regulatory Issue Summary 00-25, Potential Deficiency in Qualification of Okonite Single-Conductor Electrical Control Cables, December 26, 2000

Drawing 500732, Embedded Conduit Layout Elevation 85'-0" Area GW, Change 5

Drawing 500606, Conduit Layout Outdoors Area 1, Revision 0

Integrated Problem Response Team Report on Medium Voltage Cable, October 6, 1993

Technical Report 02810-TR-001, Component Cooling Pump 4kV Cable Evaluation, Revision 1

Integrated Problem Response Team Report on Medium Voltage Cable, October 3, 1993

Action Requests:

A0304782, A0422414, A0319647, A0318814, A0532960, A0482841, A0630781, A0630777

Section 4OA5.2.1.8 Emergency Core Cooling System Gas Voiding

Non-Conformance Reports:

N1969, CCP Miniflow Orifice Erosion, August 25, 1999

N2191, Void at SI-8807A/B Resulting in a Multiple TS 3.0.3 Entry, December 1, 2004

N2194, Void at CCP-SIP Suction Cross Tie, Draft Report dated January 26, 2005

Calculations:

STA-089, Determine the Allowable Gas Accumulation Volume in the Cross Tie Piping of the CCPs and SIPs, February 10, 1999

STA-108, ECCS Pump Suction Void Evaluation, October 22, 1999

J-113, Sizing of FE-998, CVCS Centrifugal Charging Pump Recirc Line Flow Element, November 20, 1996

Work Orders:

Work Order C0190153, Install Temp UT Level Indicator on Line 4296 U1"

Work Order C0189343, Install UT LI on Line 4296, Unit 2"

Procedures:

STP M-89A, Void Volume Measurement in SIP/CCP Suction Crosstie Piping, Revision 8A

OP B-3A, Safety Injection System - Shutdown and Clearing, Revision 9A

PEP M8801-3, MOV Flow Test - Charging Injection Valves, Revision 1

STP V-18D, ECCS Check Valve Flow Test, Revision 2A

STP V-2H, Miscellaneous Auxiliary Building Valves, Revision 16

STP-V-3L3, Exercising Valves SI-8807A and SI-8807B, Safety Injection Charging Pump Suction Crosstie, Revision 13

STP V-15, ECCS Flow Balance Test, Revision 25A

STP V-3L13, Exercising Valve SI-8976, RWST to Safety Injection Pump, Revision 11

STP P-CCP-A, Performance Test of Centrifugal Charging Pumps, Revision 14

Drawings:

447111, Dri, Seal Wtr Rethdr frm Cnt, Change 10

449304, Seal Water Return Header from Containment Penetration, Change 4

Design Change Notice DCN 1-SM-049316, CCP recirculation line - RO-43, RO-44, FE/FI-998"
Revision 3

Other References:

Fault Tree Analysis Chart for NCR N2194, Void at CCP-SIP Suction Cross Tie Revision 2, Draft

Events and Causal Factors Chart for NCR N2194, Void at CCP-SIP Suction Cross Tie
Revision 0, Draft

Technical Specification 3.5.2, ECCS-Operating and associated Technical Specification Bases

Memorandum from T. Baldwin Engineering Evaluation of SOER 97-01, dated July 10, 1998

Memorandum from Nuclear Operations Support IE Notice 88-23: Potential for Gas Binding of
High- Pressure Safety Injection Pumps During a Loss of Coolant Accident dated May 17, 1991

Licensee Event Report 1999-003-00, Entry into Technical Specification 3.0.3 Due to Voiding in
the Emergency Core Cooling Systems Cause by Inadequate Administrative Controls

Licensee Event Report 1998-011-01, Emergency Cooling System Outside Design Basis Due to
Gas Voiding in the Suction Piping

Section 4OA5.2.1.9 Manual Actions for Responding to a Steam Generator Tube Rupture

50.59 Review for SGTR Dose Increase Due to Analysis Error

OP1.DC11, Conduct of Operations-Abnormal Plant Conditions

DATA from Steam Generator Tube Rupture Scenario run on January 11, 2005

EOP E-3; Steam Generator Tube Rupture Appendix L, Revision 25

PGE-01-535, Oct 26,2001,Steam Generator Tube Rupture (SGTR) Re-analysis Report

Section 4OA5.2.1.10, Control and Protection for Components that Supply Offsite Power to Engineered Safety Features Buses

Calculations:

114-DC, Protection Relay Settings for Bus and Feeders, Revision 8
154-DC, UAT and SST Differential Relay Current Balancing Transformers, Revision 0
154C-DC, 230/12kV Standby Startup Transformer 21 Settings for Differential Relays, Revision 1
154D-DC, 12kV System Protection, Revision 1
154G-DC, Overcurrent and Differential Protection Relay Setpoints, Revision 0
259-DC, Verify the Adequacy of Overcurrent Relay Settings for Unit Aux. Transformer, Revision 1
357A-DC, Units 1 & 2 Load Flow, Short Circuit, and Motor Starting, Revision 9

Drawings:

437531, Electrical Single Line Meter & Relay Diagram 12kV System, Revision 27
437530, Electrical Single Line Meter & Relay Diagram 12kV Start-Up System, Revision 35
437659, Electrical Schematic Diagram Stand-By Start-Up Transformer No. 21 and Associated Circuit Breakers, Revision 23

Work Orders:

C0165061, C0165054, R0213322 01, R0213322 01, R0181714 01, R0200638 01, R0181808

PMT 62.10, Standby Startup Transformer 21 Inrush and Differential Load Test, Revision 0

PMT 62.06, Standby Startup Transformer 11 Inrush Test, Revision 0

Action Requests:

A0497080

Other References:

87UT21, Pims Data Sheet for Startup Trans 21 Diff Relay, dated February 25, 2002

51HG13, Pims Data Sheet for 4kV Bus G Aux Trans 12 Bkr OC Relay, dated September 15, 2002

51HG13, Pims Data Sheet for 4kV Bus G Aux Trans 22 Bkr OC Relay, dated September 15, 2002

51HG14, Pims Data Sheet for St-Up Tranf 12 Sect G OC Relay, dated September 15, 2002

51HG14, Pims Data Sheet for St-Up Tranf 22 Sect G OC Relay, dated September 15, 2002

GE Instruction Manual SEL-387E, Current Differential and Voltage Protection Relay, dated March 12, 2004

GE Instruction Manual GEH-1778L, Time Overcurrent Relays, dated November, 1991

STP I-1A, Attachment 12.1, Mode 1 Checklist

OP AP-27, Loss of Vital 4kV and/or 480V Bus Revision 1

DCP E-050322, Replace Startup Transformer 21 and its 230kV Disconnect Switch, Revision 1

Section 4OA5.2.1.11 Margin Review for ESF Bus Load, Load Shed, Load Sequencing, and Breaker Coordination/Fault Protection

Calculations:

357A-DC, Units 1 & 2 Load Flow, Short Circuit, and Motor Starting, Revision 9

170-DC, Overcurrent Relay Settings for Class 1E, 4kV Motors, Revision 15

Drawing 437614, Electrical Schematic Diagram Bus Potential & Synchronizing 4160V System, Revision 33

Drawings:

437591, Electrical Schematic Diagram Residual Heat Removal Pumps, Revision 23

437627, Electrical Schematic Diagram 4160V Bus Section H Automatic Transfer, Revision 32

Procedures:

STP M-13B1, ENGD SFGDS Auto Timers Setting Verif Loads Started SSPS Relay K608 Train A, performed May 16, 2002

STP M-13B2, ENGD SFGDS Auto Timers Setting Verif Loads Started SSPS Relay K608 Train B, performed May 16, 2002

STP M-13B3, ENGD SFGDS Auto Timers Setting Verif Loads Started SSPS Relay K609 Train A, performed May 18, 2002

STP M-13B4, ENGD SFGDS Auto Timers Setting Verif Loads Started SSPS Relay K609 Train B, performed May 16, 2002

STP M-13B1, ENGD SFGDS Auto Timers Setting Verif Loads Started SSPS Relay K608 Train A, performed May 14, 2004

STP M-13B2, ENGD SFGDS Auto Timers Setting Verif Loads Started SSPS Relay K608 Train B, performed May 14, 2004

STP M-13B3, ENGD SFGDS Auto Timers Setting Verif Loads Started SSPS Relay K609 Train A, performed May 13, 2004

STP M-13B4, ENGD SFGDS Auto Timers Setting Verif Loads Started SSPS Relay K609 Train B, performed May 13, 2004

Other References:

Data sheet for Agastat Series ETR Time Delay Relay, undated
Action Request A0630036

Section 4OA5.2.1.12, Battery 12 Sizing and Manual Actions to Ensure Design Load Life

Calculations:

235B-DC, Battery 12 Sizing, Load Flow, Voltage Drop, Short Circuit and Charging and Charger Sizing Calculation

359-DC, Vital 125VDC Calculation for PRA Analysis (Station Blackout), Revision 0

360-DC, System Analysis Methodology & Scenario Development, Revision 2

Drawings:

445075, Single Line Meter and Relay Diagram 125 Volt DC System, Revision 16

437546, Single Line Meter and Relay Diagram 125 Volt DC System, Revision 38

445076, Single Line Meter and Relay Diagram 125 Volt DC System, Revision 15

Section 4OA5.2.1.13, Electrical and Control Design for AFW Level Control Valves

Design Criteria Memoranda:

DCM No. S-3B, Auxiliary Feedwater System, Revision 14A.

DCM No. T-12, Pipe Break (HELB/MELB), Flooding, and Missiles, Figure 4-23B, Area GE/GW Temperature vs Time Response, MSLB at EI 115', 0.1 sq ft Break without BIT, Revision 14A.

Calculations:

EZ-002, Environmental Qualification Requirements, Revision 1.

Drawings:

444302, Electrical Diagram of Connections 125 Volt Battery No. 13 and D.C. Distribution Panel No. 13, Revision 27

445076, Single Line Meter and Relay Diagram 125 Volt DC System, Revision 15

437546, Single Line Meter and Relay Diagram 125 Volt DC System, Revision 38

444300, Electrical Diagram of Connections 125 Volt Battery No. 11 and D.C. Distribution Panel No. 11, Revision 35

437584, Electrical Schematic Diagram Auxiliary Feedwater Pump Turbine Control, Revision 19

455060, Electrical Schematic Diagram Auxiliary Feedwater Pump Turbine Control, Revision 12

437507, Electrical Schematic Diagram Auxiliary Feedwater Motor Operated Valves, Revision 23

102003 Sheet 4, Unit 1 Piping Schematic, Auxiliary Feedwater System, Revision 70

437507, Unit 1 Schematic Diagram, Auxiliary Feedwater Motor Operated Valves, Revision 23.

437583, Unit 1 Schematic Diagram, Auxiliary Feedwater Pumps, Revision 24

437584, Unit 1 Schematic Diagram, Auxiliary Feedwater Pump Turbine Control, Revision 19.

441237, Unit 2 Single Line Meter and Relay Diagram, 480 Volt System, Bus Section 2F, Revision 30.

441237, Unit 2 Single Line Meter and Relay Diagram, 480 Volt System, Bus Section 2H, Revision 37.

441301, Unit 2 Schematic Diagram, Auxiliary Feedwater Motor Operated Valves, Revision 18.

500971, Mechanical Equipment Location Plan at Elevation 85' - 0", 91' - 0", & 100' - 0", Containment and Fuel Handling Buildings, Revision 27.

57726, Mechanical Equipment Location Plan at Elevation 115' - 0" Auxiliary, Containment and Fuel Handling Buildings, Revision 24.

1-HG-020, Pipe Support, Elev 100', Iso H26-201, Revision 1.

1-HG-034, Pipe Support, Elev 100', Iso H26-201, Revision 0.

1-HG-035, Pipe Support, Elev 100', Iso H26-201, Revision 1.

1-HG-036, Pipe Support, Elev 100', Iso H26-201, Revision 1.

1-HG-037, Pipe Support, Elev 100', Iso H26-201, Revision 0.

1-HG-038, Pipe Support, Elev 100', Iso H26-201, Revision 0.

1-HG-039, Pipe Support, Elev 100', Iso H26-201, Revision 1.

1-HG-040, Pipe Support, Elev 100', Iso H26-201, Revision 1.

1-HG-041, Pipe Support, Elev 100', Iso H26-201, Revision 0.

1-HG-042, Pipe Support, Elev 100', Iso H26-201, Revision 0.

1-HG-043, Pipe Support, Elev 100', Iso H26-201, Revision 1.

1-HG-044, Pipe Support, Elev 100', Iso H26-201, Revision 1.

Maintenance, Surveillance, and Test Procedures:

MP-E-53.7A, Repair/Overhaul of Model NH92 ITT Controls Hydramotors Valve Actuators, Revision 14.

MP I-3-L113, Steam Generator 1-4 Auxiliary Feedwater Supply Level Control Channel LCV-113 Calibration, Revision 8.

MP-I-3-P433, Unit 1 Auxiliary Feedwater Pump 1-2 Discharge Pressure Channel PT-433 Calibration, Revision 0.

Operating Procedures:

Operating Order O-2 (Operation of Hagan Controllers), Revision 9.

EOP E-2; Loss of Main or Secondary Coolant

OP D-1:V Auxiliary Feedwater System- Alternate Auxiliary Feedwater Supplies

NCRs/Action Requests:

N0002070, A0467095, A0476270, A0525618, A0525619, A0556995, A0557582, A0557678, A0581305, A0581407, A0587150, A0606847, A0610168, A0610170, A0621459, A0624963, A0626242, A0626906, A0626940, A0627034, A0629995, A0630014

Work Orders:

R0248556 01, R0014119 01, R0007752 01

Other documents:

Operator Continuing Training Lesson Plan, Lsn R991C1, AFW System Review

UFSAR Chapter 15.4, Limiting Faults

EQ File No. IH-07, Limitorque Valve Actuators, Revision 7.

EQ File No. IH-14, ITT Barton NH90 Series Electro-hydraulic Actuators, Revision 11.

ITT General Controls Engineering Report No. 721.82.145, Shelf and Storage Life Limits of Age-Sensitive Non-Metallic Materials Used in NH90 Actuators, Revision 2, July 18, 1985.

Vendor Manual DC 663165-77-7, ITT Barton NH90 Series Electro-hydraulic Actuators, Revision 7.

Section 4OA5.2.1.14 - Design and Testing of Auto-Transfer Features for Offsite Power System

Diablo Canyon Technical Specifications, Section 3.8

Calculations:

170-DC, Overcurrent Relay Settings for Class 1E, 4kV Motors, Revision 15

160-DC, Overcurrent Relays for Non-1E 12kV and 4kV Motors, Revision 4

174A-DC, 4.16kV First Level Undervoltage Relays for Diesel Start and Load Shed, Revision 2

357P-DC, 4160V Second Level Undervoltage Protection Relay and Timer Setpoint Calculation, Revision 0

Drawings:

19423, Logic Diagram 12kV Bus Section D & E Automatic Transfer, Revision 3

19424, Logic Diagram 12kV Bus Section D & E Automatic Transfer, Revision 3

437625, Electrical Schematic Diagram 4160V Bus Section F Automatic Transfer, Revision 25

437626, Electrical Schematic Diagram 4160V Bus Section G Automatic Transfer, Revision 31

437627, Electrical Schematic Diagram 4160V Bus Section H Automatic Transfer, Revision 32

458863, Logic Diagram 4160V Bus Section F Automatic Transfer, Revision 14

458864, Logic Diagram 4160V Bus Section G Automatic Transfer, Revision 14

458865, Logic Diagram 4160V Bus Section H Automatic Transfer, Revision 12

Work Orders:

R0214235, R0214185

Section 4OA5.2.1.15, Alternate Water Supplies to the Auxiliary Feedwater System

Procedures:

OP C-7; Condensate System Revision 3
OP C7:I Condensate System-Make Available and Startup

Calculations:

M831, Evaluate the CST Bases Requirements, Revision 0

M232, Auxiliary Feedwater System - Suction Line From Firewater and Transfer Tank to Auxiliary Feedwater Pumps, Revision 1

M210, Available NPSH to AFW Pump 1-1 from Condensate Storage Tank, Revision 0
UFSAR Section 6.5.3

Drawings:

663071, Firewater and Transfer Tank Shell and Nozzle Details, Revision D
438038, Requirements for Water Storage Tanks, Revision 7

Design Criteria Memoranda:

S-3B, Auxiliary Feedwater, Revision 14A
T-17, Long Term Cooling Water, Revision 2B
S-16, Makeup Water System, Revision xx
T-42, Station Blackout, Revision 16
T-20 High Energy Line Breaks, Revision 5

Other References:

Non-Conformance Report N0002070
Action Requests A0539052 and A0593052

Section 4OA5.1.16, Pressurizer PORV Modification and Manual Actions to Respond to Inadvertent SI Actuation

Calculations:

STA-119, RETRAN Spurious Safety Injection Analysis for DCP, Revision 0
STA-147, SGTR Analysis Input Assumptions, Revision 0

Nonconformance Reports:

N1973, Untimely and Incomplete Response to a Westinghouse NSAL
N2041, Unit 2 Reactor Trip and SI due to Inadvertent MSIV Closure, Revision 0
N2048, Inadvertent ECCS Actuation Analysis Deficiency

Procedures:

STP M106, Test of Backup Nitrogen Accumulator System to Pressurizer Power Operated Relief Valve PCV-456, Revision 16

STP M105, Test of Backup Nitrogen Accumulator System to Pressurizer Power Operated Relief Valve PCV-455C, Revision 15

OP C-2:II; Main Steam and Steam Dump Systems - Local Operation of Steam Dumps

Calculations:

J-002, Review of Backup Air/Nitrogen Accumulators, Revision 6
M-9, Backup Air Supply System, Revision 4

Other References:

Licensee Event Report 1-90-017-01, Reactor Trip Resulting from Failed Open Pressurizer Spray Valve due to Incorrect Screw Installation

Safety Evaluation Related to Amendment Numbers 171 and 172

Technical Specification 3.4.11 and associated Bases.

NRC Inspection Report 50-275/323;96-24 and 97-03

Westinghouse Nuclear Safety Advisory Letter 93-013, Inadvertent ECCS Actuation at Power

Memorandum from NECS Nuclear Systems, Cycle and Duration Requirements for Sizing of the Air Receivers on the Pressurizer Power Operated Relief Valves dated November 16, 1992

Drawing Number 053096, Pressurizer PORV-High Pressure N2 Receiver, Revision 14

UFSAR Section 15.2.15

Action Requests:

A0512317	A0630781	A0535731	A0535006
A0301721	A0630777	A0571031	A0501171
A0313919	A0601949	A0609391	A0405030
A0410818	A0609612	A0604598	A0312419
A0304782	A0621236	A0620630	A0454051
A0422414	A0510777	A0621236	A0449600
A0319647	A0512323	A0621238	A0468665
A0318814	A0519741	A0626342	A0630719
A0532960	A0534171	A0628181	
A0482841	A0534934	A0528837	

Section 4OA5.2.1.17, Component Cooling Water Modification to Prevent Water Hammer in Containment Air Coolers

Procedures:

OP AP-11; Backup Cooling to a Centrifugal Charging Pump Revision 21
STP V-652A, Penetration 52A Containment Isolation Valve Leak Testing

Modification Packages:

DCP M-049284, Revision 0, Addition of Nitrogen Pressurization to CCW Surge Tank

DCP P-049371, Revision 0, Unit 1-Replace Existing Balls in FCV-253 and FCV-500 with Modified Balls during 1R9

DCP P-050371, Revision 0, Unit 2-Replace Existing Balls in FCV-253 and FCV-500 with Modified Balls during 2R8

Drawings:

6006473, SHT 236, Air Operated Ball Valve
663219, SHT 267, Grinnel Diaphragm Valve
106707, SHT 4
102007, SHTS 1, 3, 4, 7, 7A, Reactor Coolant System
106714, SHT 2, Component Cooling Water System

Calculations:

J-125, Determine Lift Pressure for Valve ½-8030

M-998, Revision 0, Determine Required CCW Surge Tank Pressurization to Prevent Flashing in the CFCUs

M-1017, Revisions 0-3, CCW Flow Balancing

Other References:

PG&E Letter DCL-96-218, 30 Day Response to NRC Generic Letter 96-06

PG&E Letter DCL-97-012, 120 Day Response to NRC Generic Letter 96-06

PG&E Letter DCL-97-046, Update to Response to Generic Letter 96-06 for Long-Term Actions

PG&E Letter DCL-97-130, Update to Response to Generic Letter 96-06 for Long-Term Actions

PG&E Letter DCL-98-078, Response to Request for Additional Information Regarding Generic Letter 96-06

PMT 19.04, Unit 2, FCV-253 and FCV-500 Overpressurization Leak Test

PMT 19.05, Unit 1, FCV-253 and FCV-500 Overpressurization Leak Test

RCS-1-8029, Primary Water to Containment Isolation

RCS-1-664, Primary Water to Containment (Test Connection)RCS-1-528, Containment Primary Water Header Drain

DIA-FLO Diaphragm Valves Selection Guide, ITT Engineered Valves

Design Specification No. 8179, Revision 2N, Design Specification for Nuclear Service Valves – Manual, Electric Motor and Pneumatic Operated

Section 4OA5.2.1.18, Setpoint Methodology for Selected Safety-Significant Setpoints

Design Criteria Memoranda:

S-3B, Auxiliary Feedwater System, Revision 14A.

T-18, Electrical System Protection, Section 4.6.4, 480 V System [480 V motor protection], Revision 10A.

Calculations:

J-142, RWST Nominal Setpoint and Indication Uncertainty Calculations, Revision 16.

NSP-1-16-014A, Nominal Setpoint Calculation for Condensate Storage Tank Low-Low Level Comparator LS-464, Revision 2.

PAM-0-09-940, Post-Accident Containment Recirculation Sump Level Uncertainty, Revision 4.

PAM-0-16-40, LR-148, LI-148, LI-155 Indication for Condensate Storage Tank Level, Revision 4.

PAM-0-16-44, Post-Accident and EOP Decision Point Accuracy for Condensate Storage Tank Level Indication Loop 16-14C (LR-100), Revision 3.

PAM-0-19-942, Post-Accident Monitoring - Containment Sump Wide Range Level, Revision 3.

SC-I-09-L920, Maintenance Services Scaling Calculation, Refueling Water Storage Tank 1-1, Level Channel LT-920, Revision 6.

SC-I-09-L940, Maintenance Services Scaling Calculation, Containment Recirculation Sump Narrow Range Level Channel LT-940, Revision 2.

SC-I-16-L40, Maintenance Services Scaling Calculation, Condensate Storage Tank 1-1 Level Channels LT-40, LT-44, & LI-195, Revision 5.

SC-I-89, Maintenance Services Scaling Calculation, Containment Wide Range Level Channels LT-942A and LT-943A, Revision 4.

195H-DC, Adequacy Analysis for Thermal Overload of DC MOV, Revision 2, June 1, 1999.

195C-DC, Appendix 1, Thermal Overload Sizing for 460 V Class 1E Motors for MOVs, Revision 4.

366A-DC, Appendix 4, Guides for MOV Motor Protection and TOL Selection, Revision 0.

Drawings:

102009 Sheet 4, flow diagram showing refueling water storage tank, Revision 69.

102009 Sheet 5, flow diagram showing containment sump, Revision 65.

102016 Sheet 7, flow diagram showing Unit 1 condensate storage tank, Revision 101.

102033 Sheet 17A, Instrument Loop Diagram, Refueling Water Storage Tank Level, Revision 98.

102033 Sheet 23A, Instrument Loop Diagram, Condensate Storage Tank 1-1, Revision 106.

049093 Sheet 23A, Installation Detail, Containment Recirculation Sump Level Element, Revision 51.

049093 Sheet 42, Installation Detail, Containment Wide Range Water Level, Revision 68.

Electro-Mechanics, Inc. Drawing 9694-42800-C, Pressure Transducer - MI Cable Connection, Oil Filled Reference Leg Top Assembly, Revision C.

455060, Schematic Diagram, Auxiliary Feedwater Pump Turbine Control, Revision 12.

Action Requests:

A0173104, A0250872, A0486796, A0501615, A0504352, A0630773, A0630928, A0539565

Equipment Control Guidelines:

ECG 64.1, Electrical Equipment Protective Devices - Motor Operated Valves Thermal Overload Protection and Bypass Devices, Revision 2.

AD13.DC1, Control of the Surveillance Testing Program, Attachment 7.8, Motor Operated Valves Thermal Overload Protection and Bypass Devices, Revision 19.

Other documents:

Modification Package DCP No. E-050490, [Replace starter, overload relay, and overload auxiliary relay, Revision 0.

Work Order R0150582 01; component 49-1230, Record No. 0000113542

Test Procedure GL 89-10 motor test data for 1-FCV-95, test dates June 3, 2004 and June 6, 2004

Field and Design Basis Setpoint Data Sheets for LCV-106/49-1G-4; LCV-107/49-1G-68; LCV-108/49-1G-69; LCV-109/49-1G-70; FCV-95/49-1230; FCV-38/49-1F-30.

AR PK06-20,PPC Select Alarm Revision 6

STP R-20, Boric Acid Inventory

Section 4OA5.2.1.19, Capabilities for Restoring Offsite Power Following Prolonged Loss of Offsite Power

Drawings:

57484, Single Line Diagram 230kV and 500kV Switchyards, Revision 16

435838, Single Line Meter and Relay Diagram 500kV Switchyard, Revision 8

440003, Single Line Diagram of AC Station 500 kV Switchyard Diablo Canyon, Revision 10

443566, Single Line Meter and Relay Diagram A.C.STA.Power 250 & 500 kV Switchyards, Revision 1

435876, Single Line Meter & Relay Diagram 230kV Switchyard, Revision 17

Other References:

Supplemental Safety Evaluation of PG & E Response to Station Blackout Rule (10 CFR 50.63) for Diablo Canyon (TAC Nos. M68537 and M69538), dated May 25, 1992

AD8.DC51, Outage Safety Management Control of Off-Site Power Supplies to Vital Buses, Revision 9

OP J-6B:IX, Diesel Generator Extended Online Maintenance, Revision 0

Section 4OA5.2.1.20 - Modification to Replaced Startup Transformers and Install New Load Tap Changers.

Data Sheets:

2K29ST11, PIMS Data Sheet for LTC Motor Timing Relay for Startup Transformer 1-1 (THU11) Reinhausen Device K29 / ABB Device 121Z, dated November 3, 2004

2K29ST21, PIMS Data Sheet for LTC Motor Timing Relay for Startup Transformer 2-1 (THU21) Reinhausen Device K29 / ABB Device 121Z, dated November 15, 2004

2K30ST11, PIMS Data Sheet for LTC Motor Timing Relay for Startup Transformer 1-1 (THU21) Reinhausen Device K30 / ABB Device 121Y, dated November 3, 2004

2K30ST21, PIMS Data Sheet for LTC Motor Timing Relay for Startup Transformer 2-1 (THU21) Reinhausen Device K30 / ABB Device 121Y, dated November 3, 2004

90ST11A1, PIMS Data Sheet for Start-up Transformer 1-1 LTC Voltage Regulating Relay (ABB Device 90-1), dated December 2, 2004

90ST21A1, PIMS Data Sheet for Start-up Transformer 2-1 LTC Voltage Regulating Relay (ABB Device 90-1), dated March 5, 2003

90ST11A2, PIMS Data Sheet for Start-up Transformer 1-1 LTC Voltage Regulating Relay (ABB Device 90-2), dated March 5, 2003

90ST21A2, PIMS Data Sheet for Start-up Transformer 2-1 LTC Voltage Regulating Relay (ABB Device 90-2), dated March 5, 2003

90ST11B1, PIMS Data Sheet for Start-up Transformer 1-1 LTC Backup Control Relay (ABB Device 86V-1), dated March 5, 2003

90ST21B1, PIMS Data Sheet for Start-up Transformer 2-1 LTC Backup Control Relay (ABB Device 86V-1), dated March 5, 2003

90ST11B2, PIMS Data Sheet for Start-up Transformer 1-1 LTC Backup Control Relay (ABB Device 86V-2), dated March 5, 2003

90ST21B2, Start-up Transformer 2-1 LTC Backup Control Relay (ABB Device 86V-2), dated March 5, 2003

Other References:

Modification Package DCP E-049322, Replace Startup Transformer 11 with New Transformer Equipped with Load Tap Changer, Revision 0

MP E-50.30C, Time Delay Relay Maintenance, Revision 0A

MP E-62.3, Tap Changer Functional Test for Standby-Startup Transformers 11 and 21, Revision 1

Work Orders:

R0221639, R0147280, R0148891 01, R0148891 02
Calculation 357I-DC, 230/12kV Startup Transformer LTC Control Devices, Revision 2
Action Request A0625650

Section 4OA5.2.1.21, Ability of AFW to Withstand a Steam Line Break

Action Requests:

A0629860, A0630009

Non-Conformance Reports:

N0002070

Other References:

DCP J-49461, Qualification of FCV-38, Revision 0

LBIE 98-158, Qualification of FCV-38, Revision 0

UFSAR Section 6.5

NRC Safety Evaluation Reports SSER 24, SSER 31

PG&E letter DCL-84-363, Equipment Qualification, dated November 29, 1984

PG&E letter DCL-85-101, Equipment Qualification, dated March 8, 1985

PG&E letter DCL-85-138, Equipment Qualification - Main Steam Line Break, dated April 3, 1985

Westinghouse letter PGE-4966, Steam Line Break Mass and Energy Release Data in GE/GW Area, dated February 23, 1983

Westinghouse letter PGE-4773, Steam Line Break Mass and Energy Release Data, dated December 7, 1982

NUREG-0800 Standard Review Plan, Revision 2: Section 10.4.9, "Auxiliary Feedwater System," and Section 15.1.5, "Steam System Piping Failures Inside Containment and Outside Containment (PWR)"

NRC Information Notice 89-58, "Disablement of Turbine-Driven Auxiliary Feedwater Pump Due to Closure of One of the Parallel Steam Supply Valves"

Section 4OA5.2.1.22, Analysis and Design Features to Withstand Tsunami Effects

Drawings:

59455, Civil Plan - Circulating Water System, Revision 8

438093, Civil Plan of Intake and Discharge Conduit Circulating Water System, Revision 16

438098, Civil Profile of Discharge Conduits Circulating Water System, Revision 15

438118, Flood Plan - Discharge Structure Circulating Water System, Revision 11

438119, Civil Roof Plan, Discharge Structure Circulating Water System, Revision 13

438120, Longitudinal Section and Details of Discharge Structure Circulating Water System, Revision 14

438121, Sections and Details - Discharge Structure Circulating Water System, Revision 9

438122, Sections and Details - Discharge Structure Circulating Water System, Revision 14

438123, Sections and Details - Discharge Structure Circulating Water System, Revision 6

438124, Sections and Details - Discharge Structure Circulating Water System, Revision 5

438125, Sections and Details - Discharge Structure Circulating Water System, Revision 4

Other References:

Design Criteria Memorandum T-9, Wind, Tornado, and Tsunami, Revision 14

Casualty Procedure CP M-5, Tsunami Warning, Revision 11C

UFSAR Sections 2.4.6 and 2.4.11

Engineering Evaluation, "Tsunami Effects at the Discharge Structure," dated February 2, 2005
Action Request A0630734

4OA5.3.1 Review of Industry Operating Experience

Design Criteria Memoranda:

S-3B, Auxiliary Feedwater System, Revision 14A.

Drawings:

102003 Sheet 4, Unit 1 Piping Schematic, Auxiliary Feedwater System, Revision 70.

Other documents:

USNRC IE Bulletin 88-04, Potential Safety Related Pump Loss, May, 1988

PG&E letter DCL 88-180, Response to NRC Bulletin 88-04, Potential Safety-Related Pump Loss, dated July 8, 1988

PG&E letter DCL 88-230, Supplemental Response to NRC Bulletin 88-04, Potential Safety-Related Pump Loss, dated September 30, 1988

PG&E letter DCL 89-127, Supplemental Response to NRC Bulletin 88-04, Potential Safety-Related Pump Loss, dated May 9, 1989

Flowserve letter, Minimum Flow Analysis - Motor Driven Auxiliary Feedwater Pumps, dated February 25, 2005

Flowserve letter, Minimum Flow Analysis - Turbine Driven Auxiliary Feedwater Pumps, dated February 25, 2005

Westinghouse letter, "Diablo Canyon Units 1 & 2, NRC Bulletin 88-04 - Pump Minimum Flow Requirements - Westinghouse Response to NRC Audit Questions for the Auxiliary Feedwater Pumps," dated February 11, 2005

Westinghouse Safety Evaluation SECL-89-509, Adequacy of Safety Related Auxiliary Pumps Minimum Flow Requirements, Revision 1, dated October 7, 1989.

Research Paper by S. Gopalakrishnan, A New Method for Computing Minimum Flow, 5th International Pump User's Symposium, Houston, Texas, May, 1988.

Research Paper by C. C. Palgrave, Backflow Control Improves Pump Performance, Oil and Gas Journal, February 25, 1985.

Westinghouse Letter number LTR-SEE-05-04, Diablo Canyon Units 1 and 2,-NRC Bulletin 88-04- Pump Minimum Flow Requirements-Westinghouse Response to NRC Audit Questions for the Auxiliary Feedwater Pumps, dated February 11, 2005.

Westinghouse Letter number PGE-01-524, Diablo Canyon Units 1 and 2, Motor Driven Auxiliary Feedwater Pump Mechanical Minimum Flow, June 5, 2001.

NPG-8.2, Dissemination of Operating Experience, Revision 6 (October 28, 1987)

OM4.ID3, Assessment of Industry Operating Experience, Revision 7 (April 2, 2004)

PG&E UFSAR, Revision 15.

PG&E Technical Specifications, Unit 1-Amendment No. 135, Unit 2-Amendment 135.

Safety Review Event Follower 88-04, Inadequate Qualification and Documentation of Fire Barrier Penetration Seals, dated November 18, 1988

NCR DCO-88-TN-N107, Simultaneous RHR Pump Operation on Mini Flow Recirculation, dated December 11, 1992

Safety Review Event Follower 87-59, Potential RHR Pump Loss, dated December 4, 1987

PG&E Letter Emergency Core Cooling System Outside Design Basis Due to Gas Voiding in the Suction Piping, dated July 23, 1999

PG&E Memorandum, IEN 90-64 and OE 4529: Potential for Common Mode Failure of High Pressure Safety Injection Pumps or Release of Reactor Coolant Outside Containment During a Loss of Coolant Accident, dated June 4, 1991

PG&E Letter, Response to Generic Letter 90-06, dated December 21, 1990

Safety Review Event Follower 89-215, Electrical Bus Bar Failures, dated September 26, 1989

NRC Information Notice, Electrical Bus Bar Failures, September 7, 1989

PG&E Letter Response to NRC Bulletin 88-04, Potential Safety-Related Pump Loss, dated July 8, 1988

Action Request A0631659