UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

 OCCURRED DATE: 06-JAN-2011 TIME: 0915 HOURS OPERATOR: Exxon Mobil Corporation REPRESENTATIVE: Carol Pullen TELEPHONE: (281) 654-2928 CONTRACTOR: REPRESENTATIVE: 	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER
TELEPHONE: 3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR	SHUTDOWN FROM GAS RELEASE X OTHER Faulty Deck Drain Sump 6. OPERATION:
ON SITE AT TIME OF INCIDENT: 4. LEASE: G01083 AREA: WD LATITUDE: BLOCK: 73 LONGITUDE: 5. PLATFORM: A RIG NAME:	X PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER
<pre>6. ACTIVITY: EXPLORATION (POE) DEVELOPMENT/PRODUCTION (DOCD/POD) 7. TYPE: HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) PW/JT (>3 days)</pre>	8. CAUSE: X EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
RW/JT (>3 days) Other Injury FATALITY POLLUTION FIRE EXPLOSION LWC HISTORIC BLOWOUT UNDERGROUND SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES COLLISION HISTORIC >\$25K	9. WATER DEPTH: 168 FT. 10. DISTANCE FROM SHORE: 22 MI. 11. WIND DIRECTION: SPEED: M.P.H. 12. CURRENT DIRECTION: SPEED: M.P.H. 13. SEA STATE: FT.

EV2010R

17. INVESTIGATION FINDINGS:

On January 6, 2011, at approximately 0915 hours, a mystery sheen 3 miles long x 5 miles wide was observed moving northwest through the West Delta (WD) 95 area. At approximately 1045 hours, the Bureau of Ocean Energy and Management, Regulation, and Enforcement (BOEMRE) was notified of the sighting and directed inspectors who were already flying offshore to investigate the sheen. The inspectors conducted a fly-over of the WD 95 Block and did not locate the sheen in the reported location; however, as they continued their fly-over, the sheen was observed and followed for approximately three miles to the source located in WD 73. BOEMRE Inspectors landed on ExxonMobil's OCS-G01083, WD 73, Platform A to investigate and discovered that a pump on the deck drain sump failed releasing approximately 11.6 gallons of oil into Gulf waters.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The pollution was due to a failed pump on the deck drain sump, with the sump not functioning properly.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

N/A

N/A

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The BOEMRE New Orleans District makes no recommendations to the Agency.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

E-100 - Operator not preventing unauthorized discharge of pollutants into offshore waters.

\$

MMS - FORM 2010

EV2010R

25. DATE OF ONSITE INVESTIGATION:

06-JAN-2011

26. ONSITE TEAM MEMBERS:

Robert Neal / Justin Josey /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

David Trocquet

APPROVED DATE: 04-JAN-2012

MMS - FORM 2010

PAGE: 3 OF 5 29-FEB-2012

POLLUTION ATTACHMENT

1.	VOLUME: 11.6 GAL BBL
	7040 YARDS LONG X 50 YARDS WIDE
	APPEARANCE: SILVERY SHEEN
2.	TYPE OF HYDROCARBON RELEASED: 🕱 OIL
	DIESEL
	CONDENSATE
	HYDRAULIC
	NATURAL GAS
	OTHER
3.	SOURCE OF HYDROCARBON RELEASED: Deck drain sump
4.	WERE SAMPLES TAKEN? NO
5.	WAS CLEANUP EQUIPMENT ACTIVATED? NO
	IF SO, TYPE: SKIMMER CONTAINMENT BOOM ABSORPTION EQUIPMENT DISPERSANTS OTHER
6.	ESTIMATED RECOVERY: 0 GAL BBL
	RESPONSE TIME: HOURS
8.	IS THE POLLUTION IN THE PROXIMITY OF AN ENVIRONMENTALLY SENSITIVE AREA (CLASS I)? NO
9.	HAS REGION OIL SPILL TASK FORCE BEEN NOTIFIED? NO
10.	CONTACTED SHORE: NO IF YES, WHERE:
11.	WERE ANY LIVE ANIMALS OBSERVED NEAR: NO
12.	WERE ANY OILED OR DEAD ANIMALS OBSERVED NEAR SPILL: NO

MMS - FORM 2010 EV2010R