

U.S. CONSUMER PRODUCT SAFETY COMMISSION WASHINGTON, D.C. 20207

EXPLICITED BY FATITION
RELIFICACION ADDISH PRODO

RULE: 44 KING ADIKIN, PRODG

... YAMA FORTIONS ADMOVED: __

May 14, 1997

Mr. Robert Stack Standards Engineer International Approval Services, Inc. 8501 East Pleasant Valley Road Cleveland, Ohio 44131

Re: Review of Selected Investigation Reports Involving Vent Disconnection from Gas-Fired Central Furnaces

Dear Mr. Stack:

In a letter dated October 29, 1996, the engineering staff of the Consumer Product Safety Commission (CPSC) recommended that Section 2.19 of the American National Standard for Gas-Fired Central Furnaces, ANSI Z21.47, be expanded to require appliance shutoff in the event that a vent pipe becomes disconnected. Staff believes that without coverage for disconnected vents, the vent safety shutoff system (VSSS) provisions in Section 2.19 are inadequate. These recommendations were discussed at the November 1996 meeting of the Central Furnace Subcommittee. At the meeting it was suggested that CPSC staff review a sample of relevant CPSC investigations for specific technical information requested by the subcommittee and share that information with the Technical Working Group (TWG) at the upcoming May 1997 meeting. CPSC staff agreed to perform the review, and work is underway.

Due to the seriousness of the hazard, staff is providing results of the investigations reviewed to date. CPSC engineering staff has completed a detailed review of 60 out of 143 selected CPSC investigation reports involving central furnaces which occurred from 1989 through 1996. The data is summarized on the enclosed four pages by investigation case number. The results indicate that the investigation reports contain much of the information requested by the subcommittee, although some detailed information was either not available or not recorded.

While the remaining 83 investigation reports will be reviewed, staff is very concerned that one-third (19) of the 60 cases reviewed involved disconnected vents, which resulted in 28 deaths and 33 injuries. The enclosed tables represent the individual cases reviewed to date. They are a subset of a convenience sample (i.e., not statistically selected) and may not be representative of all such incidents that occur. Also enclosed are purged copies of the 19 investigations reviewed

Mr. Robert Stack
Page 2

involving disconnected vents.

The incident information reviewed thus far strongly suggests the need to extend VSSS coverage to address disconnected vents and positive pressure vents. Given the seriousness of these incidents, staff views ANSI Z21.47 to be deficient without VSSS coverage that addresses disconnected vent coverage on natural draft furnaces, as well as positive vent pressure units. CPSC staff strongly urges the TWG to develop the performance requirements necessary to remove this avoidable risk of CO poisoning and to have a draft proposal available to be presented at the September 1997 Central Furnace Subcommittee meeting. The engineering staff will provide a final review of the investigation reports to the Central Furnace Subcommittee by the end of July 1997.

This recommendation represents the position of the Commission staff. It has not been reviewed or accepted by the Commissioners. If you have any questions please call me at (301) 504-0508 extension 1295.

Sincerely,

Ronald A. Jordan

Project Manager, Fire/Gas Codes &

Standards

Directorate for Engineering Sciences

Enclosures

19 pursed copies of mounte separate provided much separate

Page 1 of 4

REVIEW OF SELECTED FURNACE INVESTIGATIONS INVOLVING DISCONNECTED VENT PIPES (1989-1996) Vent Failure Mode/Condition & Result

	A entire a tues	vent Failure Mode/Condition & Result					
Case Number	Incident Date	Incident Date Vent Failure Mode/Condition	CO exposure? (yes/no)	CO concentration (in ppm)	Number of Deaths	Number of Injuries	Total Number of Victims
950310CCC2471	12/16/94	Disconnected vent	Ves	60	>	•	•
960326CCC6106	02/07/96	Disconnected vent	yes	Co Co	ے د		0
960501CMC9017	04/11/86	Disconnected went	300	MINIOWIT	~	c	N
940208CCC2268+	10/18/02	Disconnected work	20	unknown	0	0	0
040303000000	76.00	Ensconnected vent	yes	268, 238, 180		0	•
04041HCC2210	01/04/94	Disconnected vent	yes.	0 to 14	Un.	י אני	5 ·
910208HCN0653	21/22/24	vent or strepox miseligned at draft diverter	yes	2000, 300	-	0	- (
911004HCC2003	09/22/91	disconnected (not anathon)	yes	unknown	ω	_	.
911112HCN0464	11/08/01	Disconnected a proceed	yes	unknown		C	-
940107CEP9003 +	12/26/97	Disconnected	yes	200-300+	10	0	10
	01/23/03	Disconnected well	yes	unknown	0	_	-
•	COUCUE	Disconnected well	yes	unknown	_	0	-4
r	11/24/02	Disconnected werk	yes	unknown	0	_	-
9201100003172	11/01/01	Disconnected well	yes	unknown	0	6	G,
920414HCN15057	03/00/20	Discount Veril	3	unknown	0	0	Þ
92020AHCN0945	11/20/01	Disconnected werk	yes	unknown	0	7	7
921209HCNO460	_	INSCORPECTED WEIL	yes	unknown	0	2	No :
910222HCN0703	•	Discontinuo vent	yes	unknown	Ĺ	2	yn I
		wasangned nuernissing cover plate	yes	unknown		C	→ (
	6007770	Disconnected year	yes	3000	0	c s	œ.
				TOTALS	28	33	61

Note 1: investigations were selected for review based on queries of Narrative field using keywords "Vent, Disconnect, and Separation" and "CO poisoning, Disconnect, and Separation" Product Code used was "310"; Date Range was 01/01/87 through 12/31/96

Source: CPSC investigations involving gas furnaces with disconnected vent pipes. Note 2: These investigations are a subset of a convenience sample (i.e. not statistically selected) of gas furnace-related incidents and may not be representative of all such incidents that occur. These investigations were chosen to litustrate the hazards associated with disconnected vent pipes and cannot be used to determine the relative frequencies of hazard patterns.

Page 2 of 4

REVIEW OF SELECTED FURNACE INVESTIGATIONS INVOLVING DISCONNECTED VENT PIPES (1989-1996)

Location of

Description of Vent Failure Mode/Condition

Investigation Case Number

Description

911004HCC2003 910208HCN0653 940831HCC2216 940203CCC3249 940208CCC2288 360501CMC9017 60326CCC8106 50310CCC2471 corroded vent & recirculation of exhaust into intake 3/4 in. gap b/w flue outlet/vent and HTPV vent pipe separated at elbow and cracked unit operated w/o vent attached vent pipe terminated at 1st floor ceiling disconnected flue pipe vent pipe fell apart unknown flue outlet collar 90 degree elbow Vent Disconnect

930324CCC2284 940107CEP9003 911112HCN0464 flue disconnected due to corrosion Vent T separated 2.5 in.

920204HCN0945 920110CCC3172 920414HCN1506 921215HCN0481 930225HWE5022 vent left unconnected during maintenance vent separated at an elbow joint vent disconnected at flue outlet at top of furnace duct tape connecting vent removed exhaust vent was not connected during installation vent corroded and became separated 2 to 3 in. from chimney vent loosened & dislodged at coupling at chimney, leaving 4 in. gap

921209HCN0460 disconnected vent connector vent misaligned at flue outlet/combust, chamber plate not on unit screws missing at points of separation

unknown at flue outlet unknown 90 degree elbow

entry point into chimney entry point into chimney furnace outlet flue outlet collar

elbow W unknown flue outlet unknown

b/w vertical section and elbow flue outlet & vertical vent pipe flue outlet

Note 1: Investigations were selected for review based on queries of Narrative field using keywords "Vent, Disconnect, and Separation" and "CO poisoning, Disconnect, and Separation" Product Code used was "310"; Date Range was 01/01/87 through 12/31/96 that occur. These investigations were chosen to illustrate the hazards associated with disconnected vent pipes and cannot be used to determine the relative frequencies of hazard patterns vote 2. These investigations are a subset of a convenience sample (i.e. not statistically selected) of gas furnace-related incidents and may not be representative of all such incidents

Source: CPSC investigations involving gas furnaces with disconnected vent pipes

Page 3 of 4

REVIEW OF SELECTED FURNACE INVESTIGATIONS INVOLVING DISCONNECTED VENT PIPES (1989-1996)

Description of Vent

case Number	Vent Type	Vent Material	Connection Type	Fáting Type	Vent Configuration	Diameter (inches)	Length (feet)
950310CCC2471 960326CCC8106	single vent into chimney	galvanized steel	mechanical fasteners	90 degree elbow	unknown	unknown	unknown
960501CMC9017	Sizola verk	DINCHONT	UNKNOWN	unknown	unknown	unknown	nwown
940208CCC2268	circle vert	plastic (MTPV)	adnesive/solvent	vent tee, 90 degree elbow	horizontal	unknown	unknown
940203CCC3249	LINE VEIN	passuc	LINKNOWN	90 degree elbow	horizontal & vertical	2	unknown
940831HCC2216	unkoowo	TO POST OF THE PERSON AND THE PERSON	WHOCH	unknown	unkaowa	unknown	unknown
910208HCN0653	none attached	Cincomi	CHARLE	unknown	unknown	unknown	unknown
911004HCC2003	smale vani		LINDOW!	unknown	unknown	unknown	писоми
911112HCN0464	Single vent		mechanical factors of out tape	90 degree elbow	horizontal & vertical	w	uwanhau
940107CEP9003	unknown	inknown	inchesia idaerera, auresive, meta pipe interiace	tee titing	horizontal & vertical	u	unknown
930324CCC2284	single vent into chimney	nahvanizad steel		Unknown	unknown	unknown	nwoavin
930225HWE5022	unknown	unknown	inkoon	2- 90 degree elbows	horizontal	unknown	8 to 10 ft
921215HCN0481	unknown	unknown	diet lace in liquid recours	coupling(?)	unknown	unknown	nwonstru
920110CCC3172	unknown	metal	social and a science	unknown	unknown	unknown	unknown
920414HCN1506	single	plastic	artherise and a second	unknown	unknown	unknown	nwondru
920204HCN0945	unknown	unknown	Inknown	elbow	horizontal	2	unknown
921209HCN0460	common vent	metal	SCIPMS	UNKNOWN	unknown	unknown	unknown
910222HCN0703	single	metal	not specified	flue connector	vertical	unknown	unknown
890228HCC1249	single vent into chimney	metal	screws	elbow	vertical & horizontal	unknown	unknown

Product Code used was "310"; Date Range was 01/01/87 through 12/31/96 ation" and "CO poisoning, Disconnect, and Separation"

Note 2. These investigations are a subset of a convenience sample (i.e. not statistically selected) of gas furnace-related incidents and may not be representative of all such incidents that occur. These investigations were chosen to illustrate the hazards associated with disconnected vent pipes and cannot be used to determine the relative frequencies of hazard patterns Source: CPSC investigations involving gas furnaces with disconnected vent pipes.

Page 4 of 4

REVIEW OF SELECTED FURNACE INVESTIGATIONS INVOLVING DISCONNECTED VENT PIPES (1989-1996) Description of Furnace

1 4 6 6 7 6 6 6 6 6 6						
Age of Furnace	Year Installed	Fuel Type	BTU Input Rating	Furnace Category	Furnace Configuration	VSSS? (yeshia)
13	unknown	natural gas	unknown	inknown	in known	
unknown	I DE COMO	oranana Grandana			, citatowa	TIMORIA
دن	1903	properso	50,000	CHANGE	UNKNOWN	mynown
unknown	unknown		50,000	-	horizontal	yes
unknown	1086-1088	LF-gas	80,000 000,000	unknown	unknown	usiknown
unkaouro.	1000	Spf. remen	0,000	unknown	vertical	70
unknown	CHACHAIN III	COMPLET	Unknown	unknown	unknown	unknown
0 200	10901	nwon	unknown	unknown	unknown	unknown
» c	7061	CHANNIN	UNKNOWN	unknown	ยกได้กับพา	นกหาดพก
o months	CINCIDAIN	HWOHIL	unknown	unknown	Vertical, Upflow	unknown;
47	1070	UNKNOWN	185,000	7	unknown	G
.	0/81	LP-gas	100,000	unknown	unknown	unknown
3 5	UMONATE	natural gas	unknown	unknown	unknown	inknown
67	unknown	natural gas	unknown	unknown	highbov	
Q 15	unknown	natural gas	140 000	inknown	inknow)	ē
Ç,	1987	naturat nas	50 000	in kind in the second	GIANG WILL	CHANGE
15	@1976	Tall Wall Day	437 500	LIMORIUM.	unknown	unknown
⊕ ¢	1057	riatural gas	137,300	UWOUND	uaknown	nwonknown
90	(B) 1937	Haturat gas	unknown	unknown	vertical	3
•	9/4	LF-gas	no specified	unknown	not specified	60
operation of	no specified	natural gas	4 5,000	no specified	no specified	ō
	Age of Furnace 13 unknown 3 unknown unknown unknown unknown 17 10+ 29 8 2 months 17 10+ 29 915 5 6 915 935 917 no specified		Year installed unknown unknown 1993 unknown 1986-1986 unknown 1982 unknown 1982 unknown 1993 1976 unknown unknown 1987 @1976 @1974 no specified	Year Installed Fuel Type unknown natural gas unknown propane 1993 unknown 1986-1988 natural gas unknown unknown 1982 unknown 1982 unknown 1982 unknown 1993 unknown 1996 natural gas unknown natural gas unknown natural gas unknown natural gas unknown natural gas 1987 natural gas 1987 natural gas 1974 LP-gas no specified natural gas	Year Installed Fuel Type BTU Input Rating unknown propane unknown 1993 unknown 50,000 unknown LP-gas 82,000 unknown unknown unknown unknown unknown unknown unknown 1982 unknown unknown 1982 unknown 1993 unknown unknown unknown unknown 1993 unknown 1996 LP-gas 100,000 1976 LP-gas unknown natural gas unknown unknown natural gas unknown 1987 natural gas 110,000 1987 natural gas 137,500 01974 LP-gas no specified natural gas unknown 1974 LP-gas no specified	Year Installed Fuel Type BTU Input Rating Furnace Category Furnace Configuration unknown propane unknown unknown propane unknown unknown unknown 1993 unknown 50,000 unknown natural gas unknown unkno

310 : Date Range was 01/01/87 through 12/31/96 onnect, and Separation*

Note 2. These investigations are a subset of a convenience sample (i.e. not statistically selected) of gas furnace-related incidents and may not be representative of all such incidents that occur. These investigations were chosen to illustrate the hazards associated with disconnected vent pipes and cannot be used to determine the relative frequencies of hazard patterns.

Source: CPSC investigations involving gas furnaces with disconnected vent pipes.