

# AIRMUNITIONS LETTER

~~SECRET~~

HEADQUARTERS  
OGDEN AIR MATERIEL AREA  
UNITED STATES AIR FORCE  
Hill Air Force Base, Utah

17 April 1961

OCAMA AIRMUNITIONS LETTER  
NC. 136-11-56F

~~EXCLUDED FROM GENERAL  
DISTRIBUTION~~

SUBJECT: Advance Explosive Ordnance Disposal Technical Information

TO: SEE DISTRIBUTION

AUTHORITY: This AML is published under the authority of and in compliance with AFR 136-10.

(U) SUMMARY OF NUCLEAR WEAPONS INCIDENTS (AF FORM 1058) AND  
RELATED PROBLEMS - DECEMBER 1960

WARNING NOTICE

~~Information contained in this AML is intended for the exclusive use of personnel assigned to the activity mentioned in the subject line and is not to be disseminated outside the activity mentioned in the subject line. The transmission of the revelation of its contents to an unauthorized person is prohibited by law. This information is not releasable to foreign nationals.~~

~~SECRET~~

~~EXCLUDED FROM GENERAL DISTRIBUTION~~

#128

112 OF 400

~~6~~

~~FOR UNCLASSIFIED FILES COPY~~

~~15-21~~

~~SECRET~~

AIRMUNITIONS LTR 136-11-56F  
Page 2 of 6

1. The purpose of this AML is to present a summary of incidents wherein nuclear weapons were involved and to provide a resume of the methods and procedures used by the EOD personnel involved.
2. This summary includes the incidents listed below:

NWI-60-5

1. Location:

On Base (Kelly Air Force Base, Texas)

2. Date:

December 1960

3. Type of Incident:

Nuclear weapon dropped while being hoisted aboard C-124 aircraft.

4. Brief:

A Mk 39 YI Mod 2 weapon was being hoisted aboard a C-124 aircraft when one of the hoisting cables broke. The weapon, secured to its transportation dolly, dropped to the ramp and overturned. Damage to the weapon consisted of a scratch on the curved portion of the nose, and a damaged fin. Inspection of the Arm/Safe Switch, dessicant compartments, parachute, thermal battery and safing switch, timers and pull out rods, revealed that none of the devices had functioned. The weapon custodian was present during the operation and assumed all further responsibility. No RSP or disposal operations by EOD personnel were required. (Figures 1, 2, and 3.)

5. Unusual Problems:

None

6. Contamination:

None

NWI-60-6

1. Location:

On Base (Kingsley Field, Klamath Falls, Oregon)

~~SECRET~~

~~SECRET~~



~~SECRET~~

DDA  
②

~~SECRET~~

~~SECRET~~





FIGURE 2.

~~SECRET~~

~~SECRET~~

~~SECRET~~

~~RESTRICTED DATA - ATOMIC ENERGY ACT 1954~~



~~SECRET~~

~~RESTRICTED DATA - ATOMIC ENERGY ACT 1954~~

~~SECRET~~

AIRMUNITIONS LTR 136-11-56F  
Page 6 of 6

2. Date:

December 1960

3. Type of Incident:

Abnormal result of service electrical check of a W-25 Warhead.

4. Brief:

a. When a service electrical check of a W-25 Warhead in an MB-1 Rocket was being made with the T-304B Tester, DS-1 lamp did not light, although DS-2 lighted. All excess personnel were evacuated from the area and the one hour waiting period was observed. After one hour, the test was again made and both lamps gave acceptable readings.

b. Paragraph 5-3.4, of T.O. 11N-W25-1 states the DS-1 lamp monitors the high voltage power supply and that, if either tester lamp does not light, wait one hour and do not disturb the warhead or make any electrical disconnections until the waiting period has elapsed.

5. Unusual Problems:

None

6. Contamination:

None

FOR THE COMMANDER

*Lt Col R. F. Douglas*

JOE M. WHITFIELD  
Colonel, USAF  
Commander  
2705th Airmunitions Wing

DISTRIBUTION

1 cy per organization authorized  
Explosive Ordnance Disposal  
Personnel possessing AFSC's  
3254B, 461X0 (EOD Qualified)  
46171 or 46131

~~SECRET~~

