

AIRMUNITIONS LETTER

~~SECRET~~

~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~

HEADQUARTERS
OGDEN AIR MATERIEL AREA
UNITED STATES AIR FORCE
Hill Air Force Base, Utah

19 April 1961

OOAMA AIRMUNITIONS LETTER
NO. 136-11-56H

SUBJECT: Advance Explosive Ordnance Disposal Technical Information

TO: SEE DISTRIBUTION

AUTHORITY: This AML is published under the authority of and in compliance with AFR 136-10.

(U) SUMMARY OF NUCLEAR WEAPONS INCIDENTS (AF FORM 1058) AND RELATED PROBLEMS - MARCH 1961

~~WARNING~~

~~Information contained in this document is classified "Secret" and is to be controlled by the same security procedures as apply to information of this nature.~~

This document contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, USC Sections 793 and 794, the transmission or the revelation of its contents in any manner to an unauthorized person is prohibited by law. This information is not releasable to foreign nationals.

~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~

~~SECRET~~

~~EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION SCHEDULES~~

~~EXCLUDED FROM GENERAL DECLASSIFICATION SCHEDULES~~

~~THIS DOCUMENT IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE BY A CONTROLLING OFFICIAL~~

~~FOR CLASSIFIED FILES COPY~~

1130

112

[Redacted]

~~SECRET~~

~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~

AIRMUNITIONS LTR 136-11-56H
Page 2 of 18

1. The purpose of this Airmunitions Letter is to present a periodic summary of incidents wherein nuclear weapons were involved, and to provide a resume of the EOD operations conducted at the site(s).
2. This summary includes an incident reported during March 1961 and which will hereafter be referred to as NWI-61-3.

NWI-61-3

1. Location:

Near Yuba City, California

2. Date:

March 1961

3. Type of Incident:

Crash of B-52 aircraft

4. Brief:

a. A B-52 aircraft carrying two [REDACTED] bombs crashed near Yuba City, California. Upon impact, both bombs were torn from the plane and severely damaged.

b. An AMC EOD team was dispatched to the site and arrived there approximately four hours after initial notification. The following preliminary observations and findings were made:

(1) Appropriate security of the impact area had been effected by Beale Air Force Base and the County Sheriff's Office personnel.

(2) Radiation monitoring had been conducted with negative results.

(3) The aircraft disintegrated upon impact and wreckage was strewn over a large area (Figures 1 and 2).

~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~

~~SECRET~~

~~SECRET~~

~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~

AIRMUNITIONS LTR 136-11-56H
Page 3 of 18

(4) The Beale Air Force Base EOD Element had searched the area, picked up all scattered HE, and recovered or located all significant weapon components, except one. One tritium bottle, which was located later was monitored with negative results and packaged with the other bottle.

c. To facilitate description, the bombs will be referred to as Bomb A and Bomb B.

(1) Bomb A was not as severely damaged as Bomb B. Figure 2 shows the parachute assembly in the foreground and Figure 3 shows the main case section and primary space chamber after removal from the case. The Primacord had detonated but the reef line cutters were intact.

(2) Bomb B received more damage and had broken into several pieces. Figures 4 and 5 show the secondary. [REDACTED]

[REDACTED] Figure 8 depicts the main case section, Figures 9 and 10 the front and rear polar cap assemblies, and Figure 11 the parachute assembly. The HE had broken into small pieces and the pit was intact. [REDACTED]

[REDACTED] As in Bomb A, the Primacord had detonated but the reef line cutters were intact.

d. Rendering Safe Procedures - Bomb A.

(1) Since the tritium bottle had been torn loose upon impact, Beale Air Force Base EOD personnel had crimped the gas tube protruding from the polar cap. Monitoring with the T-290, AMC EOD personnel removed the polar cap. Powdered HE could be observed inside. Interior monitoring with a PDR-27 gave a fluctuation of .1 mr/hr. The entire HE sphere was distorted and apparently shattered inside the plastic space chamber. Ten gallons of engine oil were poured over the HE and satisfactorily acted as a desensitizer and also as a coagulant to facilitate removal of the HE sludge.

(2) The polar cap retaining bolts were removed and the cap assembly detached (Figure 12), revealing the broken and powdered HE. The rear portion of the space chamber had broken away, permitting easy access to the HE. [REDACTED]

~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~

~~SECRET~~

~~SECRET~~
RESTRICTED DATA NUCLEAR ENERGY ACT 1954

~~SECRET~~
~~RESTRICTED DATA~~
~~Atomic Energy Act 1954~~

~~SECRET~~
RESTRICTED DATA NUCLEAR ENERGY ACT 1954




Figure 1. Aircraft wreckage - looking North from point of impact.

~~SECRET~~

~~RESTRICTED - INFORMATION NOT TO BE~~

~~SECRET~~

~~Reference Data
Atomic Energy Act 1954~~

~~SECRET~~





Figure 2. Aircraft wreckage - looking South. Bomb A Parachute assembly in foreground.

~~SECRET~~



~~SECRET~~
DATA ATOMIC ENERGY ACT


DNA (6) (3)

Figure 3. Bomb A



~~SECRET~~

~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~



~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~

~~SECRET~~

~~SECRET~~
DATA (S)

~~SECRET~~

~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~





Figure 5. Bomb B

~~RESTRICTED DATA ATOMIC ENERGY ACT 1954~~

~~SECRET~~

DNA 131

~~SECRET~~



~~RECORDED - SECURITY - ENERGY~~

~~SECRET~~

DATA
(b)(3)

~~SECRET~~

~~RESTRICTED DATA - SECURITY INFORMATION - 1954~~



Figure 7. Bomb B

~~RESTRICTED DATA - SECURITY INFORMATION - 1954~~

~~SECRET~~

DIVA
52(3)

~~SECRET~~

~~UNCLASSIFIED DATA ATOMIC ENERGY~~



SECRET
23 Aug 1954

~~SECRET~~

MK
b(2)

~~SECRET~~




~~SECRET~~

DINA
(5)(3)

~~SECRET~~

~~UNCLASSIFIED DATA ATOMIC ENERGY~~




~~UNCLASSIFIED DATA ATOMIC ENERGY~~

~~SECRET~~

~~SECRET~~

DNA
(3)

~~SECRET~~




Bomb A

Figure 13.

~~SECRET~~

DATA
(b)(3)

~~SECRET~~
~~Restricted Data~~
~~Atomic Energy Act 1954~~



~~SECRET~~
RESTRICTED DATA
ATOMIC ENERGY ACT 1954

~~SECRET~~
RESTRICTED DATA

~~SECRET~~




Figure 12. Bomb A

~~SECRET~~

3/11/57 (5) (3)

~~SECRET~~

~~Security Data
Control Act 1954~~

ALBUQUERQUE LTR 136-11-26H
Page 17 of 18

~~SECRET~~



Figure 14. View from aft end of Room 4

~~SECRET~~

11/17/54
(5)

~~SECRET~~

AIRMUNITIONS LTR 136-11-56H
Page 18 of 18

e. Rendering Safe Procedures - Bomb B.

(1) The HE sphere had completely shattered, and Beale AF Base EOD personnel had recovered the HE [REDACTED]. The pit was found intact. AMC EOD personnel completed the RSP, which consisted of locating the remaining detonators, locating and identifying remaining weapon components and cleaning up nuclear residue. The RSP was simplified and quickly accomplished due to the broken condition of the bomb.

f. Recovered HE and detonators were burned, and the nuclear components were turned in to the Munitions Maintenance Squadron at Beale Air Force Base.

g. [REDACTED] spare detonators not found during the AMC EOD operation are being recovered by the Beale AF Base EOD Element.

h. Excellent support and cooperation were given all phases of the EOD mission.

5. Unusual problems:

Rain and muddy terrain hampered the operation.

6. Contamination:

None.

FOR THE COMMANDER

Lt Col A. F. Douglas
for JOE M. WHITFIELD
Colonel, USAF
Commander
2705th Airmunitions Wing

DISTRIBUTION
1 cy per organization authorized
Explosive Ordnance Disposal
Personnel possessing AFSC's
3254B, 461X0 (EOD Qualified)
46171 or 46131



~~SECRET~~