



Log 2071 SP-20

National Transportation Safety Board

Washington, D. C. 20594

Safety Recommendation

Date: August 10, 1989

In reply refer to : A-89-81 and -82

Honorable James B. Busey
Administrator
Federal Aviation Administration
Washington, D.C. 20591

On June 5, 1988, a Dornier 228-201, N259MC, operated by Fisher Brothers Aviation, Inc., as a Midway Commuter under the provisions of 14 CFR Part 135, experienced a loss of directional control and braking during a single-engine taxi for takeoff. The captain reported that as the airplane began to roll forward, he noticed that he did not have nose wheel steering. He applied the brakes but they did not respond. He then moved the hydraulic pump switch from the "NORM" position to the "MAN ON" position, which allows the hydraulic pump to operate from battery power instead of generator power. As the captain reached for the parking brake handle to stop the airplane, N259MC collided with another Dornier, N264MC, parked adjacent to it at Midway Airport, Chicago, Illinois. Both airplanes were damaged; there were no injuries.¹

Investigation of the accident revealed that the generator on the running, No. 2 engine was disconnected from the generator bus. The nose wheel steering and wheel braking system on the Dornier airplane is electro-hydraulically actuated. During ground operation, should the generators, or in the case of single-engine operation, the generator, become disconnected from the generator bus, a loss of nose wheel steering and normal braking will occur. The airline's training program, operation manual, and the Dornier 228-series Pilot Operating Handbook did not address single-engine ground operation and the effects of an interruption in generator power. At numerous airports within the continental United States, it has become an accepted and routine practice for many operators of multiengine commercial airplanes to conduct single-engine ground operations. The Safety Board is concerned that there are airplanes, as this accident illustrates, which have characteristics in their systems warranting enhanced pilot awareness when single-engine ground operations are contemplated. It is not difficult to imagine the potential catastrophic consequences had the accident airplane's steering and brake system failed as it was approaching a runway in use.


Therefore, the National Transportation Safety Board recommends that the Federal Aviation Administration:

¹For more information, read Field Accident Brief No 1723 (attached).

Require the Dornier 228-series Pilot Operating Handbook to address single-engine ground operation procedures. These procedures should place special emphasis on the need to perform nose wheel steering and brake integrity checks before taxi and include a discussion on the feasibility of placing the hydraulic switch in the MAN ON position. (Class II, Priority Action) (A-89-81)

Review the pilot operating handbooks of other multiengine airplanes used in commuter operations and verify that adequate procedures are included to accomplish safe single-engine ground operations; if adequate procedures are not included, require development and inclusion of appropriate single-engine ground operation procedures. (Class II, Priority Action) (A-89-82)

KOLSTAD, Acting Chairman, BURNETT, LAUBER, NALL, and DICKINSON, Members, concurred in these recommendations.


By: James L. Kolstad
Acting Chairman

Brief of Accident

File No. - 1723 6/05/88 CHICAGO, IL A/C Res. No. N259HC Time (Lcl) - 1140 CDT

-----Basic Information-----

Type Operating Certificate--COMMUTER Aircraft Damage
Name of Carrier -MIDWAY COMMUTER SUBSTANTIAL
Type of Operation -SCHEDULED, DOMESTIC, PASSENGER Fire Crew Serious Minor None
Flight Conducted Under -14 CFR 135 NONE Pass 0 0 0 2
Accident Occurred During -TAXI None 0 0 0 1

-----Aircraft Information-----

Make/Model - DORNIER 228-201 Eng Make/Model - AIRESEARCH IPE-33J-5 ELT Installed/Activated - YES/NO
Landing Gear - TRICYCLE-RETRACTABLE Number Engines - 2 Stall Warning System - YES
Max Gross Wt - 12500 Engine Type - TURBOPROP
No. of Seats - 19 Rated Power - 715 HP

-----Environment/Operations Information-----

Weather Data Itinerary Airport Proximity
Wx Briefing - COMPANY Last Departure Point ON AIRPORT
Method - IN PERSON SAME AS ACC/INC
Completeness - FULL Destination
Basic Weather - VMC SPRINGFIELD, IL
Wind Dir/Speed - 300/010 KTS ATC/Airspace
Visibility - 15.0 SM Type of Flight Plan - IFR
Lowest Sky/Clouds - 20000 FT SCATTERED Type of Clearance - NONE
Lowest Ceiling - NONE Type Apch/Lndg - NONE
Obstructions to Vision - NONE
Precipitation - NONE
Condition of Light - DAYLIGHT

-----Personnel Information-----

Pilot-In-Command Age - 37 Medical Certificate - VALID MEDICAL-WAIVERS/LIMIT
Certificate(s)/Rating(s) Biennial Flight Review Flight Time (Hours)
ATP, CFI Current - YES Total 4300 Last 24 Hrs - 4
SE LAND, ME LAND Months Since - 4 Make/Model - 300 Last 30 Days - 80
Aircraft Type - UNK/NR Instrument - 150 Last 90 Days - 120
Multi-Eng - 2200

Instrument Rating(s) - AIRPLANE

-----Narrative-----

THE CAPT WAS COMPLETING THE CHECKLIST DRG FAX LOADING & THE F/O SECURED THE DOOR & CAME FWD. THE CAPT STARTED THE #2 ENG & RGN SINGLE ENG TAXI WHILE ATMTG A RGT TURN TO STAY CLR OF A PARKED DORNIER (N264MC), AS N259MC RGN ROLLING FWD, THE CAPT NOTED THE NOSEWHEEL STEERING (NWS) WAS INOP. HE APPLIED NORMAL BRAKING, BUT GOT NO RESPONSE & N259MC RGN A LEFT TURN. THE CAPT SWITCHED THE HYDR PUMP FM "NORMAL" TO "MAN ON" (MANUAL); HOWEVER, BFR HYD PRES WAS BUILT UP BY BATTERY PWR, N259MC COLLIDED WITH N264MC. AN INV REVEALED THE #2 GENERATOR (GEN) WAS NOT CONNECTED TO THE GEN BUS. NO PART MALFUNCTION/FAILURE WAS FND DRG CHECKS OF THE ACFT SYSTEMS. THE NWS & NORMAL BRAKES WERE ELECTRO-HYDRAULICALLY ACTUATED. W/O GENERATOR PWR, THE HYD SYS, NWS & NORMAL BRAKES WOULD NOT HAVE BEEN OPERATING WITH THE HYD SW IN THE "NORMAL" PSN. AN EMERG (PARKING) BRAKE WAS AVAILABLE, BUT IT WAS NOT USED. THE TRAINING PROGRAM, OFN MANUAL & DORNIER 228-SERIES PILOT OPERATING HANDBOOK DID NOT ADDRESS SINGLE-ENG GROUND OPN OR THE EFFECTS OF AN INTERRUPTION IN GENERATOR PWR.

Brief of Accident (Continued)

File No. - 1723 6/05/88 CHICAGO, IL A/C Reg. No. N259MC Time (Lc1) - 1140 CDT

Occurrence #1 LOSS OF CONTROL - ON GROUND
Phase of Operation TAXI - TO TAKEOFF

- Findings(s)
- 1. CREW/GROUP COORDINATION - INADEQUATE - PILOT IN COMMAND
 - 2. ELECTRICAL SYSTEM, GENERATOR - NOT ENGAGED
 - 3. HYDRAULIC SYSTEM - NOT ENGAGED
 - 4. LANDING GEAR, STEERING SYSTEM - NOT OPERATING
 - 5. LANDING GEAR, NORMAL BRAKE SYSTEM - NOT OPERATING
 - 6. BRAKES (EMERGENCY) - NOT USED - PILOT IN COMMAND
 - 7. AIRCRAFT MANUALS, SYSTEM INFORMATION - INADEQUATE
 - 8. AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND
 - 9. PROCEDURE INADEQUATE - MANUFACTURER

Occurrence #2 ON GROUND COLLISION WITH OBJECT
Phase of Operation TAXI - TO TAKEOFF

Findings(s)
10. OBJECT - AIRCRAFT PARKED

-----Probable Cause-----

The National Transportation Safety Board determines that the Probable Cause(s) of this accident is/are finding(s) 3,6,8
Factor(s) relating to this accident is/are finding(s) 1,2,7,9,10