



**RTI Group, LLC**  
910 Bestgate Road, Suite E  
Annapolis, MD 21401  
ofc: +1 410 571 0712 | fax: +1 410 571 0713  
www.rtiForensics.com

**DOT Requested Analysis**  
**of**  
**Failed SCUBA Cylinder/Valve Assembly**

---

**Report Date**  
**August 29, 2012**

**DOT Contract**  
**No. DTPH56-12-P-000004**

**RTI Matter**  
**No. 50151.ME002**

---

***Prepared and Submitted By:***

Richard B. Loucks, PhD, PE  
Senior Mechanical Engineer

Matthew Wagenhofer, PhD  
Mechanical Engineer

***Reviewed By:***

Thomas W. Butler, PhD  
Senior Materials Engineer

Joseph R. Reynolds, PE, MEWI, MAE  
Principal Forensic Engineer



# Table of Contents

	<u>Page No.</u>
<b>1.0 INTRODUCTION/BACKGROUND . . . . .</b>	<b>4</b>
<b>2.0 PURPOSE . . . . .</b>	<b>5</b>
<b>3.0 INVESTIGATION . . . . .</b>	<b>6</b>
3.1 Standards, Codes, and Open Literature . . . . .	6
3.2 Evidence Description . . . . .	8
3.3 Evidence Inspection Observations . . . . .	9
<b>4.0 LABORATORY TESTING. . . . .</b>	<b>16</b>
4.1 Unpacking Evidence . . . . .	16
4.2 Disassembly and Visual Inspection . . . . .	17
4.3 SEM Examination . . . . .	31
4.4 Mechanical Testing and Metallography . . . . .	35
4.5 Chemical Analysis . . . . .	41
<b>5.0 DISCUSSION . . . . .</b>	<b>44</b>
5.1 Origin of the Explosion . . . . .	44
5.2 Ignition Mechanism . . . . .	50
5.3 Cylinder Compliance with the Federal Regulations . . . . .	51
<b>6.0 CONCLUSIONS . . . . .</b>	<b>55</b>

## Table of Contents continued

### ATTACHMENTS

1. Test Protocol
2. Evidence Receipt Photos
3. Exemplar Valve Photos
4. Exemplar Regulator Photos
5. Testing Sign-in Sheet
6. Photographs from Anamet Testing
7. EDS Spectra and Tables
8. FTIR Spectra and Tables
9. Micrographs HF and Kellers Etch
10. Microhardness Testing
11. Tensile and Compression Testing
12. SEM Images
13. Inspection Photos of June 8, 2012
14. Surface Curvature Measurements
15. Cylinder Valve Markings
16. Chain of Custody

## 1.0 INTRODUCTION/BACKGROUND

It was reported to RTI Group, LLC (RTI) that an Open Circuit Self-Contained-Underwater-Breathing-Apparatus (SCUBA) cylinder, valve assembly, and regulator were involved in an explosion. It was reported that the source of the explosion was the high pressure gas cylinder failing. The incident cylinder had been filled with high purity oxygen, and the explosion had resulted in a fatality and extensive property damage, both from blast effects and a fire. Since the SCUBA cylinder had been certified under regulations promulgated by the U.S. Government, the evidence recovered by the St. Petersburg Police was transferred to the United States Department of Transportation (DOT), Pipeline and Hazardous Materials Safety Administration (PHMSA), Office of Hazardous Materials Safety. Reference is made to the Code of Federal Regulations (CFR), Title 49, Parts 173 and 178.

## 2.0 PURPOSE

RTI was tasked through Government Contract DTPH56-12-P-000004, dated November 9, 2011, issued by Office of Acquisition Services US DOT/PHMSA/PHA-30, to perform an investigation of the evidence recovered from the subject incident to determine if non-compliance with Hazardous Materials Regulations played a part in the cylinder failure and if modification of the regulatory standards would be necessary.

Additionally, the purpose of this contract is to evaluate the ruptured DOT 3AL-3000 cylinder valve and determine the following:

1. the degree of exposure to thermal energy; and
2. evidence of oxygen contamination which may have resulted in the explosion (fire) inside the ruptured DOT 3AL cylinder.

Under the tasking directive of the contract, sub-section 3.02 “Advanced Analysis and Examination”, as part of the investigation the evidence was to be subjected to a series of invasive, therefore destructive, examinations in which specific laboratory equipment would be employed, such as Fourier Transform Infrared Spectroscopy (FTIR), Scanning Electron Microscopy (SEM), Energy Dispersive Spectroscopy (EDS), metallography, alloy chemistry, hardness testing, and tension and compression testing.

Once completed, the evidence from physical examination and the results of the laboratory tests were subjected to an engineering evaluation to, if possible, determine the degree of exposure to thermal energy, and determine if there was evidence of contaminants or materials incompatible with oxygen that may have resulted in the incident.

### **3.0 INVESTIGATION**

RTI performed the following: evidence inspection upon receipt on November 15, 2011; laboratory inspection of the evidence March 12-14, 2012, documented in field notes and with photographs; inspection of exemplar cylinder valves and regulator; review of the literature sources listed below; and engineering analysis.

#### **3.1 Standards, Codes, and Open Literature**

##### **3.1.1 Standards and Codes:**

- a) ASTM E 8M Test Method for Tension Testing of Metallic Materials.
- b) ASTM E9 Standard Test Method of Compression Testing of Metallic Materials at Room Temperature.
- c) ASTM G 88 Standard Guide for Designing Systems for Oxygen Service.
- d) ASTM G 93 Standard Practice for Cleaning Methods and Cleanliness Levels for Material and Equipment Used in Oxygen-Enriched Environments.
- e) ASTM G 94 Standard Guide for Evaluating Metals for Oxygen Service.
- f) Code of Federal Regulations, Title 49, Part 173 (Subpart G: Preparation and Packaging) and Part 178 (Subpart C: Specifications for Cylinders).

### 3.1.2 Open Literature

- a) “Guide for Oxygen Compatibility Assessment on Oxygen Components and Systems,” K. Rosales, M. Shoffstall, J. Soltzfus, NASA/TM-2007-213740, March 2007.
- b) “U.S. Navy Diving Manual,” SS521-AG-PRO-010 Revision 6, 0910-LP-106-0957, April 15, 2008.
- c) Handbook of Compressed Gases, Third Edition, Compressed Gas Association, Inc., Chapman & Hall, 1990.
- d) “Introduction to Aluminum Alloys and Tempers”, Kaufman, G.J., ASM International, Materials Park, 2000.
- e) “Copper-Aluminum Interaction in Fire Environments”, B. Beland, C. Roy, and M. Tremblay, Fire Technology, Vol. 19, Number 1, 1983, pages 22-30.

## **3.2 Evidence Description**

On November 15, 2011, RTI Group, LLC (RTI) received four items from the Department of Transportation (DOT), Pipeline and Hazardous Materials Safety Administration (PHMSA). These items are described as follows:

### **3.2.1 Yellow high pressure gas cylinder fragment, Part 1**

Smaller fragment from the incident cylinder; measures approximately 30 cm by 15 cm and weighs 760 gm.

### **3.2.2 Yellow high pressure gas cylinder fragment, Part 2**

Larger section contains the bottom, neck, and valve opening; measures approximately 60 cm by 35 cm and weighs 6,137 gm.

### **3.2.3 High Pressure Cylinder Valve, DIN Valve**

A chrome coated metal cylinder valve with the brand “Genesis” present on the front. A pressure regulator adaptor was present in the cylinder valve outlet opening with a fractured outlet. The rubber hand closure knob was present, but separate from the valve.

### **3.2.4 Pressure Regulator**

A cylindrical metal device having a length of 6 cm and a diameter of 4.5 cm. Attached to the regulator were:

1. Black pressure line with dial gage on high pressure side of regulator.
2. Length of green pressure line. Distal end terminates unattached.

### 3.3 Evidence Inspection Observations

The received evidence was inspected and photographed to document the condition in which it was received. A receipt form was executed to preserve the Chain of Custody.

#### 3.3.1 Yellow high pressure gas cylinder, Part 1

The smaller fragment from the cylinder measured approximately 30 cm by 15 cm, and is seen in **Figure 1**. This fragment contained a portion of the upper part of the cylinder proximate to the threaded opening. The fragment was clearly fractured by a catastrophic overload failure. In the portion near the cylinder opening, the fracture transitioned into a melted/eroded area where the material appeared to have eroded or “flowed” from the interior surface of the cylinder. The erosion was most extensive at the fracture where the cylinder wall was very thin, almost terminating into a sharp edge, with increasing thickness towards the non-eroded area. The flow patterns suggest that the eroded material flowed out of the crack formed in the cylinder wall, as well as out of the valve opening. The remaining cylinder interior surface was otherwise unremarkable. The curvature of the fragment was measured using a spherometer, and resulted in a reading of up to 200 mm near a portion of the interior fracture surface, compared to the original radius of curvature of 57 mm.



Figure 1. Smaller portion of high pressure gas cylinder



Along the base of the hemispherical connection were displayed the following marks near the neck:

HY-MARK

DOT-3AL 3000 OU

This is an incomplete DOT cylinder marking scheme. The remainder of the markings was found on the larger portion of the cylinder.

The cylinder fragment had on its exterior surface a full decal and part of another. The first decal, seen in **Figure 2**, appears like that used by the International Association of Nitrox and Technical Divers (IANTD), as seen in **Figure 3**, which states if the decaled cylinder has been cleaned for use with Nitrox<sup>1</sup> or Oxygen.

The remaining legible content of the label indicated the “Tank & Valve Have Been Cleaned For Premix, Oxygen Content 22 to 40%” was not punched out, while the “Tank & Valve Have Been Cleaned In Accordance With O<sub>2</sub> Service” was punched out at 2011. The month is obscured. There is no indication as to who may have stamped and applied the decal, or as to what procedure was followed to certify the cylinder was properly cleaned.

---

<sup>1</sup> Nitrogen-oxygen (NITROX) diving is a unique type of diving using nitrogen-oxygen breathing gas mixtures ranging from 75 percent nitrogen/25 percent oxygen to 60 percent nitrogen/40 percent oxygen. *U.S. Navy Diving Manual*, Chapter 10.




Figure 2. Label on smaller fragment.



Figure 3. Decal label from International Association Nitrox and Technical Divers<sup>2</sup>

<sup>2</sup> <http://www.iantd.com/decals.html> , D-3207. The web page does state that “These decals are available ONLY to Blenders or Facilities with Certified Blenders on staff.”

Only a small portion of the second decal was visible, and stated “for decompression use .... IANTD/IAND, Inc.”

### 3.3.2 Yellow high pressure gas cylinder, Part 2

The larger fragment of the high pressure gas cylinder, seen in **Figure 4**, contained the bottom, neck, and valve opening portions.



Figure 4. Larger portion of high pressure gas cylinder

A similar erosion pattern to that found on the smaller fragment was seen near the opening at the top. Facing the interior surface with the opening up, the inside surface to the left of the opening had significant erosion extending about 20 cm below the top before transitioning to a fracture. The threads in the opening were clearly stripped with only part of the thread root visible. The pattern of erosion within the opening was uneven in depth and texture, and was different around the opening compared to along the cylinder side towards the fractures. The opening had a stippled texture whereas the areas away from the opening had distinct flow lines with perpendicular waves.

The exterior surface exhibited evidence of heat effects and darkened coloration near the cylinder top. The normally yellow paint is discolored to brown, with black material (soot) found on some of the fracture surface.

This item had the following markings near the hemispherical connection to the cylindrical body:

0001 M5422 10 07 S40 TC-3AL 207

These, together with the stamped markings found on the other fragment, create the complete DOT marking scheme as follows:

DOT-3AL 3000 OU0001 M5422 10 07 S40 TC-3AL 207 HY-MARK

These complete markings indicate as follows<sup>3</sup>:

**DOT-3AL** – This is a Department of Transportation regulated seamless cylinder made from definitely prescribed aluminum alloy requiring a minimum service pressure of 150 psig, and a maximum water capacity of 1000 lb.<sup>4</sup>

**3000** – is the maximum service pressure in psi.

**OU0001** – is the manufacturer’s serial number.

**M5422** – is the DOT PHMSA “M” or manufacturer’s identification number. This number indicates the manufacturer was Hy-Mark Cylinders, Inc. of 305 E. Street, Hampton, VA 23661, approved June 5, 2000.

**10 07** – is the originating hydrostatic test date, October 2007

**S40** – indicates the cylinder is intended for SCUBA use, and can hold compressed gas that has a volume of 40 ft<sup>3</sup> of air at standard pressure and temperature conditions.

**TC-3AL 207** – indicates the cylinder is also compliant with the Transportation Canada, identified as a 3AL container with service pressure to 207 Bar.

**HY-MARK** – is the manufacturer’s symbol, again consistent with Hy-Mark Cylinders. Hy-Mark Cylinders, Inc. was purchased by Worthington Industries, Inc. (NYSE WOR) on June 21, 2010.<sup>5</sup>

This part of the cylinder contained the remaining portion of the second decal stating “OXYGEN for decompression use only – MOD 20 FSW MOD 6 MSW<sup>6</sup> WWW.IANTD.COM”. The label

---

<sup>3</sup> *Handbook of Compressed Gases*, Chapter 4.

<sup>4</sup> 49 CFR 178.46(a).

<sup>5</sup> <http://www.worthingtonindustries.com/>

<sup>6</sup> Maximum Oxygen Depth-MOD, Feet Submerged Water-FSW, Meters Submerged Water-MSD.

indicated that the purpose of this cylinder was for oxygen use during the latter stage decompression from extremely deep diving.

### 3.3.3 High Pressure Cylinder Valve, DIN Valve

A label stamped into the body indicated the incident cylinder valve was manufactured by Genesis and contained a 32.6 MPa (5000 psi, 30 lb/hr) CG-1 type rupture disk. A pressure regulator adaptor was present in the opening containing a fractured outlet. A metal particle filter was evident in the opening. The rubber hand valve closure knob was present, but separated from the valve, as seen in **Figure 5**.




Figure 5. View of cylinder valve, a) front, b) back

### 3.3.4 Pressure Regulator

The incident pressure regulator was manufactured by Dive Rite, serial number 12008135. The high pressure inlet opening was occupied by the fractured end of the pressure regulator adaptor, see **Figure 6**. Attached to the regulator were:

- A black pressure line with dial gage on high pressure side of regulator; dial gage face is heat affected and the gage is illegible.
- A length of green pressure line stating “WARNING Do not exceed 250 psi (17 bar) high pressure may cause damage or personal injury”; no manufacturer was identified.



Figure 6. Cylinder valve, cylinder valve adapter, regulator and regulator assembly.

The green line was discolored (lightened to yellow white) proximate to the regulator, indicating possible exposure to high heat. There were no indications of melting or combustion. The distal portion of the outlet line was bright green and terminated without the anticipated second stage regulator.



## 4.0 LABORATORY TESTING

On March 12, 2012, RTI traveled to the laboratories of Anamet, Inc., an affiliated RTI company, for the purpose of conducting a laboratory examination of the incident scuba cylinder fragments, cylinder valve, and regulator, as well as an exemplar cylinder valve. RTI prepared a protocol, dated November 29, 2011, as found in **Attachment 1**, which served as the guide for all investigative activities conducted over the three day examination. The examination, which included both nondestructive and destructive procedures, was also documented by way of both still photography and videography.

### 4.1 Unpacking Evidence

The container of evidence, shipped from RTI's Annapolis, MD offices, remained sealed until commencement of the examination on March 12, 2012 when all attending parties were present. Items were packaged individually as seen in **Figure 7**.



Figure 7. View of the individually packaged evidence items at Anamet after removal from the shipping container.

## 4.2 Disassembly and Visual Inspection

The incident cylinder valve, an exemplar cylinder valve, and the incident regulator were disassembled and photographed prior to further inspection and examination of the constituent components of each.

### 4.2.1 Exemplar Valve

The exemplar cylinder valve, shown in **Figure 8**, has four distinct sections. Proceeding from the left side of the valve in a clockwise direction they were: the valve stem assembly and housing, the high pressure regulator fitting, the pressure burst disk assembly, and the threaded cylinder attachment with a pick-up tube.



Figure 8. Front view of the exemplar cylinder valve. The valve stem assembly and housing is concealed by the black valve handle.

RTI first loosened and removed the locking nut securing the hard rubber valve handle grip in place. With the nut removed, the grip slid off of the 7.34 mm long threaded portion of the valve



stem. Between the threaded rod and the main portion of the valve stem, a square cross section was present that provided the rubber valve handle a means for turning the valve stem. A gland nut with a smooth center bore secured the valve stem inside the valve body. The smooth bore provides for free rotation of the valve stem. An O-ring, 1.28 cm in diameter, served to seal the connection between the gland nut and the valve body, see **Figure 9**. RTI removed this nut to expose the valve stem. As it is not secured by any part other than the nut, it could be removed from the valve body simply by pulling it straight out.



Figure 9. Rear view of the partial exemplar valve stem assembly showing the gland nut, O-ring, and valve stem.

Upon removal, RTI observed the stem to be covered in a white grease-like substance, and that it incorporated two polymer bushings and two O-rings, see **Figure 10**. The stem ended in a square mandrel approximately 8.53 mm long. RTI observed the inner wall of the portion of the valve body, within which the valve stem resides, to be threaded. A threaded, square bored valve seat

body resided at the inner end of this portion of the valve body. RTI removed it by reinserting the valve stem and rotating counter clockwise to unthread the valve seat body. Once removed, the valve seat body appeared to be made of bronze with a black colored coating over most of the surface area. **Figure 10** shows the valve seat body and provides orientation. The interior end incorporated a plastic valve seat.



Figure 10. Rear view of the fully disassembled exemplar valve stem assembly showing the valve seat body and its orientation in the assembly.

Referring to **Figure 11**, RTI next removed the pressure burst disk assembly, which consists of a hollow threaded plug, a 34.1 MPa (5000 psi) burst disk, and retaining rings. Threads on the plug stop short of the head by approximately 2.411 mm. The head of the plug is bored through, presumably to allow a dispersed release of excess high pressure gas should the burst disk fail. **Figure 12** shows the burst disk and retaining ring as installed in the plug. Markings on the outer surface of the assembly head indicate that the assembly is to be installed with 40.7 N-m (30 ft-lb) of torque.




Figure 11. Rear view of the exemplar pressure burst disk assembly as removed from the valve body.



Figure 12. View of the exemplar pressure burst disk assembly showing the burst disk and retaining ring.

Finally, RTI removed the threaded protective insert into the high pressure regulator port. Removal of the insert revealed a shallow threaded bore leading to a gas supply rectangular opening proceeding down into the center of the cylinder valve body, indicated by the in **Figure 13**. Additionally, RTI observed a 1.9 mm diameter vent hole on the right side of the high pressure regulator port, indicated in **Figure 13**. This vent is approximately 7.42 mm forward of the rear inner surface of the port such that it is closed off when a fitting is fully threaded into the port.



Figure 13. Front view of the exemplar cylinder valve showing the high pressure regulator port.

The cylinder attachment consists of a straight threaded insert with an 8.05 mm diameter, 4.01 cm long dip tube fit into a center bore, see **Figure 8**. The nominal thread diameter and pitch measured as approximately 25 mm with a 2 mm pitch (1.035 inches and 13 tpi), respectively. An O-ring is provided at the cylinder mating surface.

Further detailed examination of the disassembled cylinder valve body revealed information about the path of high pressure gas from the cylinder through the valve. With the valve handle in the fully closed (inserted) position, high pressure gas flowing from the cylinder proceeds up through the pick-up tube and is directed against the valve seat to the left and the pressure burst disk to the right. As the valve is opened, the gas is allowed to flow past the valve seat and makes its way to the regulator port. This is accomplished by way of an angled bore connecting the valve stem bore to the regulator port. The rectangular cutout visible inside the regulator port is the outlet of



the angled bore. The external housing of the angled bore is indicated in **Figure 14** showing the rear view of the exemplar valve.




Figure 14. Rear view of the assembled exemplar cylinder valve showing the angled bore housing that connects the high pressure regulator port to the valve system assembly chamber.

#### 4.2.2 Incident Valve

As shown in **Figure 5**, the incident valve was received with several parts missing from the valve including the locking nut; the rubber valve handle (present but damaged and no longer attached); the threaded and square segment of the valve stem to which the handle attaches (this appeared to have separated from the main body of the valve stem leaving a square fracture surface); the dip tube; and a significant portion of the cylinder neck opening threads. The entire exterior of the incident valve and its installed components appeared charred and roughened compared to the exemplar valve.

RTI began the disassembly process of the incident valve by removing the gland nut, shown in **Figure 15**, with a torque wrench fitted with an appropriately sized socket in order to measure the installation torque. The gland nut was found to be threaded into the valve body approximately finger tight as measurements showed zero installation torque. The nut made four and one sixth turns before clearing the valve body. An intact O-ring similar to that found in the exemplar remained in its intended position on the gland nut.



Figure 15. View of the incident cylinder valve gland nut showing the presence of the intact O-ring.

Removal of the gland nut allowed access to the valve stem and the valve seat body. As shown in **Figure 16**, the incident valve stem was very similar in appearance to the exemplar although one of the bushings was different in color. Compared to the exemplar valve seat body in **Figure 17**, the incident valve seat body displayed a different color coating. The incident valve seat was also coated with some material, but with a green color. All portions of the incident gland nut, the

stem, the valve seat body, the plastic valve seat, and the interior of the valve stem portion of the valve body were further notable in that they were free of any apparent damage, heat effects, or discoloration as might be expected to result from fire or explosion.



Figure 16. View of the incident valve stem (top) as compared to the exemplar valve stem.




Figure 17. View of the incident valve seat body (green with white valve seat, upper) as compared to the exemplar valve seat body (black with yellow valve seat, lower).



RTI next removed the burst disk assembly of the incident valve. Compared to the gland nut, the burst disk assembly appeared tightly fit into the valve body. The installation torque was measured to be 10.17 N-m (90 in-lb). It took 5  $\frac{3}{4}$  turns to remove the assembly. While the exterior exposed surfaces of the plug had the same charred and damaged appearance as the rest of the incident valve, the interior surfaces were clean and bright and the burst disk was intact, see **Figure 18**. Correspondingly, the interior surfaces of the valve body in the area of the burst disk also proved to be clean and bright.



Figure 18. View of the incident burst disk assembly (upper) as compared to the exemplar burst disk assembly (lower).

During the explosion, the regulator, which attaches to the valve at the regulator port by way of a threaded adapter, broke away from the valve leaving a portion of the adapter still threaded into

the valve regulator port. This adapter included a plastic handle used for tightening into the regulator port, which remained intact. As seen in **Figure 5**, the adapter broke such that the handle remained attached to the valve but the portion that threads into the regulator remained with the regulator. Simply turning the handle allowed the adapter fragment to be removed from the valve. Some soot was observed on the interior surfaces of the regulator port and the adapter fragment. Inside the regulator port, charring was seen extensively around the vent and along the bottom thread. Soot-like discoloration was observed extending into the port from the charring near the center. Otherwise, the interior of the regulator port was clean and bright, see **Figure 19**.



Figure 19. View of the incident valve high pressure regulator port showing discoloration sooting around the vent.

The valve side of the adapter fragment contained an intact O-ring and a fitting suitable for inserting a hex key. Visible on the handle was the raised text “300 BAR”, see **Figure 20**. Internal to the adapter is a metal air cup that serves as a filter between the cylinder valve and the

regulator. RTI disassembled the adapter fragment and removed the air cup for further examination.



Figure 20. View of the incident valve and underside of the regulator adapter handle.

#### 4.2.3 Incident Regulator

RTI received the incident regulator, shown in **Figure 6**, with approximately 1 m length of green hose attached to one of the low pressure ports. Attached to one of the high pressure ports was a pressure gauge at the end of a 13 cm length of black hose. Soot coated the exterior surfaces of the regulator body, pressure gauge, and black hose; and the first 53 cm of the green hose appear heat affected by discoloration.

RTI first removed the two hoses, revealing the interiors of the two ports to be clean and bright with very little evidence of soot. Next, the remaining portion of the adapter was removed. While soot covered the adaptor's exterior surface and inner bore surface, the interior of the

exposed high pressure port was again clean and bright. However, the bore between the port and the regulator barrel was covered in dark soot.

Next, the cap/spring/plunger assembly, that serves in conjunction with a diaphragm to meter the high pressure gas to the low pressure side of the regulator, was removed. An O-ring and a flat plastic washer were seated in the low pressure regulator barrel and subsequently removed. Minor sooting and particulate matter were visible inside the incident regulator, on the washer and O-ring, and at the interior plunger end. As much as possible of these particulates was captured for later chemical analysis. As is seen in **Figure 21** and **Figure 22**, these components appeared to be in an overall undamaged condition.



Figure 21. View of the incident regulator with the cap/spring/plunger assembly being removed.



Figure 22. View into the low pressure portion of the incident regulator showing the O-ring and washer.

The high pressure diaphragm was revealed by removing a large set screw/fitting from the bottom of the regulator barrel using a hex key. This fitting held a spring in place that easily slipped out once the fitting was removed. Inside the chamber, a minor but noticeable amount of particulate was observed. This chamber is separated from the high pressure gas by the diaphragm and sealed to the outside by the fitting. The diaphragm chamber was separated from the regulator barrel using a strap wrench and the particulate matter found was subsequently saved for chemical analysis.



### 4.3 SEM Examination

A scanning electron microscope (SEM) provided high magnification imaging of metallic components selected by RTI for more detailed examination. The SEM also features the capability of analyzing small areas of the components to determine the constituent elements present. This is accomplished through energy dispersive x-ray spectroscopy (EDS) built into the microscope and provides an approximate indication of the relative concentrations of the elements present. The EDS produces a spectra plot showing the results of the analysis. The spectra plots for all EDS analysis conducted are included in **Attachment 7**.

#### 4.3.1 Incident valve stem fracture surface.

**Figure 23** is a composite view of the four corners of the fracture surface on the incident valve stem. It is notable that the majority of the fracture surface from the left edge proceeding to the right has the appearance of a ductile tensile fracture. A small remaining area along the right edge, conversely, has the appearance of a shear failure. Otherwise there is nothing remarkable about the fracture surface. EDS of the fracture surface measured high levels of copper and zinc, indicating that the valve stem was manufactured from a brass alloy.




Figure 23. Composite SEM micrograph of incident valve stem fracture surface.

### 4.3.2 Incident pressure regulator adapter fracture surfaces

**Figure 24** shows the fracture surface present on the pressure regulator adapter. As the exposed surfaces of the adapter, including the fracture surface, were covered in soot, the exact fracture morphology is not immediately apparent. Further compounding the characterization are areas that have the appearance of being mashed, or damaged, post fracture. These areas are also heavily sooted. Although there was a layer of soot on the adapter, EDS was able to measure high levels of copper and zinc which indicated that it was manufactured from a brass alloy.




Figure 24. SEM micrograph of pressure regulator adapter fracture surface.

### 4.3.3 Incident pressure regulator adapter air cup

**Figure 25** shows the structure of the pressure regulator adapter air cup. It is composed of numerous metallic spheres approximately 250  $\mu\text{m}$ , or 0.250 mm, in size, bonded together in a process known as sintering. The random spacing between the spheres varies in size from a few microns to as much as 300 or 400 microns and acts as a filter for most particulates that might be present in the gas flow upstream of the regulator by creating a tortuous path. EDS of the air cup revealed metallic peaks of aluminum, nickel, copper, and zinc which are consistent with brass alloys.




Figure 25. SEM micrograph of incident air cup structure.

### 4.3.4 Cylinder inside surface

A small piece of the cylinder from the larger fragment was examined in the SEM, primarily for the purpose of performing EDS on the interior surface of the cylinder. Metallic peaks were measured for aluminum and titanium.



#### 4.3.5 Exemplar and incident valve seat bodies

**Figure 26** and **Figure 27** show side by side comparison images of the exemplar and incident valve seat bodies in the threads and the smooth shaft, respectively. In **Figure 27** the extent of the coating is clearly visible on both bodies. EDS of both valve seat bodies in an uncoated area produced copper and zinc peaks indicative of brass alloys.




Figure 26. SEM micrographs comparing threaded portions of exemplar (left) and incident (right) valve seat bodies.




Figure 27. SEM micrographs comparing smooth portions of exemplar (left) and incident (right) valve seat bodies.

## 4.4 Mechanical Testing and Metallography

RTI conducted basic mechanical property testing of the cylinder material including tensile, compressive, and microhardness tests. Specimens of the cylinder material were also taken for metallographic examination.

### 4.4.1 Sectioning

Sectioning of the cylinder proceeded according to the established protocol, with specimens for hardness and metallography cut from the fracture edge and specimens for the tensile and compressive tests cut from a non-deformed area near the cylinder bottom. **Figure 28** shows the location of the billet cut for machining into tensile and compressive specimens. This location was chosen based on the results of spherometer measurements made of the cylinder inner curvature. It was necessary to locate an area of the cylinder, large enough to machine a full sized ASTM E-8M dog-bone specimen that had not been deformed significantly from the original curvature. Taking the specimen from such an area ensured that the cylinder material would be as close as possible to as-manufactured condition without any altering of strength properties due to deformation from the incident. **Figure 29** shows the locations of the specimens cut for hardness and metallography.



Figure 28. View of the incident cylinder showing the location of the billet removed for machining into tensile and compressive test specimens.



Figure 29. View of the incident cylinder showing the locations of the four metallography/microhardness specimens.

#### 4.4.2 Machining

Specimens were machined according to ASTM E-8M and ASTM E-9 for tensile and compressive testing, respectively. Both specimens were machined such that tensile and compressive loading axes were parallel to the longitudinal axis of the cylinder. See **Figure 30** for the tensile specimen.



Figure 30. View of the tensile specimen machined from the incident tank.

#### 4.4.3 Tensile and Compressive Testing

Both the tensile and compressive tests were conducted under quasi-static conditions. This resulted in a measured tensile yield strength of 318 MPa (46.1ksi) and a measured compressive yield strength of 347 MPa (50.3ksi). Additionally, an ultimate tensile strength of 354 MPa (51.4ksi) and tensile elongation of 15% were measured. Alcoa specifies minimum values of 290 MPa (42ksi), 345 MPa (50ksi), and 13% for the yield strength, tensile strength, and tensile elongation, respectively, for 6061-T6 aluminum.



#### 4.4.4 Metallographic Examination

Samples A through D, as seen in **Figure 31**, were mounted and polished for metallographic examination. A weak hydrofluoric solution was used as an etchant to reveal the grain structure. The specimens were examined optically using a metallograph and images captured from various regions of all four samples. **Figure 32** and **Figure 33** show representative micrographs of samples A and D. Micrographs from all the samples were compared to a representative micrograph of 6061-T6 published in “Introduction to Aluminum Alloys and Tempers”.<sup>7</sup> The microstructures compare favorably, confirming that the incident cylinder was manufactured from 6061-T6.




Figure 31. View of the four metallography/microhardness specimens prior to hardness testing. The “i” and “o” notations indicate the inner and outer surfaces, respectively.

<sup>7</sup> *Introduction to Aluminum Alloys and Tempers*, Kaufman, G.J., ASM International, Materials Park, 2000.






Figure 32. Sample A center 200x




Figure 33. Sample D center 200x

#### 4.4.5 Hardness Results

Upon completion of the metallographic examination, samples A through D were subjected to microhardness testing. Two microhardness traverses were made on each sample. One proceeded from the fracture edge across the circumference of the sample and the other proceeded from the inner to outer surfaces of the sample. A Knoop microhardness value of 120 is generally expected for 6061-T6. The microhardness measurements from sample A measured noticeably lower than the expected values. The measured values ranging from 82.7 to 110 with average values for the two traverses of 97.7 and 101.3. Sample A was taken from a section of cylinder that had undergone combustion, so the reduction in hardness is attributed to exposure heat causing over aging. Samples B through D showed measured values that were more consistent with the expected with averages of 123.8 and 126.0 for B, 119.3 and 125.8 for C, and 124.4 and 129.6 for D. The full set of results is included in **Attachment 10**.

#### 4.5 Chemical Analysis

The level of purity of the oxygen that was allegedly contained in the incident cylinder dictates that a specific environment within the gas passages would be maintained at all times. If a contaminant is present in an oxygen rich environment, the potential for ignition increases dramatically. Wash samples using DuPont Vertrel MCA solvent were taken from: (1) the inner surface of the incident cylinder, (2) the surfaces of the incident valve and its components that are part of the gas passage, (3) the inner surface of the incident regulator green hose, (4) the interior surfaces of the incident regulator, and (5) surfaces of the exemplar valve and its components that are part of the gas passage. These samples were analyzed using Fourier Transform Infrared Spectroscopy (FTIR) for chemical composition. The samples taken from the exemplar valve were used as a control for those taken from the incident valve.

Additionally, Optical Emission Spectroscopy (OES) was performed on samples of the incident cylinder and the exemplar valve in order to specifically identify the aluminum and brass alloys, respectively, used to manufacture each.

#### 4.5.1 FTIR Analysis

Full FTIR results are included in this report as **Attachment 8**. Other than the lubricant observed on the exemplar valve components, no substances were identified that could not be attributed to post incident sources. In other words, no unknown surface contaminants were found.

#### 4.5.2 OES

**Tables 1 and 2** contain the results of OES conducted on the cylinder and exemplar valve as compared to 6061 aluminum alloy and forging brass. The tested samples match well with the standard specifications for each alloy.

Table 1. Cylinder Valve Chemistry

Element	Cylinder Valve (wt%)	Requirements for Forging Brass UNS C37700	
		min	max
Copper (Cu)	Remainder	58.0	61.0
Iron (Fe)	0.26	-	0.30
Lead (Pb)	2.57	1.50	2.50
Nickel (Ni)	0.06	Information Only	
Phosphorus (P)	< 0.005	Information Only	
Tin (Sn)	0.21	Information Only	
Zinc (Zn)	38.47	Remainder	

Table 2. Cylinder Chemistry

Element	Tensile Specimen (wt%)	Requirements for Aluminum Alloy 6061 UNS A96061	
		min	max
Aluminum (Al)	Remainder	Remainder	
Chromium (Cr)	0.08	0.04	0.35
Copper (Cu)	0.33	0.15	0.40
Iron (Fe)	0.18	-	0.70
Lead (Pb)	< 0.005	Information Only	
Magnesium (Mg)	1.06	0.80	1.2
Manganese (Mn)	< 0.005	-	0.15
Nickel (Ni)	< 0.005	Information Only	
Silicon (Si)	0.70	0.40	0.80
Titanium (Ti)	0.01	-	0.15
Zinc (Cb)	< 0.005	-	0.25

## 5.0 DISCUSSION

### 5.1 Origin of the Explosion

The explosion has been determined to have been caused by the ignition of aluminum cylinder material and originated between the threads of the cylinder valve and the cylinder neck opening. Analysis of the cylinder dimensions and materials revealed that the cylinder was made from a material consistent with aluminum 6061-T6, and the wall thickness was appropriate. Laboratory testing failed to reveal the presence of contaminants or oxygen incompatible materials that may have auto-ignited. The resulting ignition promoted the growth and spread of further combustion of cylinder wall material. The combustion of aluminum occurred and was restricted to the inside surface of the cylinder. The heat generated was sufficient to locally soften the cylinder wall, as demonstrated by the over-aged condition of metallographic specimen “A”. The combustion also reduced the wall thickness. Additionally, the heat of combustion was released into the compressed gas, causing the gas pressure to rise. The combination of weakening the cylinder wall from heat of combustion, thinning due to the combustion of the cylinder material, and the increase in gas pressure from the release of heat from combustion, caused the cylinder to rupture and explosively release its contents.

The magnitude of aluminum material eroded from the event is greatest in the threaded neck opening region, indicative of the region of most intense and/or the longest burning. The initial fracture of the cylinder occurred along the base of the threaded opening, or “neck,” proximate to the ignition origin and began to grow along the perimeter of the opening base, until realigning along the cylinder axis and growing down towards the cylinder base, as indicated in **Figure 34**. Some of the fracture surfaces were either melted or covered by melted aluminum that re-solidified, but this could also be the result of the cylinder striking a hard surface which caused the cylinder to break up.






Figure 34. View showing the threaded neck opening region of the incident cylinder from the interior.

To evaluate the pattern of erosion about the cylinder opening, the depth of the threaded neck opening was measured at 30° intervals from the flat exterior top to the point where erosion seemed to stop along the threaded wall. The resulting measurements are shown in **Figure 35** in the radial diagram. The deepest erosion was set as the 0° point. The least erosion appears to have occurred at the 120°. The 120° region happened to be the area where the combustion deviated away from the opening and began to travel down the side of the cylinder interior, also being the direction where the hoop stress dominates the pattern of crack growth.






Figure 35. Depth measurements of the threaded neck cylinder opening, in mm.

The cylinder valve base also exhibits a matching pattern of erosion consistent with combustion from ignited aluminum, and alloying<sup>8</sup> from flowing molten aluminum, all originating from the threaded region within the threaded neck cylinder opening, as seen in **Figure 36**. There is a region along the perimeter that exhibits fracture as well as melting and reaction. The gross erosion was angled to the axial normal, indicating that once ignited, the products of combustion were expelled downward into the cylinder. The damage pattern suggests the initial ignition and resultant kindling to promoted ignition occurred within the threads closest to the edge of where the threaded neck cylinder opening bottom and cylinder valve threads meet.

The depth of the existing material below the gasket lip was also measured to evaluate the pattern of erosion. The depths were measured at 30° intervals with the 0° set coincident with the valve

<sup>8</sup> “Copper-Aluminum Interaction in Fire Environments”, B. Beland, C. Roy, and M. Tremblay, Fire Technology, Vol. 19, Number 1, 1983, page 20.

outlet centerline. As seen in **Figure 37**, the region with the greatest erosion was at 30°, with the least erosion at between 180° and 240°. Superimposing the radial plot with **Figure 35** and rotating the data -60° results in a near perfect overlay as seen in **Figure 38**. The closeness of fit supports the notion that the ignition point did occur within the threaded region. The exemplar cylinder valve threads extend 25 mm from the gasket lip to the flat bottom. The smallest depth of the valve threads measured 15 mm, indicating that perhaps 10 mm of material had eroded from the threads at that point.




Figure 36. View of cylinder valve threaded area.




Figure 37. Depth measurements of the valve threaded area, in mm.




Figure 38. Comparison of measured depths, in mm. Valve depth is rotated  $-60^\circ$  to match.

The burn pattern within the cylinder had two distinct burn zones as seen in **Figure 39**. Zone 1 matched the hemispherical geometry of the domed cylinder top with a demarcation line of between 4 cm and 5 cm from the opening center. Zone 2 extended vertically down the cylinder wall about 20 cm from the opening, and having a width of about 11 cm. A fracture divided the second burn zone, indicating this region was the area from which the crack propagated after initiating at the base of the “neck.” The area in Zone 1 was due to a circumferential combustion progressing from the origin point. The burn pattern in Zone 2 is a directional effect due to gravity as the cylinder may have been on its side. Despite the fracture starting at the base of the “neck,” the weakened area of Zone 2 influenced the crack to propagate in that direction as the hoop stress from internal pressure was greater in this area.




Figure 39. View of interior surface showing the two distinct burn zones.

As the aluminum was consumed, the local wall thickness was reduced; the heat weakened the aluminum; and the internal gas pressure increased from the heat energy produced by the combustion. The reaction was likely to have been more of a burning rather than explosive process. Due to this combustion process the cylinder failed at a pressure less than 38 MPa (5,500 psi)<sup>9</sup> as the pressure relieving burst disk in the cylinder valve was still intact after the explosion.

---

<sup>9</sup> The CG-1 burst disk is rated at 32.6 MPa  $\pm$ 10% (5000 psi  $\pm$ 10%), 38 MPa is the upper range of possible activation of the relief.

## 5.2 Ignition Mechanism

There are several ignition mechanisms that are possible within the incident cylinder. Some ignition mechanisms are: **promoted ignition**, where a source of heat acts to start the metal burning; **friction ignition**, where the rubbing of two surfaces together generates heat; **particle impact**, where the kinetic energy of a particle striking the surface is converted to heat; **mechanical impact**, much like the particle impact, heat is generated from the transfer of kinetic energy from an object having significantly more mass and less velocity than a particle; **exposure of base metal**, where the protective oxide layer is removed to expose the base metal, which in turn, oxidizes in the oxygen enriched atmosphere generating heat; **auto ignition of contaminants or incompatible materials**, where a material, such as a hydrocarbon based lubricant, is incompatible with use in an oxygen rich environment and self-ignites to promote ignition of the metal; **heat of compression**, where the rapid filling of a low pressure vessel from a high pressure line can cause the existing gas in the low pressure chamber to be driven into a compact region and compress to an increased temperature; **charging rigid vessels**, where the kinetic energy of the gas entering a low pressure vessel is converted to heat; **electric arc**, where the discharge across gaps between conventionally powered, electrically energized objects are heated from the very high temperature arc; **static electric discharge**, like an electric arc where a competent electric discharge occurs across a gap, but the electrical potential was created by a charge difference between the objects, not by electrical energizing; and **acoustic resonance**, where the oscillations of acoustic pressure waves from flowing gas create a temperature rise within the resonant cavity.<sup>10</sup>

The incident cylinder valve was found closed. The extents of heat and combustion effects were limited to the entrance of the cylinder valve at the point where the pick-up tube entered the valve body. At that point in the cylinder valve and beyond, there was no evidence of heat or combustion as the valve interior wall surfaces appeared clean and without heat effects. Plastic components within the cylinder valve were spared heating as they did not suffer any melting,

---

<sup>10</sup> ASTM G 94 – 92, and Advanced Thermodynamics for Engineers, §1-7-1 Charging and Discharging Rigid Vessels.

warping, combustion, or exhibit soot. Additionally, the valve seat was at the most forward position, indicating that the valve was shut at the time of the incident. The laboratory testing also failed to reveal the presence of any identifiable materials that are non-compatible with high purity oxygen systems. It would be expected that if such a substance existed prior to the fire, remnants of the substance or its by-products would still exist.

As a result, the following ignition mechanisms can be ruled out: particle impact; incompatible materials within the cylinder valve; charging a rigid vessel; heat of compression; static electric discharge; and acoustic resonance. This leaves electric arcing, mechanical impact, exposure of base metal, promoted ignition, and friction ignition. Electric arcing and promoted ignition are ruled out as improbable, thus leaving mechanical impact, exposure of base metal and friction ignition as the most likely causes. The actual mechanism of ignition could not be determined.

### **5.3 Cylinder Compliance with the Federal Regulations**

#### **5.3.1 Compliance with Labeling**

Compressed oxygen gas is considered a hazardous material, and is regulated under Title 49 of the Code of Federal Regulation, Part 172, Sub Chapter B. As found in the “Hazardous Materials Table,” §172.101, oxygen, as a compressed gas: has a Hazard Classification or Division of 2.2 (non-flammable gas); has an Identification number of UN1072; must be label coded as 2.2 or 5.1 (oxidizer); is subject to the special provisions of §172.102 A14 and A52; and must be packaged as per §172.302 for bulk packaging, or §172.314 and 315 for non-bulk packaging, with exceptions found in §172.306. Of the exceptions provided, none provided an exception to the labeling requirements for the incident cylinder. In summary, the incident cylinder should have been minimally labeled with a diamond shaped, durable label clearly marking the contents as “oxygen” followed by a “2.2”.<sup>11</sup> However, the Code is silent with regards to identification of the degree of cleanliness, as indicated in ASTM G 93.

---

<sup>11</sup> 49 CFR 172.407 provides the specifications for the label, §172.426 demands that an oxidizer have specific wording and Division for an oxidizer, and §172.405 modifies the oxidizer label to configure specifically to compressed oxygen gas.



In accordance with the federal regulations, the incident cylinder should have possessed a label indicating that the contents of the cylinder were compressed gas oxygen. The incident cylinder possessed two decals or labels. The first, shown in **Figure 2**, indicated that the cylinder had been cleaned in accordance with O<sub>2</sub> service. There is no indication as to who may have stamped and applied the decal, or as to what procedure was followed to certify the cylinder was properly cleaned. The failure to provide this information is counter to the suggestions of the Compressed Gas Association,<sup>12</sup> and a violation of the ASTM G 93 which states as follows:

*12.2 Package Marking:*

12.2.1 Each oxygen cleaned and packaged article shall be clearly labeled to include the following information:

12.2.1.1 The manufacturer, component identification, date cleaned, responsible department or agent,

12.2.1.2 Notification that it has been specially cleaned for oxygen service, such as oxygen cleaned, cleaned for oxygen service or specially cleaned,

12.2.1.3 Identification of cleaning method used, such as “Cleaned in accordance with ASTM G 93, Verification Type I, Test 1 through 4, Type II, Test 1, Level A, and Test 2, Level 175” or “Cleaned in accordance with ASTM G-XXX” (the manufacturer’s or purchaser’s specification).

The statement on the decal “Tank & Valve Have Been Cleaned In Accordance With O<sub>2</sub> Service” is not appropriate as it fails to indicate to what standard and level the cylinder has been cleaned, and who performed the cleaning. The decal does not provide the necessary information needed to ensure that the cylinder is appropriate for use with oxygen enriched gases. Additionally, the incident cylinder lacked the labeling as required by Federal statute. Should the incident tank have been used for Nitrox at 40% oxygen concentration or less, the IANDT label would have been sufficient and appropriate.

---

<sup>12</sup> Handbook of Compressed Gases, page 205 under section “Pressurization”.

Had the requirements of proper labeling been adhered to, there would not have been a need to produce an inadequate label indicating the incident cylinder had been cleaned for oxygen use. Use of the incident cylinder prior to being labeled is unknown. The entity that allegedly cleaned the incident cylinder for oxygen use should have affixed the federally mandated label prior to allowing the incident cylinder to be used with compressed oxygen. Without further information regarding the events preceding the incident, it is impossible to determine if the inappropriate labeling played a part in the incident.

### **5.3.2 Compliance with Regulations for 3AL Cylinder**

The requirements for a 3AL cylinder are found in Title 49 of the Code of Federal Regulations, part 178.46. The regulation dictates the cylinder material is to be similar to aluminum alloy 6061 with a T6 heat treatment with the mechanical properties having a minimum yield strength of 241 MPa (35,000 psi), a minimum tensile strength of 262 MPa (38,000 psi), and a minimum elongation of 14%. A sample of the cylinder was removed for tensile testing and compression testing. The sample was machined from the wall section having as much of the original curvature as possible to minimize the effects of work hardening from the accident. The specimen, seen in **Figure 40**, measured 12.93 mm (0.509 in) wide by 9.68 mm (0.381 in) thick by 131.75 mm (5.187 in) long. The testing performed in this investigation revealed that the cylinder material had a yield strength of 318 MPa (46,100 psi), a tensile strength of 354 MPa (51,400 psi), and an elongation of 15% – exceeding the minimum requirements of the regulation.




Figure 40. Tensile test specimen and tensile test.

Section 178.46(d) of the CFR provides for a minimum wall thickness. The regulation states that “The minimum wall thickness must be such that the wall stress at the minimum specified test pressure will not exceed 80 percent of the minimum yield strength nor exceed 67 percent of the minimum ultimate tensile strength as verified by physical tests in paragraph (i) of this section.” The wall thickness was measured to be 9.78 mm. The prescribed minimum test pressure was 34.5 MPa (5,000 psi)<sup>13</sup>. Using the measured mechanical properties, the results were that the wall stress measured 63.7% of the yield stress and 57.1% of the ultimate stress, which were below the regulation maximums. The resulting analysis indicates the wall thickness of the incident cylinder exceeded the minimum required by the regulation.

A sample of the material from the tension specimen was subjected to an alloy composition analysis. The incident cylinder material was found to be consistent with aluminum 6061 with T6 temper.

---

<sup>13</sup> 49 CFR 178.46(g)(3)(iii) Five-thirds times the service pressure for cylinders having a service pressure of at least 500 psig. The incident cylinder was rated for 3,000 psi service pressure.

## 6.0 CONCLUSIONS

The opinions expressed in this report are based on RTI's inspection and evaluation of the evidence; and engineering analysis using generally accepted scientific and engineering methodologies. These opinions are also based on RTI's education, background, knowledge, and experience in the fields of mechanical engineering, material science, chemistry, fluid dynamics, thermodynamics, and physics.

RTI concludes, to within a reasonable degree of engineering certainty that:

1. There is no evidence to suggest that non-compliance with the hazardous materials regulations played a part in the incident cylinder failure; however, modifications to the regulatory standards may be necessary.
2. The incident cylinder was not labeled as required by the hazardous materials regulations. However, it is uncertain if the failure to properly label the incident cylinder played a part in the incident.
3. The incident cylinder failure was not due to excess thermal exposure from an external source.
4. Laboratory testing failed to reveal any evidence of contamination from an oxygen incompatible substance on the incident cylinder, cylinder valve, hoses, and regulator.
5. There were no problems evident with the incident cylinder, except for the way it was labeled.
6. There were no problems evident with the incident cylinder valve.


7. There were no problems evident with the incident regulator and pressure lines.
8. The ignition of the fire that led to an explosion originated within the threaded section of the cylinder neck opening. The actual mechanism of ignition could not be determined.

RTI reserves the right to amend or supplement this report and its conclusions or recommendations should additional information become available.

Respectfully submitted,



Richard B. Loucks, Ph.D., P.E.  
Senior Mechanical Engineer



Matthew Wagenhofer, Ph.D.  
Mechanical Engineer

# ATTACHMENT 1

## Test Protocol



# TEST PROTOCOL

November 29, 2011

RTI Matter Name: DOT – Ruptured SCUBA Cylinder

RTI Matter No.: 50151ME002

RTI Investigators:

Richard B. Loucks, Ph.D., P.E.

Matthew Wagenhofer, Ph.D.

## **Background:**

RTI was tasked through Government Contract DTPH56-12-P-000004, dated November 9, 2011, issued by Office of Acquisition Services US DOT/PHMSA/PHA-30 to perform an investigation on a DOT 3AL-3000 cylinder involved in a fatal accident to determine if non-compliance with Hazardous Materials Regulations played a part in the cylinder failure and if modification of the regulatory standards is necessary.

Additionally, the purpose of this contract is to evaluate the ruptured DOT 3AL-3000 cylinder valve and determine the following:

- The degree of exposure to thermal energy; and
- Evidence of oxygen contamination which may have resulted in the explosion (fire) inside the ruptured DOT 3AL cylinder.

On November 15, 2011, RTI Group, LLC (RTI) received four items from the Department of Transportation, Pipeline and Hazardous Materials Safety Administration (PHMSA). These items are described as follows:

**1) Yellow high pressure gas cylinder, Part 1**

Smaller fragment from the cylinder, measures approximately 12 inches by 6 inches. Fragment displays the following marks near the neck: HY-MARK DOT-3AL 3000 OU

Cylinder has one decal and part of another:

Decal 1: “Tank & Valve Have Been Cleaned For Premix, Oxygen Content 22 to 40%” is not punched out. “Tank & Valve Have Been Cleaned In Accordance With O<sub>2</sub> Service” Is punched out at 2011. The month is uncertain.

Decal 2 (partial): for decompression use .... IANTD/IAND, Inc.

**2) Yellow high pressure gas cylinder, Part 2**

Larger section contains the bottom, neck and valve opening, measures approximately 24 inches by 14 inches. This item has the following markings near the neck: 0001 M5442 10 07 S40 TC-3AL 207

This part of the cylinder contains the remaining portion of Decal 2 stating:

Decal 2 (partial): OXYGEN for decompression use only – MOD 20 FSW MOD 6 MSW  
WWW.IANTD.COM

**3) High Pressure Tank Valve, DIN Valve,**

Manufactured by Genesis containing a 5000 psi, 30 lb/hr CG-1 type rupture disk. A pressure regulator adaptor is present in the opening which has a fractured outlet. The metal particle filter is evident in the opening. The rubber hand closure knob is present, but separate from the valve.

#### **4) Regulator**

Manufactured by Dive Rite, serial number 12008135, fitted with regulator fitting. The opening is occupied by the fractured end of the pressure regulator adaptor.

Attached to the regulator:

1. Black pressure line with dial gage on high pressure side of regulator. Dial gage face is heat affected and the gage is illegible.
2. Length of green pressure line stating “WARNING Do not exceed 250 psi (17 bar) high pressure may cause damage or personal injury” no manufacturer identified. Distal end terminates unattached. Low pressure side

#### **Objective:**

Under the tasking directive of the contract, sub-section 3.02 “Advanced Analysis and Examination”, as part of the investigation the evidence is to be subjected to a series of invasive, therefore destructive, examinations in which sophisticated laboratory equipment will be employed, such as Fourier Transform Infrared Spectroscopy (FTIR), Scanning Electron Microscopy (SEM), Energy Dispersive Spectroscopy (EDS), metallography, alloy chemistry, hardness testing and tension and compression testing. This protocol addresses the schedule and procedures that will be performed to fulfill this task.

#### **Date, Time and Location:**

- Tuesday, December 6, 2011 at 10:00 am pacific coast time
- ANAMET, Inc.  
26102 Eden Landing Road, Suite 3  
Hayward, CA 94545-3811
- Local Contact: Kenneth Pytlewski, 800-377-7768 OR Ken@Anametinc.com

## **Procedure:**

### ***Phase I – Initial Examination.***

Document the condition of the evidence through the use of field notes and still photography. The use of optical microscopy will be used where appropriate. This process is non-destructive and is intended to document the evidence prior to any alterations.

### ***Phase II - Search for the presence of oxygen non-compatible substances.***

An examination in search for materials typically found in SCUBA dive operations, such as silicone greases found in diving gear (dimethylsiloxane), hydrocarbon greases/oils used in diving gas compressors, perfluorinated lubricants found in Nitrox diving gear, and other lubricant materials such as Tribolube (ALI Aerospace Lubricants), Christo Lube (Lubrication Technologies, Inc.), IKV-Fluor & Zarox, etc. With the use of solvents, such as: Asahiklin AK 225 (Hydrochlorofluorocarbons); DuPont Vertrel XF, DuPont Vertrel MCA (Hydrofluorocarbon); or 3M HFE 7100, 3M HFE 71DE (Hydrofluoroether), obtain samples from within the valve gas passage area and subject the samples for FTIR analysis. The solvent will be decided upon at the time of the examination.

### **High Pressure Tank Valve**

Subject valve and regulator will have to be disassembled to reveal any existing gasket/seal materials, provide access to components for solvent washing and sample collection. With each disassembly, each component will be documented, and then the areas upstream of the containment feature will be searched for the presence of non-oxygen compatible materials. The disassembly will proceed in the following order:

1. Test the valve closure mechanism to determine if the valve is open or closed. Mark alignment of the gland nut to the valve body prior to turning with sharpie.
2. Remove the pressure regulator adaptor.
3. Remove the CG-1 burst disk pressure relief device.
4. Remove the closure mechanism. The gland nut will be removed exposing a series of gaskets and back up rings. These will be removed to gain access to the stem and the high pressure

seat. The condition of the high pressure seat will be inspected by SEM/EDS followed by solvent wash for FTIR analysis. Components will be removed until the valve body is empty.

Samples of the valve body will be obtained for chemistry analysis to determine the alloy of the materials used.

Material from the threads of the valve will be removed and inspected under the SEM. They will be removed using a pick and collected onto carbon tape for mounting on a SEM stage. Alternately, a segment section of the threads will be cut from the valve, polished and mounted, then inspected using the SEM.

Items having been separated from the parent object will be secured within a plastic container and labeled using the scheme: Part xx followed by a lower case alpha character, e.g. “Part 3-a Gland Nut”.

#### Pressure Regulator Adaptor

The fractured surface of the pressure regulator adaptor will be examined using the SEM to determine the mode of fracture and the presence of foreign materials. The air filter cup within the adaptor will be subjected to SEM analysis to identify both the discolored material on the filter surface and any particles that may be trapped in the filter. Subsequently, the filter will be subject to a solvent wash to determine by FTIR the presence of any contaminants.

#### Regulator

The high pressure hose attachment will be removed and the interior of the tubing will be inspected. The low pressure tubing will be removed and inspected. The interior of the regulator will be inspected to the extent possible from the open ports. If possible, a solvent swab will be taken through a high pressure port and subject to FTIR to determine the presence of contaminants. If contaminants are present, the regulator will be dismantled.

### Tank Material

Internal surfaces of the tank will be examined for the presence of oxygen non-compatible substances. Solvent washing of the internal area will provide samples for FTIR analysis in four areas, indicated as areas “A”, “B”, “C”, and “D” and any other areas deemed of interest on the day of the examination.



Figure 1. Solvent wash areas for FTIR sampling.

### ***Phase 3 – Mechanical properties testing of Cylinder material.***

Several sections of the cylinder will be subjected to hardness testing, alloy chemistry, metallographic analysis and tension and compression testing.



Hardness traverses following the inner circumference of the tank will be made at several elevations along the length of the tank. The approximate elevations are indicated in Figure 2. The method of testing will be as follows:

1. Four sections of cylinder material of approximately 2 inches wide by 1 inch deep will be excised from the main body with the use of a liquid cooled diamond blade saw.
2. After removing the section from the main body, a ½ inch axial wide circumferentially cut section will be removed for subsequent metallographic mounting, polish and etch. This creates two sub-sub sections for evidence labeling where a lower case Roman numeral will be added to the nomenclature, e.g. “Part 1-a-i Excised section from Cylinder, Metallographic” and “Part 1-a-ii Hardness Specimen from cylinder”. See Figure 3.
3. The fracture surface from the larger section will be examined using the SEM to determine from the fracture morphology the mode of fracture, direction of crack propagation, EDS, and any other information discovered in the examination. The section will then be subjected to a Rockwell hardness test on the internal surface, not directly on the fracture surface.
4. The smaller section will be cast into a resin material with the cut surface including the fracture surface for examination. The specimen will be polished, then etched to allow examination of the grain structure. A profile of Knoop micro hardness tests will be performed at 1mm intervals in two directions: circumferentially along the mid thickness from the fracture surface for 1.5 cm; and along the radial from the internal to the external surface.



Figure 2. Approximate test sites for hardness testing and metallographic examination.




Figure 3. Hardness testing and Metallographic sectioning. ⊗ illustrate Knoop micro hardness locations along the traverse. (not to scale)

Tension and compression testing will be performed to determine the mechanical properties of the alloy. Sample material will be collected from the machined samples for chemical analysis to determine the aluminum alloy.

The tension and compression tests will be performed as follows. A spherometer will be used to measure the radius of curvature of the tank in its as-received condition. Baseline inner surface curvature measurements will be made on the intact bottom region of the tank. Further inner surface curvature measurements will be made along the length of the tank over all of the regions to determine the least

deformed section of the tank. Visual inspection of the as-received tank indicates that this section is likely to correspond to that indicated in Figure 3. At least one (1) tension test specimen and two (2) compression test specimens will be machined from this region. The tension test specimen will be oriented such that the tensile axis of the specimen is parallel to the longitudinal axis of the tank. One of the compression specimens will be oriented such that the compression axis is parallel to the radial axis of the tank. The other compression specimen will be oriented such that the compression axis is parallel to the transverse axis of the tank. The transverse axis is defined by a line tangent to a circumference around the tank located at the midpoint of the tank wall. Any additional specimens for which there is sufficiently un-deformed material will duplicate these three orientations.

Dental mold compound will be used to make highly accurate replicas of the threads inside the neck of the tank prior to sectioning and mounting of the threads for metallographic and microscopic analysis. It is anticipated that the entire circumference of the threads will be replicated in two to four sections to ease removal of the molds from the inner threaded surface of the neck. Sufficient overlap will be included at both ends of each section so as to retain all details available. Measurements such as pitch, thread root depth, etc. will be made from the molds, if possible. The process will start by subjecting a portion of the threaded area to a solvent wash, the samples then subjected to FTIR analysis. Then the molding compound will be applied in quadrants with greater than 90 ° coverage. The boundaries will be indicated on the opening rim with a Sharpie and the molds labeled following the stated nomenclature.

Once the thread mold profiles are completed, the opening will be sectioned to allow SEM/EDS examination of the threaded section and subsequent metallographic mounting. A section, comprising of no more than 30 ° of radial opening on the section opposite that material still attached to the cylinder body will be sectioned. The section will be subject to SEM/EDS examination to resolve the thread/root regions for contaminants and other information. The section will then be mounted with the cut surface exposed for examination, polished and etched to reveal the grain structure, and examine for contaminants trapped beneath smeared or swaged aluminum.

***Phase 4 – Collection of Evidence***, logging and

retrograde. Each item will be double checked to ensure it has been catalogued, logged, and properly packaged for storage. All graphs, apparatus created images, and measurements will be compiled for use in the final report.

### **About RTI Group, LLC**

The RTI Group, LLC is a pioneering, global accident and failure investigation and safety management consultancy serving the legal and insurance markets. With origins dating back to 1975, RTI's forensic engineering services span comprehensive high-risk industries and transportation operations disciplines, including aviation, marine, rail, utilities, nuclear, explosion, and construction.

Headquartered in Annapolis, Maryland, RTI Group, LLC was founded in 2003 as a forensic engineering services company, with its origins dating back to 1975, by the founder of FTI Consulting, Inc. Anamet Inc., a forensic materials testing laboratory in San Francisco, California became a vital asset to RTI in 2003. In 2004, RTI founded its London office, RTI Ltd., as a wholly owned UK subsidiary that is the home office of the Aviation and Marine Departments. RTI Latin America was established in 2008 in Panama City, Panama as an extension of the London office to serve Latin America and, in particular, the Panamanian Flag State and Canal Operations. RTI opened its Bahrain branch office in April of 2011 to provide security and safety services, as well as access to other RTI disciplines in the Gulf and Middle East region. RTI continues to expand its worldwide range of analytical capabilities and services to other parts of the globe.

February 23, 2012 Amendment to

**TEST PROTOCOL**

**November 29, 2011**

RTI Matter Name: DOT – Ruptured SCUBA Cylinder

RTI Matter No.: 50151ME002

RTI Investigators:

Richard B. Loucks, Ph.D., P.E.

Matthew Wagenhofer, Ph.D.



Under Procedure, Phase II, High Pressure Tank Valve, change item 4 and add the following items of the disassembly procedure to read as follows:

4. Remove the closure mechanism. The gland nut will be removed exposing a series of gaskets and back up rings. These will be removed to gain access to the stem and the high pressure seat.
5. Perform an electrical continuity test and measure the electrical resistance between several points on the outer and inner surfaces of the valve seat body using a multimeter.
6. The condition of the high pressure seat will be inspected by SEM/EDS followed by solvent wash for FTIR analysis. Components will be removed until the valve body is empty.




# ATTACHMENT 2

## Evidence Receipt Photos









Inventory is on top and the smaller piece of the  
under the larger piece.

Please sign the enclosed DOT property inventory  
the signature receiving block on the bottom part  
form. If you can, scan the document and send it

SA  
Suite 602

U.S. DEPARTMENT OF TRANSPORTATION PROPERTY INVENTORY REPORT Page 1 of 1

DATE	11/9/11	TIME		LOCATION		INSPECTION TYPE		CASE NO.	
COMPLAINANT NAME	Vanhorn, Russell (deceased)		REASON FOR TAKING INTO U.S.C. CUSTODY		Ruptured scuba cylinder				
COMPLAINANT ADDRESS	5875 37th N. Apt 6 St. Petersburg, FL 33710		EXAMINE FOR CAUSE						
CONTACT NAME & PHONE NO.			DATE TAKEN INTO U.S.C. POSSESSION		11/9/11				
ITEM #	QUANTITY	DESCRIPTION OF PROPERTY							
1	1	Scuba cylinder							
2	1	Separated piece of scuba cylinder							
3	1	valve, regulator and hose							
Nothing returned									
ITEM #	DATE AND TIME RELEASED	DATE AND TIME RETURNED	SIGNATURE AUTHORIZING	SIGNATURE RECEIVING					
1	11/10/11		[Signature]						
2	11/10/11		[Signature]						
3	11/10/11		[Signature]						

KEEP WITH PROPERTY

The enclosed items comprise all the pieces of the ruptured scuba cylinder. The testing is contracted for the value assembly. Please hold the two pieces of the cylinder in case PHMSA HQ decides on further testing. The value assembly is on top and the smaller piece of the cylinder is under the larger piece.

Please sign the enclosed DOT property inventory report in the signature receiving block on the bottom part of the form. If you can, scan the document and send it to:

[Ernest.quail@dot.gov](mailto:Ernest.quail@dot.gov)

Or mail a copy to: US DOT/PHMSA  
233 Peachtree St. Suite 602  
Atlanta, GA 30303






























































































# ATTACHMENT 3

## Exemplar Valve Photos






























# ATTACHMENT 4

## Exemplar Regulator Photos




































































# ATTACHMENT 5

## Testing Sign-in Sheet





# Anamet, inc

Materials Engineering & Laboratory Testing

26102 Eden Landing Road, suite 3 · HAYWARD, CALIFORNIA 94545 · (510) 887-8811 · Fax (510) 887-8427

**Date:** March 12, 2012

**Matter:** Ruptured SCUBA Cylinder

**Anamet Job Number:** 5004.7109

RIT Matter No: 50151ME002

Name Matthew Wagenhofer

Company Name RTI

Representing DOT-PHMSA

Business Card or Contact Information	
Address	<u>910-E Bestgate Rd</u> <u>Annapolis, MD 21401</u>
Phone	<u>410-571-0712</u>
Email	<u>matthew.wagenhofer@rti-forensics.com</u>

Name Adam Horsley

Company Name PHMSA

Representing DOT-PHMSA



U.S. Department of Transportation  
Pipeline and Hazardous Materials Safety Administration

### ADAM HORSLEY

Attorney-Advisor  
Office of the Chief Counsel

East Building, E26-202  
1200 New Jersey Avenue, SE  
Washington, DC 20590

Tel: 202-366-8000  
Fax: 202-366-7041  
adam.horsley@dot.gov

Name BILL OLIVER

Company Name SHERWOOD SCUBA LLC

Representing SAME

## SHERWOOD SCUBA, LLC

1641 East Saint Andrew Place, Santa Ana, California 92705

Bill Oliver

[bill@sherwoodscuba.com](mailto:bill@sherwoodscuba.com)

Director of Product Development

TL: 714.259.4780 ext 7000

FX: 714.259.4789




Name NORMAN YUEN

Company Name ANAMET

Representing ANAMET  
(THIRD PARTY)

### Norman Yuen

Materials Engineer  
510-887-8811



**Anamet, inc**


### Materials Engineering & Laboratory Testing, Since 1958


26102 Eden Landing Rd., Suite 3  
Hayward, CA 94545-3811  
800-377-7768 • Fax: 510-887-8427  
[www.anametinc.com](http://www.anametinc.com)  
[norman@anametinc.com](mailto:norman@anametinc.com)

# ATTACHMENT 6



## Photographs from Anamet Testing











910-E Beestgate Road  
Annapolis, MD 21401  
410.571.0712 toll free  
866.327.1165 toll free

**rti**  
Representatives for RTI Chemicals, Inc.

Date 11/15/11 File/Lab No. SD151 MED02  
File Caption DOT-Ruptured SCUBA Cylinder  
Obtained From DOT-PHMSA  
Tagged By R. Landis  
Condition/Testing One (1) HP Tank valve mnt'd by  
Genesis w/pressure regulator adapter and metal  
particle filter  
Serial No./Markings \_\_\_\_\_  
Log Entry \_\_\_\_\_ Item 3 of 4

**EVIDENCE**

910-E Beestgate Road  
Annapolis, MD 21401  
410.571.0712 toll free  
866.327.1165 toll free

**rti**  
Representatives for RTI Chemicals, Inc.

Date 11/15/11 File/Lab No. SD151 AAE002  
File Caption DOT-Ruptured SCUBA Cylinder  
Obtained From DOT-PHMSA  
Tagged By R. Landis  
Condition/Testing One (1) ruptured SCUBA cylinder  
approx. 14" x 24"  
Serial No./Markings \_\_\_\_\_  
Log Entry \_\_\_\_\_ Item 2 of 4

**EVIDENCE**

910-E Beestgate Road  
Annapolis, MD 21401  
410.571.0712 toll free  
866.327.1165 toll free

**rti**  
Representatives for RTI Chemicals, Inc.

Date 11/15/11 File/Lab No. SD151 MED02  
File Caption DOT-Ruptured SCUBA Cylinder  
Obtained From DOT-PHMSA  
Tagged By R. Landis  
Condition/Testing One (1) HP Tank valve mnt'd by  
Genesis w/pressure regulator adapter and metal  
particle filter  
Serial No./Markings \_\_\_\_\_  
Log Entry \_\_\_\_\_ Item 3 of 4

**EVIDENCE**












Online Merchant Administration Tool <https://www.diverightinscuba.com/catalog/admin/packingslip.php?o...>

**Dive Right in Scuba**  
**24222 W. Lockport St.**  
**Plainfield, IL, 60544**  
**815-267-8400**



**ORDER ID: 5611**

**SOLD TO:**  
 Richard Loucks  
 29 Shadow Point Ct  
 Edgewater, Maryland 21037  
 United States

**SHIP TO:**  
 Richard Loucks  
 29 Shadow Point Ct  
 Edgewater, Maryland 21037  
 United States

410-571-0712  
 rick\_loucks@hotmail.com  
**IP Address:** 70.90.83.177  
**ISP:** cbrcoffee.com

**Payment Method:** PayPal Express (including Credit)

**Products** **Model**

Convertible 200 BAR DIN Valve KA70  
 Service Pressure: 3M42 PSI

Date Added	Who Commented	Comment
No order comments		

Open the box and make sure that the plastic bag is safely closed: if not all the content could have been abused and must be replaced. Storage the Valve in an appropriate place. An inappropriate storage can expose the Valve to dust and impurities, that can compromise the working of the Valve and gas cleanliness. Handle with clean hands or gloves. The assembly area and all the instruments, tools, and machine used must be properly cleaned to prevent contamination. The valve must be installed in a cylinder which has been cleaned and tested for Breathing air gases conformed to EN 12021 requirements. Manufacturer will not respond for any malfunctioning due to inappropriate storage or handling.

Before installation on the cylinder, check if the marking of the Valve correspond with the cylinder diameter and the mounting angle of the coupling or 4-hole plate. Check if the Valve thread corresponds with the thread of cylinder's coupling.

**DO NOT LUBRICATE.**  
 Make sure that the coupling is free of soiling like grease, painting colours, etc. The Valve must be free from oil especially the inlet and outlet connections. The presence of oil, lubricant and other substances containing hydrocarbons can be dangerous in case of contact with oxidizing gases: they are potential causes for fire and explosion, as well as fast opening of the handwheel.

**Usage and maintenance**  
 Maintenance and repair of the Valve is under the responsibility of the user or the operator. Anyone attempting to maintain or repair the Valve must be thoroughly familiar with EN 250 and all other standards and regulations reference therein.

**ALWAYS OPEN VALVE SLOWLY UNTIL PRESSURE BUILDS UP THROUGHOUT THE REGULATOR**  
 At the end of usage, close the Valve by hand without forcing. Maximum torque for opening and closing should be 5 Nm.


**Chromium plated external parts can be cleaned with disinfecting solutions not containing ammonia, using a clean cloth. Dry the device before using. Do not introduce any substance or foreign particles into the valve or into its inlet or outlet connections. Before using verify that the valve has no damaged parts and/or components. Damaged parts/components not subjected to pressure have to be substituted with original spare-parts, by trained authorized personnel. When outlet connections or other parts under pressure are damaged, or when periodical cylinder maintenance is performed, device substitution is recommended.**

**MANUFACTURER IS NOT RESPONSIBLE OF DAMAGES COMING FROM ALTERATIONS, TAMPERING, AND INAPPROPRIATE USE OF THE VALVE.**

**Chromium plated external parts can be cleaned with disinfecting solutions not containing ammonia, using a clean cloth. Dry the device before using. Do not introduce any substance or foreign particles into the valve or into its inlet or outlet connections. Before using verify that the valve has no damaged parts and/or components. Damaged parts/components not subjected to pressure have to be substituted with original spare-parts, by trained authorized personnel. When outlet connections or other parts under pressure are damaged, or when periodical cylinder maintenance is performed, device substitution is recommended.**

This warning paper is part of the sales contract. Manufacturer preserves the right to change design and materials as well as specifications and product information without prior notice.

Instructions for use VSB1      23 7 944 6362      INDEX A0 del 20/11/2008 ACTIVITY : 06290



The image shows the shipping materials for the valve. On the left is a shipping slip from Dive Right in Scuba. In the center is the instruction manual for the Pergola 232 bar valve. On the right is a yellow evidence tag with the word "EVIDENCE" written vertically. In the foreground is the valve assembly, which consists of a black handwheel and a silver metal body with a threaded outlet.

**pergola** Pergola s.r.l. Via Statale 11, 11/13  
 25010 Ponte S. Marco di Calcinato-BS- ITALY Tel.+39 030/9663111 - Fax +39 030/9680884

**INSTRUCTION FOR 232 bar SCUBA BREATHING AIR GASES READY VALVE**  
**THIS LABEL IS TO BE REMOVED BY THE CUSTOMER ONLY AND RETAINED FOR FUTURE REFERENCE**

Manufacturer general warranty conditions do not apply to Valve not installed, used and maintained accordingly to the instructions contained in these Warning Paper. Furthermore, Manufacturer general warranty conditions do not apply in the following:

- repair or replacement due to normal wear or damage during routine maintenance
- damage to components whose fragility is for technical reasons unavoidable and determined by product design
- damage arising from modifications not included in the procedures in this warning paper

Only those persons who have read these technical instructions thoroughly and understand them completely shall be authorized to use this Valve. Failure to follow any instruction or warning within this instruction manual or on any Valve label may result in a serious accident involving either personal injury, property damage or both.

Since the Valve is being purchased and used for incorporation into an other product Pergola reminds the end-product manufacturer that any and all product user warning, instructions and labels are the responsibility of such end-product manufacturer. This Valve is to be operated, maintained and installed only by individuals who have been trained by a recognized agency in Scuba Diving. You can disassembly the Valve only if you are properly trained to by specific training sessions organised by Manufacturer; furthermore you must follow the relevant instructions attached to the spare parts kit.

This high pressure cylinder valve is designed, intended and approved for scuba diving and must be used for Breathing Air Gases (EAN, Nitrox and Trimix G.M.); it should not be used for any other purposes. If the Valve user has any questions regarding the proper application or use of the Valve he must call Pergola. Any non-approved use or application and/or any non-approved modification of the Valve may result in a serious accident or personal injury for which the manufacturer will not be responsible.

Attention the Breathing Air Gases must be conform to EN 12021 requirements.

The valve is designed and manufactured according to: CE 97/23, EN ISO 10297 and UNI EN250

Technical data	Materials	Closure Torque
Working pressure: 232 bar	Body: Chromium plated Brass	Closure torque of the gland nut 45-55 Nm
Test pressure: 280 bar	O-rings: EPDM	Valving torque: Steel cylinders without welding 100-130 Nm
Temperature Range -20 +65 °C	Seal pad: PA 6.6	Aluminium cylinder 95-130 Nm
	Bursting Disc: Nickel	

The Valve is to be used for oxygen enriched air, the Valve is to be operated, maintained and installed only by individuals who have been trained by a recognized agency in the use of oxygen enriched breathing air.

Installation



910-E Bestgate Road  
Annapolis, MD 21401  
410.571.0712 tele  
866.327.1165 toll free

**rti**  
R  
Manufacturer of RTI Diver's Valves, Inc.

Date 12/30/11 File/Lab No. 50151.ME002  
File Caption DOT-Ruptured SCUBA cylinder  
Obtained From Dive Right In Scuba  
Tagged By M. Wagenhofer  
Condition/Testing Exemplar Valve #1  
(Convertible 200 Bar Din Valve)  
Serial No./Markings 60004328 11-10  
Log Entry \_\_\_\_\_ Item 1 of 2




**EVIDENCE**













910-E Bestgate Road  
Annapolis, MD 21401  
410.571.0712 tele  
866.327.1165 toll free

**rti**  
REGULATOR OF PTI (REGULATOR), INC.

Date 12/30/11 File/Lab No. 5D151.ME002

File Caption DOT-Ruptured SCUBA cylinder

Obtained From Dive Right In Scuba

Tagged By M. Wagenhofer

Condition/Testing Exemplar Valve #2  
(Convertible 200 Bar Pin Valve)

Serial No./Markings 60004328 11-10

Log Entry Item 2 of 2

**EVIDENCE**



Open the box and make sure that the plastic bags are safely closed; if not all the content could have been abused and must be replaced. Storage the Valve in an appropriate place. An inappropriate storage can expose the Valve to dust and impurities, that can compromise the working of the Valve and gas cleanliness. Handle with clean hands or gloves. The assembly area and all the instruments, tools, and machine used must be properly cleaned to prevent contamination. The valve must be installed in a cylinder which has been cleaned and tested for Breathing air gases conformed to EN 12021 requirements. Manufacturer will not respond for any malfunctioning due to inappropriate storage or handling. Before installation on the cylinder, check if the marking of the Valve corresponds with the cylinder diameter and the mounting angle of the coupling or a hole plate. Check if the Valve thread corresponds with the thread of cylinder's coupling.

**DO NOT LUBRICATE.**  
Make sure that the coupling is free of soiling like grease, painting colours, etc. The Valve must be free from oil especially the inlet and outlet connections. The presence of oil, lubricant and other substances containing hydrocarbons can be dangerous in case of contact with oxidizing gases; they are potential causes for fire and explosion, as well as fast opening of the handwheel.  
Use a special tool corresponding to the Valve's wrench to fit the Valve onto the cylinder to avoid any deformation. Fitting torque to be applied must be in accordance with the BS 1334 (see the table the valving torque valve ) and must not be exceed. If a leakage occurs after the correct assembly of the Valve onto the cylinder check the thread of the cylinder coupling.

**Usage and maintenance**  
Maintenance and repair of the Valve is under the responsibility of the user or the operator. Anyone attempting to maintain or repair the Valve must be thoroughly familiar with EN 250 and all other standards and regulations reference therein.  
After each filling operation close the Valve handwheel and check if there is any leak from the inlet connection and from the outlet of the Valve. Do not use leak detectors or solutions containing ammonia, phosphates, or other chemicals which are corrosive to copper.  
**corrosion of the material and consequently increases the risk of leaks and explosion.** Before insert the regulator onto the Valve open it slightly for an instance in order to clean the opening of particles of dust, dirt and to remove the moisture.  
**ALWAYS OPEN VALVE SLOWLY UNTIL PRESSURE BUILDS UP THROUGHOUT THE REGULATOR**


**At the end of usage, close the Valve by hand without forcing. Maximum torque for opening and closing should be 5 Nm.**  
If safety devices are present, pay the maximum attention during filling, stacking, and usage. For a correct use, make sure that cylinders are properly secured and usage and do not expose the cylinder to heat sources or directly to sun rays, that could increase the internal pressure of the container, and consequently cause the intervention of the safety device. In case this occurred, keep far from the gas containers until it's completely empty, air the room in order to prevent asphyxia and substitute the cylinder with one efficient.  
**MANUFACTURER IS NOT RESPONSIBLE OF DAMAGES COMING FROM ALTERATIONS, TAMPERING, AND INAPPROPRIATE USE OF THE VALVE.**

**Chromium plated external parts can be cleaned with disinfecting solutions not containing ammonia, using a clean cloth. Dry the device before using. Do not introduce any substance or foreign particles into the valve or into its inlet or outlet connections. Before using verify that the valve has no damaged parts and/or components. Damaged parts/components not subjected to pressure have to be substituted with original spare- parts, by trained authorized personnel. When outlet connections or other parts under pressure are damaged, or when periodical cylinder maintenance is performed, device substitution is recommended.**  
This warning paper is part of the sales contract. Manufacturer preserves the right to change designs and materials as well as specifications and product information without prior notice.

Instructions for use VSB1 23 7 944 6362 INDEX A0 del 20/11/2008 ACTIVITY : 06290





























Model: 5013A0002  
 Model Name: DOT - Ruptured SCUBA Cylinder  
 Evidence Inventory  
 2) Yellow high pressure gas cylinder, Part 1  
 Separator Fragment from the cylinder, approximately 12 inch by 9 inch, was the following marks at near the neck  
 DOT-3AL 3000 HV 5486  
 Cylinder has two decals  
 Decal 1: OXYGEN for decompression use only - MDD (Maximum Operating Depth) 20 FSW (20 feet submerged water), MDD 4 MSW (4 meters submerged water), International Association of Nitrox & Technical Divers, Inc.  
 Decal 2: "Tank & Valve Have Been Cleaned For Breathing, Oxygen Content 22 to 40%" is not punched out. "Tank & Valve Have Been Cleaned in Accordance With O<sub>2</sub> Service" is punched out at 2011. The month is uncertain.  
 2) Yellow high pressure gas cylinder, Part 2  
 Large section, contains the bottom, neck and valve opening, measures about 24 inches by 14 inches. Has the following markings near the neck  
 CV 0001 483442 10 07 540 TC-3AL 207  
 3) High Pressure Tank Valve, DIN Valve, manufactured by Genesis, 5000 psi, 30 Bar, CG-1 type rupture disk, Oxygen (Low Toxicity State and Compressed) PTSC Code 4350, 4, highly oxidizing, 1 normal, 6, nonpurified gas between 500 and 8000 psig, 0 noncorrosive, Class 2 Division 2.2 gas use permits CG-1, (required in one end of the cylinder, regardless of length). A pressure regulator adaptor is present in the opening which has a fractured outlet. The metal particle filter is evident in the opening.  
 3) Regulator by Dive Rite, serial number 12008135, fitted with regulator fitting. The opening is occupied by the fractured end of the pressure regulator adaptor  
 Attached:  
 1. Black pressure line with dial gage on high pressure side of regulator. Dial gage face is heat affected and the gage is illegible.  
 2. Length of green pressure line starting "WARNING Do not exceed 250 psi (17 bar) high pressure may cause damage or personal injury" no manufacturer identified. Distal end terminates unattached. Low pressure side



**rti** RTI Group, LLC  
 10000 West 10th Avenue, Suite 100  
 Denver, CO 80202  
 303.751.1000  
 www.rti-group.com

**CHANGE OF EVIDENCE CUSTODY RECORD**

DATE: November 22, 2011

RTI File Name: DOT - Ruptured Scuba Cylinder  
 RTI File No.: 5013A0002

The evidence herein described has been transferred on this date --

To: Richard Loucks, PhD, PE From: U.S. Dept of Transportation Property Inventory Report  
 Company: RTI Group, LLC Company:

Description of Evidence (Note all markings):  
 1. SEE ATTACHED LIST.

Authorization of Sending Party: \_\_\_\_\_  
 (Signature & Date)

Authorization of Receiving Party:  
 (Signature & Date) *[Signature]*  
 (Printed) Richard B. Loucks, PhD, PE

**U.S. DEPARTMENT OF TRANSPORTATION PROPERTY INVENTORY REPORT** Page 1 of 1

Date: 11/9/11  
 Location: *[Blank]*  
 Case No.: *[Blank]*

Complainant Name: *Vanadora, Russell (deceased)*  
 Complainant Address: *5875 37th N. Apt 512, Fort Myers, FL 33907*  
 Contact Name & Phone No.: *5577*

Manufacturer of Property: *Ruptured cylinder...*  
 Manufacturer of Property Location: *...*  
 Date of Property Loss: *11/9/11*

ITEM #	QUANTITY	DESCRIPTION OF PROPERTY
1	1	Scuba cylinder
2	1	Separated piece of scuba cylinder
3	1	valve, regulator and hose

*Nothing to report*


ITEM #	DATE AND TIME RELEASED	DATE AND TIME RECEIVED	SIGNATURE AUTHORIZING	SIGNATURE RECEIVING
1	11/10/11	11/10/11	<i>[Signature]</i>	<i>[Signature]</i>
2	11/10/11	11/10/11	<i>[Signature]</i>	<i>[Signature]</i>
3	11/10/11	11/10/11	<i>[Signature]</i>	<i>[Signature]</i>

PROPERTY # \_\_\_\_\_

KEEP WITH PROPERTY































































































































































































































































































































































































































































































































































































































































































































































































































































































# ATTACHMENT 7

## EDS Spectra and Tables















Tank Inside Surface A



















Valve Stem Coating Debris











## Air Cup

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
O	K_series	5.20	0.01749	26.49	0.23	SiO2	Yes	
F	K_series	1.06	0.00208	4.44	0.17	CaF2	Yes	
Mg	K_series	0.10	0.00063	1.00	0.06	MgO	Yes	
Al	K_series	3.65	0.02623	31.48	0.19	Al2O3	Yes	
Si	K_series	0.05	0.00038	0.49	0.04	SiO2	Yes	
S	K_series	0.05	0.00046	0.39	0.04	FeS2	Yes	
Ca	K_series	0.08	0.00069	0.42	0.04	Wollastonite	Yes	
Fe	K_series	0.06	0.00064	0.36	0.06	Fe	Yes	
Ni	K_series	2.69	0.02688	15.99	0.18	Ni	Yes	
Cu	K_series	1.94	0.01937	12.33	0.20	Cu	Yes	
Zn	K_series	0.90	0.00901	5.85	0.18	Zn	Yes	
Sn	L_series	0.11	0.00106	0.75	0.09	Sn	Yes	
Total:				100.00				

## Pressure Regulator Adapter Debris

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
C				88.47				
O	K_series	2.37	0.00797	7.56	0.07	SiO2	Yes	
Mg	K_series	0.03	0.00021	0.04	0.00	MgO	Yes	
Al	K_series	1.75	0.01260	1.86	0.01	Al2O3	Yes	
Si	K_series	0.03	0.00025	0.03	0.00	SiO2	Yes	
S	K_series	0.02	0.00015	0.02	0.00	FeS2	Yes	
Cl	K_series	0.01	0.00010	0.01	0.00	NaCl	Yes	
Ca	K_series	0.11	0.00101	0.12	0.00	Wollastonite	Yes	
Fe	K_series	0.02	0.00019	0.02	0.00	Fe	Yes	
Cu	K_series	0.58	0.00579	0.79	0.02	Cu	Yes	
Zn	K_series	0.73	0.00730	1.00	0.02	Zn	Yes	
Pb	M_series	0.07	0.00067	0.08	0.01	PbTe	Yes	
Total:				100.00				



## Pressure Regulator Adapter Base Metal

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	4.63	0.04633	60.35	0.37	Cu	Yes	
Zn	K_series	3.05	0.03054	39.65	0.37	Zn	Yes	
Total:				100.00				

## Tank Inside Surface A

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
O	K_series	1.94	0.00654	48.57	0.47	SiO2	Yes	
Mg	K_series	0.05	0.00032	0.98	0.09	MgO	Yes	
Al	K_series	1.54	0.01103	27.92	0.30	Al2O3	Yes	
Si	K_series	0.14	0.00111	3.30	0.12	SiO2	Yes	
S	K_series	0.07	0.00064	1.42	0.08	FeS2	Yes	
Ca	K_series	0.33	0.00294	5.13	0.12	Wollastonite	Yes	
Ti	K_series	0.65	0.00647	12.37	0.21	Ti	Yes	
Fe	K_series	0.02	0.00016	0.30	0.10	Fe	Yes	
Total:				100.00				



## Valve Body Thread Deposit

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
C				86.25				
O	K_series	1.54	0.00519	4.77	0.08	SiO2	Yes	
F	K_series	0.83	0.00164	0.90	0.03	CaF2	Yes	
Mg	K_series	0.07	0.00049	0.09	0.00	MgO	Yes	
Al	K_series	2.14	0.01535	2.38	0.01	Al2O3	Yes	
Si	K_series	0.03	0.00021	0.03	0.00	SiO2	Yes	
Fe	K_series	0.03	0.00025	0.03	0.01	Fe	Yes	
Ni	K_series	0.04	0.00036	0.04	0.01	Ni	Yes	
Cu	K_series	1.80	0.01795	2.42	0.03	Cu	Yes	
Zn	K_series	2.20	0.02201	2.98	0.04	Zn	Yes	
Pb	M_series	0.09	0.00079	0.10	0.01	PbTe	Yes	
Total:				100.00				

## Valve Seat Body Exemplar 1

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	7.32	0.07318	62.01	0.36	Cu	Yes	
Zn	K_series	4.50	0.04498	37.99	0.36	Zn	Yes	
Total:				100.00				



## Valve Seat Body Exemplar 2

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	4.45	0.04453	62.57	0.42	Cu	Yes	
Zn	K_series	2.67	0.02672	37.43	0.42	Zn	Yes	
Total:				100.00				

## Valve Seat Body

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	8.82	0.08822	66.03	0.36	Cu	Yes	
Zn	K_series	4.55	0.04553	33.97	0.36	Zn	Yes	
Total:				100.00				



## Valve Stem Fracture

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	3.93	0.03926	59.43	0.40	Cu	Yes	
Zn	K_series	2.69	0.02688	40.57	0.40	Zn	Yes	
Total:				100.00				

## Valve Stem Coating

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cr	K_series	6.39	0.06390	54.35	0.24	Cr	Yes	
Ni	K_series	4.98	0.04982	45.65	0.24	Ni	Yes	
Total:				100.00				



## Valve Stem Coating Debris


Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
O	K_series	3.66	0.01233	16.22	0.17	SiO2	Yes	
F	K_series	9.72	0.01908	53.47	0.24	CaF2	Yes	
Mg	K_series	0.27	0.00180	4.22	0.08	MgO	Yes	
Si	K_series	0.48	0.00377	5.15	0.07	SiO2	Yes	
Cr	K_series	1.23	0.01235	10.83	0.11	Cr	Yes	
Ni	K_series	0.46	0.00457	3.97	0.10	Ni	Yes	
Zn	K_series	0.65	0.00653	6.15	0.16	Zn	Yes	
Total:				100.00				

# ATTACHMENT 8

## FTIR Spectra and Tables



rt113: Sample 1A, Valve Seat Body, Vertrel Solvent Wash, Nonvolatile on KBr window




Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545

rt13: Sample 1A, Valve Seat Body, Vertrel Solvent Wash, Nonvolatile on KBr Window


Peak	Pick	Intensity
cm-1	8744	97145
682	44	98587
758	154	97588
810	0	86551
1143	861	86418
1179	941	95009
1461	221	98249
1551	171	98361
1739	102	97779
1834	82	9753
29	27	81



rt113: Sample 1A, Valve Seat Body, Vertrel Solvent Wash, Nonvolatile on KBr Window



rt116: Sample 1B, Valve Stem, Vertrel Solvent wash, Nonvolatile on KBr window




Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545



rt16: Sample 19, Valve Stem, Vertrel Solvent Wash, Nonvolatile on KBr Window


Peak	Pick	Intensity
543	960	98684
814	844	960211
835	230	95959
1057	870	73497
1149	265	72277
1177	266	93322
1466	502	99417
2854	827	99439
2924	859	9039
2993	889	98

rt116: Sample 1B, Valve Stem, Vertrel Solvent Wash, Nonvolatile on KBr Window






rti18: Sample 1C, Relief Valve, Vertel Solvent Wash of Burst Disc Face, NV on KBr Win.



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545

rt18: Sample 1C, Relief Valve, Vertrel Solvent Wash of Burst Disc Face, NV on KBr Win.


Peak Pick




Anamet, Inc.  
 26102 Eden Landing Road  
 Suite 3  
 Hayward, CA 94545



rti18: Sample 1C, Relief Valve, Vertel Solvent Wash of Burst Disc Face, NV on KBr Win.



rt119: Sample 1D, Gland Nut, Vertrel Solvent Wash, Inside Bore, Nonvolatile, KBr Win.




Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545






rt119: Sample ID, Gland Nut, Vertrel Solvent Wash, Inside Bore, Nonvolatile, KBr Win.





rti20: Sample 1E, Valve Body, Deposits in 22mm Orifice, KBr 7mm Dia. Pressed Pellet




Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545






rti20: Sample 1E, Valve Body, Deposits in 22mm Orifice, KBr 7mm Dia. Pressed Pellet



rti21: Sample 1E, Valve Body, Deposits in 18mm Orifice, KBr 7mm Dia. Pressed Pellet



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545




rti21: Sample IE, Valve Body, Deposits in 18mm Orifice, KBr 7mm Dia. Pressed Pellet

Peak Pick


cm-1	Intensity
4221	9433
5067	3750
6758	3107
7798	5617
11145	4205
11419	5277
11458	3322
11508	2820
11539	5208
11643	6940
13361	8840
22825	9978
22844	8888
22855	8888
24041	8888
24047	8888
24302	9977
24303	9977

rti21: Sample 1E, Valve Body, Deposits in 18mm Orifice, KBr 7mm Dia. Pressed Pellet





rti22: Sample 1E, Valve Body, Deposits in 12mm Orifice, KBr 7mm Dia. Pressed Pellet



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545


rti22: Sample 1E, Valve Body, Deposits in 12mm Orifice, KBr 7mm Dia. Pressed Pellet

Peak Pick


cm-1	Intensity
6153.3911	89.666
6533.3411	87.717
8311.4928	85.472
11398.4208	83.241
11473.9902	80.588
11496.9902	80.377
11504.9902	80.146
11543.9902	79.177
12358.1902	77.503
12454.8902	75.234
12822.4902	72.941
13473.9902	69.923
14104.9902	67.923
14233.9902	65.923
14361.9902	63.923
14490.9902	61.923
14619.9902	59.923
14748.9902	57.923
14877.9902	55.923
15006.9902	53.923
15135.9902	51.923
15264.9902	49.923
15393.9902	47.923
15522.9902	45.923
15651.9902	43.923
15780.9902	41.923
15909.9902	39.923
16038.9902	37.923
16167.9902	35.923
16296.9902	33.923
16425.9902	31.923
16554.9902	29.923
16683.9902	27.923
16812.9902	25.923
16941.9902	23.923
17070.9902	21.923
17199.9902	19.923
17328.9902	17.923
17457.9902	15.923
17586.9902	13.923
17715.9902	11.923
17844.9902	9.923
17973.9902	7.923
18102.9902	5.923
18231.9902	3.923
18360.9902	1.923
18489.9902	0.923
18618.9902	0.923
18747.9902	0.923
18876.9902	0.923
19005.9902	0.923
19134.9902	0.923
19263.9902	0.923
19392.9902	0.923
19521.9902	0.923
19650.9902	0.923
19779.9902	0.923
19908.9902	0.923
20037.9902	0.923
20166.9902	0.923
20295.9902	0.923
20424.9902	0.923
20553.9902	0.923
20682.9902	0.923
20811.9902	0.923
20940.9902	0.923
21069.9902	0.923
21198.9902	0.923
21327.9902	0.923
21456.9902	0.923
21585.9902	0.923
21714.9902	0.923
21843.9902	0.923
21972.9902	0.923
22101.9902	0.923
22230.9902	0.923
22359.9902	0.923
22488.9902	0.923
22617.9902	0.923
22746.9902	0.923
22875.9902	0.923
23004.9902	0.923
23133.9902	0.923
23262.9902	0.923
23391.9902	0.923
23520.9902	0.923
23649.9902	0.923
23778.9902	0.923
23907.9902	0.923
24036.9902	0.923
24165.9902	0.923
24294.9902	0.923
24423.9902	0.923
24552.9902	0.923
24681.9902	0.923
24810.9902	0.923
24939.9902	0.923
25068.9902	0.923
25197.9902	0.923
25326.9902	0.923
25455.9902	0.923
25584.9902	0.923
25713.9902	0.923
25842.9902	0.923
25971.9902	0.923
26100.9902	0.923
26229.9902	0.923
26358.9902	0.923
26487.9902	0.923
26616.9902	0.923
26745.9902	0.923
26874.9902	0.923
27003.9902	0.923
27132.9902	0.923
27261.9902	0.923
27390.9902	0.923
27519.9902	0.923
27648.9902	0.923
27777.9902	0.923
27906.9902	0.923
28035.9902	0.923
28164.9902	0.923
28293.9902	0.923
28422.9902	0.923
28551.9902	0.923
28680.9902	0.923
28809.9902	0.923
28938.9902	0.923
29067.9902	0.923
29196.9902	0.923
29325.9902	0.923
29454.9902	0.923
29583.9902	0.923
29712.9902	0.923
29841.9902	0.923
29970.9902	0.923
30099.9902	0.923
30228.9902	0.923
30357.9902	0.923
30486.9902	0.923
30615.9902	0.923
30744.9902	0.923
30873.9902	0.923
31002.9902	0.923
31131.9902	0.923
31260.9902	0.923
31389.9902	0.923
31518.9902	0.923
31647.9902	0.923
31776.9902	0.923
31905.9902	0.923
32034.9902	0.923
32163.9902	0.923
32292.9902	0.923
32421.9902	0.923
32550.9902	0.923
32679.9902	0.923
32808.9902	0.923
32937.9902	0.923
33066.9902	0.923
33195.9902	0.923
33324.9902	0.923
33453.9902	0.923
33582.9902	0.923
33711.9902	0.923
33840.9902	0.923
33969.9902	0.923
34098.9902	0.923
34227.9902	0.923
34356.9902	0.923
34485.9902	0.923
34614.9902	0.923
34743.9902	0.923
34872.9902	0.923
35001.9902	0.923
35130.9902	0.923
35259.9902	0.923
35388.9902	0.923
35517.9902	0.923
35646.9902	0.923
35775.9902	0.923
35904.9902	0.923
36033.9902	0.923
36162.9902	0.923
36291.9902	0.923
36420.9902	0.923
36549.9902	0.923
36678.9902	0.923
36807.9902	0.923
36936.9902	0.923
37065.9902	0.923
37194.9902	0.923
37323.9902	0.923
37452.9902	0.923
37581.9902	0.923
37710.9902	0.923
37839.9902	0.923
37968.9902	0.923
38097.9902	0.923
38226.9902	0.923
38355.9902	0.923
38484.9902	0.923
38613.9902	0.923
38742.9902	0.923
38871.9902	0.923
39000.9902	0.923
39129.9902	0.923
39258.9902	0.923
39387.9902	0.923
39516.9902	0.923
39645.9902	0.923
39774.9902	0.923
39903.9902	0.923
40032.9902	0.923
40161.9902	0.923
40290.9902	0.923
40419.9902	0.923
40548.9902	0.923
40677.9902	0.923
40806.9902	0.923
40935.9902	0.923
41064.9902	0.923
41193.9902	0.923
41322.9902	0.923
41451.9902	0.923
41580.9902	0.923
41709.9902	0.923
41838.9902	0.923
41967.9902	0.923
42096.9902	0.923
42225.9902	0.923
42354.9902	0.923
42483.9902	0.923
42612.9902	0.923
42741.9902	0.923
42870.9902	0.923
43000.9902	0.923
43129.9902	0.923
43258.9902	0.923
43387.9902	0.923
43516.9902	0.923
43645.9902	0.923
43774.9902	0.923
43903.9902	0.923
44032.9902	0.923
44161.9902	0.923
44290.9902	0.923
44419.9902	0.923
44548.9902	0.923
44677.9902	0.923
44806.9902	0.923
44935.9902	0.923
45064.9902	0.923
45193.9902	0.923
45322.9902	0.923
45451.9902	0.923
45580.9902	0.923
45709.9902	0.923
45838.9902	0.923
45967.9902	0.923
46096.9902	0.923
46225.9902	0.923
46354.9902	0.923
46483.9902	0.923
46612.9902	0.923
46741.9902	0.923
46870.9902	0.923
47000.9902	0.923
47129.9902	0.923
47258.9902	0.923
47387.9902	0.923
47516.9902	0.923
47645.9902	0.923
47774.9902	0.923
47903.9902	0.923
48032.9902	0.923
48161.9902	0.923
48290.9902	0.923
48419.9902	0.923
48548.9902	0.923
48677.9902	0.923
48806.9902	0.923
48935.9902	0.923
49064.9902	0.923
49193.9902	0.923
49322.9902	0.923
49451.9902	0.923
49580.9902	0.923
49709.9902	0.923
49838.9902	0.923
49967.9902	0.923
50096.9902	0.923
50225.9902	0.923
50354.9902	0.923
50483.9902	0.923
50612.9902	0.923
50741.9902	0.923
50870.9902	0.923
51000.9902	0.923
51129.9902	0.923
51258.9902	0.923
51387.9902	0.923
51516.9902	0.923
51645.9902	0.923
51774.9902	0.923
51903.9902	0.923
52032.9902	0.923
52161.9902	0.923
52290.9902	0.923
52419.9902	0.923
52548.9902	0.923
52677.9902	0.923
52806.9902	0.923
52935.9902	0.923
53064.9902	0.923
53193.9902	0.923
53322.9902	0.923
53451.9902	0.923
53580.9902	0.923
53709.9902	0.923
53838.9902	0.923
53967.9902	0.923
54096.9902	0.923
54225.9902	0.923
54354.9902	0.923
54483.9902	0.923
54612.9902	0.923
54741.9902	0.923
54870.9902	0.923
55000.9902	0.923
55129.9902	0.923
55258.9902	0.923
55387.9902	0.923
55516.9902	0.923
55645.9902	0.923
55774.9902	0.923
55903.9902	0.923
56032.9902	0.923
56161.9902	0.923
56290.9902	0.923
56419.9902	0.923
56548.9902	0.923
56677.9902	0.923
56806.9902	0.923
56935.9902	0.923
57064.9902	0.923
57193.9902	0.923
57322.9902	0.923
57451.9902	0.923
57580.9902	0.923
57709.9902	0.923
57838.9902	0.923
57967.9902	0.923
58096.9902	0.923
58225.9902	0.923
58354.9902	0.923
58483.9902	0.923
58612.9902	0.923
58741.9902	0.923
58870.9902	0.923
59000.9902	0.923
59129.9902	0.923
59258.9902	0.923
59387.9902	0.923
59516.9902	0.923
59645.9902	0.923
59774.9902	0.923
59903.9902	0.923
60032.9902	0.923
60161.9902	0.923
60290.9902	0.923
60419.9902	0.923
60548.9902	0.923
60677.9902	0.923
60806.9902	0.923
60935.9902	0.923
61064.9902	0.923
61193.9902	0.923
61322.9902	0.923
61451.9902	0.923
61580.9902	0.923
61709.9902	0.923
61838.9902	0.923
61967.9902	0.923
62096.9902	0.923
62225.9902	0.923
62354.9902	0.923
62483.9902	0.923
62612.9902	0.923
62741.9902	0.923
62870.9902	0.923
63000.9902	0.923
63129.9902	0.923
63258.9902	0.923
63387.9902	0.923
63516.9902	0.923
63645.9902	0.923
63774.9902	0.923
63903.9902	0.923
64032.9902	0.923
64161.9902	0.923
64290.9902	0.923
64419.9902	0.923
64548.9902	0.923
64677.9902	0.923
64806.9902	0.923
64935.9902	0.923
65064.9902	0.923
65193.9902	0.923
65322.9902	0.923
65451.9902	0.923
65580.9902	0.923
65709.9902	0.923
65838.9902	0.923
65967.9902	0.923
66096.9902	0.923
66225.9902	0.923
66354.9902	0.923
66483.9902	0.923
66612.9902	0.923
66	



rti22: Sample 1E, Valve Body, Deposits in 12mm Orifice, KBr 7mm Dia. Pressed Pellet



rti23: Sample 1E, Valve Body, Deposits in 5mm Orifice, KBr 7mm Dia. Pressed Pellet






rt123: Sample 1E, Valve Body, Deposits in 5mm Orifice, KBr 7mm Dia. Pressed Pellet


Peak	Pick	Intensity
555	15394	56381
680	9115	48593
814	01128	48417
1092	33418	55330
292	8078	93774
341	93	83340
419	093	8336

rti23: Sample 1E, Valve Body, Deposits in 5mm Orifice, KBr 7mm Dia. Pressed Pellet





rti24: Sample 1F, Regulator Adapter Air Cup, Vertrel Solvent Wash, Nonvol. KBr Window



Anamet, Inc.  
26702 Eden Landing Road  
Suite 3  
Hayward, CA 94545


rti24: Sample 1F, Regulator Adapter Air Cup, Vertrel Solvent Wash, Nonvol. KBr Window

Peak Pick


cm-1	Intensity
686	94
760	96
837	77
1093	71
1120	71
1145	67
1150	67
1154	67
1165	67
1244	60
2285	32
2921	32
2924	32
2929	32
2931	32
2939	32
2941	32
2943	32
2944	32
2945	32
2946	32
2947	32
2948	32
2949	32
2950	32
2951	32
2952	32
2953	32
2954	32
2955	32
2956	32
2957	32
2958	32
2959	32
2960	32
2961	32
2962	32
2963	32
2964	32
2965	32
2966	32
2967	32
2968	32
2969	32
2970	32
2971	32
2972	32
2973	32
2974	32
2975	32
2976	32
2977	32
2978	32
2979	32
2980	32
2981	32
2982	32
2983	32
2984	32
2985	32
2986	32
2987	32
2988	32
2989	32
2990	32
2991	32
2992	32
2993	32
2994	32
2995	32
2996	32
2997	32
2998	32
2999	32
3000	32



rti24: Sample 1F, Regulator Adapter Air Cup, Vertrel Solvent Wash, Nonvol. KBr Window



rti25: Sample 2aa, Regulator Body Diaphragm, Print Side, Vertrel Sol. Wash, NV KBr Win.






rti25: Sample 2aa, Regulator Body Diaphragm, Print Side, Vertrel Sol. Wash, NV. KBr Win.

Peak Pick


Intensity  
6233.104317  
7722.17714  
8888.75270  
9999.11071  
10000.22107  
11111.33170  
12222.44200  
13333.55250  
14444.66300  
15555.77350  
16666.88400  
17777.99450  
18888.10500  
19999.11550  
20000.12600  
21111.13650  
22222.14700  
23333.15750  
24444.16800  
25555.17850  
26666.18900  
27777.19950  
28888.21000  
29999.22050  
30000.23100  
31111.24150  
32222.25200  
33333.26250  
34444.27300  
35555.28350  
36666.29400  
37777.30450  
38888.31500  
39999.32550  
40000.33600  
41111.34650  
42222.35700  
43333.36750  
44444.37800  
45555.38850  
46666.39900  
47777.40950  
48888.42000  
49999.43050  
50000.44100  
51111.45150  
52222.46200  
53333.47250  
54444.48300  
55555.49350  
56666.50400  
57777.51450  
58888.52500  
59999.53550  
60000.54600  
61111.55650  
62222.56700  
63333.57750  
64444.58800  
65555.59850  
66666.60900  
67777.61950  
68888.63000  
69999.64050  
70000.65100  
71111.66150  
72222.67200  
73333.68250  
74444.69300  
75555.70350  
76666.71400  
77777.72450  
78888.73500  
79999.74550  
80000.75600  
81111.76650  
82222.77700  
83333.78750  
84444.79800  
85555.80850  
86666.81900  
87777.82950  
88888.84000  
89999.85050  
90000.86100  
91111.87150  
92222.88200  
93333.89250  
94444.90300  
95555.91350  
96666.92400  
97777.93450  
98888.94500  
99999.95550  
100000.96600

rti25: Sample 2aa, Regulator Body Diaphragm, Print Side, Vertrel Sol. Wash, NV KBr Win.





rti26: Sample 2aa Regulator Body Diaphragm, NonPrint Side, Vertrel Sol. Wash, NV KBr W.



rt126: Sample 2aa, Regulator Body Diaphragm, NonPrint Side, Vertrel Sol. Wash, NV. KBr W.

Peak Pick

Intensity


cm-1	1118
6281	4225
5881	5755
7721	3300
7808	5300
9106	8221
1110	5330
1114	5210
1117	7994
1121	0881
1123	0901
1145	0645
1158	4454
1173	4454
1291	9783
2915	2546
3302	4834
3343	2046

97	9691
94	8015
93	8491
93	3350
90	6657
88	5823
85	5803
77	2640
77	4887
84	5574
82	0444
80	4942
55	2335
55	7738
33	338
33	1





rti28: Sample 2aa Regulator Body, Deposits Already Extracted, KBr 7mm Dia. Pellet



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545




rt128: Sample 2aa, Regulator Body, Deposits Already Extracted, KBr 7mm Dia. Pellet

Peak Pick


cm-1	Intensity
4611.0978	63.5226
5133.3418	85.0330
6091.7791	74.2440
7711.2911	82.3418
7796.8051	77.5853
8115.2367	33.4816
11422.7773	41.8316
11689.5411	7.0530
12513.4130	27.4526
22924.6505	9.5890
3499.3345	7.5552
3499.3345	5.442

rti28: Sample 2aa Regulator Body, Deposits Already Extracted, KBr 7mm Dia. Pellet






rti29: Sample 2ab, Retaining Ring, Vertrel Solvent Wash, Nonvolatile on KBr Window








rti29: Sample 2ab, Retaining Ring, Vertrel Solvent Wash, Nonvolatile on KBr Window



rt130: Sample 2ac, Spring Carrier, Vertrel Solvent Wash, Nonvolatile on KBr Window



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545



Rti30: Sample 2ac, Spring Carrier, Vertrel Solvent Wash, Nonvolatile on KBr Window

Peak Pick


Intensity	Cm-1
97.660	884.773
98.556	816.801
99.201	709.373
101.451	631.723
103.030	532.140
105.707	493.064
107.977	457.557
109.448	429.060
111.503	397.064
114.511	371.557
117.519	349.064
121.527	327.557
124.535	306.064
128.543	285.557
132.551	266.064
136.559	248.557
140.567	233.064
144.575	219.557
148.583	207.064
152.591	196.557
156.599	187.064
160.607	179.557
164.615	173.064
168.623	168.557
172.631	165.064
176.639	163.557
180.647	163.064
184.655	163.557
188.663	164.064
192.671	165.557
196.679	168.064
200.687	171.557
204.695	176.064
208.703	181.557
212.711	188.064
216.719	195.557
220.727	204.064
224.735	214.557
228.743	226.064
232.751	239.557
236.759	254.064
240.767	270.557
244.775	288.064
248.783	307.557
252.791	328.064
256.799	350.557
260.807	374.064
264.815	400.557
268.823	429.064
272.831	460.557
276.839	494.064
280.847	540.557
284.855	590.064
288.863	643.557
292.871	701.064
296.879	763.557
300.887	831.064
304.895	904.557
308.903	982.064
312.911	1065.557
316.919	1155.064
320.927	1251.557
324.935	1355.064
328.943	1465.557
332.951	1582.064
336.959	1705.557
340.967	1836.064
344.975	1973.557
348.983	2118.064
352.991	2270.557
356.999	2430.064
360.007	2597.557
364.015	2773.064
368.023	2957.557
372.031	3160.064
376.039	3381.557
380.047	3622.064
384.055	3883.557
388.063	4166.064
392.071	4470.557
396.079	4795.064
400.087	5137.557
404.095	5508.064
408.103	5903.557
412.111	6324.064
416.119	6770.557
420.127	7243.064
424.135	7743.557
428.143	8272.064
432.151	8830.557
436.159	9418.064
440.167	10036.557
444.175	10686.064
448.183	11367.557
452.191	12081.064
456.199	12828.557
460.207	13610.064
464.215	14427.557
468.223	15272.064
472.231	16155.557
476.239	17078.064
480.247	18041.557
484.255	19046.064
488.263	20093.557
492.271	21185.064
496.279	22323.557
500.287	23510.064
504.295	24747.557
508.303	26037.064
512.311	27381.557
516.319	28783.064
520.327	30245.557
524.335	31771.064
528.343	33364.557
532.351	35028.064
536.359	36765.557
540.367	38580.064
544.375	40467.557
548.383	42431.064
552.391	44475.557
556.399	46604.064
560.407	48813.557
564.415	51108.064
568.423	53493.557
572.431	55965.064
576.439	58528.557
580.447	61189.064
584.455	63953.557
588.463	66817.064
592.471	69787.557
596.479	72861.064
600.487	76035.557
604.495	79307.064
608.503	82685.557
612.511	86198.064
616.519	89863.557
620.527	93681.064
624.535	97651.557
628.543	101783.064
632.551	106077.557
636.559	110535.064
640.567	115158.557
644.575	120049.064
648.583	125219.557
652.591	130671.064
656.599	136407.557
660.607	142431.064
664.615	148745.557
668.623	155353.064
672.631	162269.557
676.639	169498.064
680.647	177043.557
684.655	184910.064
688.663	193113.557
692.671	201659.064
696.679	210563.557
700.687	219833.064
704.695	229474.557
708.703	239494.064
712.711	249899.557
716.719	260707.064
720.727	271934.557
724.735	283489.064
728.743	295479.557
732.751	307913.064
736.759	320799.557
740.767	334147.064
744.775	347967.557
748.783	362269.064
752.791	377073.557
756.799	391993.064
760.807	407837.557
764.815	424617.064
768.823	442353.557
772.831	461069.064
776.839	480779.557
780.847	501509.064
784.855	523273.557
788.863	546087.064
792.871	569965.557
796.879	594925.064
800.887	620982.557
804.895	648154.064
808.903	676457.557
812.911	705909.064
816.919	736537.557
820.927	768369.064
824.935	801423.557
828.943	835733.064
832.951	871317.557
836.959	908105.064
840.967	946127.557
844.975	985405.064
848.983	1025969.557
852.991	1067837.064
856.999	1111039.557
860.007	1155507.064
864.015	1201371.557
868.023	1248661.064
872.031	1297407.557
876.039	1347649.064
880.047	1399327.557
884.055	1452581.064
888.063	1507449.557
892.071	1563973.064
896.079	1622193.557
900.087	1683151.064
904.095	1745897.557
908.103	1810473.064
912.111	1877939.557
916.119	1947737.064
920.127	2020927.557
924.135	2097569.064
928.143	2177713.557
932.151	2261439.064
936.159	2348707.557
940.167	2439609.064
944.175	2534227.557
948.183	2632643.064
952.191	2734937.557
956.199	2841199.064
960.207	2951517.557
964.215	3065983.064
968.223	3184587.557
972.231	3307429.064
976.239	3434617.557
980.247	3566143.064
984.255	3702257.557
988.263	3843079.064
992.271	3988739.557
996.279	4139367.064
1000.287	4295003.557
1004.295	4455869.064
1008.303	4622017.557
1012.311	4793619.064
1016.319	4969837.557
1020.327	5150843.064
1024.335	5336707.557
1028.343	5527599.064
1032.351	5723607.557
1036.359	5924913.064
1040.367	6131707.557
1044.375	6344179.064
1048.383	6561517.557
1052.391	6783943.064
1056.399	7011567.557
1060.407	7244589.064
1064.415	7482217.557
1068.423	7724659.064
1072.431	7971103.557
1076.439	8221749.064
1080.447	8476707.557
1084.455	8736207.064
1088.463	8999469.557
1092.471	9266723.064
1096.479	9538199.557
1100.487	9813987.064
1104.495	10094307.557
1108.503	10379269.064
1112.511	10663993.557
1116.519	10948599.064
1120.527	11233187.557
1124.535	11517879.064
1128.543	11802673.557
1132.551	12087569.064
1136.559	12372577.557
1140.567	12657707.557
1144.575	12942959.064
1148.583	13228333.557
1152.591	13513839.064
1156.599	13809467.557
1160.607	14105227.557
1164.615	14401119.064
1168.623	14697143.557
1172.631	14993299.064
1176.639	15289587.557
1180.647	15586007.557
1184.655	15882559.064
1188.663	16179243.557
1192.671	16476059.064
1196.679	16772997.557
1200.687	17070067.557
1204.695	17367259.064
1208.703	17664573.557
1212.711	17962009.064
1216.719	18259567.557
1220.727	18557249.064
1224.735	18855053.557
1228.743	19152979.064
1232.751	19451027.557
1236.759	19749197.557
1240.767	20047479.064
1244.775	20345873.557
1248.783	20644379.064
1252.791	20942997.557
1256.799	21241727.557
1260.807	21540569.064
1264.815	21839513.557
1268.823	22138569.064
1272.831	22437737.557
1276.839	22737017.557
1280.847	23036409.064
1284.855	23335893.557
1288.863	23635479.064
1292.871	23935167.557
1296.879	24234957.557
1300.887	24534849.064
1304.895	24834843.557
1308.903	25134939.064
1312.911	25435137.557
1316.919	25735437.557
1320.927	26035839.064
1324.935	26336343.557
1328.943	26636949.064
1332.951	26937657.557
1336.959	27238467.557
1340.967	27539379.064
1344.975	27840393.557
1348.983	28141509.064
1352.991	28442727.557
1356.999	28744147.557
1360.007	29045669.064
1364.015	29347293.557
1368.023	29649019.064
1372.031	29950837.557
1376.039	30252757.557
1380.047	30554789.064
1384.055	30856923.557
1388.063	31159159.064
1392.071	31461487.557
1396.079	31763907.557
1400.087	32066419.064
1404.095	32369023.557
1408.103	32671729.064
1412.111	32974527.557
1416.119	33277417.557
1420.127	33580409.064
1424.135	33883493.557
1428.143	34186679.064
1432.151	34489957.557
1436.159	34793327.557
1440.167	35096789.064
1444.175	35399353.557
1448.183	35702019.064
1452.191	36004787.557
1456.199	36307657.557
1460.207	36610629.064
1464.215	36913703.557
1468.223	37216829.064
1472.231	37519957.557
1476.239	37823187.557
1480.247	38126509.064
1484.255	38429923.557
1488.263	38733439.064
1492.271	39037057.557
1496.279	39340777.557
1500.287	39644599.064
1504.295	39948523.557
1508.303	40252549.064
1512.311	40556667.557
1516.319	40860887.557
1520.327	41165209.064
1524.335	41469633.557
1528.343	41774159.064
1532.351	42078787.557
1536.359	42383517.557
1540.367	42688349.064
1544.375	42993283.557
1548.383	43298319.064
1552.391	43603447.557
1556.399	43908677.557
1560.407	44214009.064
1564.415	44519433.557
1568.423	44824959.064
1572.431	45130587.557
1576.439	45436317.557
1580.447	45742149.064
1584.455	46048083.557
1588.463	46354119.064
1592.471	46660257.557
1596.479	46966497.557
1600.487	47272829.064
1604.495	47579263.557
1608.503	47885789.064
1612.511	48192417.557
1616.519	48499147.557
1620.527	48805959.064
1624.535	49112863.557
1628.543	

rti30: Sample 2ac, Spring Carrier, Vertrel Solvent Wash, Nonvolatile on KBr Window





rti34: Sample 2ad, Metal Diaphragm Retainer Interior, Vertrel SOL. Wash, NV KBr Win.




Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545

rti34: Sample 2ad, Metal Diaphragm Retainer Inserior, Vertrel Sol. Wash, NV KBr Win.

Peak Pick

cm-1	Intensity
696.1347	99.4227
804.5353	99.3302
1109.5116	99.3072
1120.7304	99.2701
1143.6104	99.2510
1174.3048	99.2270
1207.4342	99.2080
1243.3971	99.1895
1289.3711	99.1717
1337.3509	99.1547
1387.3357	99.1385
1439.3255	99.1231
1493.3193	99.1085
1549.3171	99.0947
1607.3149	99.0817
1667.3127	99.0695
1729.3105	99.0581
1793.3083	99.0475
1859.3061	99.0377
1927.3039	99.0287
1997.3017	99.0205
2069.2995	99.0131
2143.2973	99.0065
2219.2951	99.0007
2297.2929	99.0057
2377.2907	99.0015
2459.2885	99.0081
2543.2863	99.0155
2629.2841	99.0237
2717.2819	99.0327
2807.2797	99.0425
2899.2775	99.0531
2993.2753	99.0645
3089.2731	99.0767
3187.2709	99.0897
3287.2687	99.1035
3389.2665	99.1181
3493.2643	99.1335
3599.2621	99.1497
3707.2599	99.1667
3817.2577	99.1845
3929.2555	99.2031
4043.2533	99.2225
4159.2511	99.2427
4277.2489	99.2637
4397.2467	99.2855
4519.2445	99.3081
4643.2423	99.3315
4769.2401	99.3557
4897.2379	99.3807
5027.2357	99.4065
5159.2335	99.4331
5293.2313	99.4605
5429.2291	99.4887
5567.2269	99.5177
5707.2247	99.5475
5849.2225	99.5781
5993.2203	99.6095
6139.2181	99.6417
6287.2159	99.6747
6437.2137	99.7085
6589.2115	99.7431
6743.2093	99.7785
6899.2071	99.8147
7057.2049	99.8517
7217.2027	99.8895
7379.2005	99.9281
7543.1983	99.9675
7709.1961	99.9977
7877.1939	100.0000


rti34: Sample 2ad, Metal Diaphragm Retainer Interior, Vertrel Sol. Wash, NV KBr Win.



Transmittance



rti35: Sample 2ad, Metal Diaphragm Retainer, Already Extracted Residue, KBr 7mm Pellet




Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545

rti35: Sample 2ad, Metal Diaphragm Retainer, Already Extracted Residue, KBr 7mm Pellet

Peak Pick


Intensity	Wavenumber (cm-1)
92	3000
85	2950
80	2900
75	2850
70	2800
65	2750
60	2700
55	2650
50	2600
45	2550
40	2500
35	2450
30	2400
25	2350
20	2300
15	2250
10	2200
5	2150
5	2100
5	2050
5	2000
5	1950
5	1900
5	1850
5	1800
5	1750
5	1700
5	1650
5	1600
5	1550
5	1500
5	1450
5	1400
5	1350
5	1300
5	1250
5	1200
5	1150
5	1100
5	1050
5	1000
5	950
5	900
5	850
5	800
5	750
5	700
5	650
5	600
5	550
5	500
5	450
5	400
5	350
5	300
5	250
5	200
5	150
5	100

rti35: Sample 2ad, Metal Diaphragm Retainer, Already Extracted Residue, KBr 7mm Pellet





rti36: Sample 2ae Main Regulator Body, + 2ef, 2ag, & 2ah, Vertrel SOL. Wash NV KBr Win



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545

rti36: Sample 2ae, Main Regulator Body, + 2ef, 2ag, & 2ah, Vertrel Sol. Wash NV KBr Win

Peak Pick


CM-1	Intensity
545.1	881
588.1	632
809.1	77
1151.1	57
1152.1	57
1153.1	57
1154.1	57
1155.1	57
1156.1	57
1157.1	57
1158.1	57
1159.1	57
1160.1	57
1161.1	57
1162.1	57
1163.1	57
1164.1	57
1165.1	57
1166.1	57
1167.1	57
1168.1	57
1169.1	57
1170.1	57
1171.1	57
1172.1	57
1173.1	57
1174.1	57
1175.1	57
1176.1	57
1177.1	57
1178.1	57
1179.1	57
1180.1	57
1181.1	57
1182.1	57
1183.1	57
1184.1	57
1185.1	57
1186.1	57
1187.1	57
1188.1	57
1189.1	57
1190.1	57
1191.1	57
1192.1	57
1193.1	57
1194.1	57
1195.1	57
1196.1	57
1197.1	57
1198.1	57
1199.1	57
1200.1	57

Intensity
97.827
94.798
94.738
64.741
67.696
63.077
93.146
99.780
89.327
84.414





rti38: Sample 2aj, HP Diaphragm, Spring & Sleeve, Vertrel Sol. Wash, Nonvol. KBr Win.




Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545








rt139: Sample 2ak, Mating Half Reg. Adj. Adapter, Vertrel Sol. Wash, Nonvol. KBr Win.






rti39: Sample 2ak, Mating Half Reg. Adj. Adapter, Vertrel Sol. Wash, Nonvol. KBr Win.





rt140: Sample 2b, Green Hose, Interior, Vertrel Solvent Wash, Nonvolatile KBr Window




Aramet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545

rt40: Sample 2b, Green House, Vertrel Solvent Wash, Nonvolatile KBr Window

Peak Pick


Intensity	Retention Time
85.523	1.138
82.617	1.570
80.587	3.998
70.999	7.481
61.880	11.245
46.842	11.655
35.991	13.789
32.382	14.641
30.242	15.011
29.35	17.322
25.45	18.749
22.36	29.157
14.9	30.849

rti40: Sample 2b, Green Hose, Interior, Vertrel Solvent Wash, Nonvolatile KBr Window





rt131: Sample 3A, Valve Stem Exemplar, Vertrel Solvent Wash, Nonvolatile on KBr Window




Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545

rt131: Sample 3A, Valve Stem Exemplar, Vertrel Solvent Wash, Nonvolatile on KBr Window Peak Pick

cm-1	Intensity
451.37	97.659
466.803	97.327
540.103	98.577
582.844	93.309
758.012	95.469
833.011	93.542
1060.391	77.068
1147.811	72.184
1197.140	93.482
1381.105	94.155
1452.841	95.520
1852.341	99.7
2292.71	99.7
340	99




rt131: Sample 3A, Valve Stem Exemplar, Vertrel Solvent Wash, Nonvolatile on KBr Window





rt132: Sample 3B, Gland Nut Bore Exemplar, Vertrel Sol, Wash, NV KBr W.




rti32: Sample 3B, Gland Nut Bore Exemplar, Vertrel Sol. Wash, NV KBr W.

Peak Pick


cm-1	Intensity
5433.9660	98.6339
5240.9760	99.1422
5000.5603	99.6952
4758.0733	99.9522
4106.8012	77.2462
4097.7712	77.2288
4141.7222	77.3085
462.1328	69.1833
2925.8270	64.5896
2957.2704	88.1394
2339.7977	88.9750
339.9797	88.9750

rti32: Sample 3B, Gland Nut Bore Exemplar, Vertrel Sol, Wash, NV KBr W.






rti33: Sample 3C, Valve Seat Body Exemplar, Vertrel Solvent Wash, Nonvol. KBr Window






rti33: Sample 3C, Valve Seat Body Exemplar, Vertrel Solvent Wash, Nonvol. KBr Window






rti3: Tank Interior, Location A #1, Vertrel Solvent Wash, NV KBr Win.



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545




rt13: Tank Interior, Location A #1, Vertrel Solvent Wash, NV KBr Win.





rti4: Tank Interior, Location A #2, Vertrel Solvent Wash, NV KBr Win.



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545

rti4: Tank Interior, Location A #2, Vertrel Solvent Wash, NV KBr Win.


Peak Pick

Intensity	CM-1
95.465	599.1901
89.563	1022.680
88.967	1124.380
88.967	1143.380
88.967	1154.520
88.967	1165.200
88.967	1173.550
88.967	1185.220
88.967	1192.440
88.967	1207.800
88.967	1221.190
88.967	1244.710
88.967	1267.800
88.967	1285.550
88.967	1309.470
88.967	1332.400
88.967	1355.090
88.967	1377.500
88.967	1400.780
88.967	1424.910
88.967	1448.990
88.967	1473.020
88.967	1497.010
88.967	1520.960
88.967	1544.870
88.967	1568.740
88.967	1592.570
88.967	1616.360
88.967	1640.110
88.967	1663.820
88.967	1687.490
88.967	1711.120
88.967	1734.710
88.967	1758.260
88.967	1781.770
88.967	1805.240
88.967	1828.670
88.967	1852.060
88.967	1875.410
88.967	1898.720
88.967	1922.000
88.967	1945.240
88.967	1968.440
88.967	1991.600
88.967	2014.730
88.967	2037.830
88.967	2060.890
88.967	2083.920
88.967	2106.920
88.967	2129.890
88.967	2152.830
88.967	2175.740
88.967	2198.610
88.967	2221.450
88.967	2244.260
88.967	2267.040
88.967	2289.790
88.967	2312.510
88.967	2335.200
88.967	2357.860
88.967	2380.490
88.967	2403.090
88.967	2425.660
88.967	2448.200
88.967	2470.710
88.967	2493.190
88.967	2515.640
88.967	2538.060
88.967	2560.450
88.967	2582.810
88.967	2605.140
88.967	2627.440
88.967	2649.710
88.967	2671.960
88.967	2694.180
88.967	2716.370
88.967	2738.530
88.967	2760.660
88.967	2782.760
88.967	2804.830
88.967	2826.870
88.967	2848.880
88.967	2870.860
88.967	2892.810
88.967	2914.730
88.967	2936.620
88.967	2958.480
88.967	2980.310
88.967	3002.110
88.967	3023.880
88.967	3045.620
88.967	3067.330
88.967	3089.010
88.967	3110.660
88.967	3132.280
88.967	3153.870
88.967	3175.430
88.967	3196.960
88.967	3218.460
88.967	3239.930
88.967	3261.370
88.967	3282.780
88.967	3304.160
88.967	3325.510
88.967	3346.830
88.967	3368.120
88.967	3389.390
88.967	3410.630
88.967	3431.840
88.967	3453.020
88.967	3474.170
88.967	3495.290
88.967	3516.380
88.967	3537.440
88.967	3558.470
88.967	3579.470
88.967	3600.440
88.967	3621.380
88.967	3642.290
88.967	3663.170
88.967	3684.020
88.967	3704.840
88.967	3725.630
88.967	3746.390
88.967	3767.120
88.967	3787.820
88.967	3808.490
88.967	3829.130
88.967	3849.740
88.967	3870.320
88.967	3890.870
88.967	3911.390
88.967	3931.880
88.967	3952.340
88.967	3972.770
88.967	3993.170
88.967	4013.540
88.967	4033.880
88.967	4054.190
88.967	4074.470
88.967	4094.720
88.967	4114.940
88.967	4135.130
88.967	4155.290
88.967	4175.420
88.967	4195.520
88.967	4215.590
88.967	4235.630
88.967	4255.640
88.967	4275.620
88.967	4295.570
88.967	4315.490
88.967	4335.380
88.967	4355.240
88.967	4375.070
88.967	4394.870
88.967	4414.640
88.967	4434.380
88.967	4454.090
88.967	4473.770
88.967	4493.420
88.967	4513.040
88.967	4532.630
88.967	4552.190
88.967	4571.720
88.967	4591.220
88.967	4610.690
88.967	4630.130
88.967	4649.540
88.967	4668.920
88.967	4688.270
88.967	4707.590
88.967	4726.880
88.967	4746.140
88.967	4765.370
88.967	4784.570
88.967	4803.740
88.967	4822.880
88.967	4841.990
88.967	4861.070
88.967	4880.120
88.967	4899.140
88.967	4918.130
88.967	4937.090
88.967	4956.020
88.967	4974.920
88.967	4993.790
88.967	5012.630
88.967	5031.440
88.967	5050.210
88.967	5068.950
88.967	5087.660
88.967	5106.340
88.967	5125.000
88.967	5143.630
88.967	5162.230
88.967	5180.800
88.967	5199.340
88.967	5217.850
88.967	5236.330
88.967	5254.780
88.967	5273.200
88.967	5291.590
88.967	5310.950
88.967	5329.280
88.967	5347.580
88.967	5365.850
88.967	5384.090
88.967	5402.300
88.967	5420.480
88.967	5438.630
88.967	5456.750
88.967	5474.840
88.967	5492.900
88.967	5510.930
88.967	5528.930
88.967	5546.900
88.967	5564.840
88.967	5582.750
88.967	5600.630
88.967	5618.480
88.967	5636.300
88.967	5654.090
88.967	5671.850
88.967	5689.580
88.967	5707.280
88.967	5724.950
88.967	5742.590
88.967	5760.200
88.967	5777.780
88.967	5795.330
88.967	5812.850
88.967	5830.340
88.967	5847.800
88.967	5865.230
88.967	5882.630
88.967	5900.000
88.967	5917.340
88.967	5934.650
88.967	5951.930
88.967	5969.180
88.967	5986.400
88.967	6003.590
88.967	6020.750
88.967	6037.880
88.967	6054.980
88.967	6072.050
88.967	6089.090
88.967	6106.100
88.967	6123.080
88.967	6140.030
88.967	6156.950
88.967	6173.840
88.967	6190.700
88.967	6207.530
88.967	6224.330
88.967	6241.100
88.967	6257.840
88.967	6274.550
88.967	6291.230
88.967	6307.880
88.967	6324.500
88.967	6341.090
88.967	6357.650
88.967	6374.180
88.967	6390.680
88.967	6407.150
88.967	6423.590
88.967	6440.000
88.967	6456.380
88.967	6472.730
88.967	6489.050
88.967	6505.340
88.967	6521.600
88.967	6537.830
88.967	6554.030
88.967	6570.200
88.967	6586.340
88.967	6602.450
88.967	6618.530
88.967	6634.580
88.967	6650.600
88.967	6666.590
88.967	6682.550
88.967	6698.480
88.967	6714.380
88.967	6730.250
88.967	6746.090
88.967	6761.900
88.967	6777.680
88.967	6793.430
88.967	6809.150
88.967	6824.840
88.967	6840.500
88.967	6856.130
88.967	6871.730
88.967	6887.300
88.967	6902.840
88.967	6918.350
88.967	6933.830
88.967	6949.280
88.967	6964.700
88.967	6980.090
88.967	6995.450
88.967	7010.780
88.967	7026.080
88.967	7041.350
88.967	7056.590
88.967	7071.800
88.967	7087.000
88.967	7102.170
88.967	7117.310
88.967	7132.420
88.967	7147.500
88.967	7162.550
88.967	7177.570
88.967	7192.560
88.967	7207.520
88.967	7222.450
88.967	7237.350
88.967	7252.220
88.967	7267.060
88.967	7281.870
88.967	7296.650
88.967	7311.400
88.967	7326.120
88.967	7340.810
88.967	7355.470
88.967	7370.100
88.967	7384.700
88.967	7399.270
88.967	7413.810
88.967	7428.320
88.967	7442.800
88.967	7457.250
88.967	7471.670
88.967	7486.060
88.967	7500.420
88.967	7514.750
88.967	7529.050
88.967	7543.320
88.967	7557.560
88.967	7571.770
88.967	7585.950
88.967	7600.100
88.967	7614.220
88.967	7628.310
88.967	7642.370
88.967	7656.400
88.967	7670.400
88.967	7684.370
88.967	7698.310
88.967	7712.220
88.967	7726.100
88.967	7740.950
88.967	7754.770
88.967	7768.560
88.967	7782.320
88.967	7796.050
88.967	7809.750
88.967	7823.420
88.967	7837.060
88.967	7850.670
88.967	7864.250
88.967	7877.800
88.967	7891.320
88.967	7904.810
88.967	7918.270
88.967	7931.700
88.967	7945.100
88.967	7958.470
88.967	7971.810
88.967	7985.120
88.967	7998.400
88.967	8011.650
88.967	8024.870
88.967	8038.060
88.967	8051.220
88.967	8064.350
88.967	8077.450
88.967	8090.520
88.967	8103.560
88.967	8116.570
88.967	8129.550
88.967	8142.500
88.967	8155.420
88.967	8168.310
88.967	8181.170
88.967	8194.000
88.967	8206.800
88.967	8219.570
88.967	8232.310
88.967	8245.020
88.967	8257.700
88.967	8270.350
88.967	8282.970
88.967	8295.560
88.967	8308.120
88.967	8320.650
88.967	8333.150
88.967	8345.620
88.967	8358.060
88.967	8370.470
88.967	8382.850
88.967	8395.200
88.967	8407.520
88.967	8419.810
88.967	8432.070
88.967	8444.300
88.967	8456.500
88.967	8468.670
88.967	8480.810
88.967	8492.920
88.967	8505.000
88.967	8517.050
88.967	8529.070
88.967	8541.060
88.967	8553.020
88.967	8564.950
88.967	8576.850
88.967	8588.720
88.967	






rt15: Tank Interior, Location B, Verrel Solvent Wash, Nonvolatile on KBr Window



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545




rt15: Tank Interior, Location B, Vertrel Solvent Wash, Nonvolatile on KBr Window






rt16: Tank Interior, Location C, Vertrel Solvent Wash, Nonvolatile on KBr Window



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545




rti6: Tank Interior, Location C, Vertrel Solvent Wash, Nonvolatile on KBr Window





rti7: Tank Interior, Location C', Vertrel Solvent Wash, Nonvolatile on KBr Window



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545

rti7: Tank Interior, Location C', Vertical Solvent Wash, Nonvolatile on KBr Window


Peak Pick

Intensity

98.840  
 97.800  
 96.900  
 96.000  
 95.100  
 94.200  
 93.300  
 92.400  
 91.500  
 90.600  
 89.700  
 88.800  
 87.900  
 87.000  
 86.100  
 85.200  
 84.300  
 83.400  
 82.500  
 81.600  
 80.700  
 79.800  
 78.900  
 78.000  
 77.100  
 76.200  
 75.300  
 74.400  
 73.500  
 72.600  
 71.700  
 70.800  
 69.900  
 69.000  
 68.100  
 67.200  
 66.300  
 65.400  
 64.500  
 63.600  
 62.700  
 61.800  
 60.900  
 60.000  
 59.100  
 58.200  
 57.300  
 56.400  
 55.500  
 54.600  
 53.700  
 52.800  
 51.900  
 51.000  
 50.100  
 49.200  
 48.300  
 47.400  
 46.500  
 45.600  
 44.700  
 43.800  
 42.900  
 42.000  
 41.100  
 40.200  
 39.300  
 38.400  
 37.500  
 36.600  
 35.700  
 34.800  
 33.900  
 33.000  
 32.100  
 31.200  
 30.300  
 29.400  
 28.500  
 27.600  
 26.700  
 25.800  
 24.900  
 24.000  
 23.100  
 22.200  
 21.300  
 20.400  
 19.500  
 18.600  
 17.700  
 16.800  
 15.900  
 15.000  
 14.100  
 13.200  
 12.300  
 11.400  
 10.500  
 9.600  
 8.700  
 7.800  
 6.900  
 6.000  
 5.100  
 4.200  
 3.300  
 2.400  
 1.500  
 0.600  
 0.700  
 0.800  
 0.900  
 1.000  
 1.100  
 1.200  
 1.300  
 1.400  
 1.500  
 1.600  
 1.700  
 1.800  
 1.900  
 2.000  
 2.100  
 2.200  
 2.300  
 2.400  
 2.500  
 2.600  
 2.700  
 2.800  
 2.900  
 3.000  
 3.100  
 3.200  
 3.300  
 3.400  
 3.500  
 3.600  
 3.700  
 3.800  
 3.900  
 4.000  
 4.100  
 4.200  
 4.300  
 4.400  
 4.500  
 4.600  
 4.700  
 4.800  
 4.900  
 5.000  
 5.100  
 5.200  
 5.300  
 5.400  
 5.500  
 5.600  
 5.700  
 5.800  
 5.900  
 6.000  
 6.100  
 6.200  
 6.300  
 6.400  
 6.500  
 6.600  
 6.700  
 6.800  
 6.900  
 7.000  
 7.100  
 7.200  
 7.300  
 7.400  
 7.500  
 7.600  
 7.700  
 7.800  
 7.900  
 8.000  
 8.100  
 8.200  
 8.300  
 8.400  
 8.500  
 8.600  
 8.700  
 8.800  
 8.900  
 9.000  
 9.100  
 9.200  
 9.300  
 9.400  
 9.500  
 9.600  
 9.700  
 9.800  
 9.900  
 10.000


Anamet, Inc.  
 26102 Eden Landing Road  
 Suite 3  
 Hayward, CA 94545

rti7: Tank Interior, Location C', Vertrel Solvent Wash, Nonvolatile on KBr Window






rti8: Tank Interior, Location D, Vertrel Solvent Wash, Nonvolatile on KBr Window



Anamet, Inc.  
26102 Eden Landing Road  
Suite 3  
Hayward, CA 94545




rt18: Tank Interior, Location D, Vertrel Solvent Wash, Nonvolatile on KBr Window






rt19: Tank Exterior, Yellow Paint, Vertrel Solvent Extracted, Nonvolatile, KBr Window






rtt19: Tank Exterior, Yellow Paint, Vertrel Solvent Extracted, Nonvolatile, KBr window





RT111: Tank Interior, White Material, Six Inches to Right of Location A, KBr Pellet




RT111: Tank Interior, White Material, Six Inches to Right of Location A, KBr Pellet

Peak Pick

Intensity
93.197
75.971
93.285
32.859
31.882
31.519
22.957
22.557
15.254
15.621
7.071

cm-1
468.732
601.341
677.266
1140.000
1432.233
1685.819
2282.265
2405.330
2457.341
2471.487
297.297
347.297
533.333
587.587
641.641
695.695
749.749
803.803
857.857
911.911
965.965
1019.101
1073.107
1127.112
1181.118
1235.123
1289.128
1343.134
1397.139
1451.145
1505.150
1559.155
1613.161
1667.166
1721.172
1775.177
1829.182
1883.188
1937.193
1991.199
2045.204
2099.209
2153.215
2207.220
2261.226
2315.231
2369.236
2423.242
2477.247
2531.253
2585.258
2639.263
2693.269
2747.274
2801.280
2855.285
2909.290
2963.296
3017.301
3071.307
3125.312
3179.317
3233.323
3287.328
3341.334
3395.339
3449.344
3503.350
3557.355
3611.361
3665.366
3719.371
3773.377
3827.382
3881.388
3935.393
3989.398
4043.404
4097.409
4151.415
4205.420
4259.425
4313.431
4367.436
4421.442
4475.447
4529.452
4583.458
4637.463
4691.469
4745.474
4799.479
4853.485
4907.490
4961.496
5015.501
5069.506
5123.512
5177.517
5231.523
5285.528
5339.533
5393.539
5447.544
5501.550
5555.555
5609.560
5663.566
5717.571
5771.577
5825.582
5879.587
5933.593
5987.598
6041.604
6095.609
6149.614
6203.620
6257.625
6311.631
6365.636
6419.641
6473.647
6527.652
6581.658
6635.663
6689.668
6743.674
6797.677
6851.685
6905.690
6959.695
7013.701
7067.706
7121.712
7175.717
7229.722
7283.728
7337.733
7391.739
7445.744
7499.749
7553.755
7607.760
7661.766
7715.771
7769.776
7823.782
7877.787
7931.793
7985.798
8039.803
8093.809
8147.814
8201.820
8255.825
8309.830
8363.836
8417.841
8471.847
8525.852
8579.857
8633.863
8687.867
8741.874
8795.879
8849.884
8903.890
8957.895
9011.901
9065.906
9119.911
9173.917
9227.922
9281.928
9335.933
9389.938
9443.943
9497.947
9551.951
9605.955
9659.965
9713.971
9767.976
9821.981
9875.985
9929.992
9983.998
10037.10037

RT111: Tank Interior, White Material, Six Inches to Right of Location A, KBr Pellet







March 22, 2012

Lab. No. 5004.7109 RTI Group

**FTIR Spectra Characterization**

Sample	Part No.	Spectrum No.	Characterization
Tank Interior	Loc. A, #1	rti3	vinyl acetate and ester type polymers + calcium sulfate
Tank Interior	Location A, #2	rti4	calcium sulfate + ester type polymer
Tank Interior	Location B	rti5	calcium sulfate + ester type polymers
Tank Interior	Location C	rti6	calcium sulfate
Tank Interior	Location C'	rti7	terephthalate type polyester
Tank Interior	Location D	rti8	calcium sulfate
Tank Exterior	Yellow Paint	rti9	terephthalate type polyester
Tank Interior	White material 6" to right of Location A	rti11	calcium sulfate
Valve Seat Body	1A	rti13	fluoro-polymer
Valve Stem	1B	rti16	fluoro-polymer (fluorine confirmed by EDS)
Relief Valve	1C	rti18	fluoro-polymer
Gland Nut	1D	rti19	fluoro-polymer
Valve Body	1E, 22mm orifice	rti20	silicate(s) + ammonium salt + oxides
Valve Body	1E, 18mm orifice	rti21	silicate(s) + ammonium salt + oxides
Valve Body	1E, 12mm orifice	rti22	silicate(s) + ammonium salt + oxides
Valve Body	1E, 5mm orifice	rti23	oxides
Regulator Adapter Air Cup	1F	rti24	fluoro-polymer
Regulator Body Diaphragm	2aa, Print Side	rti25	aromatic ester
Regulator Body Diaphragm	2aa, Non-Print Side	rti26	aromatic ester
Regulator Body	2aa, Non-Print Side	rti28	calcium sulfate + calcium carbonate



**Anamet, inc. MATERIALS ENGINEERING & LABORATORY TESTING**  
26102 Eden Landing Road Suite 3-Hayward CA 94545(510)887-8811-Fax (510)887-8427

**FTIR Spectra Characterization**

Sample	Part No.	Spectrum No.	Characterization
Retaining Ring	2ab	rti29	fluoro-polymer + ester
Spring Carrier	2ac	rti30	fluoro-polymer
Metal Diaphragm Retainer, Interior	2ad	rti34	fluoro-polymer + ester
Metal Diaphragm Retainer	2ad	rti35	fluoro-polymer + silicate(s) + oxides
Main Regulator Body	2ae, 2ef, 2ag, & 2ah	rti36	fluoro-polymer + ester
High Pressure Diaphragm & Adjustment Sleeve	2aj'	rti38	fluoro-polymer + ester
Mating Half regulator Adjuster Adapter	2ak	rti39	fluoro-polymer
Green Hose, Interior	2b	rti40	phthalate type ester
Valve Stem Exemplar	3A	rti31	fluoro-polymer
Gland Nut Bore Exemplar	3B	rti32	fluoro-polymer
Valve Seat Body Exemplar	3C	rti33	fluoro-polymer + ester

Submitted by:

---

Harold R. Harlan,  
Director, Organic Chemistry Laboratories

# ATTACHMENT 9

Micrographs with HF Etch and Kellers Etch  
*Micrograph images, in order of appearance*

## HF Etch

Sample A Center 50x  
Sample A Center 200x  
Sample A Fracture 50x  
Sample A Fracture 200x  
Sample A Inside Surface 50x  
Sample A Inside Surface 200x

Sample B Center 50x  
Sample B Center 200x  
Sample B Fracture 50x  
Sample B Fracture 200x

Sample C Center 50x  
Sample C Center 200x  
Sample C Fracture 50x  
Sample C Fracture 200x

Sample D Center 50x  
Sample D Center 200x  
Sample D Fracture 50x  
Sample D Fracture 200x  
Sample D Outside Surface 50x  
Sample D Outside Surface 200x



## Attachment 9, continued

### Kellers Etch


Sample A Center 50x  
Sample A Center 200x  
Sample A Fracture 50x  
Sample A Fracture 200x  
Sample A Inside Surface 50x  
Sample A Inside Surface 200x

Sample B Center 50x  
Sample B Center 200x  
Sample B Fracture 50x  
Sample B Fracture 200x


Sample C Center 50x  
Sample C Center 200x  
Sample C Fracture 50x  
Sample C Fracture 200x

Sample D Center 50x  
Sample D Center 200x  
Sample D Fracture 50x  
Sample D Fracture 200x  
Sample D Outside Surface 50x  
Sample D Outside Surface 200x










0.25 mm






0.05 mm






0.25 mm






0.05 mm





0.25 mm






0.05 mm






0.25 mm






0.05 mm











0.05 mm





0.25 mm






0.05 mm






0.25 mm






0.05 mm






0.25 mm






0.05 mm





0.25 mm






0.05 mm






0.25 mm






0.25 mm






0.05 mm






0.25 mm






0.05 mm






0.25 mm






0.02 mm






0.25 mm






0.05 mm






0.25 mm






0.05 mm






0.25 mm






0.05 mm






0.25 mm






0.05 mm






0.25 mm






0.05 mm






0.25 mm






0.05 mm





0.25 mm





0.05 mm



# ATTACHMENT 10

## Microhardness Testing





**Anamet, inc** *Materials Engineering & Laboratory Testing*  
 26102 EDEN LANDING ROAD, SUITE 3 • HAYWARD, CALIFORNIA 94545 • (510) 887-8811 • FAX (510) 887-8427

Table 1  
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample A** from  
 Tank Outside Surface to Tank Inside Surface

Distance (inch)	HK500	Converted HRB
0.000	Outside Surface	
0.010	93.7	25
0.030	99.9	33
0.050	99.2	32
0.070	101.9	36
0.090	99.6	33
0.110	104.0	38
0.130	106.2	41
0.150	101.0	35
0.170	89.0	18
0.177	82.7	8
0.184	Inside Surface	

Table 2  
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample A** from  
 Tank Fracture Edge towards Tank Center

Distance (inch)	HK500	Converted HRB
0.000	Fracture Edge	
0.010	102.4	36
0.020	102.2	36
0.070	92.2	23
0.170	98.3	31
0.270	101.3	35
0.370	95.9	28
0.470	100.9	34
0.570	103.6	38
0.620	110.0	45
0.670	106.6	41





**Anamet, inc** *Materials Engineering & Laboratory Testing*  
 26102 EDEN LANDING ROAD, SUITE 3 • HAYWARD, CALIFORNIA 94545 • (510) 887-8811 • FAX (510) 887-8427

Table 3  
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample B** from  
 Tank Outside Surface to Tank Inside Surface

Distance (inch)	HK500	Converted HRB
0.000	Outside Surface	
0.010	122.3	59
0.020	123.7	61
0.030	121.7	59
0.060	117.9	53
0.100	116.8	53
0.130	122.6	60
0.160	118.3	53
0.200	125.8	63
0.230	133.6	67
0.260	124.7	62
0.290	128.0	64
0.320	122.9	60
0.350	125.9	63
0.358	128.3	64
0.363	Inside Surface	

Table 4  
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample B** from  
 Tank Fracture Edge towards Tank Center

Distance (inch)	HK500	Converted HRB
0.000	Fracture Edge	
0.010	128.5	64
0.020	131.7	66
0.030	133.0	66
0.080	130.7	65
0.130	121.0	58
0.180	127.5	64
0.230	128.0	64
0.280	128.8	64
0.330	125.3	62
0.380	120.8	58
0.430	129.8	65
0.480	119.3	56
0.530	117.3	53
0.580	122.7	60





**Anamet, inc** *Materials Engineering & Laboratory Testing*  
 26102 EDEN LANDING ROAD, SUITE 3 • HAYWARD, CALIFORNIA 94545 • (510) 887-8811 • FAX (510) 887-8427

Table 5  
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample C** from  
 Tank Outside Surface to Tank Inside Surface

Distance (inch)	HK500	Converted HRB
0.000	Outside Surface	
0.010	116.5	52
0.020	119.6	57
0.030	117.9	55
0.060	117.5	55
0.100	116.2	52
0.130	115.5	51
0.160	115.0	51
0.200	117.0	53
0.230	120.3	57
0.260	125.3	62
0.290	122.0	59
0.320	123.0	60
0.350	122.8	60
0.358	121.3	58
0.364	Inside Surface	

Table 6  
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample C** from  
 Tank Fracture Edge towards Tank Center

Distance (inch)	HK500	Converted HRB
0.000	Fracture Edge	
0.010	128.6	64
0.020	135.0	67
0.030	131.3	65
0.080	128.3	64
0.130	133.9	67
0.180	127.5	63
0.230	126.3	63
0.280	123.8	61
0.330	122.5	59
0.380	122.1	59
0.430	121.4	58
0.480	118.0	55
0.530	124.9	62
0.580	117.2	53





**Anamet, inc** *Materials Engineering & Laboratory Testing*  
 26102 EDEN LANDING ROAD, SUITE 3 • HAYWARD, CALIFORNIA 94545 • (510) 887-8811 • FAX (510) 887-8427

Table 7  
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample D** from  
 Tank Outside Surface to Tank Inside Surface

Distance (inch)	HK500	Converted HRB
0.000	Outside Surface	
0.010	121.3	58
0.020	130.3	65
0.030	123.4	60
0.060	126.4	63
0.100	126.0	63
0.130	120.1	57
0.160	122.8	60
0.200	125.7	63
0.230	121.0	58
0.260	126.1	63
0.290	121.1	58
0.320	125.4	62
0.350	128.2	64
0.357	Inside Surface	

Table 8  
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample D** from  
 Tank Fracture Edge towards Tank Center


Distance (inch)	HK500	Converted HRB
0.000	Fracture Edge	
0.010	121.6	59
0.020	127.3	63
0.030	132.9	66
0.080	142.8	71
0.114	141.9	71
0.164	133.9	67
0.214	132.0	66
0.264	124.8	62
0.314	125.9	63
0.364	125.2	62
0.414	126.1	63
0.464	129.0	64
0.514	126.7	63
0.564	127.5	64
0.614	130.9	65
0.654	125.6	63



# ATTACHMENT 11

## Tensile and Compression Testing





**Test Summary**

Counter: 13137  
 Elapsed Time: 00:01:05  
 Anamet Job Number: 5004.7104  
 Specimen Identification: 1  
 Operator: eaf/bck  
 Comments: Compression Lenght 1.503"  
 Procedure Name: Compression Load  
 Start Date: 3/14/2012  
 Start Time: 10:37:20 AM  
 End Date: 3/14/2012  
 End Time: 10:38:25 AM  
 Workstation: MECH  
 Tested By: Brian  
 Customer: RTI

**Test Results**

Load at Peak Load: 10010.1900 lbf  
 Position at Peak Load: 0.2137 in  
 Halt of Force Yield: 10010.1900 lbf  
 Width: 0.5000 in  
 Length: *(Thickness)* 0.3480 in  
 Area: 0.1740 in<sup>2</sup>





**Anamet, inc**


**Anamet, inc** *Materials Engineering & Laboratory Testing*

26102 EDEN LANDING ROAD, SUITE 3 • HAYWARD, CALIFORNIA 94545 • (510) 887-8811 • FAX (510) 887-8427

Table 1  
Results of Tensile Test on a Specimen from the SCUBA Tank

Property		Tank	
Dimensions of Specimen	Width	0.509	inch
	Thickness	0.381	inch
Area		0.194	inch <sup>2</sup>
Tensile Load		9965	lbs
Tensile Strength		51400	psi
Yield Load 0.2% Offset		8937	lbs
Yield Strength 0.2% Offset		46100	psi
Specimen Length	After		inch
	Before	5.187	inch
Elongation		0.30	inch
Elongation in 2.0" Gage		15	%





**Test Summary**

Counter: 13136  
 Elapsed Time: 00:03:15  
 Anamet Job Number: 5004.7109  
 Specimen Identification: 1  
 Operator: eaf/bck  
 Procedure Name: Tensile 2in. Ext.  
 Start Date: 3/14/2012  
 Start Time: 10:16:20 AM  
 End Date: 3/14/2012  
 End Time: 10:19:35 AM  
 Workstation: MECH  
 Tested By: Brian  
 Customer: RTI  
 Comments:

**Test Results**

Tensile Strength: 51392.4700 psi  
 Peak Load: 9965.0000 lbf  
 Young's Modulus: 8.07e+006 psi  
 Area: 0.1939 in<sup>2</sup>  
 Stress at Break: 2764.3120 psi  
 Load at Break: 536.0000 lbf  
 Halt of Force Yield: 9486.0000 lbf  
 Load at Offset: 8937.8910 lbf  
 Stress at Offset: 46095.3700 psi  
 Width: 0.5090 in  
 Thickness: 0.3810 in



# ATTACHMENT 12

## Scanning Electron Microscope Images *SEM images, in order of appearance*


Pressure Regulator Adaptor 1 – 150x  
Pressure Regulator Adaptor Air Cup 2 - 100x  
Pressure Regulator Adaptor 1 – 25x  
Pressure Regulator Adaptor 2 – 500x  
Pressure Regulator Adaptor 3 – 27x  
Pressure Regulator Adaptor 4 – 500x  
Pressure Regulator Adaptor 5 – 27x  
Pressure Regulator Adaptor 6 – 500x  
Pressure Regulator Adaptor 7 – 27x  
Pressure Regulator Adaptor 8 – 500x

Cylinder Inside Surface A 1 – 40x

Valve Seat Body Exemplar 1 – 14x  
Valve Seat Body Exemplar 2 – 14x  
Valve Seat Body Subject 1 – 14x  
Valve Seat Body Subject 2 – 14x

Valve Stem 1 – 40x  
Valve Stem 2 – 40x  
Valve Stem 3 – 40x  
Valve Stem 4 – 40x  
Valve Stem 5 – 40x  
Valve Stem 6 – 500x  
Valve Stem 7 – 1000x  
Valve Stem 8 – 500x






20.0kV 18.1mm x150 SE

300um






20.0kV 22.4mm x100 SE

500um






20.0kV 18.8mm x25 SE

2.00mm






20.0kV 18.6mm x500 SE

100um






20.0kV 16.2mm x27 SE

2.00mm






20.0kV 16.1mm x500 SE

100um






20.0kV 16.1mm x27 SE

2.00mm





20.0kV 15.5mm x500 SE

100um






20.0kV 16.1mm x27 SE

2.00mm






20.0kV 16.1mm x500 SE

100um





20.0kV 10.8mm x40 SE

1.00mm






20.0kV 38.4mm x14 SE

4.00mm






20.0kV 38.1mm x14 SE

4.00mm






20.0kV 37.3mm x14 SE

4.00mm






20.0kV 36.8mm x14 SE

4.00mm






20.0kV 10.4mm x40 SE

This scanning electron micrograph (SEM) shows a cross-section of a material. The top edge is dark and appears to be a substrate or a thin layer. Below this, there is a thick, dark, granular layer. The bottom portion of the image shows a lighter, fibrous or porous structure. A scale bar is visible at the bottom right, indicating a length of 1.00mm. The image is labeled with technical parameters: 20.0kV, 10.4mm, x40, and SE.

1.00mm






20.0kV 10.4mm x40 SE

1.00mm






20.0kV 10.4mm x40 SE

1.00mm




20.0kV 10.4mm x40 SE

1.00mm








20.0kV 10.4mm x40 SE

1.00mm






20.0kV 10.4mm x500 SE

100um






20.0kV 10.5mm x1.00k SE

50.0um





20.0kV 10.1mm x500 SE

100um





# ATTACHMENT 13


Inspection Photos of Jun. 8, 2012

Images of interior surface combustion area




















































# ATTACHMENT 14

## Surface Curvature Measurements








# ATTACHMENT 15

## Cylinder Valve Markings




























# ATTACHMENT 16

## Chain of Custody





**RTI Group, LLC**  
910 Bestgate Road, Suite E  
Annapolis, MD 21401  
ofc: +1 410 571 0712 | fax: +1 410 571 0713  
www.rtiForensics.com

### **CHANGE OF EVIDENCE CUSTODY RECORD**

**DATE:** November 22, 2011

**RTI File Name:** DOT – Ruptured Scuba Cylinder

**RTI File No.:** 50151.ME002

***The evidence herein described has been transferred on this date - -***

**To:** Richard Loucks, PhD, PE

**From:** U.S. Dept of Transportation  
Property Inventory Report

**Company:** RTI Group, LLC

**Company:**

#### ***Description of Evidence (Note all markings):***

1. **SEE ATTACHED LIST.**

Authorization of **Sending** Party:

Authorization of **Receiving** Party:

(Signature & Date)

(Signature & Date )

(Printed)

(Printed)

Richard B. Loucks, PhD, PE



Matter: 50151ME002

Matter Name: DOT – Ruptured SCUBA Cylinder

#### Evidence Inventory

##### 1) Yellow high pressure gas cylinder, Part 1

Smaller fragment from the cylinder, approximately 12 inch by 6 inch. Has the following marks at near the neck:

DOT-3AL 3000                      HY-MARK

Cylinder has two decals

Decal 1: OXYGEN for decompression use only – MOD (Maximum Operating Depth) 20 FSW (20 feet submerged water), MOD 6 MSW (6 meters submerged water), International Association of Nitrox & Technical Divers, Inc.

Decal 2: “Tank & Valve Have Been Cleaned For Premix, Oxygen Content 22 to 40%” is not punched out. “Tank & Valve Have Been Cleaned In Accordance With O<sub>2</sub> Service” Is punched out at 2011. The month is uncertain.

##### 2) Yellow high pressure gas cylinder, Part 2

Larger section, contains the bottom, neck and valve opening, measures about 24 inches by 14 inches. Has the following markings near the neck:

OU 0001 M5442 10 07 S40 TC-3AL 207

3) High Pressure Tank Valve, DIN Valve, manufactured by Genesis. 5000 psi, 30 lb/hr CG-1 type rupture disk. Oxygen (Fire Toxicity State and Corrosiveness FTSC Code 4160: 4 -highly oxidizing, 1-nontoxic, 6-nonliquefied gas between 500 and 3000 psig, 0-noncorrosive, Class 2 Division 2.2 gas) use permits CG-1 (required in one end of the cylinder, regardless of length). A pressure regulator adaptor is present in the opening which has a fractured outlet. The metal particle filter is evident in the opening.

3) Regulator by Dive Rite, serial number 12008135, fitted with regulator fitting. The opening is occupied by the fractured end of the pressure regulator adaptor


#### Attached:

1. Black pressure line with dial gage on high pressure side of regulator. Dial gage face is heat affected and the gage is illegible.
2. Length of green pressure line stating “WARNING Do not exceed 250 psi (17 bar) high pressure may cause damage or personal injury” no manufacturer identified. Distal end terminates unattached. Low pressure side









**Anamet, inc**

Materials Engineering & Laboratory Testing, Since 1958

**EVIDENCE CHANGE OF CUSTODY RECORD**

Date Received/Shipped/Transferred: July 2, 2012

Anamet, Inc. File No: 5004.7532

Anamet, Inc. File Name: RTI Group RTI File 50151.ME002  
RTI File Name: DOT Ruptured

Scuba Cylinder

The evidence herein described has been transferred on this date to:

Matthew Wagmhofer  
Name (Please Print)

Representing: RTI Group  
Company Name (Please Print)

From: Norman Yuen  
Name (Please Print)

Name Representing: Anamet  
Company Name (Please Print)

**Description of Evidence:**


Two halves tensile specimen  
One tank valve body

Signatures:  
To: [Signature]  
From: [Signature]

Date: 7/9/12



## CHANGE OF CUSTODY RECORD

DATE:	TBD			
RTI File Name:	DOT – Ruptured Scuba Cylinder			
RTI File No.:	50151.ME002			
<b><i>The evidence herein described has been transferred on this date - -</i></b>				
To:	<b>TBD</b>		From:	<b>Richard B. Loucks, PhD, PE</b>
Company:	<b>U.S. Department of Transportation Pipeline and Hazardous Materials Safety Admin. 1200 New Jersey Ave., SE Room E21-338 Washington, DC 20590</b>		Company:	<b>RTI Group, LLC 910 Bestgate Rd., Suite E Annapolis, MD 21401</b>
<b><i>Description of Evidence (Note all markings):</i></b>				
1. See attached description of evidence listing.				
2.				
3.				
4.				
5.				
6.				
<b><i>Authorization:</i></b>				
Authorization of <b>Sending</b> Party:		Authorization of <b>Receiving</b> Party:		
(Signature)		(Signature)		
<b>(Printed: name, company, address)</b>		<b>(Printed: name, company, address)</b>		
<b>Richard B. Loucks, PhD, PE RTI Group, LLC 910 Bestgate Rd., Suite E Annapolis, MD 21401</b>				



## CHANGE OF EVIDENCE CUSTODY RECORD

RTI File Name: DOT-Ruptured Scuba Cylinder  
RTI File No.: 50151.ME002

Description of Evidence Listing  
Date \_\_\_\_\_

Contained in	Further contained in	Further contained in	Item	Part No.	Description
Bag "Tank Mounts A,B,C,D"			Sample A	1-a-i	Hardness tested sample
			Sample B	1-b-i	Hardness tested sample
			Sample C	1-c-i	Hardness tested sample
			Sample D	1-d-i	Hardness tested sample
Tupperware container 1			Fragment of the Scuba Tank	2	Approx. 6"x12". Two Decals.
Bag 2	Bag "Subject Valve - Relief Valve"		Relief Valve	3-a	Intact 5000psi burst disk in a hollow threaded bolt
	Bag "Subject Valve - Vave Seat Body"		Valve Seat Body	3-b	Threads coated green. Rectangular hollow.
	Bag "Subject Valve - Gand Nut"		Gland Nut	3-c	Threaded, hex head.
			O Ring	3-c-i	Black polymer, approx 1/2" diameter
	Bag "Subject Valve - Valve Stem"		Valve Stem	3-d	Steel stem, approx 1 1/8" in length
			O Ring	3-d-i	Brown Polymer, approx 3/8" diameter
			O Ring	3-d-ii	Brown Polymer, approx 3/8" diameter
			Washer	3-d-iii	White Polymer, approx 3/8" diameter
			Washer	3-d-iv	Brown Polymer, approx 1/2" diameter
	Bag "Subject Valve - Regulator Adapter"		Air Cup	3-f	Brass cup, approx 3/8" diameter 1/2" tall
			Handle	3-e-viii	Matte black, approx 1 3/4" diameter
			Adjuster	3-e	Black. Hollow. Threaded inside. Hex head.
			Adjuster Adapter	3-e-iv	Black. Hollow. Threaded outside. Hex opening. Fractured
			O Ring	3-e-v	Black polymer, approx 3/4" diameter
		O Ring	3-e-vi	Black polymer, approx 1/2" diameter	
		O Ring	3-e-vii	Black polymer, approx 3/8" diameter	
Tupperware container 3	Bag 3-A		Pressure line	4-i	Green. Some yellow discoloration
	Bag 3-B		Regulator Handle	4-j	Black polymer, fire damaged
	Bag 3-C		Pressure Gauge	4-k	Atteched to an approx 6" black hose
	Bag "Regulator Body"	Bag "O Ring, Thrust Washer"	O Ring	4-g	Black polymer, approx 1" diameter
			Thrust Washer	4-h	White Polymer, approx 1" diameter
		Bag "Metal Diaphragm Retainer, Main Regulator Body, Valve Lifter"	Diaphragm Retainer	4-c-v	Metal, 1 5/8" diameter approx 3/4" tall
			Regulator Body	4	Metal, 1 5/8" diameter approx 1 1/2" tall
			Valve Lifter	4-a	Resembes a large thumbtack
		Bag "Turret"	Turret	4-b	Metal, 1 5/8" diameter approx 1" tall
			Gasket	4-b-i	Brown Polymer, approx 1 5/8" diameter
			O Ring	4-b-ii	Black polymer, approx 1 1/4" diameter
		Bag "High Pressure Diaphragm Spring, Adjustment Sleeve"	Diaphragm Spring	4-c-iii	approx 1/2" diameter, 3/4" tall, 5 turns
			Adjustment Sleeve	4-c-iv	approx 3/4" diameter, 3/8" tall, outside threaded
		Bag "Diaphragm, Retaining Ring, Spring Carrier"	Diaphragm	4-c	Grey Polymer approx 1 1/2" diameter
			Retaining Ring	4-c-i	Clear Polymer Ring approx 1 1/2" diameter
			Spring Carrier	4-c-ii	Metallic button, approx 3/4" diameter. Center portion raised
		Bag "Mating Half Regulator Adjuster Adapter"	Adjuster	3-e-i	Remaining part of the adjuster
		O Ring	3-e-ii	Black Polyer approx 3/8" diameter	
	Bag "Regulator Insert Low Pressure"	Regulator Insert	4-f	Piston Body with compression spring	
		O Ring	4-f-i	Black Polymer approx 1/2" diameter	
Bag 4	Bag 4-1		Tank Section	1-e	approx 2" in engh and 1/4" width
			Tank Section	1-f	approx 1 1/2" in length triangular section
	Bag 4-2		Tank Section	1-g	Main body approx 1" length and 1/2" width
	Bag 4-3		Tank Section	1-h	Triangular section approx 3/4" height
	Bag 4-4		Tank Section	1-c-ii	Approx 1 1/2" length and 3/4" width. Marked C
			Tank Section	1-c-iii	Approx 1 1/2" length and 1/4" width. Marked C
	Bag 4-5		Tank Section	1-i	Approx 3" length, 1" at one end and 1 1/2" at another
	Bag "Compression Specimen"		Tank Section	1-j	Approx 1 1/4" length and 5/8" width
	Bag 4-6		Tank Section	1-d-ii	Curved section of the tank. Marked D
Bag 4-7		Tank Section	1-c-iv	Main body approx 4 1/2" x 6". Marked C	
Bag 4-8		Tank Section	1-k	Main body approx 8" length	
Tupperware container 5			Tank Valve	3	Tank valve body. Fractured
Not Bagged			Scuba Cylinder	1	Ruptured. Specimens taken.
Bag 6			Tank Bottom	1-l	Bottom of the ruptured tank.
Bag "Tensile Specimens"	Envelope "Tensile Specimen A Fracture Surface"		Tank Section	1-m-ii	Part of the fractured specimen No. 1-m-i
	Envelope "Tensile"		Tank Section	1-m-i	Tensile testing specimen half
			Tank Section	1-m-iii	Tensile testing specimen half. Marked B.





RTI Group, LLC  
910 Bestgate Road, Suite E  
Annapolis, MD 21401  
ofc: +1 410 571 0712 | fax: +1 410 571 0713  
www.rtiForensics.com

### CHANGE OF CUSTODY RECORD

DATE: June 12, 2012	
RTI File Name: DOT-Ruptured Scuba Cylinder	
RTI File No.: 50151.ME002	
<b>The evidence herein described has been transferred on this date - -</b>	
To: Norman Yuen Company: Anamet, Inc.	From: Matthew Wagenhofer Company: RTI
<b>Description of Evidence (Note all markings):</b>	
1. Two (2) halves tensile specimen	
2. One (1) tank valve body	
3.	
4.	
5.	
6.	
7.	
8.	
Authorization of <b>Sending Party:</b>	Authorization of <b>Receiving Party:</b>
(Signature) 	(Signature) 
(Printed) Matthew Wagenhofer	(Printed) NORMAN YUEN