| Brookhaven National Laboratory – Photon Sciences - National Synchrotron Light Source | | | | | |
|---|--------------|---------------------|-------------|--|--|
| Beamline Hazard Analysis - Beamline X17B2 | | | | | |
| LS-BHA-X17B2 | Revision: 03 | Effective: 10/17/11 | Page 1 of 1 | | |
| | | | | | |
| The following tasks are included in the beamline safety review. Any operations not listed here, or performed by others than | | | | | |
| those listed, need additional review by ES&H personnel and/or beamline personnel. | | | | | |

| Prepared By: | M. Vaughan, L. Wang | Approved By: | Lori Stiegler |
|--------------|---------------------|--------------|---------------|
| | | | |

| Tasks / Equipment | Performed by: | | Controls | | |
|--|-------------------|-------|--|--|--|
| , , , | Beamline Staff | Users | | | |
| Inert compressed gas | Y | Y | Compressed gas training – TQ-COMPGAS1 or NSLS User training Transport cylinders using a cylinder cart Properly secure cylinders Wear safety glasses with side shields while connecting lines Leak check gas lines | | |
| Solvents | Y | Y | Limit quantities at beamline to < 250 ml Use PPE - safety glasses, nitrile gloves | | |
| Using the LN2 Fill Station or pressurized transfer | Y | Y | LS-PROC-LN2FILL-MANL training for fill station Use full face shield along with goggles or safety glasses Long pants and sleeves - avoid clothing which can trap cryogens (pockets, cuffs) Cryogen or heavy gloves Enclosed shoes | | |
| Class 2/3a laser | Υ | Υ | Laser registration, warning signs | | |
| Soldering | Υ | N | Use a designated area, periodically clean surfaces | | |
| High temperature | Υ | Υ | No access while hotTraining | | |
| High pressure | Y | Υ | No access while press is being moved Training | | |
| Cutting/razor blades | Y | Y | Be aware of hand positioning Use safety knife when possible Consider using cut resistant gloves for frequent cutting tasks | | |