

#### NTSB National Transportation Safety Board

# Pipeline Safety: A Perspective from the NTSB


Lessons Learned from PG&E
Natural Gas Transmission Pipeline
Rupture and Fire

Robert L. Sumwalt NTSB Board Member




NTSB is an independent federal agency, charged by Congress to investigate transportation accidents, determine probable cause, and issue safety recommendations.











#### **The Board**


- Five Presidentially appointed Board Members
  - Nominated by the President, confirmed by the Senate
  - Serve for five year terms








# 13,569 Safety Recommendations issued since 1967



#### **WWW.NTSB.GOV**





Pacific Gas and Electric Company

San Bruno, California

San Bruno, September 9, 2010

September 9, 2010








#### Fatalities, Injuries, Physical Damage

- 8 fatalities
- 10 serious injuries
- 48 minor injuries

- 108 houses affected
  - 38 homes destroyed
  - 17 homes severe-to-moderate damage
  - 53 minor damage


















#### Construction of the Pipe






# Typical DSAW Sean Weld






#### **Incomplete Pup 1 Seam Weld**






# Rupture Sequence






# Rupture Sequence






# Rupture Sequence











# **Summary of PG&E Practices**

- "The accident pipe segment did not meet any known pipeline specifications."
- "Construction and quality control measures for the 1956 relocation project were inadequate in that they did not identify visible defects."
- "The integrity management program, including self-assessment of that program, was ineffective."
- "Emergency response to the pipeline rupture was slow, and isolation and shutdown of gas flow were unacceptably delayed."



## **Summary of PG&E Practices**

- "The post-accident drug and alcohol testing program had multiple deficiencies."
- "SCADA staff roles and duties were poorly defined."
- "SCADA work clearance procedures were inadequate."
- "Critical components at the Milpitas Terminal were susceptible to single-point failures."
- "The public awareness program, including self-assessment, was deficient and ineffective."



#### **NTSB's Probable Cause**

#### Pacific Gas and Electric Company's:

- (1) inadequate quality assurance and quality control in 1956 during its Line 132 relocation project, which allowed the installation of a substandard and poorly welded pipe section with a visible seam weld flaw that, over time grew to a critical size, causing the pipeline to rupture during a pressure increase stemming from poorly planned electrical work at the Milpitas Terminal; and
- (2) inadequate pipeline integrity management program, which failed to detect and repair or remove the defective pipe section.

## Contributing to the Accident

- California Public Utilities Commission's (CPUC) and the U.S. DOT's exemptions of existing pipelines from the regulatory requirement for pressure testing, which likely would have detected the installation defects.
- CPUC's failure to detect the inadequacies of PG&E's pipeline integrity management program.



# Contributing to the Severity of the Accident

- the lack of either automatic shutoff valves or remote control valves on the line
- PG&E's flawed emergency response procedures and delay in isolating the rupture to stop the flow of gas.



#### Organizational Accidents:

- Result largely from actions/inactions of companies/organizations.
- Have multiple contributing causes, involve people at numerous levels within the system, and are characterized by a pervasive lack of proactive measures to ensure adoption and compliance with a safety culture.
- Are catastrophic events with substantial loss of life, property, and environment; they also require complex organizational changes in order to avoid them in the future.



## Safety Recommendations

- 39 Safety Recommendations
  - PHMSA (16)
  - -PG&E (12)
  - CPUC (5)
  - U.S. Secretary of Transportation (4)
  - INGAA and AGA (1)
  - Governor of California (1)



#### To PHMSA

- Require that automatic shutoff valves or remote control valves in high consequence areas and in class 3 and 4 locations be installed and spaced at intervals that consider the factors listed in 49 CFR 192.935.
- Delete the grandfather clause and require that all gas transmission pipelines constructed before 1970 be subjected to a hydrostatic pressure test that incorporates a spike test.
- Require that all natural gas transmission pipelines be configured so as to accommodate in-line inspection tools, with priority given to older pipelines.



#### To INGAA and AGA

 Report to the NTSB on your progress to develop and introduce advanced inline inspection platforms for use in gas transmission pipelines not currently accessible to existing inline inspection platforms, including a timeline for implementation of these advanced platforms.



Pacific Gas and Electric Company Vacuus Gas Transmission Pipeline Rupture and Fire San Bruno, California September 9, 2010



Transportation Salety Board



# Could this accident happen in your organization?



#### What is Leadership?

"Leadership is about influence. Nothing more. Nothing less."

John Maxwell





NTSB