

DATE OF INSPECTION  
 3 July 1979

TYPE OF INSPECTION  
 A  INTERNAL & EXTERNAL B  INTERNAL & EXTERNAL WITH PRESSURE TEST C  OPERATIONAL

1. FROM  
 BASE MAINT OFFICER CAMP LEJEUNE N.C.  
 2. TO  
 NAVFACENGCOM NORFOLK VA.

14. CERTIFICATE ISSUED  YES  NO  
 14 DEC 1979  
 15. BOILER INSPECTOR  
 Jean L. Sellen  
 NAVY OR NATIONAL BOARD NO  
 NAVFAC 225  
 16. REASON FOR NOT ISSUING CERTIFICATE

BOILER DATA  
 3. MANUFACTURER  
 RILEY STOKER  
 4. PROPERTY NO. 1  
 5. MFG. SERIAL NO. 1944  
 6. MFG. MODEL NO. P-25-25-W-W-  
 7. BUILDING NO. 1700  
 8. YEAR BUILT 1942  
 9. CAPACITY 100,000 #/HR  
 10. FUEL (Check)  
 COAL  OIL  GAS  
 11. PRESSURE  
 DESIGNED 193 psi OPERATING 150 psi TEST 290 psi  
 12. FEED WATER TREATMENT  
 SATISFACTORY  UNSATISFACTORY  
 13. TYPE  
 WATER TUBE  FIRE TUBE  C. I.

17. BOILER USE  
 EXPORT  
 19. COMBUSTION  
 % CO<sub>2</sub> \_\_\_\_\_ % EXCESS O<sub>2</sub> \_\_\_\_\_

18. COMBUSTION CONTROL (Mfg. Name)  
 BAILEY & FIREYE  
 20. FLUE GAS TEMPERATURE  
 AFTER BOILER \_\_\_\_\_ °F AFTER HEAT TRAP \_\_\_\_\_ °F

SAFETY DEVICES  
 SAFETY VALVES

21. MANUFACTURER  
 Consolidated  
 22. NUMBER AND SIZE 2-3" 1-1/2"  
 23. PSI SETTING 185-187-190  
 24. CONDITION —

STEAM PRESSURE GAUGE

25. MANUFACTURER  
 ASHCROFT  
 26. CORRECTIONS  
 WATER LEG CONSTANT \_\_\_\_\_ psi OTHER \_\_\_\_\_ psi  
 27. REASON IF NOT TESTED


FIRING EQUIPMENT

ITEM	IN SERVICE	ALTERNATE
28. MANUFACTURER	FABER oil BURNER	RILEY STOKER
29. TYPE	GUN & NOZZLE - STEAM atom	Atrita #4 HAMMER & REC.
30. FUEL GRADE	#6	COAL

31. INSPECTOR'S COMMENTS

32. ATTACHMENT(S) (Check)  
 COPY OF INSPECTOR'S REPORT  
 SPECIAL COMMENTS

33. SIGNATURE  
 R.M. Wilson  
 BY DIRECTION



DATE: 11 July 1979

ACTIVITY: Marine Corps Base, Camp Lejeune, North Carolina

BUILDING NO: 1700 BOILER NO: 1

Based on the existing condition and present rate of deterioration, it is estimated that the boiler has a remaining life of


5 or more years

( ) years

The following corrective action is recommended:

1. Front wall refractory is shifting and pushing front wall burner eye tubes into flame pattern. Temporary repairs have been made to pull tubes back into place and refractory patched around burner eye and tube anchors.
2. Burner eye and boiler front wall refractory has been noted in prior inspection reports.
3. Boiler plant operators are having to cut back on boiler load due to flame impingement on wall tubes in back of furnace. This is caused by deterioration of the throat flare of the burner eyes as noted in enclosure (1), Report from Utilities on burner throat measurements.
4. Approximately thirty percent of the outer skin casing has deteriorated and leaks flue gases.
5. These repairs should be accomplished within next fiscal year due to:
  - a. An improved combustion efficiency (flame distortion from burner eye shape).
  - b. The potential problem and damage to burner eye tubes of moving into flame pattern from further front wall refractory movement.







DEPARTMENT OF THE NAVY

# Memorandum

MAIN/CLW/rn

11370

DATE: 19 Jul 1979

FROM: General Foreman, Steam Generation


TO: Director, Utilities Division

SUBJ: Replacement of Throat Tile in Boilers, Bldg 1700

1. Boilers have been giving trouble for the last two or three years. There has been problems with heavy carbon build up around throat and down the front of boiler. We have also had trouble with impingement of tubes and flame hitting walls in back of furnace. Boiler air flow has been checked and new guns and nozzles have been installed to correct situation. Guns (new) have also been moved in and out of blast tube to try to get rid of impingement problem, but nothing seems to help. We have suspected for quite some time that this situation was due to the shape of the throat. After careful observation and measurements, I feel sure that the throat tile is what is causing all, or most of our trouble.

2. Measurements were taken in Boiler No. 3, which indicate that the throat needs replacing. According to Print #4AB-3349-1 by Riley Stoker Corporation, throat measurements are 6" from throat ring to where flare in tile starts, 18" from throat ring should be 48" in diameter which is the overall drop of the tile. The measurements for Boiler No. 3 are: 8 to 10" from throat ring to where flare starts, 24 to 28" from throat ring, and 45" in diameter. Due to cracks and patching, there is very little uniformity in throats. With this situation as is, and if not corrected in the near future, we will most likely have to cut back on boiler load due to impingement. Presently on No. 2 Boiler, around 78,000-80,000 pounds of steam is all we can run due to flame hitting back walls; we are now using 85° nozzles.

COLON L. WETHERINGTON



DATE OF INSPECTION  
 10-31-77

TYPE OF INSPECTION  
 A  INTERNAL & EXTERNAL B  INTERNAL & EXTERNAL WITH PRESSURE TEST C  OPERATIONAL

1. FROM  
 Base Maint Office Camp Lejeune N.C.  
 2. TO  
 Commandant Naval Marine Corps (Code 411)

14. CERTIFICATE ISSUED  YES  NO  
 Expires 11-30-77  
 15. BOILER INSPECTOR  
 E.O. Mabley  
 NAVY OR NATIONAL BOARD NO.  
 NAVFAC 101

3. MANUFACTURER  
 Riley Stoker  
 4. PROPERTY NO. 1  
 5. MFG. SERIAL NO. 1944  
 6. MFG. MODEL NO. P25-25-WW  
 7. BUILDING NO. 1700  
 8. YEAR BUILT 1942  
 9. CAPACITY 100,000 #/HR  
 10. FUEL (Check)  
 COAL  OIL  GAS  
 11. PRESSURE  
 DESIGNED 19.3 psi OPERATING 150 psi TEST 290 psi  
 12. FEED WATER TREATMENT  
 SATISFACTORY  UNSATISFACTORY  
 13. TYPE  
 WATER TUBE  FIRE TUBE  C. I.

16. REASON FOR NOT ISSUING CERTIFICATE

17. BOILER USE  
 Export  
 19. COMBUSTION  
 % CO<sub>2</sub> % EXCESS O<sub>2</sub>

18. COMBUSTION CONTROL (Mfg. Name)  
 Bailey & Fireye  
 20. FLUE GAS TEMPERATURE  
 AFTER BOILER \_\_\_\_\_ °F ; AFTER HEAT TRAP \_\_\_\_\_ °F

SAFETY DEVICES  
 SAFETY VALVES

21. MANUFACTURER  
 Consolidated

22. NUMBER AND SIZE 2-3" 1-6"  
 23. PSI SETTING 195-187-193  
 24. CONDITION

25. MANUFACTURER  
 Ashcroft  
 27. REASON IF NOT TESTED

26. CORRECTIONS  
 WATER LEG CONSTANT 10 1/2 psi; OTHER \_\_\_\_\_ psi

FIRING EQUIPMENT

ITEM	IN SERVICE	ALTERNATE
28. MANUFACTURER	Faber Oil Buewer	Riley Stoker
29. TYPE	Gun + Nozzle	Atata #4 Hammer + preg
30. FUEL GRADE	#6	Coal

31. INSPECTOR'S COMMENTS

32. ATTACHMENT(S) (Check)  
 COPY OF INSPECTOR'S REPORT  SPECIAL COMMENTS

33. SIGNATURE  
 R.M. Quinn  
 BY DIRECTION





INSPECTION REPORT-BOILERS  
 NAVFAC 9-11014/41 (3/67)  
 Supersedes NAVDOCKS 2544  
 S/N 0105-LF-004-0000

DATE OF INSPECTION

21 MAY 1979

TYPE OF INSPECTION

A  INTERNAL & EXTERNAL B  INTERNAL & EXTERNAL WITH PRESSURE TEST C  OPERATIONAL

1. FROM

BASE MAINT. OFFICER CAMP LEJEUNE N.C.

2. TO

NAUFACENG-COM NORFOLK VA.

14.

CERTIFICATE ISSUED  YES  NO  
 EXPIRES 28 MAY 1979

15. BOILER INSPECTOR

Joseph L. Sellers  
 NAVY OR NATIONAL BOARD NO.

NAUFAC 225

16. REASON FOR NOT ISSUING CERTIFICATE

BOILER DATA

3. MANUFACTURER

RILEY STOKER

4. PROPERTY NO.

3

5. MFG. SERIAL NO.

1946

6. MFG. MODEL NO.

P-25-25-WW

7. BUILDING NO.

1700

8. YEAR BUILT

1942

9. CAPACITY

100,000 #/HR

10. FUEL (Check)

COAL  OIL  GAS

11. PRESSURE

DESIGNED

193 psi

OPERATING

150 psi

TEST

300 psi

12. FEED WATER TREATMENT

SATISFACTORY  UNSATISFACTORY

13. TYPE

WATER TUBE  FIRE TUBE  C. I.

17. BOILER USE

EXPORT

19. COMBUSTION

% CO<sub>2</sub>

% EXCESS O<sub>2</sub>

18. COMBUSTION CONTROL (Mfg. Name)

BAILEY & FIREYE

20. FLUE GAS TEMPERATURE

AFTER BOILER \_\_\_\_\_ °F : AFTER HEAT TRAP \_\_\_\_\_ °F

SAFETY DEVICES

SAFETY VALVES

21. MANUFACTURER

Consolidated

22. NUMBER AND SIZE

2-3" 1-6"

23. PSI SETTING

185-187-190

24. CONDITION

—

STEAM PRESSURE GAUGE

25. MANUFACTURER

ASHCROFT

26. CORRECTIONS

WATER LEG CONSTANT \_\_\_\_\_ psi; OTHER \_\_\_\_\_ psi

27. REASON IF NOT TESTED

FIRING EQUIPMENT

ITEM	IN SERVICE	ALTERNATE
28. MANUFACTURER	FABER OIL BURNER	RILEY STOKER
29. TYPE	GUN & NOZZLE - STEAM ATOM	ATRITA #4 HAMMER & PEG
30. FUEL GRADE	#6	COAL

INSPECTOR'S COMMENTS

COMMENT(S) (Check)

COPY OF INSPECTOR'S REPORT

SPECIAL COMMENTS

33. SIGNATURE

R. M. Dillon

BY DIRECTION





DATE: 21 May 1979

ACTIVITY: Marine Corps Base, Camp Lejeune, North Carolina

BUILDING NO: 1700

BOILER NO: 3

Based on the existing condition and present rate of deterioration, it is estimated that the boiler has a remaining life of

5 or more years

( ) years

The following corrective action is recommended:

1. Front wall refractory is shifting and pushing front wall burner eye tubes into flame pattern. Temporary repairs have been made to pull tubes back into place and refractory patched around burner eye and tube anchors.


2. Burner eye and boiler front wall refractory has been noted in major inspection reports.

3. Approximately ten percent of the outer skin casing has deteriorated and leaks flue gases.

4. These repairs should be accomplished within next fiscal year due to:

a. An improved combustion efficiency (flame distortion from burner eye shape).

b. The potential problem and damage to burner eye tubes of moving into flame pattern from further front wall refractory movement.



DEPARTMENT OF THE NAVY

# Memorandum

MAIN/CLW/rn

11370

DATE: 19 Jul 1979

FROM: General Foreman, Steam Generation

TO: Director, Utilities Division


SUBJ: Replacement of Throat Tile in Boilers, Bldg 1700

1. Boilers have been giving trouble for the last two or three years. There has been problems with heavy carbon build up around throat and down the front of boiler. We have also had trouble with impingement of tubes and flame hitting walls in back of furnace. Boiler air flow has been checked and new guns and nozzles have been installed to correct situation. Guns (new) have also been moved in and out of blast tube to try to get rid of impingement problem, but nothing seems to help. We have suspected for quite some time that this situation was due to the shape of the throat. After careful observation and measurements, I feel sure that the throat tile is what is causing all, or most of our trouble.

2. Measurements were taken in Boiler No. 3, which indicate that the throat needs replacing. According to Print #4AB-3349-1 by Riley Stoker Corporation, throat measurements are 6" from throat ring to where flare in tile starts, 18" from throat ring should be 48" in diameter which is the overall drop of the tile. The measurements for Boiler No. 3 are: 8 to 10" from throat ring to where flare starts, 24 to 28" from throat ring, and 45" in diameter. Due to cracks and patching, there is very little uniformity in throats. With this situation as is, and if not corrected in the near future, we will most likely have to cut back on boiler load due to impingement. Presently on No. 2 Boiler, around 78,000-80,000 pounds of steam is all we can run due to flame hitting back walls; we are now using 85° nozzles.

COLON L. WETHERINGTON





DATE OF INSPECTION  
 26 JUNE 1978

TYPE OF INSPECTION  
 A  INTERNAL & EXTERNAL B  INTERNAL & EXTERNAL WITH PRESSURE TEST C  OPERATIONAL

1. FROM  
 BASE MAINT. OFFICER CAMP LEJEUNE N.C.  
 2. TO  
 COMMANDANT Hdqtrs MARINE CORPS (CODE LFF)

14. CERTIFICATE ISSUED  YES  NO  
 EXPIRES 15 FEB 1979  
 15. BOILER INSPECTOR  
 Jesse I. Sellers  
 NAVY OR NATIONAL BOARD NO.

BOILER DATA  
 3. MANUFACTURER  
 RILEY STOKER CORPORATION  
 4. PROPERTY NO. 3  
 5. MFG. SERIAL NO. 1946  
 6. MFG. MODEL NO. P-25-25-WW  
 7. BUILDING NO. 1700  
 8. YEAR BUILT 1942  
 9. CAPACITY 100,000 #/HR  
 10. FUEL (Check)  
 COAL  OIL  GAS  
 11. PRESSURE  
 DESIGNED 193 psi OPERATING 150 psi TEST 300 psi  
 12. FEED WATER TREATMENT  
 SATISFACTORY  UNSATISFACTORY  
 13. TYPE  
 WATER TUBE  FIRE TUBE  C. I.

16. REASON FOR NOT ISSUING CERTIFICATE

17. BOILER USE  
 EXPORT  
 19. COMBUSTION  
 % CO<sub>2</sub> \_\_\_\_\_ % EXCESS O<sub>2</sub> \_\_\_\_\_

18. COMBUSTION CONTROL (Mfg. Name)  
 FIREYE & BAILEY  
 20. FLUE GAS TEMPERATURE  
 AFTER BOILER \_\_\_\_\_ °F ; AFTER HEAT TRAP \_\_\_\_\_ °F

SAFETY DEVICES  
 SAFETY VALVES

21. MANUFACTURER  
 Consolidated  
 22. NUMBER AND SIZE 2-3" - 1-6"  
 23. PSI SETTING 185-187-190  
 24. CONDITION

STEAM PRESSURE GAUGE

25. MANUFACTURER  
 ASHCROFT  
 26. CORRECTIONS  
 WATER LEG CONSTANT 10 psi; OTHER \_\_\_\_\_ psi  
 27. REASON IF NOT TESTED

FIRING EQUIPMENT


ITEM	IN SERVICE	ALTERNATE
28. MANUFACTURER	FABER OIL BURNER	RILEY STOKER
29. TYPE	GUNF NOZZLE - STEAM ATOM.	ATRITA #4 HAMMER & PEG
30. FUEL GRADE	#6	COAL

31. INSPECTOR'S COMMENTS  
 REPLACE CENTER SAFETY VALVE GASKET - REPLACED ALL AIR HEATER TUBES 2ND PASS

REBUILD FRONT BRICK WALL FIREBOX - REPAIR STEAM DRUM INSULATION

32. ATTACHMENT(S) (Check)  
 COPY OF INSPECTOR'S REPORT  SPECIAL COMMENTS

33. SIGNATURE  
 R.M. Dillon  
 BY DIRECTION





**INSPECTION REPORT-BOILERS**  
 NAVFAC 9-11014/41 (3/67)  
 Supersedes NAVDOCKS 2544  
 S/N 0105-LF-004-0000

DATE OF INSPECTION

4-13 To 4-27-77

TYPE OF INSPECTION

A  INTERNAL & EXTERNAL

B  INTERNAL & EXTERNAL WITH PRESSURE TEST

C  OPERATIONAL

1. FROM

Base MAINT OFFICER Camp Lejeune NC.

2. TO

Commandant Hdqtrs Marine Corps (Codelife)

14.

CERTIFICATE ISSUED  YES  NO

Expires 12-1-77

15. BOILER INSPECTOR

E.O. Mobley

NAVY OR NATIONAL BOARD NO.

NAV FAC 101

16. REASON FOR NOT ISSUING CERTIFICATE

**BOILER DATA**

3. MANUFACTURER

Riley Stoker Corporation

4. PROPERTY NO.

3

5. MFG. SERIAL NO.

1946

6. MFG. MODEL NO.

P.25-25-WW.

7. BUILDING NO.

1700

8. YEAR BUILT

1942

9. CAPACITY

100,000 #/HR.

10. FUEL (Check)

COAL  OIL  GAS

11. PRESSURE

DESIGNED

OPERATING

TEST

193 psi

150 psi

300 psi

12. FEED WATER TREATMENT

SATISFACTORY  UNSATISFACTORY

13. TYPE

WATER TUBE

FIRE TUBE

C. I.

17. BOILER USE

EXPORT

18. COMBUSTION CONTROL (Mfg. Name)

Fireye & Bailey

19. COMBUSTION

% CO<sub>2</sub>

% EXCESS O<sub>2</sub>

20. FLUE GAS TEMPERATURE

AFTER BOILER \_\_\_\_\_ °F ; AFTER HEAT TRAP \_\_\_\_\_ °F

**SAFETY DEVICES**

**SAFETY VALVES**

21. MANUFACTURER

Consolidated

22. NUMBER AND SIZE

2-3" - 1-6"

23. PSI SETTING

185-187-190

24. CONDITION

-

**STEAM PRESSURE GAUGE**

25. MANUFACTURER

Ashcroft

26. CORRECTIONS

WATER LEG CONSTANT 10 psi; OTHER \_\_\_\_\_ psi

27. REASON IF NOT TESTED

**FIRING EQUIPMENT**

ITEM	IN SERVICE	ALTERNATE
28. MANUFACTURER	Faber Oil Burner	Riley Stoker
29. TYPE	Gun & Nozzle Steam Atom.	Atrita #4 Hammer & Peg
30. FUEL GRADE	# 6	Coal

31. INSPECTOR'S COMMENTS

patch Refractory & Rebuild Front Brick wall firebox

32. ATTACHMENTS (Check)


COPY OF INSPECTOR'S REPORT

SPECIAL COMMENTS


33. SIGNATURE

J. O. Dawes

BY DIRECTION







ES TO HAVE NOT LESS THAN .2% COPPER

AND IS NOT TO BE USED IN ANY WAY INJURIOUS TO ITS INTERESTS AND IS TO BE RETURNED UPON REQUEST.

WE ARE NOT RESPONSIBLE FOR ANY INJURY OR DAMAGE DUE TO THE USE OF DESIGN ON THIS DRAWING OF ANYTHING NOT ACTUALLY FURNISHED BY US WHETHER SO SPECIFICALLY INDICATED OR NOT AND WE ARE ALSO NOT RESPONSIBLE FOR DESIGN, INSTALLATION OR OPERATION OF ANY PART OF FOUNDATION OR SETTING OR ACCESSORY EQUIPMENT NOT ACTUALLY FURNISHED

DO NOT SCALE USE DIMENSIONS ONLY

"N" DENOTES MATERIAL NOT FURNISHED	DRAWN H.R. WHITTLE
"F" DENOTES MATERIAL FURNISHED BY RILEY STOKER CORPORATION	TRACED
	DATE 4-12-41
	CHECKED H.F. Johnson
	APPROVED


**RILEY STOKER CORPORATION**  
 WORCESTER, MASSACHUSETTS


BURNER INSTALLATION FOR #3 1/2 RILEY FLAKE TYPE BURNERS (SPECIAL-INSIDE INSULATION) WITH #4 HEADS.

FOR U.S. MARINE BARRACKS, NEW RIVER, N.C.

No. 4AB-3349 — 3537







15'-1 1/2" INSIDE CASINGS  
 14'-7 1/2"  $\phi$  TO  $\phi$  W.W. TUBES

5 1/2" 6 @ 3 3/8" = 20 1/4"

5'-2"  $\phi$  BURNER  
 5'-3 3/16"

$\phi$  BOILER

2'-6"  
 68 7/8" dia

38 3/8" FOR TUBES

$\phi$  BOILER

X  
 PB-1

W.P.

Y

9/16" HOLES IN ANGLE  
 1/2" TAPPED HOLES IN FILLER

ENLARGED SECTION AT "Y"

SCALE 3" = 1'-0"

SECONDARY AIR DAMPERS  
 FOR DRILLING SEE 5AB-3774

2'-11 1/2"

2'-11 1/2"

23"

2'-8 1/2"

18"


4 1/2" 6"

18" 22 1/2"




4 1/2"


8"













DATE OF INSPECTION

11-10-77

TYPE OF INSPECTION

A  INTERNAL & EXTERNAL

B  INTERNAL & EXTERNAL WITH PRESSURE TEST

C  OPERATIONAL

1. FROM

Base Maint Offices Camp Lejeune N.C.

2. TO

Commandant Hdqtrs Machine Coops (Cde 101)

14.

CERTIFICATE ISSUED  YES  NO

15. BOILER INSPECTOR

E.O. McElroy

NAVY OR NATIONAL BOARD NO.

BOILER DATA

3. MANUFACTURER

NAU FAC 101

4. PROPERTY NO.

16. REASON FOR NOT ISSUING CERTIFICATE

This unit suffered a fire box explosion 11-3-77 with severe damage to refractory tile and casing - Briddles are intact and unit holds hydrostatic pressure. Unit was being lit off on coal firing at time of incident.

5. MFG. SERIAL NO.

7. BUILDING NO.

8. YEAR BUILT

10. FUEL (Check)

11. PRESSURE

DESIGNED

OPERATING

TEST

12. FEED WATER TREATMENT

13. TYPE

17. BOILER USE

18. COMBUSTION CONTROL (Mfg. Name)

19. COMBUSTION

20. FLUE GAS TEMPERATURE

% CO<sub>2</sub>

% EXCESS O<sub>2</sub>

AFTER BOILER \_\_\_\_\_ °F

AFTER HEAT TRAP \_\_\_\_\_ °F

SAFETY DEVICES

SAFETY VALVES

21. MANUFACTURER

22. NUMBER AND SIZE

23. PSI SETTING

24. CONDITION

25. MANUFACTURER

26. CORRECTIONS

WATER LEG CONSTANT 1 1/2 psi

OTHER \_\_\_\_\_ psi

27. REASON IF NOT TESTED

FIRING EQUIPMENT

ITEM

IN SERVICE

ALTERNATE

28. MANUFACTURER

Faber Oil Burner

Riley Stoker

29. TYPE

GUNT Nozzle - Steam atom.

Atcote 44 Hammer type

30. FUEL GRADE

H.C.

Coal

31. INSPECTOR'S COMMENTS

Replace backwork, refractory and refractory tile and casing. Side and front walls and top

32. ATTACHMENT(S) (Check)

COPY OF INSPECTOR'S REPORT


SPECIAL COMMENTS

33. SIGNATURE

E.O. McElroy

BY DIRECTION





DATE OF INSPECTION  
 5-18/6-8-77

TYPE OF INSPECTION  
 A  INTERNAL & EXTERNAL B  INTERNAL & EXTERNAL WITH PRESSURE TEST C  OPERATIONAL

1. FROM  
 Base Maint Office Complexione No.

2. TO  
 Commandant Adgtes Marine Corps (Code 111)

14. CERTIFICATE ISSUED  YES  NO  
 Expires 12-1-77

15. BOILER INSPECTOR  
 E.O. Mabley  
 NAVY OR NATIONAL BOARD NO.

BOILER DATA

3. MANUFACTURER  
 Riley Stoker Corp.

4. PROPERTY NO. 4 5. MFG. SERIAL NO. 1978 6. MFG. MODEL NO. P 25-25-W.W.

7. BUILDING NO. 1700 8. YEAR BUILT 1942 9. CAPACITY 100,000 #/HR.

10. FUEL (Check)  COAL  OIL  GAS 11. PRESSURE  
 DESIGNED 193 psi OPERATING 150 psi TEST 387 psi

12. FEED WATER TREATMENT  SATISFACTORY  UNSATISFACTORY 13. TYPE  WATER TUBE  FIRE TUBE  C. I.

16. REASON FOR NOT ISSUING CERTIFICATE  
 NAV FAC 101

17. BOILER USE  
 Export

18. COMBUSTION CONTROL (Mfg. Name)  
 Bailey & Fireeye

19. COMBUSTION  
 — % CO<sub>2</sub> — % EXCESS O<sub>2</sub>

20. FLUE GAS TEMPERATURE  
 AFTER BOILER — °F ; AFTER HEAT TRAP — °F

SAFETY DEVICES  
 SAFETY VALVES

21. MANUFACTURER Consolidated 22. NUMBER AND SIZE 2-3" x 1-6" 23. PSI SETTING 185-187-193 24. CONDITION —

STEAM PRESSURE GAUGE

25. MANUFACTURER Ashcroft 26. CORRECTIONS  
 WATER LEG CONSTANT 10 1/2 psi; OTHER — psi

27. REASON IF NOT TESTED

FIRING EQUIPMENT


ITEM	IN SERVICE	ALTERNATE
28. MANUFACTURER	Faber Oil Burner	Riley ATRITA #4.
29. TYPE	Gun & Nozzle - Steam Atom	Hammer & Peg.
30. FUEL GRADE	#6	Coal

31. INSPECTOR'S COMMENTS  
 Replace Basket - Top Flange of Water Column & Flange on Safety Valve  
 Repair Fire box Refractory - Replace Front Wall & Burner eyes

32. COPIES OF INSPECTOR'S REPORT  SPECIAL COMMENTS

33. SIGNATURE  
 J. A. Davis BY DIRECTION





DATE: 28 June 1978

ACTIVITY: Marine Corps Base, Camp Lejeune, North Carolina

BUILDING NO: 1700

BOILER NO: 4

Based on the existing condition and present rate of deterioration, it is estimated that the boiler has a remaining life of

5 or more years

( ) years

The following corrective action is recommended:

The addition of the lower firebox, header refractory and burner eye to be repaired or replaced at this time, based on:

1. Prior inspection reports by teh previous Boiler Inspector, E. O. Mobley,

NAVFAC 101.

2. Visual inspection from bottom deck on 27 June 1978.

3. Due to extensive repairs to be done at this time.

Jesse L. Sellers  
NAVFAC 225





DATE OF INSPECTION  
 8-31-77

TYPE OF INSPECTION  
 A  INTERNAL & EXTERNAL B  INTERNAL & EXTERNAL WITH PRESSURE TEST C  OPERATIONAL

1. FROM  
 Base Maint Office Camp Lejeune MC.

14. CERTIFICATE ISSUED  YES  NO  
 EXPIRES 11-30-77  
 15. BOILER INSPECTOR

2. TO  
 Commandant Hdqtrs Marine Corps (Cedelet)

E.O. [Signature]  
 NAVY OR NATIONAL BOARD NO

BOILER DATA

3. MANUFACTURER  
 Riley Stoker Corp.

4. PROPERTY NO. 2	5. MFG. SERIAL NO. 1945	6. MFG. MODEL NO. P-25-25 U.W.
7. BUILDING NO. 1700	8. YEAR BUILT 1942	9. CAPACITY 100,000 A/H.R.
10. FUEL (Check) <input checked="" type="checkbox"/> COAL <input checked="" type="checkbox"/> OIL <input type="checkbox"/> GAS		11. PRESSURE DESIGNED 193 psi OPERATING 150 psi TEST 300 psi
12. FEED WATER TREATMENT <input checked="" type="checkbox"/> SATISFACTORY <input type="checkbox"/> UNSATISFACTORY		13. TYPE <input checked="" type="checkbox"/> WATER TUBE <input type="checkbox"/> FIRE TUBE <input type="checkbox"/> C. I.

16. REASON FOR NOT ISSUING CERTIFICATE  
 NAU FAC 101

17. BOILER USE  
 EXPORT

19. COMBUSTION  
 \_\_\_\_\_ % CO<sub>2</sub>    \_\_\_\_\_ % EXCESS O<sub>2</sub>

18. COMBUSTION CONTROL (Mfg. Name)  
 Bailey & Fireeye

20. FLUE GAS TEMPERATURE  
 AFTER BOILER \_\_\_\_\_ °F ; AFTER HEAT TRAP \_\_\_\_\_ °F

SAFETY DEVICES  
 SAFETY VALVES

21. MANUFACTURER  
 Consolidated

22. NUMBER AND SIZE  
 2-3" 1-6"

23. PSI SETTING  
 125-127-190

24. CONDITION  
 -

STEAM PRESSURE GAUGE

25. MANUFACTURER  
 Ashcroft

26. CORRECTIONS  
 WATER LEG CONSTANT \_\_\_\_\_ psi; OTHER \_\_\_\_\_ psi

27. REASON IF NOT TESTED

FIRING EQUIPMENT

ITEM	IN SERVICE	ALTERNATE
28. MANUFACTURER	Faber Oil Burner	Riley Stoker
29. TYPE	Unit No 331c Steam Atom.	Atkins #4 Hammer & Cog.
30. FUEL GRADE	#6	Coal

31. INSPECTOR'S COMMENTS

Contractory patched - front brick wall & refractory to be replaced

ATTENTION: (Check)  
 COPY OF INSPECTOR'S REPORT

33. SIGNATURE  
 [Signature]  
 BY DIRECTOR



