

AERONAUTICAL CHARTING FORUM
Charting Group
Meeting 09-02 - October 28-29, 2009
RECOMMENDATION DOCUMENT
FAA Control # 09-02-220

Subject: Multiple Intermediate Segments in Recent RNP AR (SAAAR) IAPs.

Background/Discussion: IACC and FAA specifications require the charting of the intermediate and final approach fix and segments shown in the profile view of IAP charts. The course reversal, when published, must also be shown in the profile view. (See Attachment # 1) The profile view provides an additional procedural cross-check during the critical phase of flight on an IAP when other than terminal/en route obstacle clearance is provided. This is critical for obstacle clearance in non-precision IAPs (See **F70 RNAV 18 IAP**) and for ATC compliance in multiple intercept point ILS IAPs (See **KSEA ILS 16R IAP**). In 1974 the TWA 514 CFIT accident may have been avoided had the profile view been in compliance with these IACCs specifications, which were in effect on the date of that accident (See **KIAD 1974 VOR/DME 12 IAP**).

Until recently RNP AR IAP procedures (thus charts) have had one intermediate segment, thus IACC compliant profile views (See **KRIL RNP AR Z 26 IAP**). The RNP AR order, 8260.52 implies a single intermediate segment. With the recent publication of initiated RNP AR IAPs at KBOI and KRDU, the ad hoc concept of multiple intermediate segments has now appeared “*to facilitate flow control and industry use.*” (See Attachment #2, Flight Procedures Standards Waiver. Also, see **KBOI RNP AR RNP Z 28R IAP** and note foreshortened profile view)

It should be noted here that the issue of the chart clutter in the new KBOI and KRDU RNP AR procedures is not an issue being brought forth by this Recommendation Document. That is being handled by the PARC’s Charting Action Team and DOT’s Volpe. This Recommendation Document is limited to the issue of foreshortened profile views. It should also be noted that this issue of foreshortened profile views is concurrently being brought before the PARC. The FAA’s RNAV/RNP Office recently recommended that NBAA also bring the profile view issue to the ACF’s Charting Group.

Attachment #2 illustrates what is essentially a boiler-plate waiver for each of the RNP AR IAPs at KBOI and KRDU. In NBAA’s view these waivers do not document an equivalent level of safety. Further, NBAA believes this is an incorrect use of the Flight Procedures Standards waiver process; that process is intended for waivers of TERPs criteria under TERPs, Paragraph 141. The waivers at issue are waivers of charting standards. Charting standards should not be subject to blanket waivers, rather when justified, the charting standards should be changed.

There are presently three low-traffic airports (KBZN, KOTH, and KLWS) where RNP AR procedures are being developed with multiple intermediate segments. Thus, it appears the NFPO is developing procedures criteria and charting specifications on an ad hoc basis, following the KBOI and KRDU “model.” Presumably, this will result in the routine issuance of waivers to the IACC and FAA profile-view charting specifications. Who will fly what simulator to

verify that these procedures are “*validated in the simulator with satisfactory results?*” (Attached waiver’s equivalent level of safety #4.)

Troubling as well are deviations from these charting specifications without a waiver being documented (See KLWS RNAV (RNP) 12 & 8260-3 excerpt). This procedure is being presented for coordination without any reference to the deviation from the IACC specification and the FAA Order. Will future RNAV (RNP) AR procedures with multiple IF’s and deviating from the requirement to chart the intermediate segment in the profile view also fail to document the applicable waiver, in effect establishing a “normalization of deviance”?

The importance of complying with these charting requirements is noted in NTSB’s recommendation to the FAA concerning adherence to the IACC specification resulting from the accident investigation of TWA 514 (see attached). FAA’s administrator accepted this recommendation (see attached letter).

Recommendations: The development of multiple IF RNP AR IAPs should be suspended, pending an objective safety review by this forum in coordination with the PARC. NBAA does not object to consideration being given in the interim to change air-carrier-initiated multiple IF RNP AR IAPs to special instrument approach procedures. Any other RNP AR IAPs currently in development should contain only one IF so that present charting specifications will be respected.

After due consideration, if an objective consensus is reached that final-segment-only profile views are acceptable (or preferred) in RNP AR IAPs, NBAA will fully support both IACC and FAA charting specifications being changed to reflect this ***for RNP AR IAPs only.***

Comments: This recommendation affects IACC and FAAO 8260.19D profile charting requirements. It also affects the NFPO’s apparent internal policy change to design all pending and future RNP RA IAPs with multiple intermediate segments.

Submitted by: Richard J. Boll II

Organization: NBAA

Phone: 316-655-8856

FAX:

E-mail: richard.boll@sbcglobal.net

Date: October 2, 2009

ATTACHMENT # 1 – ICAA AND FAA PROFILE VIEW SPECIFICATIONS

IACC Specification:

3.4.5.1.1:

A profile diagram of the instrument approach procedure shall be placed in the space provided below the planview. Those facilities, intersections, fixes, etc. identified in the procedure to be used in executing a course reversal and/or involved in the Intermediate/final approach segment with minimum altitudes, as required by the procedure, shall be shown. Size and style of type shall be as indicated in the appendix.

FAA Specifications (FAAO 8260.19D):

805 i (4):

Develop intermediate segments for all IAPs except "hold-in-lieu-of-PT" and "PT No-FAF" procedures. Where intermediate segments have been established, the intermediate fix (IF) will be defined on the procedure in the planview.

852 b (3):

On procedures that do not authorize a PT or holding pattern at the FAF, enter the fix/facility from which the profile is to start. The profile must include the intermediate fix. If required for clarity, the profile may be extended to include all fixes established on the final or intermediate course.

ATTACHMENT # 2 – BOISE RNP AR 28R TERPS WAIVER

US Department of Transportation Federal Aviation Administration		FLIGHT PROCEDURES STANDARDS WAIVER		FLIGHT STANDARDS USE ONLY CONTROL NO:
1. Flight Procedure Identification: Boise, ID (BOI) Boise Air Terminal/Gowen Fld RNAV (RNP) Z RWY 28R				
2. Waiver Required and Applicable Standard: The profile must include the intermediate fix (IF). FAAO 8260.19D, Paragraph 805 i (4) 852, b (3)				
3. Reason for Waiver (<i>Justification for nonstandard treatment</i>): Five (5) separate intermediate segments with designated IF fixes are used on this procedure to facilitate flow control and industry use, therefore, an intermediate fix will not be charted in the profile.				
4. Equivalent Level of Safety Provided: 1. Procedure is Special Aircraft and Aircrew Authorization Required (SAAAR). 2. Intermediate segments/fixes (IFs) will be charted on the Planview. 3. Procedure coded for multiple Intermediate Fixes (IFs) per user request. 4. Validated in simulator with satisfactory results.				
5. How Relocation or Additional Facilities Will Affect Waiver Requirement: NA - RNAV Procedure				
6. Coordination With User Organizations (<i>Specify</i>): AJW-324: _____				
7. SUBMITTED BY				
DATE:	Office Identification: AJW-32	Title: Manager, National Flight Procedures Office	Signature: Danny E. Hamilton	

F70 RNAV 18 IAP

MURRIETA/TEMECULA, CALIFORNIA

AL-6941 (FAA)


RNAV (GPS) RWY 18 MURRIETA/TEMECULA/FRENCH VALLEY (F70)

APP CRS	Rwy Idg	6000
179°	TDZE	1350
	Apt Elev	1350

NA DME/DME RNP-0.3 NA. Visibility reduction by helicopters NA. Circling not authorized west of Rwy 18-36. When local altimeter setting not received, use Ramona altimeter setting and increase all MDAs 100 feet and all visibilities ¼ mile.


MISSED APPROACH: Climb to 7000 direct FARGA and left turn via 077° track to HANLI and left turn via 321° track to SETER and hold.

AWOS-3 119.025	MARCH APP CON* 133.5 324.1	UNICOM 122.8 (CTAF)
--------------------------	--------------------------------------	-------------------------------



SW-3, 24 SEP 2009 to 22 OCT 2009

SW-3, 24 SEP 2009 to 22 OCT 2009



	7000	FARGA	HANLI	SETER	TIQMU	Procedure Turn NA
		077° track	321° track			
		KEBSE 2.8 NM to RWY 18	DISEY 5.6 NM to RWY 18	MUHRU		
		2340	3300	3800	4700	
		TCH 40				VGSI and descent angles not coincident.
		2.8 NM	2.8 NM	1.5 NM	6.9 NM	
CATEGORY		A	B	C	D	
LNAV MDA		1880-1	530 (600-1)	1880-1½ 530 (600-1½)	NA	
CIRCLING		2040-1	690 (700-1)	2040-2 690 (700-2)	NA	

MURRIETA/TEMECULA, CALIFORNIA

MURRIETA/TEMECULA/FRENCH VALLEY (F70)

Amdt 1 08073

33°34'N-117°08'W

RNAV (GPS) RWY 18

KSEA ILS 16R IAP


SEATTLE, WASHINGTON

AL-582 (FAA)

LOC/DME I-CJL 110.75 Chan 44 (Y)	APP CRS 163°	Rwy Idg TDZE Apt Elev 8500 415 433
-----------------------------------------------	------------------------	------------------------------------------------------------------------

ILS or LOC RWY 16R
SEATTLE-TACOMA INTL (SEA)

DME or RADAR required.		ALSF-2	MISSED APPROACH: Climb heading 158° and SEA VORTAC R-161 to cross TEBNE/SEA 2.4 DME/RADAR at or below 2000, then climb to 5000 via SEA VORTAC R-161 to MILLT INT/SEA 11 DME/RADAR and hold, continue climb-in-hold to 5000.
ATIS 118.0	SEATTLE APP CON 133.65 273.45	SEATTLE TOWER 119.9 239.3 (Rwys 16C/34C, 16L/34R) 120.95 239.3 (Rwy 16R/34L)	GND CON 121.7



NW-1, 24 SEP 2009 to 22 OCT 2009

NW-1, 24 SEP 2009 to 22 OCT 2009

*When assigned by ATC, intercept glidepath at 3200 or 4000 or 5000 or 6000.		SEA R-161 116.8	TEBNE SEA 2.4 RADAR 2000	5000 SEA R-161	MILLT INT SEA 11 RADAR																																																																		
Procedure Turn NA	WATEL I-CJL 18.2 RADAR	AGANE I-CJL 15.3 RADAR	CELAK I-CJL 12.3 RADAR	BUGNE I-CJL 10 RADAR	FINKA I-CJL 6 RADAR																																																																		
GS 3.00° TCH 55	*6000	*5000	*4000	*3200	1900																																																																		
CATEGORY	A	B	C	D																																																																			
S-ILS 16R	615/18		200 (200-½)																																																																				
S-LOC 16R	800/24		385 (400-½)		800/40 385 (400-¾)																																																																		
CIRCLING	1000-1 567 (600-1)		1000-1½ 567 (600-1½)		1000-2 567 (600-2)																																																																		
<table border="1"> <tr> <td colspan="6">ELEV 433</td> </tr> <tr> <td>TDZE 415</td> <td>891</td> <td>391</td> <td>163° 4.4 NM from FAF</td> <td>191</td> <td></td> </tr> <tr> <td>0.6% DOWN</td> <td>0.6% DOWN</td> <td>0.6% DOWN</td> <td></td> <td>0.6% DOWN</td> <td></td> </tr> <tr> <td>0.8% UP</td> <td>0.8% UP</td> <td>0.8% UP</td> <td></td> <td>0.8% UP</td> <td></td> </tr> <tr> <td>8500 X 150</td> <td>9426 X 150</td> <td>1190 X 150</td> <td></td> <td></td> <td></td> </tr> <tr> <td>34L</td> <td>34R</td> <td>34R</td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="6">HIRL all Rws</td> </tr> <tr> <td colspan="6">TDZ/CL Rws 16L, 16C, 16R and 34R</td> </tr> <tr> <td colspan="6">FAF to MAP 4.4 NM</td> </tr> <tr> <td>Knots</td> <td>60</td> <td>90</td> <td>120</td> <td>150</td> <td>180</td> </tr> <tr> <td>Min:Sec</td> <td>4:24</td> <td>2:56</td> <td>2:12</td> <td>1:46</td> <td>1:28</td> </tr> </table>						ELEV 433						TDZE 415	891	391	163° 4.4 NM from FAF	191		0.6% DOWN	0.6% DOWN	0.6% DOWN		0.6% DOWN		0.8% UP	0.8% UP	0.8% UP		0.8% UP		8500 X 150	9426 X 150	1190 X 150				34L	34R	34R				HIRL all Rws						TDZ/CL Rws 16L, 16C, 16R and 34R						FAF to MAP 4.4 NM						Knots	60	90	120	150	180	Min:Sec	4:24	2:56	2:12	1:46	1:28
ELEV 433																																																																							
TDZE 415	891	391	163° 4.4 NM from FAF	191																																																																			
0.6% DOWN	0.6% DOWN	0.6% DOWN		0.6% DOWN																																																																			
0.8% UP	0.8% UP	0.8% UP		0.8% UP																																																																			
8500 X 150	9426 X 150	1190 X 150																																																																					
34L	34R	34R																																																																					
HIRL all Rws																																																																							
TDZ/CL Rws 16L, 16C, 16R and 34R																																																																							
FAF to MAP 4.4 NM																																																																							
Knots	60	90	120	150	180																																																																		
Min:Sec	4:24	2:56	2:12	1:46	1:28																																																																		

SEATTLE, WASHINGTON

Orig-B 09239

47° 27' N-122° 19' W

SEATTLE-TACOMA INTL (SEA)



ILS or LOC RWY 16R

VIAD 1974 VOR/DME 12 IAP


Orig
VOR/DME RWY 12

AL-5100 (FAA)

DULLES INTERNATIONAL
WASHINGTON D.C.



CATEGORY	A	B	C	D
S-12		780-1	470 (500-1)	
CIRCLING	800-1	487 (500-1)	800-1½ 487 (500-1½)	880-2 567 (600-2)



Knots	60	90	120	150	180
Min:Sec					

VOR/DME RWY 12

38°57' - 77°27'W

WASHINGTON, D.C.

18 JULY 1974

PUBLISHED BY NOS, NOAA, TO IACC SPECIFICATIONS

DULLES INTERNATIONAL

KRIL RNP AR Z 26 IAP

RIFLE, COLORADO

AL-6741 (FAA)


APP CRS	Rwy Idg	7011
261°	TDZE	5548
	Apt Elev	5548

RNAV (RNP) Z RWY 26
RIFLE/GARFIELD COUNTY RGNL (RIL)

RF and GPS required. Visibility reduction by helicopters NA.
Procedure NA for aircraft with wingspan greater than 136 feet.
 For uncompensated Baro-VNAV systems, procedure NA below -21°C (-6°F) or above 38°C (101°F). Missed approach requires RNP less than 1.0.
 *Missed approach requires minimum climb of 425 feet per NM to 6500.
 When VGSI inoperative, procedure NA at night.




ODALS
 MISSED APPROACH: Climb to 13000 via 261° track to SIYOP and via 261° track to PUVOY and via left turn to TEROE and via 231° track to WADAK and via 231° track to YIRDU and via 216° track to WOKPA and hold, continue climb-in-hold to 13000.

ASOS 135.275	DENVER CENTER 134.5 327.8	UNICOM 122.8 (CTAF)
------------------------	-------------------------------------	-------------------------------



SW-1, 24 SEP 2009 to 22 OCT 2009

SW-1, 24 SEP 2009 to 22 OCT 2009



CATEGORY	A	B	C	D
RNP 0.10 DA*	5990-1¼	442 (500-1¼)		NA
RNP 0.30 DA	6193-2	645 (700-2)		NA

SPECIAL AIRCRAFT AND AIRCREW AUTHORIZATION REQUIRED

MIRL Rwy 8-26
 REIL Rws 8 and 26

RIFLE, COLORADO
 Orig-A 09127

39°32'N-107°44'W

RIFLE/GARFIELD COUNTY RGNL (RIL)
RNAV (RNP) Z RWY 26

KBOI RNP AR RNP Z 28R IAP

BOISE, IDAHO

AL-57 (FAA)


APP CRS	Rwy Idg	10000
280°	TDZE	2871
	Apt Elev	2871

RNAV (RNP) Z RWY 28R
BOISE AIR TERMINAL (GOWEN FIELD) (BOI)

GPS required. For uncompensated Baro-VNAV systems, procedure NA below -14°C (7°F) or above 42°C (107°F). Visibility reduction by helicopters NA.



MISSED APPROACH: Climb to 6000 via track 280° to ATTOL and hold, continue climb-in-hold to 6000.

ATIS 123.9 290.4	BOISE APP CON 119.6 269.4	BOISE TOWER 118.1 257.8	GND CON 121.7 348.6	CLNC DEL 125.9 323.2
----------------------------	-------------------------------------	-----------------------------------	-------------------------------	--------------------------------



NW-1, 24 SEP 2009 to 22 OCT 2009

NW-1, 24 SEP 2009 to 22 OCT 2009



CATEGORY	A	B	C	D
RNP 0.15 DA		3204/60	333 (400-1¼)	
RNP 0.30 DA		3304-1½	433 (500-1½)	

**SPECIAL AIRCRAFT & AIRCREW
AUTHORIZATION REQUIRED**

BOISE, IDAHO
Orig 09239

BOISE AIR TERMINAL (GOWEN FIELD) (BOI)
43°34'N-116°13'W **RNAV (RNP) Z RWY 28R**

LEWISTON, IDAHO

APP CRS	Rwy Idg	5002
113.52°	TDZE	1415
	Apt Elev	1442


RNAV (RNP) Z RWY 12

LEWISTON-NEZ PERCE COUNTY (LWS)


GPS and RF required. Visibility reduction by helicopters NA. For uncompensated BARO-VNAV systems, procedure NA below -16C (3F) or above 36C (98F). *Missed approach requires minimum climb of 260 feet per NM to 3400. Procedure NA at night. **▲** NA when local weather not available.

MISSED APPROACH: Climb to 6000 via track 116.62 to VOSKY and via left turn to EVHOG and via track 049.82 to OFINO and hold.

ASOS 135.575	SEATTLE CENTER 123.95 282.3	LEWISTON TOWER * 119.4 (CTAF) 318.8	GND CON 121.9	UNICOM 122.95
-----------------	--------------------------------	----------------------------------------	------------------	------------------




BIDDY	4634.286N/11724.824W
FOJJO	4630.336N/11717.430W
HOBOP	4628.596N/11713.315W
PUW	4640.458N/11713.410W
HILUR	4632.381N/11713.843W
JENAS	4629.813N/11712.847W
OFINO	4631.323N/11609.915W
WANEY	4637.649N/11706.363W
TIZHO	4635.705N/11712.994W
NILDE	4627.203N/11710.026W
ONLAW	4625.288N/11705.517W
IYTAM	4624.567N/11704.113W
RW12	4622.907N/11701.412W
VOSKY	4619.951N/11656.611W
EVHOG	4619.084N/11647.956W



CATEGORY	A	B	C	D
RNP 0.30 DA*		1683 - 1	268 (300-1)	
RNP 0.30 DA		1887 - 1 3/4	472 (500-1 3/4)	

SPECIAL AIRCRAFT AND AIRCREW AUTHORIZATION REQUIRED



LEWISTON, IDAHO
 Orig

46°22'N-117°01'W

LEWISTON-NEZ PERCE COUNTY (LWS)
RNAV (RNP) Z RWY 12

NOTES / EXPLANATIONS FROM OPPOSITE SIDE OF FORM:
SEE ATTACHED AIRSPACE LETTER

\$ RNP 0.50 REQUIRED TO MITIGATE TERRAIN/CONTROLLED AIRSPACE REQUIREMENT AND TO ACCOMMODATE MINIMUM SEGMENT LENGTH REQUIREMENTS..

ACT: -16.4C
APT ISA: +12.12C
DELTA ISA LOW: -28.52
CRITICAL LOW TEMP: -16C
DELTA ISA HIGH: +24.87C
CRITICAL HIGH TEMP: +36C

MISSED APPROACH FAA08260.52, PARA 4.2 (STANDARD RNP MA)

RF TURN RADIUS/BANK ANGLE COMPUTATIONS:
SEGMENT ALT KIAS KTAS HAA VKTW TR BA
FOWBO-WANEY 10266 210.00 253.12 8823.8 108.42 5.30 19.77
WANEY-TIZHO 8652 210.00 246.34 7209.9 92.10 4.70 19.57
TIZHO-HILUR 6985 210.00 239.33 5542.6 75.43 4.00 19.88
JENAS-NILDE 4489 210.00 230.99 3556.7 55.57 4.40 15.23
ONLAW-IYTAM 2650 165.00 173.75 1209.2 50.00 7.00 5.58
VOSKY-EVHOG 6000 265.00 296.80 4558.2 65.58 5.50 19.20

3.1 DEGREE GLIDESLOPE AND 56.0' TCH UTILIZED TO ELIMINATE GQS PENETRATIONS.

PARA 251 RWY 12 20:1 PENETRATIONS:
KLWSL011 TREE 462258.69N/1170132.73W 1390.00 MSL
KLWSL014 TREE 462300.88N/1170133.91W 1393.00 MSL

PARA 251 RWY 12 34:1 PENETRATIONS:
KLWSL011 TREE 462258.69N/1170132.73W 1390.00 MSL
KLWSL014 TREE 462300.88N/1170133.91W 1393.00 MSL

VISI APPROVAL LETTER
VISUAL SEGMENT PENETRATIONS:
KLWSL011, 1390' MSL TREE 705' FROM APPROACH END OF RUNWAY 12, 51' RIGHT OF CENTERLINE, PENETRATES OIS BY 4.96'.
KLWSL014, 1393' MSL TREE 914' FROM APPROACH END OF RUNWAY 12, 60' RIGHT OF CENTERLINE, PENETRATES OIS BY 0.29'.
BOTH OBSTACLES HAVE A 1B ACCURACY CODE ASSIGNMENT. TREES WILL BE CHARTED ON THE PROCEDURE.

XP OBSTACLE CLIMB GRADIENT OF 260 FT PER NM TO 3400 REQUIRED.

PART B - SUPPLEMENTAL DATA			
1. COMMUNICATIONS WITH:		2. WEATHER SERVICE	
ZSE ARTCC SEA APP CON LWS ATCT		NWS OTHER: ASOS FAA A/C	
SATISFACTORY ON: <input checked="" type="checkbox"/> VHF <input checked="" type="checkbox"/> UHF <input type="checkbox"/> HF		LOCATION: KLSW	
		HRS OPTN: 24	
4. MONITOR STATUS		3. ALTIMETER SETTING	
PRIMARY		SOURCE: KLWS	
NAVAID:		DISTANCE: 0	
MONITOR POINT:		HOURS REMOTE OPERATION:	
HRS CAT 1		ADJUSTMENT:	
OPTN: CAT 3			
5. AIRSPACE		SECONDARY	
FLOOR OF CONTROLLED AIRSPACE UNDER FAC		NAVAID:	
CONTROL ZONE:		MONITOR POINT:	
HOURS OPTN		HRS CAT 1	
TRANSITION AREA		OPTN: CAT 3	
6. APPROACH & RUNWAY LIGHTING		7. RUNWAY MARKINGS BSG - 12, 30	
ALS		8. RUNWAY VISUAL RANGE	
(S) SALS		APPROACH	
<input checked="" type="checkbox"/> MALS-R 26		ROLL OUT	
<input checked="" type="checkbox"/> HIRL 8, 26		ELEV RWY THRESHOLD: 1369.9	
<input checked="" type="checkbox"/> MIRL 12, 30		ELEV GS ANTENNA:	
		THRESHOLD CROSSING HEIGHT: 56.0	
9. GLIDE SLOPE		10. FINAL APPROACH	
GS ANGLE: 3.1		COURSE AIMING <input checked="" type="checkbox"/> RUNWAY THRESHOLD	
DISTANCE FROM RWY:		ON CENTERLINE <input checked="" type="checkbox"/> F.T. FROM THRESHOLD	
		F.T. FROM CENTERLINE	
11. WAIVERS OF STANDARDS		NUMBER OF WAIVERS ON FILE	
		NONE	
DATES OF APPROVAL			
PART C - REMARKS: ASOS IS ON SERVICE-A. PRECIPITOUS TERRAIN EVALUATION COMPLETE.			
<div style="border: 2px solid red; padding: 5px; display: inline-block;"> <p>What about not charting the intermediate segment in the profile view?</p> </div>			
PART D - PREPARED BY: KEITH D. SHYKES		DATE: 07/14/2009	
TITLE: AERONAUTICAL INFORMATION SPECIALIST		OFFICE: AJW-324	

QUALITY CHECKED

**NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C.**

ISSUED: September 4, 1975

Forwarded to:
Honorable James E. Dow
Acting Administrator
Federal Aviation Administration
Washington, D. C. 20591

SAFETY RECOMMENDATION(S)

A-75-74 thru -77

On December 1, 1974, Trans World Airlines Flight 514, a B-727-231, crashed at Berryville, Virginia. During the National Transportation Safety Board's public hearing into the accident, testimony was heard regarding cartographic specifications and procedures used by the Jeppesen Company and the National Ocean Survey (NOS) to prepare instrument approach charts.

The Safety Board determined that the Jeppesen approach chart used by the crew of TWA 514 and the NOS approach chart used by the FAA controllers handling the flight were properly constructed; both met the requirements outlined in FAA Form 8260.5.

However, differences do exist between the Jeppesen charts and the NOS charts. The two charts vary considerably in areas where FAA Form 8260.5 does not specify exact format. The specific areas in which the Jeppesen charts and the NOS charts differ are (1) depiction of the minimum sector altitudes, (2) size and structure of the profile view, (3) criteria for the depiction of obstacles on the plan view, (4) color of inks, (5) size of type, and (6) portrayal of navigational facilities.

The Jeppesen Company produces most of the instrument approach charts used by the civil aviation community. The company receives a wide range of comments and suggested changes in these charts from pilots, carriers, and other segments of the industry, and is constantly revising its published charts to respond to the needs and requirements of its users.

The official United States Government specifications for cartographic presentation are contained in the Interagency Air Cartographic Committee (IACC) Manual No. 4, Flight Information Publication, Low-Altitude, Instrument Approach Procedures. The National Ocean Survey is governed by the cartographic specifications of the IACC Manual. This interagency committee is made up of representatives of the Federal Aviation Administration, the Department of Commerce, and the Department of Defense.

APPENDIX I

Honorable James E. Dow

The Safety Board believes that the latitude allowed in preparation of the two published charts creates an undesirable degree of dissimilarity. While these variations do not necessarily create a hazard, the application of uniform criteria and uniform cartographic depictions would eliminate any areas of possible misinterpretation. In order to insure that the best cartographic techniques are identified and employed, we believe that both types of charts should be analyzed to determine the most effective specifications for instrument approach charts. Once identified, these specifications should provide a basis for revision of IACC Manual No. 4.

In order to insure consistency between the preparation of FAA Form 8260.5 and the revised IACC specifications, the Safety Board further believes that reference to these revised specifications should be required of FAA personnel engaged in the preparation of FAA Form 8260.5.

Accordingly, the National Transportation Safety Board recommends that the Federal Aviation Administration:

1. In concert with the two other IACC Members (Department of Commerce and Department of Defense) and the Jeppesen Company, conduct a study of the cartographic techniques and specifications used throughout the aviation industry for approach charts for the purpose of identifying those techniques and specifications that best lend themselves to uniformity and standardization.
2. Based on the above study, initiate steps to revise the IACC manual to include those techniques and specifications that best lend themselves to uniformity and standardization and to which there is unanimous agreement by the parties engaged in the study.
3. Require that the IACC manual be used as the minimum standards for cartographic presentation of specified data on all instrument approach charts used in U. S. civil and military aviation.
4. Require that the revised IACC manual be used as a mandatory reference by FAA personnel whenever a new instrument approach procedure is developed or whenever an existing procedure is modified.

APPENDIX I

Honorable James E. Dow

McADAMS, THAYER, BURGESS, and HALEY, Members, concurred in the above recommendation. REED, Chairman, did not participate.



By: John H. Reed
Chairman

**DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION**

WASHINGTON, D.C. 20590

September 23, 1975

Honorable John H. Reed
Chairman, National Transportation Safety Board
800 Independence Avenue, S. W.
Washington, D. C. 20594



Dear Mr. Chairman:

This is in response to NTSB Safety Recommendation A-75-78.

Recommendation. Revise paragraph 1011 of FAA Handbook 8260.19, dated December 12, 1974, to require that on approach procedures, for which neither a procedure turn nor a 1-minute holding pattern is authorized, the profile must start either at the intermediate fix or at an altitude equal to the minimum sector altitude for the quadrant in which the procedure begins.

Comment. Change 14 to Handbook 8260.19 is in preparation. This will include the following instruction:

"On procedures when neither a procedure turn nor a one-minute holding pattern is authorized, the profile view shall include the intermediate fix and should be extended to include all fixes that are established on the final approach course extended."

This will ensure a smooth transition from the airway structure to the profile of the instrument approach procedure.

Minimum Sector Altitudes (MSA) are provided for emergency use. The MSA's were never intended for operational use since sectorization is not generally accomplished to obtain lower altitudes or to be compatible with operational altitudes published for specific terminal routes. Additionally, the range of MSA data is 25 nautical miles (plus a four-mile buffer) which may not correspond with all terminal routes portrayed on an instrument approach chart.

Sincerely,

James E. Dow
James E. Dow
Acting Administrator

MEETING 09-02: Mr. Richard Boll, NBAA, presented the issue and suggested that until the larger issue of RNAV RNP approach chart complexity is resolved through the FAA PARC Charting WG review, the “waivered” public use RNAV AR procedures, i.e. Boise and Lewiston, should be withdrawn from public use. Instead, these public use procedures should be restricted for use only by approved operators who accept the waiver to not chart the 5 intermediate fix route segments in the profile view.

Mr. Tom Schneider, FAA/AFS420, suggested another option could be to chart only the IF route that is aligned to the FAC. This idea was not received well, and some commented that it could be misleading and might cause additional misunderstanding. In the case of Boise, only 1 of 5 routes would then be shown in the profile. Mr. Schneider then suggested that maybe a reference note could be added to the profile view to tell pilots to refer to the chart planview for IF route segment information.

It was discussed that the FAA PARC Charting WG, led by Mr. Pedro Rivas, ALPA, has been tasked with reviewing RNAV RNP Chart Saturation regarding these types of situations and will provide recommendations. Mr. John Moore, FAA AeroNav Services, and Mr. Schneider commented that the ACF does not have the authority to suspend any program, including RNAV AR procedure development.

It was mentioned that the PARC Charting WG plans to complete its review of RNAV RNP Chart Saturation and provide recommendations to the PARC by April 2010. An alternative would be to carry the issue until the next ACF pending ACF consideration of the PARC’s recommendations.

Still at issue is how many public use RNAV RNP AR procedures with multiple IF segments are “in the pipeline” and might be released in the interim. Mr. Schneider said there are several such procedures in work.

ACTION: Mr. Richard Boll will coordinate with Mr. Brad Rush, FAA/AeroNav Services, as to a point of contact within AeroNav Services management to express NBAA’s concern.

ACTION: Mr. Pedro Rivas to report on recommendations from the PARC.

MEETING 10-01: Mr. Brad Rush, FAA/AeroNav, and Mr. Richard Boll reported no new information was available but the PARC was expected to comment on the recommendations noted in the RNAV (RNP) Charting Options.

Mr. Tom Schneider, FAA/AFS-420, noted that the charting of multiple IF’s on RNP SAAAR procedures will be a waived practice.

ACTION: Mr. Pedro Rivas, ALPA, to report on recommendations from the PARC.

MEETING 10-02: See RNAV (RNP) Chart Options in paragraph V. D).

STATUS: CLOSED