

## February 2008 Electrical Safety Occurrences

There were 8 electrical safety occurrences for February 2008:

- 3 resulted in shocks to workers
- 2 involved lockout/tagout
- 1 involved cutting an electrical wire
- 3 involved electrical workers and 5 involved non-electrical workers
- 3 involved subcontractors

In compiling the monthly totals, the search initially looked for occurrence discovery dates in this month (excluding Significance Category R reports), and for the following ORPS "HQ keywords":

01K – Lockout/Tagout Electrical, 01M - Inadequate Job Planning (Electrical),


08A – Electrical Shock, 08J – Near Miss (Electrical), 12C – Electrical Safety

The initial search yielded 9 occurrences. However, one occurrence (NE-ID--BEA-INLLABS-2008-0001) involved the repair of a lathe and a lockout/tagout for rotating equipment rather than an electrical hazard. Culling out this occurrence yielded 8 electrical safety occurrences for the month.

Below is the current summary of 2008 electrical safety occurrences:

Period	Electrical Safety Occurrences	Shocks	Burns	Fatalities
Jan-08	17	7	0	0
Feb-08	8	3	0	0
2008 total	25 (avg. 12.5/month)	10	0	0
2007 total	140 (avg. 11.7/month)	25	2	0
2006 total	166 (avg. 13.8/month)	26	3	0
2005 total	165 (avg. 13.8/month)	39	5	0
2004 total	149 (avg. 12.4/month)	25	3	1

The average rate of electrical safety occurrences in 2008 is now 12.5 per month, which remains more than the average rate of 11.7 per month experienced in 2007.



## Electrical Safety Occurrences – February 2008

No	Report Number	Subject/Title	EW <sup>(1)</sup>	N-EW <sup>(2)</sup>	SUB <sup>(3)</sup>	SHOCK	BURN	ARCF <sup>(4)</sup>	LOTO <sup>(5)</sup>	EXCAV <sup>(6)</sup>	CUT/D <sup>(7)</sup>	VEH <sup>(8)</sup>
1	EM-ORO--FWEC-TRUWPFAC-2008-0001	Deficient Lock Out Tag Out Procedure		X					X			
2	EM-RL--PHMC-PFP-2008-0002	Tape measure contacts plug in receptacle causing arc and damage to the tape and plug		X								
3	EM-SR--WSRC-HTANK-2008-0001	TANK 29 B-10 Riser Heat Trace Wire Damage While Removing Insulation		X							X	
4	FE--NETL-GOPE-NETLALBANY-2008-0001	Electrician Receives a Mild Shock Unexpectedly	X			X						
5	NA--LASO-LANL-TA55-2008-0004	Management Concern: Electrical Cord Discovered with Two Male Ends		X	X							
6	NA--NVSO-NST-LO-2008-0001	Lock Out/Tag Out Procedure Violation	X		X				X			
7	NA--SS-SNL-NMFAC-2008-0003	Crossed Neutral in Flexible Cord Connector results in Electrical Shock in Bldg. 808	X			X						
8	NA--SS-SNL-NMFAC-2008-0004	Asbestos Abatement Worker Receives Electrical Shock while Installing Plastic Sheeting in Bldg. 807		X	X	X						
	TOTAL		3	5	3	3			2		1	

### Key

(1)EW = electrical worker, (2)N-EW = non-electrical worker, (3)SUB = subcontractor, (4)ARCF = significant arc flash, (5)LOTO = lockout/tagout, (6)EXCAV = excavation, (7)CUT/D = cutting or drilling, (8)VEH = vehicle event

## ORPS Operating Experience Report

ORPS contains 53633 OR(s) with 56951 occurrences(s) as of 3/5/2008 7:39:57 AM  
 Query selected 8 OR(s) with 8 occurrences(s) as of 3/5/2008 2:14:34 PM

Download this report in Microsoft Word format. 

<b>1)Report Number:</b>	<a href="#">EM-ORO--FWEC-TRUWPFAC-2008-0001</a> After 2003 Redesign		
<b>Secretarial Office:</b>	Environmental Management		
<b>Lab/Site/Org:</b>	Oak Ridge Operations		
<b>Facility Name:</b>	TRU Waste Processor FAC		
<b>Subject/Title:</b>	Deficient Lock Out Tag Out Procedure		
<b>Date/Time Discovered:</b>	02/14/2008 14:10 (ETZ)		
<b>Date/Time Categorized:</b>	02/14/2008 16:00 (ETZ)		
<b>Report Type:</b>	Notification/Final		
<b>Report Dates:</b>	Notification	02/15/2008	11:57 (ETZ)
	Initial Update	02/15/2008	11:57 (ETZ)
	Latest Update	02/15/2008	11:57 (ETZ)
	Final	02/15/2008	11:57 (ETZ)
	Revision 1	02/19/2008	16:20 (ETZ)
<b>Significance Category:</b>	4		
<b>Reporting Criteria:</b>	10(3) - A near miss, where no barrier or only one barrier prevented an event from having a reportable consequence. One of the four significance categories should be assigned to the near miss, based on an evaluation of the potential risks and the corrective actions taken. (1 of 4 criteria - This is a SC 4 occurrence)		
<b>Cause Codes:</b>			
<b>ISM:</b>	3) Develop and Implement Hazard Controls		
<b>Subcontractor Involved:</b>	No		
<b>Occurrence Description:</b>	While clearing a lockout/Tagout (LO/TO)it was discovered that a lock and tag had been hung on the wrong (adjacent) breaker. Work associated with LO/TOS was formally suspended(Work Suspension 2008-002). A critique was conducted and identified a deficiency in procedure T-CM-FW-P-IS-019 Lock out/Tag Out, the procedure for verification of installation of LO/TO was inadequate. It did not require an adequate verification for the installation of a LO/TO. There was no immediate danger to workers.		
<b>Cause Description:</b>			
<b>Operating Conditions:</b>	Facility In Standby		
<b>Activity Category:</b>	Facility/System/Equipment Testing		
<b>Immediate Action(s):</b>	1. Suspended on all work associated with LO/TO. Work stopped on all		

	equipment with LO/TOs installed 2. Conducted a critique. Identified deficiency in LO/TO Procedure 3. Developed and issued a Timely Order to Operators detailing the expectations for adequate verification of LO/TO. Compensatory measures were put in place providing guidance on the adequate verification of the installation of LO/TO.						
<b>FM Evaluation:</b>							
<b>DOE Facility Representative Input:</b>							
<b>DOE Program Manager Input:</b>							
<b>Further Evaluation is Required:</b>	No						
<b>Division or Project:</b>	TRU Project						
<b>Plant Area:</b>	Processing Building						
<b>System/Building/Equipment:</b>	Waste Processing Building/ Remote Handled Waste Processing E						
<b>Facility Function:</b>	Nuclear Waste Operations/Disposal						
<b>Corrective Action:</b>							
<b>Lessons(s) Learned:</b>							
<b>HQ Keywords:</b>	01G--Inadequate Conduct of Operations - Inadequate Procedure 01K--Inadequate Conduct of Operations - Lockout/Tagout Noncompliance (Electrical) 12I--EH Categories - Lockout/Tagout (Electrical or Mechanical) 14D--Quality Assurance - Documents and Records Deficiency 14E--Quality Assurance - Work Process Deficiency						
<b>HQ Summary:</b>	A deficiency in verification requirements for lock-out/tag-out (LO/TO) was discovered during preoperational functional checks of the Remote Handled Waste Processing equipment. In addition to conducting the preoperational checks, operators were also installing LO/TO's to support ongoing inspections; the two tasks overlapped so that some of the functional checks required suspending inspection LO/TOs. A missing LO/TO was discovered during one of these suspension and attributed to the verification deficiency. Work was stopped and a critique was held.						
<b>Similar OR Report Number:</b>							
<b>Facility Manager:</b>	<table border="1"> <tr> <td>Name</td> <td>THOMPSON, CHRIS</td> </tr> <tr> <td>Phone</td> <td>(865) 574-3441</td> </tr> <tr> <td>Title</td> <td>FACILITIES MANAGEMENT DIRECTOR</td> </tr> </table>	Name	THOMPSON, CHRIS	Phone	(865) 574-3441	Title	FACILITIES MANAGEMENT DIRECTOR
Name	THOMPSON, CHRIS						
Phone	(865) 574-3441						
Title	FACILITIES MANAGEMENT DIRECTOR						
<b>Originator:</b>	<table border="1"> <tr> <td>Name</td> <td>THOMPSON, CHRIS</td> </tr> <tr> <td>Phone</td> <td>(865) 574-3441</td> </tr> <tr> <td>Title</td> <td>FACILITIES MANAGEMENT DIRECTOR</td> </tr> </table>	Name	THOMPSON, CHRIS	Phone	(865) 574-3441	Title	FACILITIES MANAGEMENT DIRECTOR
Name	THOMPSON, CHRIS						
Phone	(865) 574-3441						
Title	FACILITIES MANAGEMENT DIRECTOR						

<b>HQ OC Notification:</b>	Date	Time	Person Notified	Organization
	NA	NA	NA	NA
<b>Other Notifications:</b>	Date	Time	Person Notified	Organization
	02/14/2008	14:20 (ETZ)	Bob McKay	PM
	02/14/2008	14:25 (ETZ)	Tony Buhl	GM
	02/14/2008	14:30 (ETZ)	Bill McMillian	DOE PM
	02/14/2008	14:30 (ETZ)	Rick Farr	DOE FR
<b>Authorized Classifier(AC):</b>				

<b>2)Report Number:</b>	<a href="#">EM-RL--PHMC-PFP-2008-0002</a> After 2003 Redesign		
<b>Secretarial Office:</b>	Environmental Management		
<b>Lab/Site/Org:</b>	Hanford Site		
<b>Facility Name:</b>	Plutonium Finishing Plant		
<b>Subject/Title:</b>	Tape measure contacts plug in receptacle causing arc and damage to the tape and plug		
<b>Date/Time Discovered:</b>	02/13/2008 15:01 (PTZ)		
<b>Date/Time Categorized:</b>	02/14/2008 13:10 (PTZ)		
<b>Report Type:</b>	Notification/Final		
<b>Report Dates:</b>	Notification	02/19/2008	18:26 (ETZ)
	Initial Update	02/19/2008	18:26 (ETZ)
	Latest Update	02/19/2008	18:26 (ETZ)
	Final	02/19/2008	18:26 (ETZ)
<b>Significance Category:</b>	4		
<b>Reporting Criteria:</b>	10(2) - An event, condition, or series of events that does not meet any of the other reporting criteria, but is determined by the Facility Manager or line management to be of safety significance or of concern to other facilities or activities in the DOE complex. One of the four significance categories should be assigned to the occurrence, based on an evaluation of the potential risks and the corrective actions taken. (1 of 4 criteria - This is a SC 4 occurrence)		
<b>Cause Codes:</b>			
<b>ISM:</b>	2) Analyze the Hazards		
<b>Subcontractor Involved:</b>	No		
<b>Occurrence Description:</b>	At 1501 hours on 2/13/2008 an electrical fault with the potential to be of safety significance, or of concern to other facilities, occurred. An engineer was taking field measurements in Room 638, Building 2736-ZB with a typical metallic auto roll-up tape measure (16 ft X 3/4 inch width within a		

	<p>plastic housing). After taking a measurement, the engineer touched the auto retract button to retrieve the tape. As the tape moved against the wall, it collapsed and twisted, sliding along the wall, coming to rest within an approximate 1/8th inch gap between a cord plug and the electrical receptacle (120 V) it was plugged into. Upon contact, the metal tape shorted the plug's hot and neutral blades causing a momentary arc. An operator immediately told the engineer to drop the tape measure. After the engineer dropped the tape measure, it again shorted against the plug. As a result of both arcs, an approximate 3 &amp; 3/4 inch run of tape was burned, a hole approximately 1/4 inch X 1/2 inch was also burned into the edge of the tape, and the plug was damaged. The engineer did not receive any shock, the receptacle was not damaged, and the circuit breaker did not trip. These results were attributed to the tape being of light weight material and the engineer not being grounded by holding the tape measure by the plastic case and wearing rubber soled sneakers.</p> <p>On 2/14/2008 at 1310 hours, the acting Director for PFP Facility Management determined this event to be worthy of reporting as a management concern.</p>
<b>Cause Description:</b>	
<b>Operating Conditions:</b>	Routine fissile material handling and packaging operations within Building 2736-ZB
<b>Activity Category:</b>	Normal Operations (other than Activities specifically listed in this Category)
<b>Immediate Action(s):</b>	<ol style="list-style-type: none"> <li>1. Verified that there were no health-related effects among personnel involved (engineer and operator).</li> <li>2. Set up a safety boundary at the scene.</li> <li>3. De-energized the circuit at Panel LP-NP-3 breakers 12 &amp; 14.</li> <li>4. Removed the plug and tape measure.</li> <li>5. Initiated a check of equipment plugged into other receptacles on the circuit.</li> </ol> <p>Note: The plug was replaced on 02/14/2008.</p>
<b>FM Evaluation:</b>	<p>The determination of an SC-4 Management Concern was initially made by PFP facility management. Following this categorization, the FH Electrical Safety Point of Contact was asked to perform a review through application of the ORPS EFCOG Electrical Severity Measurement Tool [EFCOG / DOE Electrical Safety Improvement Project, Project Area 4 - Performance Measurement "Electrical Severity Measurement Tool" Revision 1, April 16, 2007]. The Electrical Severity (ES) equation is:</p> $ES = EHF(10) * [1 + EF(0) + SPF(10) + AFPF(0) + TP(0)] * IF(1) = 110 \Rightarrow SC\ 4\ Management\ Concern$ <p>ES = Electrical Severity  EHF = Electrical Hazard Factor - 120 volts (10)  EF = Environmental Factor - Dry (0)</p>

	<p>SPF = Shock Proximity Factor - Crossed the Prohibited Approach Boundary (10)          AFPF = Arc Flash Proximity Factor - (0)          TP = Thermal Proximity Factor - Does not apply (0)          IF = Injury Factor - None (1)</p> <p>The EFCOG developed this method for determining the severity associated with electrical energy type events to be able to quantify such events and apply some consistency in reporting them within the ORPS process.</p>						
<b>DOE Facility Representative Input:</b>							
<b>DOE Program Manager Input:</b>							
<b>Further Evaluation is Required:</b>	No						
<b>Division or Project:</b>	Plutonium Finishing Plant Closure Project						
<b>Plant Area:</b>	200 West						
<b>System/Building/Equipment:</b>	Electrical Outlet/2736-ZB/MetalTap Measure						
<b>Facility Function:</b>	Plutonium Processing and Handling						
<b>Corrective Action:</b>							
<b>Lessons(s) Learned:</b>							
<b>HQ Keywords:</b>	<p>01A--Inadequate Conduct of Operations - Inadequate Conduct of Operations (miscellaneous)          01Q--Inadequate Conduct of Operations - Personnel error          07D--Electrical Systems - Electrical Wiring          12C--EH Categories - Electrical Safety          14E--Quality Assurance - Work Process Deficiency</p>						
<b>HQ Summary:</b>	<p>An electrical fault occurred while an engineer was taking field measurements in Room 638, Building 2736-ZB with a metallic roll-up tape measure that has a plastic housing. When the engineer retracted the tape, the tape came into contact with the blades of an electric cord that was plugged into a receptacle. The tape shorted the plug's hot and neutral blades causing a momentary arc. The engineer dropped the tape measure, and it again shorted against the plug. As a result of both arcs, both the tape and plug were damaged. The engineer did not receive any shock, the receptacle was not damaged, and the circuit breaker did not trip.</p>						
<b>Similar OR Report Number:</b>							
<b>Facility Manager:</b>	<table border="1"> <tr> <td>Name</td> <td>JD MATHEWS</td> </tr> <tr> <td>Phone</td> <td>(509) 373-4598</td> </tr> <tr> <td>Title</td> <td>DIRECTOR, PFP FACILITY MANAGEMENT</td> </tr> </table>	Name	JD MATHEWS	Phone	(509) 373-4598	Title	DIRECTOR, PFP FACILITY MANAGEMENT
Name	JD MATHEWS						
Phone	(509) 373-4598						
Title	DIRECTOR, PFP FACILITY MANAGEMENT						
<b>Originator:</b>	<table border="1"> <tr> <td>Name</td> <td>SMITH, JAMES W</td> </tr> </table>	Name	SMITH, JAMES W				
Name	SMITH, JAMES W						

	Phone	(509) 372-3012		
<b>HQ OC Notification:</b>	Date	Time	Person Notified	Organization
	NA	NA	NA	NA
<b>Other Notifications:</b>	Date	Time	Person Notified	Organization
	02/14/2008	14:11 (PTZ)	JM Sondag	DOE-RL
<b>Authorized Classifier(AC):</b>	NA	Date: 02/19/2008		

<b>3)Report Number:</b>	<a href="#">EM-SR--WSRC-HTANK-2008-0001</a> After 2003 Redesign		
<b>Secretarial Office:</b>	Environmental Management		
<b>Lab/Site/Org:</b>	Savannah River Site		
<b>Facility Name:</b>	H Tank Farm		
<b>Subject/Title:</b>	TANK 29 B-10 Riser Heat Trace Wire Damage While Removing Insulation		
<b>Date/Time Discovered:</b>	02/28/2008 17:45 (ETZ)		
<b>Date/Time Categorized:</b>	02/28/2008 17:45 (ETZ)		
<b>Report Type:</b>	Notification		
<b>Report Dates:</b>	Notification	03/03/2008	08:21 (ETZ)
	Initial Update		
	Latest Update		
	Final		
<b>Significance Category:</b>	3		
<b>Reporting Criteria:</b>	10(3) - A near miss, where no barrier or only one barrier prevented an event from having a reportable consequence. One of the four significance categories should be assigned to the near miss, based on an evaluation of the potential risks and the corrective actions taken. (1 of 4 criteria - This is a SC 3 occurrence)		
<b>Cause Codes:</b>			
<b>ISM:</b>	2) Analyze the Hazards		
<b>Subcontractor Involved:</b>	No		
<b>Occurrence Description:</b>	On 2/28/08, a construction insulator, working for HTF maintenance, was tasked to remove insulation from Tank 29 B-10 riser valve CRW-V-144. The work package did not require a lockout, due to facility experience with insulation removal work packages. While removing the insulation from around valve CRW-V-144, the insulator inadvertently cut the heat trace wire. The heat trace wire was not visible to the insulator and cutting was unexpected. A minor arc was observed by a co-worker who alerted the insulator performing the work. The insulator notified his first line manager		



	and notifications were made to the Shift Operations Manager. The heat trace breaker, which had not tripped, was placed in the "off" position. An approved work package was completed to repair the heat trace wire on Tank 29. There was no other damage to the facility and no process shutdowns occurred as a result of this incident. As an interim measure, all LWO insulation removal packages are placed on "hold", unless worked with an approved lockout, until the critique is held and the corrective actions are implemented. A critique is scheduled for 3/3/08. The Shift Operations Manager has categorized this event as a Near Miss Management Concern 10(3) Significant Category 3.
<b>Cause Description:</b>	
<b>Operating Conditions:</b>	Tank 29 was in Operations Mode. No transfers in progress.
<b>Activity Category:</b>	Normal Operations (other than Activities specifically listed in this Category)
<b>Immediate Action(s):</b>	Heat tracing breaker was de-energized, area was placed in a safe condition.
<b>FM Evaluation:</b>	There were no injuries or process shutdowns as a result of this incident.
<b>DOE Facility Representative Input:</b>	
<b>DOE Program Manager Input:</b>	
<b>Further Evaluation is Required:</b>	Yes. Before Further Operation? No By Whom: Occurrence Investigator By When:
<b>Division or Project:</b>	CLOSURE/HCLOSURE
<b>Plant Area:</b>	H-TF
<b>System/Building/Equipment:</b>	241-929 / Waste Tank 29
<b>Facility Function:</b>	Nuclear Waste Operations/Disposal
<b>Corrective Action:</b>	
<b>Lessons(s) Learned:</b>	
<b>HQ Keywords:</b>	01N--Inadequate Conduct of Operations - Inadequate Job Planning (Other) 07D--Electrical Systems - Electrical Wiring 08J--OSHA Reportable/Industrial Hygiene - Near Miss (Electrical) 12C--EH Categories - Electrical Safety 14E--Quality Assurance - Work Process Deficiency
<b>HQ Summary:</b>	A construction insulator inadvertently cut a heat trace wire while removing insulation from a valve on a Waste Tank 29 riser. The work package did not require a lockout, due to facility experience with insulation removal work packages. The heat trace wire was not visible to the insulator and was unexpectedly cut. A co-worker observed a minor arc and alerted the insulator, who then notified his first line manager. The heat trace breaker, which had not tripped, was placed in the "off" position. An approved work package was completed to repair the heat trace wire on Tank 29. As an interim measure, insulation removal packages are placed on "hold", unless

	worked with an approved lockout. Notifications were made and a critique was held.			
<b>Similar OR Report Number:</b>				
<b>Facility Manager:</b>	Name	BORDERS, MICHAEL		
	Phone	(803) 208-8592		
	Title	FACILITY MANAGER		
<b>Originator:</b>	Name	JOHNSON, WAYMAN JEROME		
	Phone	(803) 208-0175		
	Title	QUALITY ENGINEER		
<b>HQ OC Notification:</b>	Date	Time	Person Notified	Organization
	NA	NA	NA	NA
<b>Other Notifications:</b>	Date	Time	Person Notified	Organization
	02/28/2008	17:45 (ETZ)	Ron Hampton	DOE-FR
	02/28/2008	17:45 (ETZ)	Mike Borders	FM
	02/28/2008	17:53 (ETZ)	Bill Lanham	OPS
	02/28/2008	17:54 (ETZ)	Adam Orris	Eng
	02/28/2008	17:55 (ETZ)	Kim Hauer	LWO-FM
	02/28/2008	18:00 (ETZ)	Marvin Holland	SRSOC
	02/28/2008	18:32 (ETZ)	Wayman Johnson	SIRIM
<b>Authorized Classifier(AC):</b>				

---

<b>4)Report Number:</b>	<a href="#">FE--NETL-GOPE-NETLALBANY-2008-0001</a> After 2003 Redesign		
<b>Secretarial Office:</b>	Fossil Energy		
<b>Lab/Site/Org:</b>	National Energy Technology Laboratory		
<b>Facility Name:</b>	NETL - Albany		
<b>Subject/Title:</b>	Electrician Receives a Mild Shock Unexpectedly		
<b>Date/Time Discovered:</b>	02/27/2008 10:51 (ETZ)		
<b>Date/Time Categorized:</b>	02/28/2008 14:20 (ETZ)		
<b>Report Type:</b>	Notification		
<b>Report Dates:</b>	Notification	03/03/2008	16:28 (ETZ)
	Initial Update		
	Latest Update		
	Final		
<b>Significance Category:</b>	3		
<b>Reporting Criteria:</b>	2C(2) - Failure to follow a prescribed hazardous energy control process		

	(e.g., lockout/tagout) or a site condition that results in the unexpected discovery of an uncontrolled hazardous energy source (e.g., live electrical power circuit, steam line, pressurized gas). This criterion does not include discoveries made by zero-energy checks and other precautionary investigations made before work is authorized to begin.
<b>Cause Codes:</b>	A2B3C03 - Equipment/ material problem; Inspection/ testing LTA; Post-maintenance/Post-modification testing LTA
<b>ISM:</b>	2) Analyze the Hazards 3) Develop and Implement Hazard Controls 4) Perform Work Within Controls 5) Provide Feedback and Continuous Improvement
<b>Subcontractor Involved:</b>	No
<b>Occurrence Description:</b>	An electrician removed the service panel on a 440 volt metal lathe to visually assess the electrical requirements for the lathe. The service panel was removed because the electrician needed to install a low voltage non-restart switch and was uncertain about the electrical demand used by the lathe. The service panel is routinely removed to perform maintenance activities such as belt replacement, belt adjustment, and debris removal. Access to the service panel does not normally involve exposure to electrical hazards and precautions such as unplugging the unit or lockout/tagged of the unit are only required when performing maintenance on the unit. In this instance, the electrician was merely performing a visual inspection of the electrical motor specifications, and energy isolation was not required. Upon removing the service panel, the electrician unexpectedly received a slight "tingle," at which time work was immediately halted by the electrician and the lathe tagged and removed from service.
<b>Cause Description:</b>	The plug used by the lathe was wired incorrectly. Upon inspection it was determined that one of the three phase wires had been connected to the ground position on the plug and the ground had been connected to the phase position. This reversed wiring of the ground and phase wires caused the metal surface of the lathe to be unexpectedly energized. The electrician was wearing proper footwear (rubber sole boots) at the time of the incident and therefore did not receive the full 277 volts being applied to the lathe surfaces.
<b>Operating Conditions:</b>	Normal Maintenance Operations

<b>Activity Category:</b>	Maintenance
<b>Immediate Action(s):</b>	The electrician immediately stopped work and contacted the supervisor to report what had happened. A volt meter was then used to determine voltage between the lathe and a reliable ground. A voltage of 277 volts was observed. The lathe was immediately unplugged, locked out, tagged out, and removed from service.
<b>FM Evaluation:</b>	The improperly wired electrical plug had been installed in May 2007 by a qualified electrician. It is unknown whether a subsequent modification of the plug had been made by an unqualified person.
<b>DOE Facility Representative Input:</b>	
<b>DOE Program Manager Input:</b>	
<b>Further Evaluation is Required:</b>	No
<b>Division or Project:</b>	Facility Maintenance
<b>Plant Area:</b>	Machine Shop
<b>System/Building/Equipment:</b>	Building 28 room 001
<b>Facility Function:</b>	Balance-of-Plant - Machine shops
<b>Corrective Action:</b>	
<b>Lessons(s) Learned:</b>	
<b>HQ Keywords:</b>	07D--Electrical Systems - Electrical Wiring 08A--OSHA Reportable/Industrial Hygiene - Electrical Shock 08H--OSHA Reportable/Industrial Hygiene - Safety Noncompliance 08J--OSHA Reportable/Industrial Hygiene - Near Miss (Electrical) 12C--EH Categories - Electrical Safety 14E--Quality Assurance - Work Process Deficiency 14H--Quality Assurance - Inspection and Acceptance Testing Deficiency
<b>HQ Summary:</b>	An electrician removed the service panel on a 440 volt metal lathe to visually assess the electrical requirements for the lathe. The electrician needed to install a low voltage non-restart switch and was uncertain about the electrical demand used by the lathe. Upon removing the service panel, the electrician unexpectedly received a slight "tingle". The electrician immediately stopped work and contacted the supervisor to report what had happened. A volt meter was then used to determine that the potential between the lathe and a reliable ground was 277 volts. The lathe was immediately unplugged, locked out, tagged out, and removed from service. The electrician was wearing proper footwear (rubber-soled boots) at the time of the incident and therefore did not receive the full 277 volts being applied to the lathe surfaces. Upon inspection it was determined that the plug had

	been improperly wired; one of the three phase wires had been connected to the ground position on the plug and the ground had been connected to the phase position, which caused the metal surface of the lathe to be unexpectedly energized..																			
<b>Similar OR Report Number:</b>	1. 1. EM-ID--BBWI-RWMC-2005-0005																			
	2. 2. SC--BSO-LBL-EETD-2007-0001																			
	3. 3. LM---STOL-MOUND-2007-0001																			
	4. 4. NA--SS-SNL-1000-2006-0017																			
<b>Facility Manager:</b>	<table border="1"> <tr> <td>Name</td> <td colspan="3">Rodriguez, Hector M</td> </tr> <tr> <td>Phone</td> <td colspan="3">(541) 967-5916</td> </tr> <tr> <td>Title</td> <td colspan="3">ES&amp;H MANAGER</td> </tr> </table>				Name	Rodriguez, Hector M			Phone	(541) 967-5916			Title	ES&H MANAGER						
Name	Rodriguez, Hector M																			
Phone	(541) 967-5916																			
Title	ES&H MANAGER																			
<b>Originator:</b>	<table border="1"> <tr> <td>Name</td> <td colspan="3">Rodriguez, Hector M</td> </tr> <tr> <td>Phone</td> <td colspan="3">(541) 967-5916</td> </tr> <tr> <td>Title</td> <td colspan="3">ES&amp;H MANAGER</td> </tr> </table>				Name	Rodriguez, Hector M			Phone	(541) 967-5916			Title	ES&H MANAGER						
Name	Rodriguez, Hector M																			
Phone	(541) 967-5916																			
Title	ES&H MANAGER																			
<b>HQ OC Notification:</b>	<table border="1"> <tr> <td>Date</td> <td>Time</td> <td>Person Notified</td> <td>Organization</td> </tr> <tr> <td>NA</td> <td>NA</td> <td>NA</td> <td>NA</td> </tr> </table>				Date	Time	Person Notified	Organization	NA	NA	NA	NA								
Date	Time	Person Notified	Organization																	
NA	NA	NA	NA																	
<b>Other Notifications:</b>	<table border="1"> <thead> <tr> <th>Date</th> <th>Time</th> <th>Person Notified</th> <th>Organization</th> </tr> </thead> <tbody> <tr> <td>02/27/2008</td> <td>20:30 (ETZ)</td> <td>Stephen Curfman</td> <td>NETL-Alb</td> </tr> <tr> <td>02/28/2008</td> <td>06:46 (ETZ)</td> <td>William Lowry</td> <td>NETL</td> </tr> <tr> <td>02/28/2008</td> <td>14:00 (ETZ)</td> <td>Robert Reuther</td> <td>NETL</td> </tr> </tbody> </table>				Date	Time	Person Notified	Organization	02/27/2008	20:30 (ETZ)	Stephen Curfman	NETL-Alb	02/28/2008	06:46 (ETZ)	William Lowry	NETL	02/28/2008	14:00 (ETZ)	Robert Reuther	NETL
Date	Time	Person Notified	Organization																	
02/27/2008	20:30 (ETZ)	Stephen Curfman	NETL-Alb																	
02/28/2008	06:46 (ETZ)	William Lowry	NETL																	
02/28/2008	14:00 (ETZ)	Robert Reuther	NETL																	
<b>Authorized Classifier(AC):</b>																				

---

<b>5)Report Number:</b>	<a href="#">NA--LASO-LANL-TA55-2008-0004</a> After 2003 Redesign														
<b>Secretarial Office:</b>	National Nuclear Security Administration														
<b>Lab/Site/Org:</b>	Los Alamos National Laboratory														
<b>Facility Name:</b>	Plutonium Proc & Handling Fac														
<b>Subject/Title:</b>	Management Concern: Electrical Cord Discovered with Two Male Ends														
<b>Date/Time Discovered:</b>	02/08/2008 16:30 (MTZ)														
<b>Date/Time Categorized:</b>	02/14/2008 11:35 (MTZ)														
<b>Report Type:</b>	Notification/Final														
<b>Report Dates:</b>	<table border="1"> <tr> <td>Notification</td> <td>02/19/2008</td> <td>18:48 (ETZ)</td> </tr> <tr> <td>Initial Update</td> <td>02/19/2008</td> <td>18:48 (ETZ)</td> </tr> <tr> <td>Latest Update</td> <td>02/19/2008</td> <td>18:48 (ETZ)</td> </tr> <tr> <td>Final</td> <td>02/19/2008</td> <td>18:48 (ETZ)</td> </tr> </table>			Notification	02/19/2008	18:48 (ETZ)	Initial Update	02/19/2008	18:48 (ETZ)	Latest Update	02/19/2008	18:48 (ETZ)	Final	02/19/2008	18:48 (ETZ)
Notification	02/19/2008	18:48 (ETZ)													
Initial Update	02/19/2008	18:48 (ETZ)													
Latest Update	02/19/2008	18:48 (ETZ)													
Final	02/19/2008	18:48 (ETZ)													
<b>Significance Category:</b>	4														

<b>Reporting Criteria:</b>	10(2) - An event, condition, or series of events that does not meet any of the other reporting criteria, but is determined by the Facility Manager or line management to be of safety significance or of concern to other facilities or activities in the DOE complex. One of the four significance categories should be assigned to the occurrence, based on an evaluation of the potential risks and the corrective actions taken. (1 of 4 criteria - This is a SC 4 occurrence)
<b>Cause Codes:</b>	
<b>ISM:</b>	4) Perform Work Within Controls
<b>Subcontractor Involved:</b>	Yes AK Services and Clause Construction
<b>Occurrence Description:</b>	<p><b>MANAGEMENT SYNOPSIS:</b> On the afternoon of the eighth of February, sub-contract workers experienced a tripped breaker while performing work at building PF-41 at Technical Area 55 (TA-55). The Facility and Infrastructure Recapitalization Project (FIRP) Project Leader was contacted, who came out to the site. The sub-contractor had brought several spider boxes on-site to assist with the decommissioning work at PF-41. All temporary power supplied to on-site spider boxes are on Ground Fault Circuit Interrupter (GFCI) circuits. One of these spider boxes appeared to be the source of the tripped breaker. The FIRP Project Leader unplugged everything from the spider box and then unplugged the box from the temporary power source. This is when he discovered that the spider box itself had been plugged into the temporary power source with an electrical cord that had two male ends, which violates several electrical safety codes. He immediately secured the cord and removed one end of it. A critique was held on February 14, 2008, at which time the Facilities Operations Director (FOD) declared this to be a Management Concern, Significance Category 4.</p> <p><b>BACKGROUND:</b> Two sub-contractors had been performing decommissioning work at PF-41, AK Services and Clause Construction. Clause Construction provided the site with spider boxes, which they allowed AK Services personnel to plug into, as needed. The spider boxes were set out for use and an Activity Hazards Analysis (AHA) was performed on the configuration on January 10, 2008. Sometime after that, the configuration changed.</p> <p>On or near January 28, 2008, AK Services needed to put in place a room with a heater in order to keep some materials dry. They borrowed the use of a spider box in order to supply power to the heater. AK Services contract has since been terminated and they have left the site and were not available at the critique.</p> <p>On January 7, 2008, Clause Construction personnel experience a tripped breaker due to a spider box. The FIRP Project Leader came out to the site and evaluated the load on the spider box. He thought that perhaps too many</p>

	<p>tools were being run off of one string from the spider box, so some tools were moved to another string and the spider box was put back in service.</p> <p>Then on January 8, 2008, when the same spider box tripped again, the FIRP Project Leader took a more in-depth look and discovered the electrical cord with two male ends. The spider boxes have a male side and a female side, so that they can be connected to each other, if need be. Clause Construction's cords have a male plug at one end and an open end at the other, so that they can be wired in or have a female end installed. The temporary power station receptacle that this spider box was plugged into takes a male end.</p> <p>According to the FIRP Project Leader, an unqualified worker placed a male end on the cord without inspecting the other end of the cord. This led to a cord with two male ends and the tripping of the breaker.</p> <p>According to the LANL Electrical Safety Office (ESO), this was not a near miss to injury, although the piece of equipment was hazardous. This event was run through the Electrical Severity Tool and the score is a 20. Due to this, and the lack of configuration control, the FOD declared this event a Management Concern, Significance Category 4.</p>
<b>Cause Description:</b>	
<b>Operating Conditions:</b>	Normal
<b>Activity Category:</b>	Facility Decontamination/Decommissioning
<b>Immediate Action(s):</b>	<ol style="list-style-type: none"> <li>1) The faulty cord was secured from further use.</li> <li>2) An AHA was performed on the spider box configuration on February 12, 2008, before returning to work.</li> <li>3) A Critique was held on February 14, 2008.</li> <li>4) Clause Construction created a Spider Box Configuration Verification form to prevent this type of event from occurring in the future.</li> <li>5) The TA-55 ESO will ensure that spider box configuration verification is captured institutionally.</li> <li>6) The Construction Safety Manager will ensure that spider box configuration management is captured in universal documents for sub-contractors working at LANL.</li> </ol>
<b>FM Evaluation:</b>	
<b>DOE Facility Representative Input:</b>	
<b>DOE Program Manager Input:</b>	
<b>Further Evaluation is Required:</b>	No
<b>Division or Project:</b>	TA55
<b>Plant Area:</b>	PF41
<b>System/Building/Equipment:</b>	Electrical Cord

<b>Facility Function:</b>	Plutonium Processing and Handling																							
<b>Corrective Action:</b>																								
<b>Lessons(s) Learned:</b>																								
<b>HQ Keywords:</b>	01A--Inadequate Conduct of Operations - Inadequate Conduct of Operations (miscellaneous) 01B--Inadequate Conduct of Operations - Loss of Configuration Management/Control 01M--Inadequate Conduct of Operations - Inadequate Job Planning (Electrical) 01Q--Inadequate Conduct of Operations - Personnel error 01S--Inadequate Conduct of Operations - Incorrect/Inadequate Installation 07D--Electrical Systems - Electrical Wiring 08H--OSHA Reportable/Industrial Hygiene - Safety Noncompliance 11G--Other - Subcontractor 12C--EH Categories - Electrical Safety 14D--Quality Assurance - Documents and Records Deficiency 14E--Quality Assurance - Work Process Deficiency																							
<b>HQ Summary:</b>	An electrical cord was discovered in use for temporary construction power which had two male ends, a violation of electrical safety codes. The cord was taken out of service and a critique was held																							
<b>Similar OR Report Number:</b>																								
<b>Facility Manager:</b>	<table border="1"> <tr> <td>Name</td> <td colspan="3">Stuart McKernan</td> </tr> <tr> <td>Phone</td> <td colspan="3">(505) 667-7501</td> </tr> <tr> <td>Title</td> <td colspan="3">Facilities Operations Director Designee</td> </tr> </table>				Name	Stuart McKernan			Phone	(505) 667-7501			Title	Facilities Operations Director Designee										
Name	Stuart McKernan																							
Phone	(505) 667-7501																							
Title	Facilities Operations Director Designee																							
<b>Originator:</b>	<table border="1"> <tr> <td>Name</td> <td colspan="3">VOSS, SUSAN J</td> </tr> <tr> <td>Phone</td> <td colspan="3">(505) 667-5979</td> </tr> <tr> <td>Title</td> <td colspan="3">OCCURRENCE INVESTIGATOR</td> </tr> </table>				Name	VOSS, SUSAN J			Phone	(505) 667-5979			Title	OCCURRENCE INVESTIGATOR										
Name	VOSS, SUSAN J																							
Phone	(505) 667-5979																							
Title	OCCURRENCE INVESTIGATOR																							
<b>HQ OC Notification:</b>	<table border="1"> <thead> <tr> <th>Date</th> <th>Time</th> <th>Person Notified</th> <th>Organization</th> </tr> </thead> <tbody> <tr> <td>NA</td> <td>NA</td> <td>NA</td> <td>NA</td> </tr> </tbody> </table>				Date	Time	Person Notified	Organization	NA	NA	NA	NA												
Date	Time	Person Notified	Organization																					
NA	NA	NA	NA																					
<b>Other Notifications:</b>	<table border="1"> <thead> <tr> <th>Date</th> <th>Time</th> <th>Person Notified</th> <th>Organization</th> </tr> </thead> <tbody> <tr> <td>02/13/2008</td> <td>09:54 (MTZ)</td> <td>Lily Reese</td> <td>PAAA</td> </tr> <tr> <td>02/13/2008</td> <td>10:00 (MTZ)</td> <td>Hotline</td> <td>NNSA</td> </tr> <tr> <td>02/13/2008</td> <td>10:03 (MTZ)</td> <td>Lloyd Gordon</td> <td>LANL ESO</td> </tr> <tr> <td>02/13/2008</td> <td>10:06 (MTZ)</td> <td>Chuck Keilers</td> <td>DNSFB</td> </tr> </tbody> </table>				Date	Time	Person Notified	Organization	02/13/2008	09:54 (MTZ)	Lily Reese	PAAA	02/13/2008	10:00 (MTZ)	Hotline	NNSA	02/13/2008	10:03 (MTZ)	Lloyd Gordon	LANL ESO	02/13/2008	10:06 (MTZ)	Chuck Keilers	DNSFB
Date	Time	Person Notified	Organization																					
02/13/2008	09:54 (MTZ)	Lily Reese	PAAA																					
02/13/2008	10:00 (MTZ)	Hotline	NNSA																					
02/13/2008	10:03 (MTZ)	Lloyd Gordon	LANL ESO																					
02/13/2008	10:06 (MTZ)	Chuck Keilers	DNSFB																					
<b>Authorized Classifier(AC):</b>	Susan J. Voss      Date: 02/19/2008																							
<b>6)Report Number:</b>	<a href="#">NA--NVSO-NST-LO-2008-0001</a> After 2003 Redesign																							
<b>Secretarial Office:</b>	National Nuclear Security Administration																							



<b>Lab/Site/Org:</b>	Bechtel Nevada, Livermore Operations		
<b>Facility Name:</b>	Livermore Operations		
<b>Subject/Title:</b>	Lock Out/Tag Out Procedure Violation		
<b>Date/Time Discovered:</b>	02/19/2008 10:30 (PTZ)		
<b>Date/Time Categorized:</b>	02/19/2008 10:45 (PTZ)		
<b>Report Type:</b>	Notification/Final		
<b>Report Dates:</b>	Notification	02/20/2008	14:15 (ETZ)
	Initial Update	02/20/2008	14:15 (ETZ)
	Latest Update	02/20/2008	14:15 (ETZ)
	Final	02/20/2008	14:15 (ETZ)
	Revision 1	02/20/2008	19:39 (ETZ)
<b>Significance Category:</b>	4		
<b>Reporting Criteria:</b>	10(2) - An event, condition, or series of events that does not meet any of the other reporting criteria, but is determined by the Facility Manager or line management to be of safety significance or of concern to other facilities or activities in the DOE complex. One of the four significance categories should be assigned to the occurrence, based on an evaluation of the potential risks and the corrective actions taken. (1 of 4 criteria - This is a SC 4 occurrence)		
<b>Cause Codes:</b>			
<b>ISM:</b>	3) Develop and Implement Hazard Controls		
<b>Subcontractor Involved:</b>	Yes NorCal Electric		
<b>Occurrence Description:</b>	<p>On February 14, 2008, as part of a National Security Technologies, LLC (NSTec) Livermore Operations (LO) Management Assessment, the electrical subcontractor was observed applying a personal lock and tag out (LOTO) to a single pole circuit breaker. After the LOTO was removed it was discovered by the safety representative that the employee who applied the lock did not actually perform the work.</p> <p>As part of a remodeling project a LOTO was needed to allow a wall switch to be removed. Electrical wiring to the wall switch needed to be pulled back into the overhead conduit and secured. After the subcontractor installed the LOTO, another subcontractor employee performed the actual work of disconnecting the wires and pulling the wires through the conduit. After the work was completed the LOTO was removed by the subcontractor employee who installed the LOTO.</p> <p>The subcontractors were immediately informed by the safety representative that the employee who is performing the hazardous energy operation is the person that needs to apply the lock and tag, as well as, have exclusive</p>		

	control of the key for that lock.  The condition was identified as ORPS on 2/19 when the management assessment was reviewed by the Price-Anderson Amendments Act/Worker Safety and Health screeners. No injuries or damage as a result of this occurrence.
<b>Cause Description:</b>	
<b>Operating Conditions:</b>	Does Not Apply
<b>Activity Category:</b>	Construction
<b>Immediate Action(s):</b>	The subcontractors were immediately informed by the safety representative that the employee who is performing the hazardous energy operation is the person that needs to apply the lock and tag, as well as, have exclusive control of the key for that lock.  Notifications made to NSTec and Nevada Site Office line management.
<b>FM Evaluation:</b>	Although this occurrence could meet the definition of Hazardous Energy Control 2C(2), it is our position that there was not a failure to control hazardous energy but a failure to follow the LOTO process; which could have resulted in a hazardous energy control failure. Therefore NSTec reported as a management concern.
<b>DOE Facility Representative Input:</b>	
<b>DOE Program Manager Input:</b>	
<b>Further Evaluation is Required:</b>	No
<b>Division or Project:</b>	Remodeling Project
<b>Plant Area:</b>	Livermore Operations
<b>System/Building/Equipment:</b>	Livermore Operations
<b>Facility Function:</b>	Balance-of-Plant - Offices
<b>Corrective Action:</b>	
<b>Lessons(s) Learned:</b>	
<b>HQ Keywords:</b>	01K--Inadequate Conduct of Operations - Lockout/Tagout Noncompliance (Electrical) 11G--Other - Subcontractor 12I--EH Categories - Lockout/Tagout (Electrical or Mechanical) 14E--Quality Assurance - Work Process Deficiency
<b>HQ Summary:</b>	During a Management Assessment, an electrical subcontractor was observed applying a personal lock and tag out (LOTO) to a single pole circuit breaker. After the LOTO was removed, the safety representative discovered that the employee who applied the lock did not actually perform the work, which consisted of removing a wall switch and securing the associated wiring. The safety representative immediately informed the subcontractors that the

	employee who is performing the hazardous energy operation is the person that needs to apply the lock and tag, as well as, have exclusive control of the key for that lock.			
<b>Similar OR Report Number:</b>	1. DP-NVOO--BN-LO-2001-0001			
<b>Facility Manager:</b>	Name	Ken Cooke		
	Phone	(925) 960-2525		
	Title	NSTec Livermore Operations Manager		
<b>Originator:</b>	Name	GILE, ANDREA L		
	Phone	(702) 295-7438		
	Title	PROJECT OPERATIONS SPEC.		
<b>HQ OC Notification:</b>	Date	Time	Person Notified	Organization
	NA	NA	NA	NA
<b>Other Notifications:</b>	Date	Time	Person Notified	Organization
	02/19/2008	12:30 (PTZ)	Duty Manager	SOC
	02/19/2008	12:45 (PTZ)	Dennis Armstrong	NSO/FR
<b>Authorized Classifier(AC):</b>				

---

<b>7)Report Number:</b>	<a href="#">NA--SS-SNL-NMFAC-2008-0003</a> After 2003 Redesign		
<b>Secretarial Office:</b>	National Nuclear Security Administration		
<b>Lab/Site/Org:</b>	Sandia National Laboratories - SS		
<b>Facility Name:</b>	SNL NM Site-wide F & M		
<b>Subject/Title:</b>	Crossed Neutral in Flexible Cord Connector results in Electrical Shock in Bldg. 808		
<b>Date/Time Discovered:</b>	02/01/2008 13:30 (MTZ)		
<b>Date/Time Categorized:</b>	02/01/2008 15:00 (MTZ)		
<b>Report Type:</b>	Notification		
<b>Report Dates:</b>	Notification	02/04/2008	17:57 (ETZ)
	Initial Update		
	Latest Update		
	Final		
<b>Significance Category:</b>	2		
<b>Reporting Criteria:</b>	2C(1) - Failure to follow a prescribed hazardous energy control process (e.g., lockout/tagout) or disturbance of a previously unknown or mislocated hazardous energy source (e.g., live electrical power circuit, steam line, pressurized gas) resulting in a person contacting (burn, shock, etc.)		

	hazardous energy.
<b>Cause Codes:</b>	
<b>ISM:</b>	
<b>Subcontractor Involved:</b>	Yes Enterprise Electric
<b>Occurrence Description:</b>	<p>On February 1, 2007, at approximately 1:30pm in Building 808, a line employee received a 120volt shock while holding a standard 120volt, 20-amp plug. The plug feeds a portable clean room. The portable clean room has three separate 120volt standard electrical plugs that feed its internal circuitry. Two circuits feed two fans and one circuit feeds the lights. An Electrical Construction Contractor pre-wired the apparatus in December for the building occupants.</p> <p>The impacted line employee plugged one cord into a wall receptacle and the employee heard "fan circuit 1" turn on. The worker then plugged in a second cord feeding "fan circuit 2" and did not hear any additional fans turning on. While walking the third cord to a third wall receptacle, the worker's finger simultaneously made contact with the neutral and ground pins of the cord end and received a shock. Investigation identified during the cord installation activity, the Electrical Construction Contract electrician crossed neutrals of the cords to fan 2 and the lights. Because of the crossed neutrals, the neutral connected to "fan circuit 2" was wired to the plug (lighting) the employee was holding. When the employee's finger in touched the neutral and ground terminals on the plug, the circuit to "fan circuit 2" was completed and the employee was shocked.</p> <p>A Facilities Maintenance Organization Center (FMOC) electrician was contacted for diagnostics and testing. The electrician corrected the problem and verified that all circuits are now in a safe configuration.</p> <p>The line employee was taken to medical for evaluation and released with no restrictions.</p>
<b>Cause Description:</b>	
<b>Operating Conditions:</b>	Normal
<b>Activity Category:</b>	Construction
<b>Immediate Action(s):</b>	FMOC electrical corrected the wiring and all circuits placed in a safe condition.
<b>FM Evaluation:</b>	Early Notification Dates and Times: EOC - 2/1/08 - 13:18 FR - Wayne Walker - 2/1/08, 13:56
<b>DOE Facility Representative Input:</b>	
<b>DOE Program Manager</b>	

<b>Input:</b>							
<b>Further Evaluation is Required:</b>	Yes. Before Further Operation? No By Whom: Causal Analysis Team By When: 03/17/2008						
<b>Division or Project:</b>	4000/Install 120v ext cords on a pre-fab clean rm						
<b>Plant Area:</b>	Tech Area I						
<b>System/Building/Equipment:</b>	Bldg. 808						
<b>Facility Function:</b>	Balance of Plant - Infrastructure (Other Functions not specifically listed in this Category)						
<b>Corrective Action:</b>							
<b>Lessons(s) Learned:</b>							
<b>HQ Keywords:</b>	01S--Inadequate Conduct of Operations - Incorrect/Inadequate Installation 07D--Electrical Systems - Electrical Wiring 08A--OSHA Reportable/Industrial Hygiene - Electrical Shock 11G--Other - Subcontractor 12C--EH Categories - Electrical Safety 14E--Quality Assurance - Work Process Deficiency 14G--Quality Assurance - Procurement Deficiency 14H--Quality Assurance - Inspection and Acceptance Testing Deficiency						
<b>HQ Summary:</b>	A line employee received a 120-volt shock while holding a standard 120-volt, 20-amp plug. The plug is one of three that provides electrical power to a portable clean room, two for fans and one for a light circuit. The impacted line employee plugged one cord into a wall receptacle and the employee heard "fan circuit 1" turn on. The employee then plugged in a second cord feeding "fan circuit 2" and did not hear any additional fans turning on. While walking the third cord to a third wall receptacle, the employee's finger simultaneously touched the neutral and ground pins of the cord end and received the shock. Investigation identified that a subcontractor electrician had crossed neutrals of the cords to fan 2 and the lights. When the employee's finger touched the neutral and ground, the circuit to "fan circuit 2" was completed. The employee was taken to medical for evaluation and released with no restrictions. An electrician corrected the plug wiring and verified that all circuits were in a safe configuration.						
<b>Similar OR Report Number:</b>							
<b>Facility Manager:</b>	<table border="1"> <tr> <td>Name</td> <td>Carla Lamb</td> </tr> <tr> <td>Phone</td> <td>(505) 844-1753</td> </tr> <tr> <td>Title</td> <td>ES&amp;H Coordinator - Facilities Management &amp; Ops Ctr</td> </tr> </table>	Name	Carla Lamb	Phone	(505) 844-1753	Title	ES&H Coordinator - Facilities Management & Ops Ctr
Name	Carla Lamb						
Phone	(505) 844-1753						
Title	ES&H Coordinator - Facilities Management & Ops Ctr						
<b>Originator:</b>	<table border="1"> <tr> <td>Name</td> <td>LUCERO, JEWELLEE A</td> </tr> <tr> <td>Phone</td> <td>(505) 845-4727</td> </tr> <tr> <td>Title</td> <td>REPORTING ADMINISTRATOR</td> </tr> </table>	Name	LUCERO, JEWELLEE A	Phone	(505) 845-4727	Title	REPORTING ADMINISTRATOR
Name	LUCERO, JEWELLEE A						
Phone	(505) 845-4727						
Title	REPORTING ADMINISTRATOR						

<b>HQ OC Notification:</b>	Date	Time	Person Notified	Organization
	NA	NA	NA	NA
<b>Other Notifications:</b>	Date	Time	Person Notified	Organization
	02/01/2008	15:00 (MTZ)	John Norwalk	4827
	02/01/2008	15:00 (MTZ)	Michael Quinlan	4820
	02/04/2008	07:30 (MTZ)	Wayne Walker, FR	DOE/SSO
<b>Authorized Classifier(AC):</b>	John Norwalk     Date: 02/04/2008			

<b>8)Report Number:</b>	<a href="#">NA--SS-SNL-NMFAC-2008-0004</a> After 2003 Redesign		
<b>Secretarial Office:</b>	National Nuclear Security Administration		
<b>Lab/Site/Org:</b>	Sandia National Laboratories - SS		
<b>Facility Name:</b>	SNL NM Site-wide F & M		
<b>Subject/Title:</b>	Asbestos Abatement Worker Receives Electrical Shock while Installing Plastic Sheeting in Bldg. 807		
<b>Date/Time Discovered:</b>	02/08/2008 09:40 (MTZ)		
<b>Date/Time Categorized:</b>	02/08/2008 09:40 (MTZ)		
<b>Report Type:</b>	Notification		
<b>Report Dates:</b>	Notification	02/11/2008	16:25 (ETZ)
	Initial Update		
	Latest Update		
	Final		
<b>Significance Category:</b>	2		
<b>Reporting Criteria:</b>	2C(1) - Failure to follow a prescribed hazardous energy control process (e.g., lockout/tagout) or disturbance of a previously unknown or mislocated hazardous energy source (e.g., live electrical power circuit, steam line, pressurized gas) resulting in a person contacting (burn, shock, etc.) hazardous energy.		
<b>Cause Codes:</b>			
<b>ISM:</b>			
<b>Subcontractor Involved:</b>	Yes Southwest Hazard Control/ATC, New Mexico		
<b>Occurrence Description:</b>	On February 8, 2008, at approximately 9:10am, a Facilities Management & Operations Center (FMOC) subcontract asbestos abatement worker installing plastic sheeting in preparation for asbestos abatement activities in Building 807 received an electrical shock. The asbestos abatement activities are part of the FMOC 807 Demolition project and is located on the third floor next the center stairwell.		

	<p>While installing the plastic sheeting the worker pulled a conduit away from a small section of brick wall to place the plastic material behind the conduit. The conduit pulled apart at a coupling and damaged the conductors resulting in a 120V shock to the worker. The worker was transported to SNL Medical by a co-worker for medical evaluation and was release that same day with no restrictions.</p> <p>The conduit was traced by an FMOC electrical engineering representative, safety representative, and electrical subcontractor responding to the incident. The conduit contained two # 12 hot conductors and a neutral (conduit was acting as the ground path which was typical when this building was constructed) that originated in Panel EP1 located in the basement. The two 120V, 20 amp single pole breakers supplying power to the conductors were placed in the off position and locked and tagged by the electrical subcontractor working on the project.</p> <p>The Project Manager suspended all work on the project until FMOC electrical engineering evaluates the building electrical system and develops an electrical plan for the Demolition project.</p>
<b>Cause Description:</b>	Critique/Fact Finding 2/8/08
<b>Operating Conditions:</b>	Normal
<b>Activity Category:</b>	Facility Decontamination/Decommissioning
<b>Immediate Action(s):</b>	<p>- Worker was taken to SNL Medical</p> <p>- Work on project was suspended until Electrical Engineering evaluates the building electrical system</p>
<b>FM Evaluation:</b>	<p>DOE/SSO Early Notification Date &amp; Time:  EOC - 2/8/08 - 09:55  Bill Wechsler, FR - 2/8/08 - 10:03</p>
<b>DOE Facility Representative Input:</b>	
<b>DOE Program Manager Input:</b>	
<b>Further Evaluation is Required:</b>	<p>Yes.  Before Further Operation? No  By Whom: Causal Analysis Team  By When:</p>
<b>Division or Project:</b>	4000
<b>Plant Area:</b>	Tech Area I
<b>System/Building/Equipment:</b>	Bldg. 807
<b>Facility Function:</b>	Balance of Plant - Infrastructure (Other Functions not specifically listed in this Category)
<b>Corrective Action:</b>	

<b>Lessons(s) Learned:</b>																					
<b>HQ Keywords:</b>	01N--Inadequate Conduct of Operations - Inadequate Job Planning (Other) 07D--Electrical Systems - Electrical Wiring 08A--OSHA Reportable/Industrial Hygiene - Electrical Shock 08H--OSHA Reportable/Industrial Hygiene - Safety Noncompliance 11G--Other - Subcontractor 12C--EH Categories - Electrical Safety 14E--Quality Assurance - Work Process Deficiency																				
<b>HQ Summary:</b>	A subcontract asbestos abatement worker installing plastic sheeting in preparation for asbestos abatement activities in Building 807 received an electrical shock. The worker pulled a conduit away from a small section of brick wall in order to place the plastic material behind it. The conduit pulled apart at a coupling and damaged the conductors resulting in a 120-volt shock to the worker. The worker was transported to SNL Medical by a co-worker for medical evaluation and was release that same day with no restrictions. Work has been suspended pending evaluation of the building electrical system.																				
<b>Similar OR Report Number:</b>																					
<b>Facility Manager:</b>	<table border="1"> <tr> <td>Name</td> <td>Carla Lamb</td> </tr> <tr> <td>Phone</td> <td>(505) 844-1753</td> </tr> <tr> <td>Title</td> <td>ES&amp;H Coordinator - Facilities Management &amp; Ops Ctr</td> </tr> </table>	Name	Carla Lamb	Phone	(505) 844-1753	Title	ES&H Coordinator - Facilities Management & Ops Ctr														
Name	Carla Lamb																				
Phone	(505) 844-1753																				
Title	ES&H Coordinator - Facilities Management & Ops Ctr																				
<b>Originator:</b>	<table border="1"> <tr> <td>Name</td> <td>LUCERO, JEWELLEE A</td> </tr> <tr> <td>Phone</td> <td>(505) 845-4727</td> </tr> <tr> <td>Title</td> <td>REPORTING ADMINISTRATOR</td> </tr> </table>	Name	LUCERO, JEWELLEE A	Phone	(505) 845-4727	Title	REPORTING ADMINISTRATOR														
Name	LUCERO, JEWELLEE A																				
Phone	(505) 845-4727																				
Title	REPORTING ADMINISTRATOR																				
<b>HQ OC Notification:</b>	<table border="1"> <thead> <tr> <th>Date</th> <th>Time</th> <th>Person Notified</th> <th>Organization</th> </tr> </thead> <tbody> <tr> <td>NA</td> <td>NA</td> <td>NA</td> <td>NA</td> </tr> </tbody> </table>	Date	Time	Person Notified	Organization	NA	NA	NA	NA												
Date	Time	Person Notified	Organization																		
NA	NA	NA	NA																		
<b>Other Notifications:</b>	<table border="1"> <thead> <tr> <th>Date</th> <th>Time</th> <th>Person Notified</th> <th>Organization</th> </tr> </thead> <tbody> <tr> <td>02/08/2008</td> <td>09:48 (MTZ)</td> <td>John Norwalk</td> <td>4827</td> </tr> <tr> <td>02/08/2008</td> <td>09:50 (MTZ)</td> <td>Wayne Walker, FR</td> <td>DOE/SSO</td> </tr> <tr> <td>02/08/2008</td> <td>13:54 (MTZ)</td> <td>Jeff Quintenz</td> <td>4800</td> </tr> <tr> <td>02/08/2008</td> <td>13:54 (MTZ)</td> <td>Michael Quinlan</td> <td>4820</td> </tr> </tbody> </table>	Date	Time	Person Notified	Organization	02/08/2008	09:48 (MTZ)	John Norwalk	4827	02/08/2008	09:50 (MTZ)	Wayne Walker, FR	DOE/SSO	02/08/2008	13:54 (MTZ)	Jeff Quintenz	4800	02/08/2008	13:54 (MTZ)	Michael Quinlan	4820
Date	Time	Person Notified	Organization																		
02/08/2008	09:48 (MTZ)	John Norwalk	4827																		
02/08/2008	09:50 (MTZ)	Wayne Walker, FR	DOE/SSO																		
02/08/2008	13:54 (MTZ)	Jeff Quintenz	4800																		
02/08/2008	13:54 (MTZ)	Michael Quinlan	4820																		
<b>Authorized Classifier(AC):</b>	John Norwalk      Date: 02/11/2008																				