



# Fatigue Testing of 9 m Carbon Fiber Wind Turbine Research Blades

**Joshua Paquette**

*Sandia National Laboratories*

**Scott Hughes and Jeroen van Dam**

*National Renewable Energy Laboratory*

**Jay Johnson**

*Georgia Institute of Technology*

46th AIAA Aerospace Sciences Meeting and Exhibit

Reno, NV

January 10<sup>th</sup>, 2008

Sandia is a multiprogram laboratory operated by Sandia Corporation, a Lockheed Martin Company, for the United States Department of Energy's National Nuclear Security Administration under contract DE-AC04-94AL85000.





# Background, Purpose, and Overview

---

- **Background**

- SNL initiated a blade research program in 2002 to investigate the use of carbon in subscale 9 m blades
- 7 CX-100 and 7 TX-100 blades were manufactured
- Blades from each set have undergone modal and static tests

- **Purpose of Fatigue Tests**

- Verify that blades met their design criteria
- Investigate unique structural aspects of the blades
- Examine the use of advanced sensors

- **Overview**

- Carbon in blades
- 9 m Blade Designs
- Test Setup
- Test Results
- Conclusions



# Carbon in Blades

- **Advantages:**


- High stiffness/
- Highly orthotropic
- Excellent fatigue life of fibers

- **Disadvantages:**

- Higher cost
- Limited availability
- Difficult to infuse
- Poor properties
- Possible stiffness


- **Potential solution:** triax fabric

- Relatively inexpensive
- Infusible
- Dry fabric for composite techniques
- Maintains excellent fiber straightness



\*Studies of carbon materials performed by and in collaboration with GEC and MSU


# SAERTEX Carbon Tri-ax Fatigue Performance



Source: Montana State University

# CX-100


- CX-100 (Carbon Experimental 100 kW)
- Manufactured using existing 9 m molds
- Based on ERS-100 blade with non-scalloped root
- Glass-Epoxy blade with full length carbon spar cap



CX-100 Blade Skin


# TX-100

- TX-100 (TWist-Bend Coupled Experimental 100 kW)
- Identical geometry to CX-100
- Partial-length glass spar cap
- 20° off-axis carbon in outboard (~>3.5 m) skins to produce material-induced, passive aerodynamic load alleviation



Source: NREL


Material Induced Twist-Bend Coupling



TX-100 Blade Skin



# 9 m Blade designs



CX-100 (top) and TX-100 (bottom) Geometry and Major Laminate Regions



# Fatigue Test Methodology


---

- **Test objective**
  - Demonstrate 20-year fatigue equivalent life
  - Complete test in 1-4 million cycles
- **Fatigue Equivalent Life Calculation Procedure**
  1. Perform system dynamics simulations
  2. Count fatigue cycles/second
  3. Extrapolate to 20-years
  4. Compute damage fraction using damage model along with material data, appropriate safety factors, and damage accumulation counting method




# CX-100 and TX-100 Simulations

## CX-100 (Static Driven Design)



## TX-100 (Fatigue Driven Design)





## Test Setup: CX-100

---

- **Fatigue analysis focused on carbon spar cap**
- **Slope parameter of 12 used (GL standards: 10 for glass, 14 for carbon)**
- **Single-axis flapwise point loading**
  - Hydraulic cylinder used to apply oscillating load at single point
  - Robust, simple setup
  - Only allows for target load matching in limited area
- **1.25-12.5 kN applied at saddle for 1M cycles, then increased by 10% every 500k cycles**
- **20-year fatigue equivalent life demonstrated in 6k cycles**




# Test Setup: TX-100

---

- **Fatigue analysis focused on both glass and carbon areas**
- **Slope parameter of 10 used (for off-axis loading)**
- **Single-axis flapwise resonant loading**
  - Uses oscillating mass to excite natural frequencies of blade-mass system
  - Mean load adjusted by exciter and ballast masses
  - Amplitude adjusted by exciter displacement
  - Complicated setup required to produce correct shape and amplitude
  - Potentially allows for load matching for large portion of blade span
- **1M, 2M, and 4M cycle test loads calculated**
- **Test began with 4M load and then increased 10% beginning at 1M cycle count and repeating every 500k cycles**
- **Unable to increase at 2.5M cycles, load was held constant thereafter**
- **20-year fatigue equivalent life demonstrated at 2M cycles**

# UREX


- Developed specifically for the unique aspects of testing bend-twist coupled blades
- Pair of hydraulic actuators mounted to the blade through a ballast saddle
- Rotational inertia minimized compared to mounting actuator and resonant mass above the blade
- Possible to apply torsional loading by adjusting actuator phases
- Horizontally mounted cylinder can be used to excite edge movement




UREX Schematic

# Applied Loads

**CX-100  
(Single Point Loading)**



**TX-100  
(Resonant Loading)**



Fatigue Test Applied Loads



# CX-100 Test Results

---



CX-100 Early in Fatigue Test

January 10th, 2008

46th AIAA Aerospace Sciences  
Meeting and Exhibit

14



# CX-100 Test Results

---



CX-100 Dimple (left) and Tip Movement (right) just before Failure



# CX-100 Test Results

---




CX-100 Dimple (left) and Tip Movement (right) at Failure






# CX-100 Test Results



January 10th, 2008

# CX-100 Failure Mechanism


- Dimple formed early during test around max chord
- Low pressure skin pushed outward aft of sparcap and inward forward of sparcap
- At 1.5M cycles, crack began to grow along sparcap/aft-panel intersection
- Crack resulted in greatly decreased stiffness in the area and cause severe edgewise movement



CX-100 Crack Growth

# TX-100 Test Results

---



TX-100 Early in Fatigue Test

January 10th, 2008

46th AIAA Aerospace Sciences  
Meeting and Exhibit

19



# TX-100 Test Results

---





TX-100 Sparcap Tip Stress Contours




# TX-100 Test Results



---



TX-100 Crack Growth Beginning (left) and Progression (right)




st



TX-100 Strain Gage Layout

# TX-100 Failure Mechanism

- At 723k cycle count, crack began to grow just outboard of HP sparcap termination
- Cracks grew at 65° angle from blade axis until 2.4M cycles
- Crack then changed direction and grew along 20° direction corresponding to carbon fiber direction
- Growth of crack continued until 4M cycles when excessive torsional movement of the blade tip occurred



TX-100 HP Crack Growth



# Conclusions

---

- **CX-100 failed due to buckle formation near max-chord which caused a fracture between the sparcap and aft balsa panel leading to excessive edge movement**
- **TX-100 failed due to crack which grew from sparcap termination on HP surface along carbon fiber direction causing excessive tip rotation**
- **Infused carbon was effectively implemented in a CX-100 and TX-100 blade designs**
- **Both blades failed in carbon areas**
- **Blades failed due to damage in off-axis directions, showing the difficulty in using fiber-direction fatigue calculations**





# Acknowledgements

---

## **US Department of Energy**

**Mike Jenks, Jason Cotrell, and Dave Sims (NREL)**  
**Dayton Griffin and Tim McCoy (GEC)**  
**Mark Rumsey, Perry Jones, Wesley Johnson (SNL)**  
**Mike Zuteck**  
**Derek Berry (TPI)**