

UNITED STATES GOVERNMENT

Memorandum

TENNESSEE VALLEY AUTHORITY

CDB '82 0825 017

TO : H. S. Fox, Director of Fossil and Hydro Power, 716 EB-C

FROM : M. N. Sprouse, Manager of Engineering Design, W11A9 C-K

DATE : August 25, 1982

SUBJECT: KINGSTON STEAM PLANT - ANNUAL ASH DISPOSAL AREA INSPECTION

Attached is a report from Ronald D. Powell to Frank D. Stansberry dated August 25, 1982 (CDB 820825 016), on the joint inspection of the ash disposal area at Kingston Steam Plant which includes recommendations for corrective work. I concur in these recommendations.

Original Signed By
I. L. Burroughs
 M. N. Sprouse

GLB:RDP:TLT
 Attachment: 4
 cc: R. O. Barnett, W9D224 C-K
 G. L. Buchanan, W3C126 C-K
J. P. Darling, 546 CST2-C (Attachment)
 S. B. Jack, 5100 MIB-K
 MEDS, W5B63 C-K

Principally prepared by: R. D. Powell, extension 3581.

REC'D		
10:00 AUG 27 '82		
CIVIL ENG. & DES. BRANCH		
	IN	OUT
N	Date/Time	Date/Time
✓		
	GLB	
	DLG	
	TJA	
	HCB	
	ELS	
	REH	
	CNJ	
	3B NAL	
✓	127/11	FDS 22/20
✓	127/1	RIB 27/2
	JRF	
	RAD	
	JHC	
	REB	
	SDS	
	JTP	

✓ RDP
 ✓ 27 230 KWB 27 245

Y12236.03

UNITED STATES GOVERNMENT

HRB

Memorandum

TENNESSEE VALLEY AUTHORITY

CDB '82 0825 016

TO : Frank D. Stansberry, Head Civil Engineer (Site Development, Highway, Railroad, and Bridge Design), W3A7 C-K

FROM : Ronald D. Powell, Civil Engineer (Site Development, Highway, and Railroad Design), W3A25 C-K

DATE : August 25, 1982

SUBJECT: KINGSTON STEAM PLANT - ANNUAL ASH DISPOSAL AREA INSPECTION

On August 4, 1982, Joel Paris of F&H PR and I inspected the ash disposal area at Kingston Steam Plant. We were accompanied on the inspection by Coy Wood, Yard Operations Supervisor. Findings were discussed with L. B. Kennedy, Plant Superintendent, and Ford Clayton, Assistant Plant Superintendent.

The last annual inspection was made on September 9, 1981 (CDB 810925 010). An interim inspection was made on March 10, 1982 (CDB 820316 002).

On the attached print of drawing 10N420, the different areas are designated.

Change in Dikes Since Last Inspection

There has been no significant change in the dikes since last year's annual inspection.

The small area of surface wetness at the toe of the exterior slope of the south end of dike C was observed to still exist (picture 4 and recommendation 1).

An interior dike of bottom ash, extending northeast from the existing deflector dike in the approximate location shown on the attached print of drawing 10N420, is presently under construction.

All dikes appear to be in good condition with no visible signs of instability. The tops of the dikes are surfaced with crushed stone and have a good slope to the inside.

Both the interior and exterior slopes of all earth dikes have a good vegetative cover (picture 5).

Change in Pond Operation Since Last Inspection

There has been no change in pond operation since last year's annual inspection.

Condition of Spillways, Skimmers, and Outlets

The standard spillways and skimmers in the stilling pool area appear to be in good condition and functioning properly. Five of these six spillway outlets are discharging equally. The spillway on the west end has been raised and is not discharging. The concrete end wall appears to be in good condition; however, some small trees and brush were observed to be growing



Frank D. Stansberry
August 25, 1982

KINGSTON STEAM PLANT - ANNUAL ASH DISPOSAL AREA INSPECTION

in very close proximity to the end wall and should be removed (picture 6 and recommendation 2). The dike slope behind the end wall appeared to be dry and well compacted. The riprap outfall to the plant intake channel was submerged and could not be closely inspected. There was no sign of loss of ash into the intake channel.

The plant-designed and plant-constructed spillways and skimmers from the ash disposal area to the stilling pool area appear to be in good condition and functioning properly (picture 1). There has been no noticeable settlement of these structures, although it was reported to us during our subsequent discussion with Mr. Kennedy that plant personnel had encountered a seam of very soft material while driving the piles for the foundations of these structures. This seam of soft material was reported to be 10 to 12 feet beneath the earth surface and approximately 10± feet thick. The outlets of these spillways were in good condition (pictures 2 and 3). Some algae was present in the stilling pool area around the outlet for the circular spillway.

The plant-constructed spillways of the initial ash disposal area in the east end of the north dike were submerged; however, they appeared to be functioning adequately.

The outlets of the plugged and abandoned spillways in the northern portion of dike C were submerged by Watts Bar Lake and could not be inspected for leakage.

Action on Recommendation of Last Inspection

Sparsely vegetated areas of the dike slopes have been reseeded and fertilized. Both the interior and exterior slopes of all earth dikes have a good vegetative cover.

Recommendations

1. Plant personnel shall continue to observe the area of surface wetness at the toe of the exterior slope of the south end of dike C. Any worsening of this condition shall be reported to EN DES immediately.

Y12236.02

Frank D. Stansberry
August 25, 1982

KINGSTON STEAM PLANT - ANNUAL ASH DISPOSAL AREA INSPECTION

- 2. Remove small trees and brush from around the concrete end wall for the stilling pool area discharge pipes.

Ronald D. Powell
 Ronald D. Powell

KWS RDP:TLT
 Attachments


Concur: *Frank D. Stansberry*
 Frank D. Stansberry

G. L. Buchanan
 G. L. Buchanan

8/25/82 - FDS:TLT
 cc: G. L. Buchanan, W3C1126 C-K (Attachments)

8/25/82 - GLB:TLT
 cc: R. O. Barnett, W9D224 C-K (Attachments)
 S. B. Jack, 5100 MIB-K (Attachments)
 MEDS, W5B63 C-K (Attachments)
 M. N. Sprouse, W11A9 C-K

KINGSTON STEAM PLANT 1982



①

*Looking west at ash disposal area. Spillways & skimmers
Plant designed and constructed*



②

Discharge outlet for circular spillway and skimmer into stilling pool.



③

Discharge outlets for sheet metal spillway and skimmer into stilling pool.

**KINGSTON
STEAM PLANT
1982**



④

Looking North at area of surface wetness at toe of exterior slope dike C adjacent to stilling pool.



⑤


Looking North along exterior slope of Dike C. Note excellent vegetative cover.



⑥

Looking Northeast at discharge outlet structure for standard spillways into plant intake channel

1 2 3 4 5 6 7 8 9 10 11 12



CHEMICAL TREATMENT POND
SUMMARY OF QUANTITIES

ITEM NO	DESCRIPTION	QUANTITY
123	EARTH BORROW	32,000 CY
210	CRUSHED STONE	42,000 CY
830	RIPPRAP	2,400 TONS
836	ASH EXCAVATION	100,000 CY

SECTION C-C-C
SCALE: VERT 1"=10'

SECTION D-D
SCALE: VERT 1"=10'

- NOTES:
- SOIL EXPLORATION AND LABORATORY TESTING IS REQUIRED IN MEMORANDUM REPORT FROM GERR FARMER TO G.L. BUCHANAN, DATED NOVEMBER 3, 1975. THIS REPORT IS ATTACHED TO THIS DRAWING FOR INFORMATION. ALL TESTS BASED UPON AN EVALUATION OF THE SOILS INVESTIGATION REPORT ARE AS FOLLOWS:
 - INITIAL CONSTRUCTION EXTERIOR SLOPE: SAFETY FACTOR = 1.5
 - OPERATING CONDITION WITH ASH AND WATER TO EL. 761: EXTERIOR SLOPE: SAFETY FACTOR = 1.5
 - OPERATING CONDITION WITH ASH AND WATER TO EL. 761: INTERIOR SLOPE: SAFETY FACTOR = 1.5
 - ALL WORK TO BE IN ACCORDANCE WITH T-1 SPECIFICATIONS UNLESS NOTED.
 - ALL DIKE CONSTRUCTION SHALL BE IN ACCORDANCE WITH GENERAL CONSTRUCTION SPECIFICATIONS FOR EARTHWORK AND SHALL BE CONSTRUCTED IN PLACES WHERE THE SOILS INVESTIGATION REPORT INDICATES A MINIMUM MOISTURE CONTENT, AS DETERMINED BY THE CENTRAL SOILS LABORATORY.
 - REMOVE ORGANIC TOPSOIL TO A DEPTH THAT WILL PREVENT ROOTS AND ALL PREVIOUS MATERIAL (RIPPRAP, GRAVEL, CRUSHED STONE, COARSE SAND, AND OTHER PERVIOUS MATERIAL) FROM BEING PLACED ON THE GROUND AND WITHOUT HEAVING THE GROUND SO AS TO REDUCE ITS STABILITY.
 - PIPE BACKFILL SHALL CONSIST OF IMPERVIOUS SOIL, FREE OF DEBRIS, AND SHALL BE COMPACTED TO A MINIMUM OF 95% RELATIVE COMPACTION TO THE PIPE. THE SOIL SHALL BE PLACED IN 6" LAYERS AND COMPACTED TO AT LEAST 95% OF STANDARD MAXIMUM DENSITY AS ESTABLISHED BY THE CENTRAL SOILS LABORATORY. THE BACKFILL SHALL BE PLACED SO AS TO MAINTAIN THE SAME ELEVATION ON BOTH SIDES OF THE PIPE.
 - THE DIVIDER DIKE SHALL BE CONSTRUCTED OF BOTTOM ASH. PLACEMENT OF THE DIVIDER DIKE SHALL BE SUCH THAT THE UNDERWATER DIKE JUST ABOVE THE WATER SHALL BE THOROUGHLY COMPACTED AND SCAFFLED BEFORE PLACING THE TOP OF THE DIKE. THE TOP SURFACE OF THE UNDERWATER DIKE SHALL BE PLACED ABOVE WATER LEVEL AND SHALL BE WELL COMPACTED WITH RUBBER TIED HAULING EQUIPMENT.
 - CUT SLOPES ADJACENT TO EXISTING OR PROPOSED DIKES SHALL NOT BE FROM THE TOP OF ANY DIKE. THE TOP OF CUT SHALL BE A MINIMUM OF 20" FROM THE TOP OF ANY DIKE.
 - WHEN CONNECTING THE NEW DIKE TO THE OLD DIKE, EXTREME CARE SHALL BE USED TO INSURE AN IMPERVIOUS AND STABLE CONNECTION. THE EXISTING DIKE SHALL BE THOROUGHLY COMPACTED AND SCAFFLED. THE EXISTING DIKE SHALL BE SCAFFLED TO A MINIMUM DEPTH OF 6" AND COMPACTED SO AS TO FORM A BRIDGE OVER THE EXISTING DIKE. THE EXISTING DIKE SLOPES SHALL BE IN THE BEST CONDITION. SMALL BERMS OF MINIMUM DEPTH SHALL BE USED.
 - GRASSING, CUT AND FILL SLOPES, AND DISTURBED AREAS SHALL BE SEEDED WITH A MIXTURE OF GRASS AND LEGUMES. SEEDING SHALL BE DONE IMMEDIATELY AFTER CONSTRUCTION AND TYPE 10A FOR SUMMER SEEDING. ALL AREAS ARE TO BE SEED, AND SHALL BE MULCHED IN ACCORDANCE WITH SECTIONS 180 AND 182.
 - THE RIPPRAP SHALL CONSIST OF STONE OF WEIGHT EQUAL TO OR GREATER THAN 150 LBS., AND IN ACCORDANCE WITH SECTION 830.
 - FILTER BLANKET SHALL BE 6" THICK AND IN ACCORDANCE WITH SECTION 836.
 - SUMMARY OF QUANTITIES - SEE DWG 2102(H10)

- EARTH FILL COMPACTION IN CHEMICAL PONDS SHALL BE DONE WITH SHEEPSFOOT ROLLERS AND SHALL BE AT LEAST 95% OF STANDARD PROCTOR MAXIMUM DENSITY. FILL MOISTURE SHALL BE CONTROLLED TO ACHIEVE OPTIMUM COMPACTION.
- SURFACING FOR THE EARTH FILL AROUND CHEMICAL PONDS SHALL BE 4" OF CRUSHED STONE, PER SECTION 210 OF THE T-1 SPECS.
- RIPPRAP IN CHEMICAL PONDS SHALL BE 18" THICK, WITH A MINIMUM OF 50% BY WEIGHT, CONSISTING OF STONES AT LEAST 100 POUNDS EACH. RIPPRAP SHALL CONFORM TO SECTION 830 OF THE T-1 SPECS.


SCALE: 1"=300'

NO.	DATE	BY	CHKD.	APP'D.	DESCRIPTION
1	10/21/75	J. B. GALLAGHER	J. B. GALLAGHER	J. B. GALLAGHER	PREPARED
2	10/21/75	J. B. GALLAGHER	J. B. GALLAGHER	J. B. GALLAGHER	REVISED

ASH POND DIKE

PLAN-RAISING ASH DISPOSAL AREA DIKE

**KINGSTON STEAM PLANT
TENNESSEE VALLEY AUTHORITY
DIVISION OF ENGINEERING DESIGN**



DETAIL B
SPILLWAY ACCESS
SCALE: 1"=50'

NO.	DATE	BY	CHKD.	APP'D.	DESCRIPTION
1	10/21/75	J. B. GALLAGHER	J. B. GALLAGHER	J. B. GALLAGHER	PREPARED
2	10/21/75	J. B. GALLAGHER	J. B. GALLAGHER	J. B. GALLAGHER	REVISED

COMPANION DRAWING: 10N421, N422, N423
HWY PROJECT 2102

Memorandum

TENNESSEE VALLEY AUTHORITY
CDB '82 0316 002

TO : Frank D. Stancberry, Head Civil Engineer (Site Development, Highway, Railroad,
and Bridge Design), W3A51 C-K
FROM : Jerry L. Glover, Civil Engineer (Site Development, Highway, and Railroad
Design), W3A67 C-K
DATE : March 15, 1982
SUBJECT: INTERIM DISPOSAL AREA INSPECTION

JRG

Plant: Kingston Steam Plant Area: Ash Disposal Area
Date of last annual inspection: September 9, 1981 (CDB 810925 010)
Date of this inspection: March 10, 1982 Weather: Cloudy and warm (65°±)
Inspected by: Jerry Glover (EN DES)
Joel Paris (F&H PR)
Coy Woods (Yard Operations Supervisor)
Discussed with: Ford Clayton (Assistant Plant Superintendent)

	Excellent	Good	Poor
General condition of perimeter dikes	_____	<u>X</u>	_____
Vegetative cover on slopes	_____	_____	<u>X</u>
Condition of standard skimmers and spillways	_____	<u>X</u>	_____
Condition of outlet structure and channel	_____	<u>X</u>	_____
General condition of divider dike	_____	<u>X</u>	_____

Signs of loss of ash? Yes No
Has action been taken on recommendations of annual inspection report? Yes No

Comments: Vegetative cover on the dike slopes is generally sparse. The slopes were reseeded and fertilized last spring with very poor results due to the dry weather. Seed and fertilizer have been purchased and the slopes will soon be reseeded and fertilized again.

Comments:

Jerry L. Glover
Jerry L. Glover

JIG:TLT
cc: G. L. Buchanan, W3C126 C-K

3/15/82 - GLB:TLT
cc: S. B. Jack, 5100 MIB-K
MEDS, 100 UB-K
M. N. Sprouse, W11A9 C-K