Bland

E. F. Thomas, Director of Power Production, 1005 EB-C (2)

J. R. Parrish, Director of Engineering Design, 505 UB-K Nevember 5 1970

KINGSTON STEAM PLANT - ANNUAL ASH POND DIKE INSPECTION

Attached is a memorandum report from J. L. Glover to W. N. Calvert dated October 6, 1970, of the September 30 joint field inspection at Kingston which includes recommendations for corrective work. I concur in these recommendations.

J. R. Parrish

JLG:NCH Attachment CC: F. P. Lacy, 405 UB-K (3) - w/3 attachments Power Manager's Files, 531 PRB-C W. N. Calvert, Head Civil Engineer (Highway and Railroad), 101 FB-K

J. L. Glover, Civil Engineer (Highway and Railroad), 100 FB-K

October 6, 1970

KINGSTON STEAM PLANT - ANNUAL ASH FOND DIKE INSPECTION

On September 30, 1970, L. B. Cook of DPP; L. B. Kennedy, Assistant Plant Superintendent; and J. P. H. Stivers and I of DED inspected the ash ponds at the Kingston Steam Plant and discussed the findings with A. O. Spencer, Plant Superintendent.

On the attached print of 10N400 the different areas are designated.

In general, the dikes are in good shape, and there appears to be no stability problem. The original dikes were constructed of earth. The dikes around the initial ash area were raised with ash. In the last year a great deal of work has been done on dike C and the road dike. These two dikes are being raised with earth and ash.

Since last year's inspection, fill around the northern spillway discharge pipe has been excavated from the spillway to near the middle of the dike, portions of the pipe replaced, the excavated portion backfilled with carefully compacted earth, and all the joints in the pipe grouted from the inside. This has eliminated seepage along the outside of the pipe. Both spillways have been raised two feet; and to maintain a 4-foot freeboard in the ash pond, dike C has been raised approximately two feet. Standard skimmers (picture 6) have been installed, and a concrete end wall (picture 5) has been constructed at the spillway outlet. There were no signs of any fly ash escaping through the spillway.

The outside slopes of the west dike and dike C (pictures 1 and 2) have been flattened and dressed up. Portions of the outside slope of dike C have been seeded and a good growth of vegetation established (picture 2). On some sections of the dike, vegetation has come up on its own (picture 4). The remainder of dike C is to be fertilized and seeded this fall.

On the outside slope of the east ash dike of the initial area, two experimental plots were established. Plot one was covered with approximately six inches of soil, fertilized, and seeded. This plot has an excellent growth of vegetation. No soil was placed on the second plot. This plot was limed, fertilized, and seeded. The second plot produced no vegetation. W. M. Calvert October 6, 1970

KINGSTON STEAM PLANT - ANNUAL ASH POND DIKE INSPECTION

A section of dike C that had been eroded by wave action from Watts Bar Lake has been riprapped (picture 3). This should eliminate the erosion at this section of dike.

Our recommendations for the Kingston ash ponds are as follows:

- 1. Continue grassing the earth slopes.
- 2. Keep logs and trash removed from the outside slope of dike C.
- 3. Raise dikes, with earth and ash, as required to maintain 4-foot freeboard in the pond, keeping the top of dike smooth and sloped to the inside. The top of the original dikes shall be left as a berm and the dikes raised with slopes of 2:1 on the inside and 3:1 on the outside with 16-foot top width. The maximum height of each lift shall not exceed 10 feet before providing a berm.

J. L. Glover

JLG: NCH Attachments

Concur:


W. M. Calvert


F. P. Lacy

WNC:NCH--10/7/70 CC (Attachments): F. P. Lacy, 405 UB-K

PPL: RW--10/7/70 CC (Attachments): J. R. Parrish, 505 UB-K

2





KINGSTON STEAM PLANT 1970

Outside Dike "C"; vegetation has come up on its awn.





5 Concrete endwall at spillway outlets.

6 Standard skimmers that have been placed on spillways

KINGSTON STEAM PLANT 1970

D Outside slope of raised Dike"C".





Outside of Dike"C" showing areas where seeding has and has not been attempted.



3 Area of Dike"C" riprapped to prevent erosian.