

TENNESSEE VALLEY AUTHORITY

KINGSTON FOSSIL PLANT

ANNUAL ASH POND DIKE
STABILITY INSPECTION
2009



Prepared by: Chris Buttram
Date: January 12, 2009

TVA-00023703

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**

**Executive Summary
2009 Kingston Ash Pond Annual Dike Stability Inspection**

The annual stability inspection of the Kingston Fossil Plant (KIF) disposal areas was performed by three TVA engineers on October 20, 2008. KIF has six ponds and disposal areas. Ash from burning coal is sluiced wet to the main ash pond. As the pond fills, the ash is then dredged (pumped) to smaller, elevated ponds inside the main ash pond. The plant has 2 chemical treatment ponds, a storm water control pond in the coal pile, a partially constructed pond for the sulphur removal system under construction and a treatment wetland.

The inspection found the dikes of the main ash pond in excellent condition with an excellent grass cover and no signs of instability. Minor erosion was found in some of the dike roads. Floating ash, called cenospheres, had collected near the stand pipe skimmers in the main pond.

The dredge cells are made up of 3 three smaller ponds, called Cells One, Two and the Interim Cell. The Interim Cell has been filled to capacity. Its dikes were generally in good condition, but in need of grassing to control erosion and grading to improve drainage. The drainage improvements, dewatering wells and underdrains installed to address seeps and sloughs in 2003 and 2006 were found to be functioning properly. The grass cover was sparse in several places and overseeding and fertilizing was recommended. The sparse grass cover allowed some erosion ditches to begin.

The two chemical treatment ponds and the coal yard storm water pond are all excavated below grade. The chemical ponds had good rip-rap cover on their slopes. The coal yard pond was in need of clean out, but otherwise was in good condition.

The plant has an engineered wetland south and west of the ash pond to treat seepage from the bottom ash trench and disposal area. The wetland naturally removes iron and raises the pH of the water to the point it can be pumped to the ash pond.

Finally, a new pond is under construction just east of the plant. The new pond will collect gypsum produced in from the new sulphur removal equipment being added to the plant. The new pond is expected to be complete in the summer of 2009.

Standard recommendations were to repair all erosion ditches, repair wheel ruts, remove floating ash from the pond to prevent a permit violation, remove trees from the dikes and mow the dikes regularly to control the growth of vegetation and make inspections easier. More specific recommendations were to repair all broken monitoring wells along Swan Pond Road, monitor the seeps and underdrains around the dredge cells, clean out the coal yard pond, and clean out the pump wells in the engineered wetland.

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**



General

The waste disposal areas at Kingston Fossil Plant were inspected for dike structural stability on October 20, 2008. The inspection was performed by Chris Buttram, Engineering Design Services (EDS), John Albright (EDS), and Jamey Dotson, Coal Combustion By-Products (CCBP). The previous annual inspection was performed on December 4, 2007. The results of the annual inspection are listed below according to location.

Active Ash Disposal Area

Bottom ash is sluiced into a channel southwest of the active ash disposal area. The bottom ash settles out in the channel and is removed by dragline. This ash is subsequently used for dike construction.

Fly ash is sluiced to a channel adjacent to the bottom ash channel and flows into the main ash pond. The fly ash channel was cleared of vegetation last year. Both channels flow northeast into the active ash pond. See Figure 1 and drawing API 2009.




Sluice water flows from the active ash pond into the stilling pond through the five spillways constructed in 2005. The old spillway (Kennedy Weir) was taken out of operation at the same time. From the stilling pond, the water discharges into the plant intake channel via six standard spillways equipped with discharge diffusers (see Figure 2) constructed in November 2003. Many of these structures have vegetation and brush growing inside them that needs to be removed.

All exterior dike slopes around the active ash disposal area looked to be in stable condition and had excellent vegetative cover. Continue to maintain and stabilize Dike "C" with riprap to prevent wave action erosion. The dikes had been mowed recently and were in very good condition.


**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**

Fig. 3 Discharge to Stilling Pool



Floating ash near discharge structures, as seen in Figure 3 below, should be removed to prevent an accidental release. Check the floating skimmer booms and maintain them to keep floating ash away. The seeps on the bench of Dike "C" north of the intake skimmer, mentioned on previous reports, have not been observed since wheel ruts were repaired a few years ago. No seeps or wet spots were seen in this area during the inspection.


Fig. 4 Typical Erosion on Road



Some of the dike roads exhibit areas of erosion on the edges and some rutting, see Figure 4. This photo is typical of the eroded areas of the roads. Although it does not appear to be a significant problem, these eroded areas, as well as any ruts, should be graded out and the road covered with crushed stone to prevent larger erosion gullies.

Construction of an internal divider dike inside the active ash disposal area is currently underway. The dike is one foot

Fig. 5 Ash Pond Internal Dike




to two feet above elevation 760, the elevation of the water in the pond. The divider dike will be constructed to build a base of fly ash for a dredge cell expansion, which will eventually cover approximately half of the existing main ash pond. See Figure 5.

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**

Dredge Cells


Prior to November 2003, the fly ash from the active ash disposal area was hydraulically dredged periodically into raised dredge cells located in the western portion of the disposal area. In November 2003, dredging operations ceased because of a leak in the toe of the dike slope for Cells 2 and 3. Through 2004 and 2005, ash was dredged to a newly constructed interim cell while repairs were made to the original dredge cells. Dredging resumed to the original dredge cell location in early 2006.

The interim dredge cell capacity has been depleted; however decant water from the raised dredge cells flows through the interim cell to the main ash pond. Water flow into the interim cell is essential for dust control. The divider dike between this cell and the active ash pond appeared to be in stable condition. Some areas of sparse vegetation (Fig. 7) and poor bench drainage were observed spotted on this dike. These areas should be reseeded and fertilized per T-1, section 580. Areas with poor



drainage should be graded so they will drain, even if slowly. Also, thick vegetation in drainage ditches (Fig. 6) should be thinned out or removed to keep from blocking the water flow. Wheel ruts on benches or in roads that are holding water should be filled with bottom ash and covered with stone.

Due to extensive erosion in one area, a washout two feet wide by twenty feet long by two feet deep had formed (Fig. 8). This area should be repaired by filling bottom layer with six inch lifts of compacted bottom ash until clay area is reached. Cap with one foot of clay using six inch compacted lifts. It is recommended that an erosion control blanket be used in this area for quicker vegetation growth. Monitor this area, especially after rain events, to assure that no settling occurs.




Repairs for the 2003 slope failure were completed in October 2005. Underdrains were installed in the lower two benches to relieve water pressure. The drainage

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**

ditch at the toe of the dike along Swan Pond Road was enlarged to accommodate the additional flow. This ditch has a high point approximately 400-feet north of the intersection with the plant access road. North of the high point, runoff and leachate drain into a sump pond, which is pumped to the ash pond, with an emergency overflow into Swan Pond Embayment. The pumps are electric powered with high water level alarm indicators at the control panel. South of the high point, runoff and leachate run south and east to the ash pond.

In November 2006, after the dredge cells had been back in operation for about nine months, a localized failure occurred very near the 2003 failure. It was determined that the failures were caused by excessive seepage resulting from a combination of issues: inadequate internal drainage (addressed in 2005) and infiltration of surface water on the existing dike benches. Local anomalies in the subsurface conditions were likely increasing groundwater velocities and causing an upward movement of the groundwater near the toe of the dike. A system of dewatering wells was installed in 2006, which helped ease the construction of a riprap toe buttress along the areas of this failure. The riprap allows a conduit for the water to leave the dike, lowering the phreatic surface. Approximately 30 shallow piezometers were also installed to monitor the water levels in the dike. Two spring boxes (36" diameter concrete pipes installed vertically over a bedding of gravel surrounded by filter fabric with a perforated drainpipe) were installed in the areas of the most saturation. Since last year's inspection, a third spring box has been added north of the first two to further help with relieving groundwater pressure within the dike. These wells have a high capacity for allowing water to exit the dike. The dewatering wells are still in place for an extra monitoring point. These repairs are still reducing the near-surface groundwater elevations.

Previously, ash had been dredged into three separate cells, but in 2007, the ash reached levels that buried the divider dikes for Cell 3 and now there are only two large cells (1 and 2). Dredging to these cells was stopped in mid-November 2007 based on recommendations from EDS and Geosyntec Consultants, Inc. This preventative measure was taken to reduce water levels in the dredge cell



through the winter months. Dredging restarted in March 2008 and was still in operation at the time of this inspection. Since the last inspection, the lower benches have been re-graded to provide positive drainage to a series of catch basins which divert the water collected to the lower drainage ditch. In addition to the catch basins and down drains, the benches were covered with a geomembrane, geotextile and then crushed stone to further reduce infiltration into the benches. See Figures 9 and 10 above.

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**

Drain lines with valves were installed on the old dewatering wells to allow personnel to relieve some of the water in these wells. These outlets empty directly into the riprap channel along Swan Pond Road. At the time of the inspection, the valves on some drains were closed in preparation for measurement of water levels and those wells showed water pressure above the dike slope. The valves of the other monitoring wells were open and were flowing clear water to the drainage ditch. Some of these drains had been broken (Figure 11), possibly while the slopes were being mowed.



Fig. 11 Broken Dewatering Well Outlet

These broken drains should be repaired so that the water is not draining freely down the slopes.

Plant operations has mowed the dredge cell slopes. Small trees growing on the slopes have been cut level with the ground. If trees are too large to be mowed, the trees should be cut, the stumps removed, and the area backfilled with soil, compacted and seeded and fertilized. Several areas around the dikes of the dredge cells are in need of seeding and fertilizing. It is recommended these areas should be reseeded and fertilized per T-1, section 580. At the north end of the dredge cells, one of the lower dike benches has an area that has eroded and washed out (See Figures 12 and 13 below). This area should be repaired by filling with clay in 6" lifts and compacting. After the area has been filled and compacted, reseed and fertilize per T-1, section 580. A small wet spot was noticed at




Fig. 12 & 13 Washout on dike bench

View looking up slope

View looking down slope

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**


the toe of the Cell 2 dike. This wet spot was roughly four feet by four feet and approximately 600 feet from the northwest corner of Cell 2 and approximately at Elevation 773. The area was not soft and is in the area of an old underdrain. The drain was not located at the time of this inspection. This area should be closely monitored for worsening conditions.

Besides the wetlands, there was only one spot that showed flowing redwater. When dissolved iron from the ash and water mix, it tends to give the water a red appearance. This area was first thought to be a seep, but it was discovered that the redwater was flowing out of a dewatering well that had a closed valve. The water was flowing down the slope into the riprap ditch. The riprap ditch was also stained some at the outlet area for this dewatering well.

Chemical Treatment Ponds

The chemical treatment ponds (iron and copper) are located southwest of the active ash pond. Both are excavated ponds and have no exterior slopes. The internal dike slopes are covered with riprap. These slopes were in good condition with some trees present. See Figures 14 and 15. Sediment in the ponds was tested in FY 2004 and found to be non-hazardous.


Fig. 14 & 15 Chemical Ponds



Coal Yard Drainage Basin

The coal yard drainage basin is located at the southwest corner of the coal pile. This basin was excavated below grade; therefore, there are no exterior dikes. The interior slopes appeared to be in satisfactory condition. Normal discharge from this basin is pumped into the fly ash discharge ditch and flows to the active ash disposal area. The basin was cleaned out in 2006, but is in need of another clean out. The bottom of the pond should be no higher than elevation 745 at the pump platform. Elevation 745 allows 2-feet of clearance below the pump intakes to prevent pumping solids. In addition, the

Fig. 16 Check Dams needing repair



“V-shaped” pond extensions added during the summer of 2001 to increase the pond storage volume

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**

contain coal yard sediment. Figure 16 shows rock check dams built to keep the coal fines away from the pumps. The check dams appear to be in need of repair and cleaning out. If maintained properly, the check dams will keep sediment from reaching the pumps. TVA drawing 10W225-1 (attached as API 2009-2) shows the pond and its intended bottom contours. The coal yard drainage basin should be cleaned out annually.

Engineered Wetlands

The engineered wetlands along the southwest dike receive seepage that collects in the limestone drain below the bottom ash trench. The wetland helps naturally remove iron and raise the pH of the water before it is pumped to the ash pond. The wetland appeared to be functioning and the discharge is still pumped via two pumps to the ash pond, see Figures 17 and 18 below. Vegetation within the pump structures should be removed so that the pumps do not become clogged. Several trees were noticed along the interior slopes and should be removed by pulling up the roots. Repair the damage by compacting soil into the damaged areas.

Fig. 17 & 18 Engineered Wetlands





Fig. 19 Gypsum Pond



Gypsum Pond

The gypsum pond is located on the peninsula, which is east of the plant. The pond was still being constructed at the time of this inspection, see Figure 19 below. Construction is scheduled to be finished on 6/01/09.

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**

For more photos taken during the inspection, see the attached sheets at the end of this report.

Subsequent to the inspection and prior to writing this inspection report, a dike failure at the north end of the dredge cells occurred. The cause of the failure is currently under investigation. None of the observations noted during this inspection indicated a dike failure was likely to occur in the foreseeable future.

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**

Actions Since Last Inspection

- Monitoring of the Dredge Cell dikes for seepages has continued.
- The interior of the Dredge Cells was sprayed with a polymer anti-dusting agent during May of 2008.
- Surface drainage repairs that began in January 2008 have been completed.
- A third spring box was installed on the side of the Dredge Cell paralleling Swan Pond Road. This was done to provide controlled relief of excess groundwater pressure and allow an additional release of water from the dikes.

Routine Recommendations

Active Ash Disposal Area

- Repair any dikes showing signs of erosion. Erosion ditches larger than a standard railroad crosstie should be repaired with compacted bottom ash or soil. Repeated repairs in the same location calls for riprap stabilization. EDS-Civil will assist in sizing the riprap and setting the limits if needed.
- Remove ash floating on the surface of the ash and stilling ponds, and check floating skimmer booms to ensure they are working properly.

Dredge Cells

- Monitor the limestone drain area and all exterior dike slopes (along Swan Pond Road in particular) for seepages, soft wet spots, animal burrowing, sloughing, etc., and report any changes to Engineering Design Services.
- Dredge cell drainage ditches should be kept free of cattails so they will flow as well as possible. Any existing cattails should be removed.
- Remove trees from the slopes of the dikes. Mowing at least twice a year is recommended to control the size of the trees. Preventing the trees from getting larger than 1" in diameter at the ground is preferred. Any trees larger than 3" in diameter at the base must be pulled from the dikes, roots and all. Repair and reseed the damaged area.
- Repair rutting in the access and dike roadways, as well as benches. Fill with bottom ash and regrade as required to promote drainage.

Coal Yard Drainage Basin

- Dredge the coal yard drainage basin to restore its design contours and protect the pumps from further damage. There is an estimated 2,800 cubic yards of sediment in the original pond and an extra 3,400 cubic yards in the "V" section that needs to be removed as soon as reasonable. See the attached copy of 10W225-2.
- Repair and clean out riprap check dams in the coal yard drainage basin to keep solids away from the pumps.

Engineered Wetlands

- Remove all vegetation from within the pump structures

**KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009**

- Remove trees from the interior slopes. Preventing the trees from getting larger than 1" in diameter at the ground is preferred. Any trees larger than 3" in diameter at the base must be pulled from the dikes, roots and all. Repair and reseed the damaged area.

Recommendations





Active Ash Disposal Area

- Investigate the use of spraying to inhibit vegetation growth on the interior dikes of the stilling pond.

Dredge Cells

- Repair broken dewatering well outlet pipes. These pipes should be draining directly into the lined ditch at the bottom of the cells.
- Repair the 2' x 20' area of erosion on the east slope of the interim dredge cell. Fill bottom layer with bottom ash in 6" lifts and compact. When the clay layer is reached, cap with 1' of clay via 6" compacted lifts. Lastly, cover with an erosion control blanket to help stabilize the damaged area. After repairs have been made, continue to monitor area until good vegetation has stabilized the area.
- Repair erosion washout on lower dike bench at North end of dredge cells. Repair eroded area by filling with clay in 6" lifts and compacting, then reseed and fertilize per T-1, section 580.
- Continue to monitor the wet spot at the toe of the Cell 2 dike.

KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009



KINGSTON FOSSIL PLANT
ANNUAL ASH POND DIKE STABILITY INSPECTION
2009

Fig. 23 Dewatering well overflowing redwater





Fig. 24 Redwater in riprap ditch






PHOTO TAKEN AT THIS LOCATION
IN THIS DIRECTION

TASK COMPLETED BY: _____
REV. NO. _____

NO.	DATE	BY	CHK	APP	REASON	AS SHOWN	AS NOTED

SCALE: NONE
EXCEPT AS NOTED

YARD

COAL YARD DRAINAGE BASIN
2009 ANNUAL INSPECTION

KINGSTON FOSSIL PLANT
TENNESSEE VALLEY AUTHORITY
FOSSIL AND HYDRO ENGINEERING

AUTOCAD 2000 DATE: 36 C API 2009-2 R 0

PLOT FACTOR: 1
M=92E
C.A.B. DRAWING
DO NOT ALTER MANUALLY