Paradise Fossil Plant (PAF) Fact Sheet



Issues Found

- Slumping and uncontrolled seepage along Scrubber Sludge Complex (SSC) south and east slopes, and SSC East Pond north slope.
- Steep slope along east side of SSC East Pond.
- Inadequate surface drainage conditions on exterior slopes of SSC.
- Unknown condition of abandoned spillways and sluice lines at south slope of SCC East and West Ponds.
- Erosion of interior Jacobs Creek Fly Ash Pond (JCFAP) slopes.

Remediation Projects Completed

- Installed rock buttresses along south and east slopes of SSC East Pond to improve slope stability.
- Installed seepage filters along the south slopes of the SSC East and West Ponds and the east slope of the East Pond to improve slope stability and control seepage.
- All sluicing routed to East Pond of SSC to control excessive seepage at West Pond.
- Repaired slopes along the south and east slopes of the SSC East and West Ponds to improve surface drainage conditions.
- Armored interior slope of JCFAP to repair eroded surfaces.

Future Remediation Projects

- Abandoned SSC spillway and sluice lines will be filled with concrete grout to eliminate risk associated with open pipes penetrating dikes (scheduled for completion by December 31, 2010).
- Install slope armoring and complete ditch repairs along SCC East Pond north slope (scheduled for completion by December 31, 2010).
- Install rock buttress with graded filter along SSC West Pond east slope. (scheduled for completion by December 31, 2010).

