

Memorandum

U.S. Department of Transportation Pipeline and Hazardous Materials Safety Administration

Central Region Office

Office of Pipeline Safety

Date: September 30, 2010

Subject: Summary Incident Report

Enbridge Energy Partners L.P. (Op ID 11169) Deer River, MN to Floodwood, MN (Unit 3083)

Line 2 Crude Oil Leak February 19, 2004

SMART Activity 110735

From: James Bunn, Staff Engineer *original signed*

To: David Barrett, Director – Central Region, PHP-300 *original signed*

1.0 SUMMARY

At approximately 12:52 p.m. on February, 19 2004, Enbridge Energy Partners L.P. ("Enbridge") discovered a crude oil leak on their Line 2 Pipeline in Itasca County, Grand Rapids, MN (the "Incident"). An estimated 1003 barrels (bbls) of crude oil was released from the pipeline. The Incident occurred on the pipeline right of way (ROW) near milepost number 1007 (MP 1007), northwest of the City of Grand Rapids, MN. No fatalities or injuries occurred as a result of the Incident. The Incident did occur in a high consequence area (HCA), drinking water (DW) and other populated area (OPA) was impacted. The total cost of the Incident, pipeline repair and environmental cleanup, is estimated at \$1,100,000. There were no service interruptions or supply impacts as a result of the Incident.

2.0 PIPELINE SYSTEM

Enbridge's Line 2 is a 26-inch diameter crude oil pipeline that runs from Gretna, Manitoba, Canada to Superior, WI. At the Incident location, the pipeline is constructed of API 5L X-52 line pipe manufactured by A.O. Smith in 1956. The pipeline is 26-inch diameter by 0.281-inch wall thickness, electric flash welded (EFW) type pipe, coated with a coal tar enamel system.

The Line 2 maximum operating pressure (MOP) is 809 psig.

3.0 DISCUSSION

An Enbridge maintenance crew excavating an in-line inspection (ILI) indication discovered the crude oil leak. At 12:52 p.m. Enbridge Notified the Minnesota Office of Pipeline Safety (MNOPS) Duty Officer that a leak had occurred. Brian Pierzina, MNOPS Senior inspector, conducted an on-site investigation of the Incident.

In September 2003, Enbridge ran an in-line inspection (ILI) magnetic flux leakage (MFL) and geometry tool through this portion of Line 2. The ILI tool identified a potential dent with metal loss at MP 1007. Enbridge scheduled excavation of the MP 1007 indication for February of 2004. During the indication excavation, oily soil was discovered. As the excavation continued, signs of fresh product were encountered. Once it was determined that the pipeline was most likely leaking at MP 1007, the pipeline was shut down.

In situ visual inspection of the damaged pipe joint revealed a 2-inch long through wall crack in the pipe body. A small amount of oil was leaking through the crack. The crack was located in a dent on the bottom of the pipe. A rock was identified in the backfill under the pipe. The rock location was coincident with the dent.

The rock was eventually removed from under the pipeline.

4.0 EMERGENCY RESPONSE

Enbridge employees were dispatched to the Incident site. Once the repair was completed and inspected the contaminated soil and ground water was remediated.

5.0 RETURN TO SERVICE

The pipeline was shut down at approximately 11:30 a.m. on February 20, 2004.

After the field investigation was complete, a one foot long Type B, tight fitting repair sleeve was installed in the area where the Incident occurred.

At the time of the Incident, Line 2 operating pressure was approximately 750 psig. No reduction in operating pressure was required as a result of this incident.

The pipeline was returned to service at approximately 10:30 p.m. on February 20, 2004.

6.0 FINDINGS

The Enbridge Line 2 MP 1007 Incident was caused by a crack located within a dent that initiated on the pipe external surface. The crack was apparently caused by a rock found in the backfill at the location of the dent.

EXHIBITS

Information regarding the Incident was reported by Enbridge to the National Response Center (NRC) on March 2, 2004 in NRC Report No. 714880 (Exhibit A), and to the Pipeline and Hazardous Materials Safety Administration (PHMSA) in Accident Report No. 20040063 dated March 16, 2004 (Exhibit B).

Exhibit A NRC Report No.714880

Exhibit B Accident Report No. 20040063

EXHIBIT A NRC REPORT No. 714880

NATIONAL RESPONSE CENTER 1-800-424-8802

*** For Public Use ***

Information released to a third party shall comply with any

applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 714880

INCIDENT DESCRIPTION

*Report taken at 12:28 on 02-MAR-04

Incident Type: PIPELINE

Incident Cause: EQUIPMENT FAILURE

Affected Area:

The incident occurred on 19-FEB-04 at 11:30 local time.

Affected Medium: SOIL

SUSPECTED RESPONSIBLE PARTY

Organization: ENBRIDGE ENERGY CO.

SUPERIOR, WI 54880

Type of Organization: PRIVATE ENTERPRISE

INCIDENT LOCATION

County: ITASCA

City: GRAND RAPIDS State: MN

Distance from City: Direction from City: N

MILEPOST 1007.33 NEAR 20TH ST. NW AND 8TH AVE

RELEASED MATERIAL(S)

CHRIS Code: OIL Official Material Name: OIL: CRUDE

Also Known As:

Qty Released: 10 BARREL(S)

DESCRIPTION OF INCIDENT

MATERIAL RELEASED FROM A 26" PIPELINE DUE TO A DENT WITH A CRACK IN THE LINE.

INCIDENT DETAILS

Pipeline Type: TRANSMISSION

DOT Regulated: YES

Pipeline Above/Below Ground: BELOW

Exposed or Under Water: NO Pipeline Covered: UNKNOWN

DAMAGES

Fire Involved: NO Fire Extinguished: UNKNOWN

INJURIES: NO Hospitalized: Empl/Crew: Passenger: FATALITIES: NO Empl/Crew: Passenger: Occupant:

EVACUATIONS: NO Who Evacuated: Radius/Area:

Damages: YES \$55000

Length of Direction of

<u>Closure Type</u> <u>Description of Closure</u> <u>Closure</u> <u>Closure</u>

Air:

Major

Road: N Artery: N Waterway: N

Track: N

Passengers Transferred: UNKNOWN Environmental Impact: UNKNOWN

Media Interest: NONE Community Impact due to Material: NO

REMEDIAL ACTIONS

EXCAVATED SOIL, CLEANUP COMPLETED

Release Secured: YES

Release Rate:

Estimated Release Duration:

WEATHER

Weather: CLEAR, °F

ADDITIONAL AGENCIES NOTIFIED

Federal:

State/Local: MN DUTY OFFICER, MN PCA, MN OPS

State/Local On Scene:

57773 State Agency Number:

NOTIFICATIONS BY NRC

ATSDR MN (PRIMARY)

02-MAR-04 12:35

U.S. EPA V (PRIMARY)

02-MAR-04 12:37

NOAA 1ST CLASS BB RPTS FOR MN (PRIMARY)

02-MAR-04 12:35

RSPA OFFICE OF PIPELINE SAFETY (PRIMARY) 02-MAR-04 12:42

MN DEM ATTN: MS. GOELZ (PRIMARY)

02-MAR-04 12:35

ADDITIONAL INFORMATION

CALLER HAD NO ADDITIONAL INFORMATION.

*** END INCIDENT REPORT # 714880

EXHIBIT B ACCIDENT REPORT No. 20040063

NOTICE: This report is required by 49 CFR Part 195. Failure to report can result in a civil penalty not to exceed \$25,000 for each violation for each day that such violation persists except that the maximum civil penalty shall not exceed \$500,000 as provided in 49 USC 60122 OMB No. 2137-0047

U.S. Department of Transportation Research and Special Programs Administration

ACCIDENT REPORT – HAZARDOUS LIQUID PIPELINE SYSTEMS

Report Date
No
(DOT Use Only)

INSTRUCTIONS

Important: Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the Office Of Pipeline Safety Web Page at http://ops.dot.gov.

you can obtain one from the Office Of Pipeline Safety Web Page at http://ops.dot.gov.						
PART A – GENERAL REPORT IN	Check one or mo Original R	ore boxes as appropriate: eport Supplemental	Poport Fi	inal Papart		
d. Operator street address e. Operator address C IMPORTANT: IF THE SPILL IS S COMPLETE THIS PAGE ONLY, U	ification Number (if known) / / pipeline, enter Owner's OPS 5-dig ity, County, State and Zip Code MALL, THAT IS, THE AMOUNT IS JNLESS THE SPILL IS TO WATE	it Identification Number (if know	vn) /	/ / 5 BARRELS,		
REPORTABLE UNDER §195.50 A	45 REVISED IN CT 2001.					
2. Time and date of the accident		5. Losses (Estimated)		>		
/ / / / / / / mor	/ / / / / nth dav vear	. ,	osses reimbursed by operator:			
Location of accident	, ,	Public/private property				
(If offshore, do not complete a t	hrough d. See Part C.1)	. /	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
a. Latitude:	Longitude:					
(if not available, see instructions for he	ow to provide specific location)					
b.		(describe)	Ψ_			
b. City, and County or Parish		(describe)				
CState and Zip Code		Operator Losses:				
d. Mile post/valve station o		Value of product lost \$				
(whichever gives more a		Value of operator property damage \$				
	Other Costs	\$_				
4. Telephone report		(describe)				
<u> </u>	month day year	Total Costs	\$_			
	\rightarrow					
6. Commodity Spilled Yes			c. Estimated a involved :	amount of commodity		
(If Yes, complete Parts a through c where applicable) a. Name of commodity spilled			Barrels			
b. Classification of commodity spilled:				Gallons (check only if spill is less than one barrel)		
HVLs /other flammable or toxic fluid which is a gas at ambient conditions				in one barrei)		
CO ₂ or other non-flammable, non-toxic fluid which is a gas at ambient conditions Gasoline, diesel, fuel oil or other petroleum product which is a liquid at ambient conditions			Amounts: Spilled :			
Crude oil						
0.11050 500 01111 001110	NI V (5 II () 5 I) [(5) 11 11	Recovere			
	NLY (5 gallons to under 5 barrel		_			
Corrosion Natural F	•	•	e Force Damag			
Material and/or Weld Failure		Incorrect Ope	eration	Other		
PART B – PREPARER AND AUTI	HORIZED SIGNATURE					
(type or print) Preparer's Name and Title)		Area Code and	Felephone Number		
Preparer's E-mail Address			Area Code and F	Facsimile Number		
Authorized Signature	(type or print) Name a	and Title Date	Area Code and	Telephone Number		

PART C – ORIGIN OF THE ACCIDENT (Check all that apply)					
Additional location information a. Line segment name or ID	Offshore: Yes No (complete d if offshore)				
b. Accident on Federal land other than Outer Continental	d. Area Block #				
Shelf Yes No c. Is pipeline interstate? Yes No	State // or Outer Continental Shelf				
2. Location of system involved (check all that apply)	a. Type of leak or rupture				
Operator's Property Pipeline Right of Way	Leak: Pinhole Connection Failure (complete sec. H5)				
High Consequence Area (HCA)?	Puncture, diameter (inches)				
Describe HCA	Rupture: Circumferential – Separation				
Part of system involved in accident Above Ground Storage Tank	Longitudinal – Tear/Crack, length (inches) Propagation Length, total, both sides (feet)				
Cavern or other below ground storage facility	N/A				
Pump/meter station; terminal/tank farm piping and equipment, including sumps	Otherb.Type of block valve used for isolation of immediate section:				
Other Specify:	Upstream: Manual Automatic Remote Control				
Onshore pipeline , including valve sites Offshore pipeline , including platforms	Check Valve Downstream: Manual Automatic Remote Control				
If failure occurred on Pipeline , complete items a - g:	Check Valve c. Length of segment isolatedft				
	d. Distance between valves				
Failure occurred on Body of Pipe	e. Is segment configured for internal inspection tools? Yes No				
Pump Sump Joint	f. Had there been an in-line inspection device run at the point of failure? Yes No Don't Know				
Component Valve Metering Facility Repair Sleeve Welded Fitting Bolted Fitting	Not Possible due to physical constraints in the system				
Girth Weld	g. If Yes, type of device run (check all that apply)				
Other (specify)	High Resolution Magnetic Flux tool Year run: Low Resolution Magnetic Flux tool Year run:				
Year the component that failed was installed: //	UT tool Year run:				
5. Maximum operating pressure (MOP)a. Estimated pressure at point and time of accident:	Geometry too Year run:				
PSIG	Câliper tool Year run:				
b. MOP at time of accident: PSIG	Crack tool Year run:				
c. Did an overpressurization occur relating to the accident?	Hard Spot tool Year run: Other tool Year run:				
Yes No					
PART D – MATERIAL SPECIFICATION	PART E – ENVIRONMENT				
1. Nominal pipe size (NPS)	1. Area of accident In open ditch				
2. Wall thickness	Under pavement Above ground				
3. Specification SMYS	_/ Underground Under water				
4. Seam type	Inside/under building Other				
5. Valve type					
6. Manufactured byin year /	2. Depth of cover: inches				
PART F - CONSEQUENCES					
1. Consequences (check and complete all that apply)	a Draduct ignited - Veg - No d Evaluation - Veg - No.				
a. Fatalities Injuries Number of operator employees:	c. Product ignited Yes No d. Explosion Yes No e. Evacuation (general public only) // people				
Contractor employees working for operator:	Reason for Evacuation:				
General public:	Precautionary by company				
Totals:	Evacuation required or initiated by public official				
b. Was pipeline/segment shutdown due to leak? Yes No	f. Elapsed time until area was made safe:				
If Yes, how long? days hours minutes	// hr. // min.				
2. Environmental Impact					
a. Wildlife Impact: Fish/aquatic Yes No	e. Water Contamination: Yes No (If Yes, provide the following)				
Birds Yes No Terrestrial Yes No					
	Amount in water barrels Ocean/Seawater No Yes				
b. Soil Contamination Yes No	Amount in water barrels Ocean/Seawater No Yes Surface No Yes				
If Yes, estimated number of cubic yards:	Ocean/Seawater No Yes Surface No Yes Groundwater No Yes				
	Ocean/Seawater No Yes Surface No Yes				

PART G - LEAK DETECTION						
Computer based leak determined		Yes No	Yes No			
2. Was the release initially detected by? (check one):		CPM/SCADA-based system with leak detection Static shut-in test or other pressure or leak test				
		Remote operating	personnel, incl	uding controllers		
		Air patrol or ground	Air patrol or ground surveillance			
		A third party	(Other (specify)		
3. Estimated leak duration	days hours					
PART H – APPARENT CAU	SE primary cause of		ne circle in eac	t H. Check the box corresponding to the hof the supplemental categories uctions for guidance.		
H1 – CORROSION	a. Pipe Coating	·		c. Cause of Corrosion		
External Corrosion	Bare Coated	Localized Pitting General Corrosio		Galvanic Atmospheric Stray Current Microbiologica		
	Coalcu	Other		Cathodic Protection Disrupted		
Internal Corrosion				Stress Corrosion Cracking Selective Seam Corrosion		
(Complete items a – e				Other		
where applicable.)	d. Was corroded part of	pipeline considered to be	under cathodi	c protection prior to discovering accident?		
		Protection Started: /				
	e. Was pipe previously d					
H2 – NATURAL FORCES	No Yes => Est	imated time prior to acci-	dent: /	/ years / / months Unknown		
3. Earth Movement	=> Earthquake	Subsidence La	andslide	Other)		
4. Lightning						
5. Heavy Rains/Flood	s => Washouts	Flotation M	ludslide	Scouring Other		
6. Temperature	=> Thermal stress	Frost heave Fr	rozen compone			
7. High Winds			\rightarrow (Ω)			
.			\wedge	>		
H3 — EXCAVATION DAMA	GE					
Operator Excavation	on Damage (including their c	ontractors/Not Third Part	ty)			
Third Party (complete)	ete a-f)	\bigwedge (Ω)	.,			
a. Excavator grou Ge	ւր eneral Public Governn	nent Excavator oth	er than Operat	or/subcontractor		
b. Type: Ro	ad Work Pipeline	Water Electric		Phone/Cable		
			Dellased			
Lar	ndowner-not farming related	Farming	Railroad			
Oth	ner liquid or gas transmission	pipeline operator or the	ir contractor			
Na	utical Operations	Other				
c. Excavation was		ıb-strata (boring, directio	nal drilling, etc.)		
	s an ongoing activity (Month	, 5.	0.	s, Date of last contact //		
	et prior notification of excava	• ,		,		
		// day /	/ yr.	No		
Notification re	ceived from: One Call	System Excavato	or Contra	ctor Landowner		
f Was nineline m	arked as result of location re	equest for excavation?	No Y	'es (If Yes, check applicable items i - iv)		
i. Temporar ii. Permaner	y markings: Flags	Stakes Pair		ез (п тез, спеск аррпсаме кетіз т-ту)		
	re (check one): Accur	ate Not Accurate				
iv. Were ma	rks made within required tim	e? Yes No				
Fire/Explosion as p	rimary cause of failure =>	Fire/Explosion cause:	Man made	e Natural		
11. Car, truck or other	vehicle not relating to excava	ation activity damaging p	pipe			
Rupture of Previou	sly Damaged Pipe					
13. Vandalism						

H5 – MATI Material	ERIAL AND/OR	WELD F	AILURES				
14.	Body of Pipe	=>	Dent	Gouge	Bend	Arc Burn	Other
15.	Component	=>	Valve	Fitting	Vessel	Extruded Outlet	Other
16.	Joint	=>	Gasket	O-Ring	Threads		Other
Weld							
17.	Butt	=>	Pipe	Fabrication			Other
18.	Fillet	=>	Branch	Hot Tap	Fitting	Repair Sleeve	Other
19.	Pipe Seam	=>	LF ERW HF ERW	DSAW SAW	Seamless Spiral	Flash Weld	Other
Comple	te a-g if you i	indicate	any cause in p	part H5.			
a.	Type of failure: Constructio Material De	n Defect :	=> Poor Work	kmanship Pr	ocedure not followed	Poor Construct	ion Procedures
				in transportation to fore accident occur	o the construction or red? Yes, con	fabrication site? Ye	s No
	Date of test:		-	/ mo. /	/ day		
	Test medium: Time held at te		ater Inert C re: / <u>/</u> I	· · · / -			
			at point of accide		F	PSIG	
H6 – EQU 20. Mal	IPMENT function of Cont	trol/Relief I	Equipment =>	Control-valve	Instrumentat	ion SCADA	Communications
20. Mai	ranction of cont	iroi/Telier i	Equipment =>	Block valve	Relief valve	Power failure	Other
21. Thr	eads Stripped, E	Broken Pin	ne Counting -	Nipples Nipples	Valve Threads	Dresser Couplings	Other
	al Failure	DIOROIT IP	=>		O-Ring	Seal/Pump Packing	Other
	RRECT OPERA	ATION	//-~	Gashet	- Tang	Coal/1 ump 1 acking	Outer
23. Inco a. Type:	orrect Operation Inadequ Other	uate Proce	edures Inade	quate Safety Pract	ices Failure to	Follow Procedures	
b. Numb	/ =	involved	who failed a post-a	accident test: drug	 g test: /	/ alcohol test /	/
H8 – OTHI							
24. Miscellaneous, describe: 25. Unknown							
PART I – N	Investigation Complète Still Under Investigation (submit a supplemental report when investigation is complete) PART I – NARRATIVE DESCRIPTION OF FACTORS CONTRIBUTING TO THE EVENT (Attach additional sheets as necessary)						
					_		