

Memorandum

U.S. Department of Transportation Pipeline and Hazardous Materials Safety Administration

Central Region Office

Office of Pipeline Safety

Date: September 30, 2010

Subject: Summary Incident Report

Enbridge Energy Partners L.P. (Op ID 11169) Floodwood, MN to Superior, WI (Unit 3083)

Line 2 Crude Oil Leak

June 9, 2009

SMART Activity ID 125641

From: James Bunn, Staff Engineer

To: David Barrett, Director – Central Region, PHP-300

1.0 SUMMARY

At approximately 5:00 p.m. on June 9, 2009, Enbridge Energy Partners L.P. ("Enbridge") discovered a crude oil leak on their Line 2 Pipeline in St. Louis County, Gowan, MN (the "Incident"). An estimated 5 barrels (bbls) of crude oil was released from the pipeline. The Incident occurred on the pipeline right of way (ROW) near milepost number 1056 (MP 1056), southeast of the City of Gowan, MN. No fatalities or injuries occurred as a result of the Incident. The Incident did not occur in a high consequence area (HCA) and no water was impacted. The total cost of the Incident, pipeline repair and environmental cleanup, is estimated at \$44,000. There were no service interruptions or supply impacts as a result of the Incident.

2.0 PIPELINE SYSTEM

Enbridge's Line 2 is a 26-inch diameter crude oil pipeline that runs from Gretna, Manitoba, Canada to Superior, WI. At the Incident location, the pipeline is constructed of API 5L X-52 line pipe manufactured by A.O. Smith in 1954. The pipeline is 26-inch diameter by 0.281-inch wall thickness, electric flash welded (EFW) type pipe, coated with a coal tar enamel type system.

The Line 2 maximum operating pressure (MOP) is 651 psig.

3.0 DISCUSSION

On June 5, 2009, an Enbridge employee investigating 3rd party activity near MP 1056 discovered a small pool of crude oil on the ROW. Initially, Enbridge attributed the crude oil source to a 3rd party. Enbridge obtained samples of the crude and sent them to a laboratory to identify the source. At 5:35 p.m. on June 9, Enbridge Notified the Minnesota Office of Pipeline Safety (MNOPS) Duty Officer that a leak had occurred. Ron Wiest, MNOPS Senior inspector, conducted an on-site investigation of the Incident.

Enbridge proceeded to excavate the area around the pipeline. Once the line was exposed a 30-inch long Plidco split sleeve was discovered at the Incident location. The Plidco sleeve was installed in 1989 to repair a dent in the pipeline. In 1989 Enbridge standard practice for installing Plidco split sleeves on a pipeline called for the replacement of mechanical fasteners (bolts) with bar stock so the two halves of the sleeve could be welded into place. The bar stock was inserted in the flange holes and then welded to the sleeve to secure the sleeve to the pipe line.

On June 9, 2009, crude oil was discovered leaking through a ½" long crack in a horizontal seal weld between the Plidco flange body and one of the bar stock filled bolt holes.

The Plidco sleeve flanges contained 28 (14 each at 3:00 O'clock and 9:00 O'clock) seal welds. All seal welds were tested in the field for the presence of cracks with magnetic particle inspection (MT).

4.0 EMERGENCY RESPONSE

Enbridge employees were dispatched to the Incident site. Once the repair was completed and inspected the contaminated soil was remediated.

5.0 RETURN TO SERVICE

After the field investigation was complete, a 2-inch, 3000# socket weld end cap was installed over the leaking seal weld to encapsulate the crack. A second socket weld end cap was installed over a second non-leaking seal weld where MT inspection identified a crack.

At the time of the Incident, Line 2 operating pressure was approximately 239 psig. No reduction in operating pressure was required as a result of this incident.

6.0 FINDINGS

The Enbridge Line 2 MP 1056 Incident was caused by a crack that initiated on the external surface of a Plidco repair sleeve. The crack was located between the Plidco flange body and one of the bar stock filled bolt holes. The crack was apparently caused by a defective weld.

EXHIBITS

Information regarding the Incident was reported by Enbridge to the National Response Center (NRC) on June 9, 2009 in NRC Report No. 908091 (Exhibit A), and to the Pipeline and Hazardous Materials Safety Administration (PHMSA) in Accident Report No. 20090191 dated, July 8, 2009 (Exhibit B).

Exhibit A NRC Report No. 908091

Exhibit B Accident Report No. 20090191

EXHIBIT A NRC REPORT No. 908091

NATIONAL RESPONSE CENTER 1-800-424-8802

*** For Public Use ***

Information released to a third party shall comply with any

applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 908091

INCIDENT DESCRIPTION

*Report taken at 17:30 on 09-JUN-09

Incident Type: PIPELINE

Incident Cause: EQUIPMENT FAILURE

Affected Area:

The incident was discovered on 09-JUN-09 at 15:05 local time.

Affected Medium: SOIL SOIL

SUSPECTED RESPONSIBLE PARTY

Organization: ENBRIDGE ENERGY PARTNERS

SUPERIOR, WI 54880

Type of Organization: PRIVATE ENTERPRISE

INCIDENT LOCATION

SEE LEGAL DESCRIPTION County: ST. LOUIS

State: MN

Section: SE NE 17 Township: 50 N Range: 19 W RURAL AREA

RELEASED MATERIAL(S)

CHRIS Code: OIL Official Material Name: OIL: CRUDE

Also Known As:

Qty Released: 5 BARREL(S)

DESCRIPTION OF INCIDENT

CALLER IS REPORTING A DISCHARGE OF CRUDE OIL FROM A 26 INCH STEEL PIPELINE DUE TO A FITTING THAT WAS LEAKING. CALLER WAS NOTIFIED OF DISCHARGE AT 1505 CDT.

INCIDENT DETAILS

Pipeline Type: TRANSMISSION

DOT Regulated: YES

Pipeline Above/Below Ground: BELOW

Exposed or Under Water: NO Pipeline Covered: UNKNOWN

DAMAGES

Fire Involved: NO Fire Extinguished: UNKNOWN

INJURIES: NO Hospitalized: Empl/Crew: Passenger: FATALITIES: NO Empl/Crew: Passenger: Occupant:

EVACUATIONS: NO Who Evacuated: Radius/Area:

Damages: NO

Length of Direction of

<u>Closure Type</u>

<u>Description of Closure</u>

<u>Closure</u>

<u>Closure</u>

Air: N

Road: N Major
Artery: N

Waterway: N
Track: N

Passengers Transferred: NO

Environmental Impact: UNKNOWN

Media Interest: NONE Community Impact due to Material:

REMEDIAL ACTIONS

CALLER STATES THE LINE WAS SHUTDOWN, REPAIRS WILL BE MADE AND THE CONTAMINATED SOIL

WILL BE REMOVED.

Release Secured: YES

Release Rate:

Estimated Release Duration:

WEATHER

Weather: OVERCAST, 55°F

ADDITIONAL AGENCIES NOTIFIED

Federal: NONE State/Local: NONE

State/Local On Scene: NONE
State Agency Number: NONE

NOTIFICATIONS BY NRC

ATLANTIC STRIKE TEAM (MAIN OFFICE)

09-JUN-09 17:36

USCG ICC (ICC ONI)

09-JUN-09 17:36

DOT CRISIS MANAGEMENT CENTER (MAIN OFFICE)

09-JUN-09 17:36

U.S. EPA V (MAIN OFFICE)

09-JUN-09 17:37

FLD INTEL SUPPORT TEAM DETROIT (COMMAND CENTER)

09-JUN-09 17:36

MN BUREAU OF CRIMINAL APPREHENSION (OPERATIONS CENTER)

09-JUN-09 17:36

MN DEPT OF HEALTH (MAIN OFFICE)

09-JUN-09 17:36

MN U.S. ATTORNEY'S OFFICE (MAIN OFFICE)

09-JUN-09 17:36

NTL ENVMTL EMERG CENTRE CANADA (MAIN OFFICE)

09-JUN-09 17:36

NATIONAL INFRASTRUCTURE COORD CTR (MAIN OFFICE)

09-JUN-09 17:36

NOAA RPTS FOR MN (MAIN OFFICE)

09-JUN-09 17:36

PIPELINE & HAZMAT SAFETY ADMIN (OFFICE OF PIPELINE SAFETY (AUTO))

09-JUN-09 17:36

WI DEPT NAT RES BUREAU OF LAW ENF (MAIN OFFICE)

09-JUN-09 17:36

USCG DISTRICT 9 (COMMAND CENTER)

09-JUN-09 17:36

ADDITIONAL INFORMATION

CALLER WILL NOTIFY STATE AGENCIES.

*** END INCIDENT REPORT # 908091 ***

EXHIBIT B ACCIDENT REPORT No. 20090191

NOTICE: This report is required by 49 CFR Part 195. Failure to report can result in a civil penalty not to exceed \$25,000 for each violation for each day that such violation persists except that the maximum civil penalty shall not exceed \$500,000 as provided in 49 USC 60122 OMB No. 2137-0047

U.S. Department of Transportation Research and Special Programs Administration

ACCIDENT REPORT – HAZARDOUS LIQUID PIPELINE SYSTEMS

Report Date	
No	
(DOT Use Only)	

INSTRUCTIONS

Important: Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the Office Of Pipeline Safety Web Page at http://ops.dot.gov.

you can obtain one	from the Office Of Pipelin	e Safety Web Page at	http://ops.do	ot.gov.
PART A – GENERAL REPORT INFORM	Check one or more Original Rep	boxes as appropriate: ort Supplemental	Papart E	inal Papart
d. Operator street address	n Number (if known) /		vn) /	/ / VS BARRELS,
REPORTABLE UNDER §195.50 AS RE		NO DECORIDED IN 43 OF R	3133.32(1)(4)	JI IO O III EKWIOE
2. Time and date of the accident /	/ day / year in d. See Part C.1) gitude:	Derator Losses: Value of operator proper Other Costs (describe) Other Costs (describe) Total Costs Cost of environmental records Operator Losses: Value of product lost Value of operator proper Other Costs	damage \$, bonse phase \$, emediation \$, s, entry damage \$, s, entry dam	
6. Commodity Spilled Yes No (If Yes, complete Parts a through c when a. Name of commodity spilled b. Classification of commodity spilled: HVLs /other flammable or toxic fluid CO ₂ or other non-flammable, non-to-Gasoline, diesel, fuel oil or other per Crude oil	e applicable) d which is a gas at ambient conoxic fluid which is a gas at ambi	ent conditions	involved : Barrels Gallons less tha Amounts:	s (check only if spill is an one barrel)
CAUSES FOR SMALL SPILLS ONLY (5 gallons to under 5 barrels):	(For large spills [
Corrosion Natural Forces	Excavation Damage		e Force Damac	
Material and/or Weld Failures	Equipment	Incorrect Ope	•	Other
PART B – PREPARER AND AUTHORIZ	<u> </u>			
(type or print) Preparer's Name and Title			Area Code and	Telephone Number
Preparer's E-mail Address			Area Code and	Facsimile Number
Authorized Signature	(type or print) Name and	Title Date	Area Code and	Telephone Number

PART C – ORIGIN OF THE ACCIDENT (Check all that apply)				
Additional location information	Offshore: Yes No (complete d if offshore)			
a. Line segment name or ID b. Accident on Federal land other than Outer Continental	d. Area Block #			
Shelf Yes No	State // or Outer Continental Shelf			
c. Is pipeline interstate? Yes No				
2. Location of system involved (check all that apply)	a. Type of leak or rupture			
Operator's Property Pipeline Right of Way	Leak: Pinhole Connection Failure (complete sec. H5)			
High Consequence Area (HCA)?	Puncture, diameter (inches)			
Describe HCA	Rupture: Circumferential – Separation			
Part of system involved in accident Above Ground Storage Tank	Longitudinal – Tear/Crack, length (inches) Propagation Length, total, both sides (feet)			
Cavern or other below ground storage facility	N/A			
Pump/meter station; terminal/tank farm piping and	Other			
equipment, including sumps Other Specify:	b.Type of block valve used for isolation of immediate section: Upstream: Manual Automatic Remote Control			
Onshore pipeline , including valve sites	Check Valve			
Offshore pipeline , including platforms	Downstream: Manual Automatic Remote Control Check Valve			
If failure occurred on Pipeline , complete items a - g:	c. Length of segment isolated			
Failure occurred on	d. Distance between valves			
Body of Pipe Pipe Seam Scraper Trap	e. Is segment configured for internal inspection tools? Yes No f. Had there been an in-line inspection device run at the point of			
Pump Sump Joint Component Valve Metering Facility	fa ilure? Yes No Don't Know			
Repair Sleeve Welded Fitting Bolted Fitting	Not Possible due to physical constraints in the system g. If Yes, type of device run (check all that apply)			
Girth Weld Other (specify)	High Resolution Magnetic Flux tool Year run:			
	Low Resolution Magnetic Flux tool Year run:			
Year the component that failed was installed: // 5. Maximum operating pressure (MOP)	UT tool Year run:			
 a. Estimated pressure at point and time of accident: 	Geometry tool Year run: Caliper tool Year run:			
PSIG b. MOP at time of accident:	Crack tool Year run:			
PSIG	Hard Spot tool Year run:			
c. Did an overpressurization occur relating to the accident? Yes No	Other tool Year run:			
PART D – MATERIAL SPECIFICATION	PART E – ENVIRONMENT			
1. Nominal pipe size (NPS)	1. Area of accident In open ditch			
2. Wall thickness	Under pavement Above ground			
3. Specification SMYS				
4. Seam type	Inside/under building Other			
5. Valve type				
6. Manufactured byin_year //	2. Depth of cover: inches			
PART F – CONSEQUENCES	2. Depth of cover: inches			
Consequences (check and complete all that apply)				
a. Fatalities Injuries	c. Product ignited Yes No d. Explosion Yes No			
Number of operator employees:	e. Evacuation (general public only) / / people			
Contractor employees working for operator:	Reason for Evacuation:			
General public:	Precautionary by company			
Totals:	Evacuation required or initiated by public official			
b. Was pipeline/segment shutdown due to leak? Yes No	f. Elapsed time until area was made safe:			
If Yes, how long? days hours minutes	<u>/ /</u> hr. <u>/ /</u> min.			
2. Environmental Impact				
a. Wildlife Impact: Fish/aquatic Yes No Bir ds Yes No	e. Water Contamination: Yes No (If Yes, provide the following) Amount in water barrels			
Terrestrial Yes No	Ocean/Seawater No Yes			
b. Soil Contamination Yes No	Surface No Yes			
If Yes, estimated number of cubic yards:	5 1 1 N			
c Long term impact assessment performed. Yes No	Groundw ater No Yes Drinking water No Yes (If Yes, check below.)			
c. Long term impact assessment performed: Yes No d. Anticipated remediation Yes No If Yes, check all that apply: Surface water Groundwater	Drinking water No Yes (<i>If Yes, check below.</i>) Private well Public water intake			

PART G - LEAK DETECTION INFOR	RIVIATION					
Computer based leak detection cap	pability in place?	Yes No)			
2. Was the release initially detected by	CPM/SCAD	A-based system wit	th leak detection			
	Static shut-in test or other pressure or leak test					
		Local operat	ting personnel, prod	cedures or equipment		
		Remote ope	erating personnel, in	ncluding controllers		
		Air patrol or	ground surveillance	9		
		A third party	-	Other (specify)		
Estimated leak duration days	hours	, ,				
		oro aro 25 numbo	rad causas in this E	Part H. Check the box corresponding to the		
PART H – APPARENT CAUSE	primary cause of	of the accident. Ch	neck one circle in ea	act in the supplemental categories structions for guidance.		
	e Coating	b. Visual Examina		c. Cause of Corrosion		
External Corrosion	Bare Coated	Localized I General Co	•	Galvanic Atmospheric Stray Current Microbiological		
				Cathodic Protection Disrupted		
Internal Corrosion				Stress Corrosion Cracking Selective Seam Corrosion		
(Complete items a – e				Other		
where applicable.) d. Wa				dic protection prior to discovering accident?		
ı	No Yes, Year	Protection Started	l: <u>/</u>			
		lamaged in the are		/ years / / months Unknown		
H2 – NATURAL FORCES	No Yes => Es	timated time prior t	to accident. <u>7</u>			
3. Earth Movement =>	Earthquake	Subsidence	Landslide	Other		
4. Lightning						
5. Heavy Rains/Floods =>	Washouts	Flotation	Mudslide	Scouring Other		
6. Temperature =>	Thermal stress	Frost heave	Frozen compo	nents Other		
7. High Winds			$/ > \langle \mathcal{I} \rangle$			
			$\rightarrow \rightarrow \rightarrow \leftarrow \rightarrow \leftarrow$			
H3 — EXCAVATION DAMAGE						
Operator Excavation Damag	ge (including their o	ontractors/Not This	rd Party)			
 Third Party (complete a-f) a. Excavator group 						
General Pu	blic Governr	ment Excava	ator other than Oper	rator/subcontractor		
b. Type: Road Work	Pipeline	Water Elect	ric Sewer	Phone/Cable		
I andowner-	not farming related	Farm	∕ iing Railroad			
		// ~ M				
Other liquid	or gas transmissio	n pipeline operator	or their contractor			
Nautical Ope	erations	Other				
c. Excavation was: Op	en Trench S	ub-strata (boring, d	lirectional drilling, e	tc)		
d. Excavation was an ongo	oing activity (Month	or longer) Yes	No If Y	es, Date of last contact //		
e. Did operator get prior no	otification of excava	ation activity?				
Yes; Date received	d: <u>/</u> mo.	// day	// y	r. No		
Notification received from	om: One Cal	l System Ex	cavator Cont	tractor Landowner		
f. Was pipeline marked as	result of location r	equest for excavati	ion? No	Yes (If Yes, check applicable items i - iv)		
i. Temporary marking			Paint	103 (II 103, oncox applicable terris 1 1V)		
ii. Permanent markin	-					
iii. Marks were (check			rate			
iV. Were marks made		ie? Yes	No			
H4 – OTHER OUTSIDE FORCE DAI10. Fire/Explosion as primary ca		Fire/Explosion ca	ause: Man ma	de Natural		
11. Car, truck or other vehicle no		•				
 Rupture of Previously Dama 			O OFF-			
13. Vandalism	· r -					

H5 – MAT Materia	ERIAL AND/OR	WELD F	AILURES				
14.	Body of Pipe	=>	Dent	Gouge	Bend	Arc Burn	Other
15.	Component	=>	Valve	Fitting	Vessel	Extruded Outlet	Other
16.	Joint	=>	Gasket	O-Ring	Threads		Other
Weld							
17.	Butt	=>	Pipe	Fabrication			Other
18.	Fillet	=>	Branch	Hot Tap	Fitting	Repair Sleeve	Other
19.	Pipe Seam	=>	LF ERW HF ERW	DSAW SAW	Seamless Spiral	Flash Weld	Other
Comple	ete a-g if you i	indicate	any cause in p	part H5.			
а	. Type of failure: Constructio Material De	n Defect	=> Poor Work	kmanship Pr	rocedure not followed	Poor Construct	tion Procedures
				in transportation to fore accident occur	o the construction or red? Yes, cor	fabrication site? Ye	es No
	. Date of test:			/ mo. /	/ day		
	 Test medium: Time held at te 		ater Inert C re: <u>/ /</u> I	· · · / -			
			at point of accide		F	PSIG	
H6 – EQU 20. Ma	IPMENT Ilfunction of Cont	rol/Relief I	Eauipment =>	Control-valve	Instrumenta	tion SCADA	Communications
20. IVIC		ion teller	_quipmont	Block valve	Relief valve	Power failure	Other
21. Th	reads Stripped, E	Broken Pin	ne Coupling =>	Nipples	Valve Threads	Dresser Couplings	Other
	al Failure	JIOKOII IP	=>	Gasket	O-Ring	Seal/Pump Packing	Other
	ORRECT OPERA	ATION		Gashet	O-Rang	Ocain ump r acking	Other
	23. Incorrect Operation a. Type: Inadequate Procedures Inadequate Safety Practices Failure to Follow Procedures						
b. Numb	_Other per of employees	involved	who failed a post-a	accident test: drug		_/ alcohol test /	/
H8 – OTH	_ `						
24. Miscellaneous, describe: 25. Unknown							
Investigation Complète Still Under Investigation (submit a supplemental report when investigation is complete) PART I – NARRATIVE DESCRIPTION OF FACTORS CONTRIBUTING TO THE EVENT (Attach additional sheets as necessary)							