UNITED STATES DEPARTMENT OF THE INTERIOR
MINERALS MANAGEMENT SERVICE
GULF OF MEXICO REGION
ACCIDENT INVESTIGATION REPORT

 OCCURRED DATE: 22-AUG-2008 TIME: 0926 HOURS OPERATOR: Nexen Petroleum U.S.A. Inc. REPRESENTATIVE: Miller, Karl TELEPHONE: (337) 735-2504 CONTRACTOR: REPRESENTATIVE: TELEPHONE: 	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
 4. LEASE: AREA: EI LATITUDE: BLOCK: 259 LONGITUDE: 5. PLATFORM: C RIG NAME: 	<pre>PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. X OTHER Construction</pre>
6. ACTIVITY: EXPLORATION (POE)	8. CAUSE:
X DEVELOPMENT/PRODUCTION (DOCD/POD) 7. TYPE: HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days) RW/JT (1-3 days) RW/JT (>3 days)	 EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
☐ Other Injury □ FATALITY	9. WATER DEPTH: 160 FT.
POLLUTION FIRE	10. DISTANCE FROM SHORE: 58 MI.
EXPLOSION LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: E SPEED: 10 M.P.H.
SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: ENE SPEED: 1 M.P.H.
COLLISION HISTORIC >\$25K <- \$25K	13. SEA STATE: FT.

On the morning of August 22, 2008 at approximately 0926 hours, the crane operator at Nexen Eugene Island 259 C platform was attempting to lift a gang box from the M/V Grant (field boat). The load was to be placed on the top deck of the production platform. During the lifting process, while the load was suspended over the water, the crane operator heard a loud pop and then felt the boom jerk. He immediately noticed the boom and load falling to the water, but missed the field boat located adjacent to the platform. The crane heel boom section remained attached to the crane pedestal while hanging over the side of the production platform, with the boom tip submerged in the water. Three (3) third party contractors on the platform were standing on top of the compressor building taking measurements to fabricate handrailing, when they were struck by small fragments from the boom cable when it parted. Their injuries were limited to small pieces of wire being embedded in their skin, covering shoulder and neck areas on their upper body.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Boom cable fatigue and unnecessary stress resulted in reduced strength and integrity of the boom cable, thereby resulting in boom cable failure.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Sudden movement of controls during the lifting operation possibly resulting in unnecessary stress to the boom cable.

20. LIST THE ADDITIONAL INFORMATION:

According to Nexen crane records, documents indicate that during annual and quarterly inspections, the boom heel section had evidence of a bent lacing. Documented evidence from Nexen records indicate that the bent lacing occurred while the boom tip section was being changed during a Quarterly inspection dated January 17, 2008. Nexen has provided documentation of a "pull test" that was performed by a manufacturer representative on that date justifying further use of the crane. After testing was completed, all boom sections were found to be sufficient for heavy lifting operations.

EV2010R

MMS - FORM 2010

PAGE: 3 OF 8 21-OCT-2008 21. PROPERTY DAMAGED: NATURE OF DAMAGE: 1-Facility Crane Boom 1-Destroyed from fall 2-Hand rail on platform top deck 2-Bent out of place 3-One light fixture, top deck. 3-Broken 4-One light fixture pole 4-Bent out of place and broken 5-One PSV vent line, instrument gas 5-Bent out of place

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE: Lafayette District MMS has no recommendations.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

N/A

25. DATE OF ONSITE INVESTIGATION:

23-AUG-2008

26. ONSITE TEAM MEMBERS:

/ Tom Basey / Jason Abshire /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO OCS REPORT:

30. DISTRICT SUPERVISOR:

Elliott S. Smith

APPROVED

DATE: 21-OCT-2008

<pre>OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE X OTHER Rigger</pre>	INJURY FATALITY WITNESS
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS: CITY:	STATE: TOTAL OFFSHORE EXPERIENCE: 2.5 YEARS STATE:
ZIP CODE:	
OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE X OTHER Rigger NAME: HOME ADDRESS:	INJURY FATALITY X WITNESS
CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS: CITY:	STATE: TOTAL OFFSHORE EXPERIENCE: 4 YEARS STATE:
ZIP CODE:	

OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE X OTHER Welder	INJURY FATALITY X WITNESS
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS:	STATE: TOTAL OFFSHORE EXPERIENCE: 18 YEA
CITY: ZIP CODE:	STATE:
OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE X OTHER OTHER	INJURY FATALITY X WITNESS
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY:	STATE: TOTAL OFFSHORE EXPERIENCE: 1 YEF
BUSINESS ADDRESS: CITY: ZIP CODE:	STATE:

 OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER Contract Inspector 	INJURY FATALITY X WITNESS
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS: CITY: ZIP CODE:	STATE: TOTAL OFFSHORE EXPERIENCE: 22 YEARS STATE:
<pre>OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE X OTHER Deck Hand NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS: CITY: ZIP CODE:</pre>	INJURY FATALITY X WITNESS STATE: TOTAL OFFSHORE EXPERIENCE: 14 YEARS STATE:

OPERATOR REPRESENTATIVE	INJURY FATALITY
X OTHER Relief Captain	X WITNESS
NAME :	
HOME ADDRESS:	
CITY:	STATE:
WORK PHONE:	TOTAL OFFSHORE EXPERIENCE: 11 YEARS
EMPLOYED BY:	
BUSINESS ADDRESS:	
CITY:	STATE:
ZIP CODE:	

EV2010R