UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

	OCCURRED DATE: 03-NOV-2008 TIME: 1415 HOURS OPERATOR: Stone Energy Corporation REPRESENTATIVE: LeBouef, Corbett TELEPHONE: (337) 521-0213 CONTRACTOR: ROWAN DRILLING REPRESENTATIVE: Dean Calcote TELEPHONE: (337) 462-3774	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: G04254 AREA: EW LATITUDE: 28.665763 BLOCK: 305 LONGITUDE: -89.96945 PLATFORM: A	PRODUCTION X DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO.
	RIG NAME: ROWAN ALASKA	OTHER
	ACTIVITY: X EXPLORATION (POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY X REQUIRED EVACUATION 1 LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) RW/JT (>3 days)	8. CAUSE: EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury FATALITY POLLUTION FIRE	9. WATER DEPTH: 270 FT. 10. DISTANCE FROM SHORE: 27 MI.
	LWC HISTORIC BLOWOUT UNDERGROUND SURFACE DEVERTER CURRACE FOULDMENT FAILURE OF PROCEDURES	11. WIND DIRECTION: E SPEED: 15 M.P.H. 12. CURRENT DIRECTION: SPEED: M.P.H.
	☐ SURFACE EQUIPMENT FAILURE OR PROCEDURES COLLISION ☐ HISTORIC ☐ >\$25K ☐ <=\$25K	12 CFA CTATE. 4 FT

MMS - FORM 2010 PAGE: 1 OF 4

EV2010R

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On November 3, 2008, at 1415 hours on the Rowan Alaska drilling rig located on Stone Energy Corporation's Lease OCS-G 4254, Ewing Bank Block 305, Platform A, a contract employee smashed the little finger on his left hand during the process of aligning the spool on an electric line unit. The unit had been placed, and the Injured Person (IP) was aligning the unit's electric line spool when his finger was pinched between the unit's frame and the electric line spool frame. The IP was treated by the medic and evacuated for medical treatment. The IP was diagnosed with a fracture to the finger tip and required stitches.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Human Error:

- 1) Improper placement of the hand on the load.
- 2) Employee was not paying attention to possible pinch points.
- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
 - 1) No JSA performed for the rigging up of the unit.
- 20. LIST THE ADDITIONAL INFORMATION:
 - 1) No witnesses available for statements. Two employees were in the area, but had no idea a man was injured. The injured employee walked away without notifying anyone. The two employees were on the opposite side of the spool and never heard or saw the incident.
 - 2) The IP was wearing gloves.

MMS - FORM 2010 PAGE: 2 OF 4

EV2010R 08-APR-2009

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None None

ESTIMATED AMOUNT (TOTAL):

\$

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The MMS New Orleans District makes no recommendations to the MMS Regional Office of Safety Management (OSM).

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:

04-NOV-2008

26. ONSITE TEAM MEMBERS:

Justin Josey /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

David J. Trocquet

APPROVED

DATE: 08-APR-2009

MMS - FORM 2010 PAGE: 3 OF 4

EV2010R 08-APR-2009

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER	X INJURY FATALITY WITNESS	
NAME: HOME ADDRESS: CITY: WORK PHONE:	STATE: TOTAL OFFSHORE EXPERIENCE: YEARS	S
EMPLOYED BY: BUSINESS ADDRESS:		
CITY: ZIP CODE:	STATE:	

MMS - FORM 2010 PAGE: 4 OF 4