UNITED STATES DEPARTMENT OF THE INTERIOR Bureau of Safety and Environmental Enforcement GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1. OCCURRED	
DATE: 27-SEP-2011 TIME: 2320 HOURS	STRUCTURAL DAMAGE
27-55F-2011 11ME. 2520 1100KS	CRANE X OTHER LIFTING DEVICE Running Tool
2. OPERATOR: Petrobras America Inc.	DAMAGED/DISABLED SAFETY SYS.
REPRESENTATIVE: Gomez, Rebecca	X INCIDENT >\$25K Dropped Riser Joint
TELEPHONE: (713) 808-3145 CONTRACTOR: Ensco Offshore Co.	H2S/15MIN./20PPM REQUIRED MUSTER
REPRESENTATIVE: Horricks, Thomas	SHUTDOWN FROM GAS RELEASE
TELEPHONE: (281) 560-8543	OTHER
3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	☐ PRODUCTION
4. LEASE: G16965	X DRILLING
AREA: WR LATITUDE:	WORKOVER COMPLETION
BLOCK: 206 LONGITUDE:	HELICOPTER
	MOTOR VESSEL PIPELINE SEGMENT NO.
5. PLATFORM: RIG NAME: PRIDE DEEP OCEAN MENDOCINO	X OTHER Running BOP's
RIG MAIL. INDE DELL COLAN MENDOCINO	
6. ACTIVITY: EXPLORATION (POE)	8. CAUSE:
DEVELOPMENT/PRODUCTION (DOCD/POD)	EQUIPMENT FAILURE
7. TYPE:	HUMAN ERROR EXTERNAL DAMAGE
HISTORIC INJURY	SLIP/TRIP/FALL
REQUIRED EVACUATION	WEATHER RELATED LEAK
LTA (1-3 days) LTA (>3 days	UPSET H2O TREATING
RW/JT (1-3 days)	OVERBOARD DRILLING FLUID
RW/JT (>3 days)	OTHER
Other Injury	9. WATER DEPTH: 8149 FT.
FATALITY POLLUTION	
FIRE	10. DISTANCE FROM SHORE: 166 MI.
EXPLOSION	11. WIND DIRECTION: N
LWC HISTORIC BLOWOUT	SPEED: 1 M.P.H.
UNDERGROUND	
SURFACE DEVERTER	12. CURRENT DIRECTION: N
SURFACE EQUIPMENT FAILURE OR PROCEDURES	SPEED: 1 M.P.H.
COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: 1 FT.

MMS - FORM 2010 PAGE: 1 OF 4

EV2010R 08-DEC-2011

17. INVESTIGATION FINDINGS:

On 27 September 2011 at approximatly 11:14 PM, while in the process of running the BOP on 21-1/4" marine riser for the Cascade #4 well, a joint of riser slipped out of the Vetco Gray Riser Handling Tool, (RHT). The riser joint dropped a total of 61 feet to the rig floor, crushing the spider and landing on top of the previous joint. Everyone was clear of the work area so there were injuries associated with the incident.

The post-accident investigation determined that the mechanical lock, designed to prevent the riser from coming unlatched from the RHT, was actually pinned in the unlock position.

The employee did not realize that the mechanical lock was not in the "locked" position before inserting the pin and giving the approval to make the lift. The mechanical lock could not engage because the RHT was not properly seated in the riser.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The employee failed to realize the mechanical lock was in the unlocked position when he gave approval to make the lift, resulting in the mechanical lock not engaging; thus, allowing the riser to become unlatched from the RHT.

- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
 - *Although the JSA covered making sure that RHT was properly engaged and that the safety latch was in place before trying to move the riser, actual verification was not done prior to making the lift.
 - *ENSCO's Level III procedure made no mention of the mechanical lock; only the hydraulic lock which engages the RHT but does not lock it onto the riser.
 - *No testing of the seals was required either by the ENSCO's Level III procedure or by the OEM's pre-run checklist.
- *Neither the JSA nor the procedure covered the importance of making sure the riser was properly seated in the RHT before proceeding with the task.
- 20. LIST THE ADDITIONAL INFORMATION:

n/a

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

2 joints of riser riser cart spider

crushed riser
riser cart arm broken
crushed spider

ESTIMATED AMOUNT (TOTAL): \$600,000

MMS - FORM 2010 PAGE: 2 OF 4

EV2010R 08-DEC-2011

- 22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE: Due to the specific nature of this incident, the Houma District has no recommendations to the Regional Office.
- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

A G-110 warning Incident of Non Compliance was issued on December 6, 2011, for failure to work in a safe and workmanline manner.

25. DATE OF ONSITE INVESTIGATION:

18-NOV-2011

26. ONSITE TEAM MEMBERS:

Cedric Bernard / Jeramie Liner /
James Richard /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Bryan A. Domangue

APPROVED

DATE: 08-DEC-2011

MMS - FORM 2010 PAGE: 3 OF 4

EV2010R 08-DEC-2011

MMS - FORM 2010 PAGE: 4 OF 4
EV2010R 08-DEC-2011