UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1.	OCCURRED	
	DATE:	STRUCTURAL DAMAGE
	22-APR-2010 TIME: 0120 HOURS	CRANE
		OTHER LIFTING DEVICE
2.	OPERATOR: Murphy Exploration & Production C	
	REPRESENTATIVE: Lanza, Robert	INCIDENT >\$25K
	TELEPHONE: (281) 675-9135	H2S/15MIN./20PPM
	CONTRACTOR:	REQUIRED MUSTER
	REPRESENTATIVE:	SHUTDOWN FROM GAS RELEASE
	TELEPHONE:	X OTHER Hydraulic pump seal failure
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
		X PRODUCTION
1	IENCE. CO1700	DRILLING
4.	LEASE: G21790 AREA: GC LATITUDE:	WORKOVER
	BLOCK: 338 LONGITUDE:	COMPLETION
	BLOCK: 338 LONGITODE:	HELICOPTER MOTOR VESSEL
_	DI AETODY	PIPELINE SEGMENT NO.
5.	PLATFORM: A-Front Runner RIG NAME:	OTHER
6.	ACTIVITY: EXPLORATION(POE)	8. CAUSE:
	X DEVELOPMENT/PRODUCTION	X EOUIPMENT FAILURE
_	(DOCD/POD)	HUMAN ERROR
7.	TYPE:	EXTERNAL DAMAGE
	HISTORIC INJURY	SLIP/TRIP/FALL
	REQUIRED EVACUATION	WEATHER RELATED
	LTA (1-3 days)	LEAK
	LTA (>3 days	UPSET H2O TREATING
	RW/JT (1-3 days)	OVERBOARD DRILLING FLUID
	RW/JT (>3 days)	OTHER
	Other Injury	9. WATER DEPTH: 3330 FT.
	FATALITY	31
	POLLUTION	10. DISTANCE FROM SHORE: 103 MI.
	X FIRE	10. Biblinder inon blicker. 200 in.
	EXPLOSION	11. WIND DIRECTION: NNE
	LWC HISTORIC BLOWOUT	SPEED: 7 M.P.H.
	UNDERGROUND	SFEED: / M.P.A.
	SURFACE	10 GUDDENE DIDECETON
	DEVERTER	12. CURRENT DIRECTION: NW
	SURFACE EQUIPMENT FAILURE OR PROCEDURES	SPEED: 1 M.P.H.
	COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: 3 FT.

MMS - FORM 2010 PAGE: 1 OF 6

EV2010R 02-AUG-2010

17. INVESTIGATION FINDINGS:

On 22-April-2010 at 0120 hours, a small fire occurred on the 1100 crane. Initially, two hydraulic pumps were changed out on the 1100 crane. After 8 hours of crane operation, one of the hydraulic boom pump's seals failed which caused the gear box to fill up with hydraulic fluid. The gear box holds a gear oil level of 6 inches, but once the level was reached the oil started spraying out of the gear box vent and released oil onto the Turbo Charger exhaust system. The oil ignited once it reached the Turbo Charger, and the fire was extinguished using the 20 pound extinguisher unit on the crane. After the fire was extinguished, it was observed that the vent was the source of the overflow of oil sprayed directly onto the Turbo Charger exhaust.

There was no damage to the crane, however; the fire blankets around the exhaust were replaced due to being covered in oil. After all repairs were made, the crane was placed back into service.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The cause of the incident was the failed seal on the hydraulic pump.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

The contributing cause was the location of the gear box vent allowed the overflow of oil to spray onto the Turbo Charger exhaust.

20. LIST THE ADDITIONAL INFORMATION:

To prevent this incident from reoccurring, Murphy decided to remove the current vent location and pipe the vent to the engine skid.

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

Fire blankets were the only property that Fire damage. was damaged.

ESTIMATED AMOUNT (TOTAL):

\$500

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The Houma District office has no recommendations for the Regional Office.

The Houma District concurs with Murphy's recommendations to prevent reoccurrance listed on this incident report.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

N/A

MMS - FORM 2010 PAGE: 2 OF 6

EV2010R 02-AUG-2010

26. ONSITE TEAM MEMBERS:

Casey Bisso /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Bryan A. Domangue

APPROVED DATE: 30-JUL-2010

MMS - FORM 2010 PAGE: 3 OF 6

EV2010R 02-AUG-2010

FIRE/EXPLOSION ATTACHMENT

aust sytem		
. FUEL SOURCE: Hydraulic gear box oil		
. WERE PRECAUTIONS OR ACTIONS TAKEN TO ISOLATE KNOWN SOURCES OF IGNITION PRIOR TO THE ACCIDENT ? YES		
ED: X HANDHELD WHEELED UNIT FIXED CHEMICAL FIXED WATER NONE		
E ACCIDENT ? YE CD: X HANDHELD WHEELED FIXED CH FIXED WA		

MMS - FORM 2010 PAGE: 4 OF 6

INJURY/FATALITY/WITNESS ATTACHMENT

x OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER	INJURY FATALITY WITNESS
NAME: HOME ADDRESS: CITY: WORK PHONE:	STATE: TOTAL OFFSHORE EXPERIENCE: YEARS
EMPLOYED BY: BUSINESS ADDRESS:	
CITY: ZIP CODE:	STATE:

MMS - FORM 2010 PAGE: 5 OF 6

MMS - FORM 2010 PAGE: 6 OF 6
EV2010R 02-AUG-2010