# UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

# **ACCIDENT INVESTIGATION REPORT**

	OCCURRED DATE: 30-MAR-2007 TIME: 0650 HOURS  OPERATOR: BP America Production Company	STRUCTURAL DAMAGE  CRANE  OTHER LIFTING DEVICE TOP Drive  DAMAGED/DISABLED SAFETY SYS.
	REPRESENTATIVE: Darrell Boudreaux TELEPHONE: (337) 735-5205 CONTRACTOR: Global Marine Drilling REPRESENTATIVE: Harry Wilson TELEPHONE: (281) 589-3862	INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:  ☐ PRODUCTION
	LEASE: G24101  AREA: MC LATITUDE:  BLOCK: 726 LONGITUDE:	DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO.
5.	PLATFORM: RIG NAME: GSF EXPLORER	OTHER
	ACTIVITY: X EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE:	8. CAUSE:  EQUIPMENT FAILURE X HUMAN ERROR
	HISTORIC INJURY  REQUIRED EVACUATION  LTA (1-3 days)  LTA (>3 days  RW/JT (1-3 days)  RW/JT (>3 days)	EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H2O TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury  FATALITY	9. WATER DEPTH: <b>4602</b> FT.
	POLLUTION FIRE	10. DISTANCE FROM SHORE: 45 MI.
	LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: SPEED: 25 M.P.H.
	SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: SPEED: M.P.H.
	COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: FT.

MMS - FORM 2010 PAGE: 1 OF 3

## 17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

While tripping out of the hole laying down drill pipe with the PRS-4i, a single joint of 5 7/8" drill pipe was set in the rotary and the PS 750 slips were set. The traveling block height was approximately 35 ft. in the air when the elevators were opened. The high clutch was then thought to have been engaged, and the traveling blocks began to move. Instead of hoisting, since the clutch was not actually engaged, when the driller increased the amperage on the draw works the traveling blocks began to descend. The top drive landed on and bent the joint of 5 7/8" drill pipe set in the rotary. The driller then heard a popping noise form the drill line, and observed slack in the draw works. Driller immediately applied the break for a "full stop" after the blocks had traveled 5 ft. total.

### 18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The driller did not verify the engagement of the high clutch prior to answering the phone. While his attention was momentarily diverted, he momentarily lost control of the traveling block.

### 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Immediate Cause: Lack of Awareness/Attention - The high clutch was not engaged when the driller attempted to hoist the traveling block.

Underlying Cause: Training - Directly after attempting to engage the high clutch, the driller answered the phone momentarily diverting his attention from the traveling blocks.

20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

EV2010R

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

Joint of drill pipe/Saver Sub Top drive system. Bent drill pipe.

ESTIMATED AMOUNT (TOTAL):

\$5,000

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Recommendations to prevent a recurrence of this event are as follows:

- 1) Post signs in all areas where critical equipment is operated not to use the phone while equipment is in use.
- 2) Research options on replacement of clutch control joy stick.

The New Orleans District makes no recommendations to the Office of Safety Management.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

Incident of Noncompliance G-110 was issued to document that: The driller performed an unsafe act which could have caused serious injury to personnel and equipment.

25. DATE OF ONSITE INVESTIGATION:

31-MAR-2007

26. ONSITE TEAM MEMBERS:

Elbert Clemens / Darrel Williams /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: **22-MAY-2007** 

22-MAY-2007

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R