UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1.	OCCURRED DATE:	□STRUCTURAL DAMAGE		
	11-JUN-2007 TIME: 0230 HOURS	CRANE OTHER LIFTING DEVICE		
_				
2.	OPERATOR: Anadarko Petroleum Corporation	DAMAGED/DISABLED SAFETY SYS.		
	REPRESENTATIVE: Michael Cowan TELEPHONE: (832) 636-8786	x INCIDENT >\$25K Flash gas		
	CONTRACTOR:	H2S/15MIN./20PPM compressor/engine		
	REPRESENTATIVE:	X DECLITOED MICTED		
	TELEPHONE:	REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE		
		OTHER		
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR	OTHER		
	ON SITE AT TIME OF INCIDENT:	6. OPERATION:		
		O. OFERATION.		
		X PRODUCTION		
4.	LEASE: G22987	DRILLING		
	AREA: GC LATITUDE:	WORKOVER		
	BLOCK: 680 LONGITUDE:	COMPLETION		
		HELICOPTER		
5.	PLATFORM: A (Constitution	MOTOR VESSEL		
	RIG NAME:	PIPELINE SEGMENT NO.		
	_	OTHER		
6.	ACTIVITY: EXPLORATION(POE)	8. CAUSE:		
	DEVELOPMENT/PRODUCTION	o. Green		
7.	(DOCD/POD) TYPE:	X EQUIPMENT FAILURE		
		HUMAN ERROR		
	HISTORIC INJURY	EXTERNAL DAMAGE SLIP/TRIP/FALL		
	REQUIRED EVACUATION	WEATHER RELATED		
	LTA (1-3 days) LTA (>3 days	X LEAK		
	RW/JT (1-3 days)	UPSET H20 TREATING		
	RW/JT (>3 days)	OVERBOARD DRILLING FLUID OTHER		
	Other Injury			
	☐ FATALITY	9. WATER DEPTH: 4970 FT.		
	POLLUTION	9. WAIER DEPIH: 49/0 F1.		
	X FIRE	10. DISTANCE FROM SHORE: 150 MI.		
	X EXPLOSION	10. DISTANCE FROM SHORE: 130 MI.		
	LWC HISTORIC BLOWOUT	11. WIND DIRECTION: SE		
	UNDERGROUND	SPEED: 2 M.P.H.		
	SURFACE	2 11.1 III.		
	DEVERTER	12. CURRENT DIRECTION: W		
	SURFACE EQUIPMENT FAILURE OR PROCEDURES	SPEED: 1 M.P.H.		
	COLLISION HISTORIC >\$25K <=\$25K	51110 · I M.I.II,		
		13. SEA STATE: 2 FT.		

MMS - FORM 2010 PAGE: 1 OF 5

EV2010R 27-JUL-2010

17. INVESTIGATION FINDINGS:

A fire occurred at Green Canyon Block 680, Platform A (Constitution) when the No. 1 Compressor caught fire. At approximately 0205 hours, a reducer coupling, which connected a 1/2 inch ball valve to the No. 1 3rd stage volume bottle, parted in the thread section and the valve began leaking gas. The gas was heard by the night crew who then began looking for the leak. The escaping gas contacted an ignition source in the engine air intake and ignited. This caused a backfire strong enough to remove air cleaners from their housing which was able to be heard across the platform. The platform Emergency Shut Down (ESD) was activated. All personnel were made aware of the situation and were instructed to report to their muster stations. At approximately 0210 hours, the fire was suppressed and extinguished using the onboard fire hose system and the deluge system.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The cause of this incident was determined to be a fatigue fracture of the ball valve caused by vibration over time.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

The ball valve is oversized with respect to weight and is also rated for pressures that are not physically achievable with this type of compressor.

20. LIST THE ADDITIONAL INFORMATION:

Since the fire, Anadarko has determined that the ball valve is not needed and that a simple plug will be sufficient. This would reduce the weight stress on the reducer coupling and reduce stress from vibration.

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

Flash Gas Compressor and associated Needs to be replaced Caterpillar engine

ESTIMATED AMOUNT (TOTAL):

\$75,000

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Due to the specific nature of this incident, the Houma District has no recommendations to report to the Regional Office of Safety Management.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

None

25. DATE OF ONSITE INVESTIGATION:

MMS - FORM 2010 PAGE: 2 OF 5

EV2010R 27-JUL-2010 26. ONSITE TEAM MEMBERS:

Amy Wilson /

29. ACCIDENT INVESTIGATION PANEL FORMED:

30. DISTRICT SUPERVISOR:
OCS REPORT:
Michael J. Saucier

APPROVED

DATE: **24-JUL-2007**

FIRE/EXPLOSION ATTACHMENT

1.	SOURCE OF IGNITION	ON: E :	ngine Air	Intake		
2.	TYPE OF FUEL:	X	GAS OIL DIESEL CONDENSAT			
3.	FUEL SOURCE: #1	Comp	OTHER	Stage Volu	me Bottle	
4.	. WERE PRECAUTIONS OR ACTIONS TAKEN TO ISOLATE KNOWN SOURCES OF IGNITION PRIOR TO THE ACCIDENT ? NO					
5.	TYPE OF FIREFIGH	TING E	EQUIPMENT U	TILIZED:	HANDHELD WHEELED UNIT	
					FIXED CHEMICAL	
					NONE	
				П	OTHER	

MMS - FORM 2010 PAGE: 4 OF 5

MMS - FORM 2010 PAGE: 5 OF 5
EV2010R 27-JUL-2010