UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1.	OCCURRED DATE: 07-AUG-2007 TIME: 1930 HOURS	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE
2.	OPERATOR: Chevron U.S.A. Inc. REPRESENTATIVE: Dicky Methern TELEPHONE: (504) 592-7856 CONTRACTOR: Nabors Drilling Inc. REPRESENTATIVE: Mark A. Smith TELEPHONE: (504) 362-8033	DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: G12119 AREA: VK LATITUDE: BLOCK: 786 LONGITUDE:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL
5.	PLATFORM: A-Petronius CT RIG NAME:	PIPELINE SEGMENT NO. OTHER
6.	ACTIVITY: EXPLORATION (POE) DEVELOPMENT/PRODUCTION (DOCD/POD)	8. CAUSE: EQUIPMENT FAILURE
7.	TYPE: HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days) RW/JT (1-3 days) RW/JT (>3 days)	HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H2O TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury 1 First-Aid FATALITY	9. WATER DEPTH: 1854 FT.
	POLLUTION FIRE	10. DISTANCE FROM SHORE: 96 MI.
	LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: N SPEED: 12 M.P.H.
	SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: W SPEED: 10 M.P.H.
	COLLISION ☐ HISTORIC ☐ >\$25K ☐ <=\$25K	13 SEA STATE: 4 FT

MMS - FORM 2010 PAGE: 1 OF 5

23-OCT-2007

EV2010R

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On August 8, 2007, onboard the Nabors 87 Drilling Rig, located at ChevronTexaco's OCS-G 12119, Visoca Knoll (VK) 786 A-Petronius CT Platform, a contract employee was injured when the 2 7/8" tubing fell approximately 43 inches striking the employee in the back. Injured Person (IP) was evacuated for evaluation and was released to full duty on August 8, 2007.

On August 10, 2007, a New Orleans District Inspector conducted an investigation and issued a G-110 Incident of Noncompliance (INC).

Sequence of Events:

The Driller started POOH with 2 7/8" tubing and breaking down single joints at rotary table, when the Assistant Driller entered the Driller's shack to ask a question about crossovers. The Driller turned to the Assistant Driller removing his hand from the brake handle and applied pressure with his foot on the lower bar. As the Driller returned his attention to the rotary table he noticed the block had slacked off causing the tubing to be jammed inside the top drive and stuck inside the elevator. After several unsuccessful attempts to free the bent tubing from the elevator by the floor hands, the Driller instructed the floor hands to clear the area. At this time, the tubing was to be broken out at the rotary. IP went to remove the mouse hole cover in front of the rotary when the tubing broke and struck the IP in the back.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Driller's attention to the operation was interupted when the Assistant driller entered the driller shack to ask a question.

- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
 - a. Improper communication with the floor hands and ensuring that all floor personnel was well clear of rotary table area.
 - b. Unknown reasoning why the block slacked off and allowed the joint to be jammed and stuck between the elevator and the top drive.
- 20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 5

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

One joint of 2 2/8" tubing

Bent

ESTIMATED AMOUNT (TOTAL):

\$504

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The New Orleans District has no recommendations to MMS

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

Lessee failed to perform operation in a safe workman like manner, resulting in an injury to personnel on the rig floor. The Company was issued a Incident of Noncompliance (INC) G-110

- a. DOES THE LESSEE PERFORM ALL OPERATIONS IN A SAFE AND WORKMANLIKE MANNER AND PROVIDE FOR THE PRESERVATION AND CONSERVATION OF PROPERTY AND THE ENVIRONMENT? Authority: 107(a) Enforcement Action: W/C/S 401(e)
- 25. DATE OF ONSITE INVESTIGATION:

07-AUG-2007

26. ONSITE TEAM MEMBERS:

Darryl P. Willims /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: 19-OCT-2007

MMS - FORM 2010 PAGE: 3 OF 5

EV2010R

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER	INJURY FATALITY WITNESS	
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY:	STATE: TOTAL OFFSHORE EXPERIENCE:	
BUSINESS ADDRESS: CITY: ZIP CODE:	STATE:	
OPERATOR REPRESENTATIVE X CONTRACTOR REPRESENTATIVE	INJURY	
OTHER	FATALITY WITNESS	
NAME: HOME ADDRESS: CITY: WORK PHONE:		YEAI

MMS - FORM 2010 PAGE: 4 OF 5

INJURY/FATALITY/WITNESS ATTACHMENT

NAME: HOME ADDRESS:		
HOME ADDRESS:		
CITY:	STATE:	
WORK PHONE:	TOTAL OFFSHORE EXPERIENCE:	YEARS
EMPLOYED BY:		
BUSINESS ADDRESS:		
CITY:	STATE:	
ZIP CODE:		

MMS - FORM 2010 PAGE: 5 OF 5