UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1. OCCURRED DATE: 08-AUG-2007 TIME: 2118 HOURS 2. OPERATOR: Merit Energy Company REPRESENTATIVE: Llyod Sigue TELEPHONE: (337) 262-8192 CONTRACTOR: REPRESENTATIVE: TELEPHONE:	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
4. LEASE: G15212 AREA: VR LATITUDE: BLOCK: 408 LONGITUDE: 5. PLATFORM: A RIG NAME:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER
6. ACTIVITY: EXPLORATION(POE)	8. CAUSE:
DEVELOPMENT/PRODUCTION (DOCD/POD) 7. TYPE: HISTORIC INJURY REQUIRED EVACUATION 1 LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) RW/JT (>3 days) 1	X EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED X LEAK UPSET H2O TREATING OVERBOARD DRILLING FLUID OTHER
☐ Other Injury ☐ FATALITY	9. WATER DEPTH: 389 FT.
X POLLUTION X FIRE	10. DISTANCE FROM SHORE: 95 MI.
LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: N SPEED: 2 M.P.H.
SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: S SPEED: 2 M.P.H.
COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: 0 FT.

MMS - FORM 2010 PAGE: 1 OF 8

EV2010R

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

At approximately 9:18 pm, platform personnel heard a popping noise. Operator opened the living quarters door and saw flames shooting up from the production deck downstairs. Personnel sounded the alarm and activated ESD system. (Platform was already shutting in on TSE). Personnel started down the stairway, having to use fire extinguisher along the way. Once downstairs, personnel noticed that fire was originating from pipeline pump skid. Lead operator started fighting fire in skid with chemical extinguishers. Other personnel were gathering extra extinguishers at the same time and started helping lead operator. Once fire was under control, platform personnel contacted VR 369 to send the boat. Upon arrival of the boat, all unessential personnel were instructed to board the vessel and stand by. Platform personnel pulled fire hose from boat to the pipeline pump skid and sprayed pumps with firewater until equipment was satisfactorily cooled down. Personnel then secured platform, boarded the boat and traveled to VR 369 for the remainder of the night.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Pipeline pump packing nut backed off of packing, allowing oil to spray some 30 feet. During that process, oil contacted the hot exhaust system of the other pipeline pump causing it to ignite. "Wrap around" insulation blankets were being utilized on both of the gas driven pipeline pump engines, instead of a rigid/ sealed type insulation that provides a better form of protection.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

The hatch/ cover on the pipeline pump packing rod box was not secured with nuts and bolts as it was originally designed. This in turn allowed the velocity of the leak to push the hatch/ cover open and spray oil all over equipment and engines. If hatch/ cover would have been properly secured, the leak could have (should have) been contained in the packing box which drains directly to the skid.

20. LIST THE ADDITIONAL INFORMATION:

Upon activation of the TSE/ESD, the emergency diesel generator, which drives the firewater pump, started briefly and then shut down. This action left only chemical extinguishers that could be used to fight the fire.

At the time of the incident there were 5 souls on board and three wells were producing approximately 1800 bbls of oil per day.

MMS - FORM 2010 PAGE: 2 OF 8

EV2010R 03-JAN-2008

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

PIPELINE PUMPS, ASSOCIATED WIRING

HEAT, FIRE, SMOKE

ESTIMATED AMOUNT (TOTAL):

\$350,000

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The Lake Charles District recommends a SAFETY ALERT be issued to include the following recommendations:

- 1. Make sure that covers/ hatches are secure on pipeline pump packing boxes.
- 2. Inspect packing nuts regularly to ensure tightness.
- 3. Insulate exhaust stacks on engines, where there is a probability of oil coming into contact with them, with rigid/ sealed insulation instead of blanket "wrap around" insulation.
- 4. Install barrier between gas driven engines and pipeline pump unit to avoid any fluid from contacting the engine or exhaust of engine.
- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

G-112 Cover to packing box not secured in a manner consistent with it's design. P-132 Fire water pump failed to run for at least 30 minutes during a platform shut in.

G-152 Engine exhaust not insulated in a manner to prevent exposure to hydrocarbon liquids.

25. DATE OF ONSITE INVESTIGATION:

09-AUG-2007

26. ONSITE TEAM MEMBERS:

JARROTT GUILLORY / ERIC FONTENOT /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Larry Williamson

APPROVED

DATE: 07-DEC-2007

MMS - FORM 2010 PAGE: 3 OF 8

EV2010R

03-JAN-2008

FIRE/EXPLOSION ATTACHMENT

1.	SOURCE OF	IGNITION	Ex	haust	stack	on	gas	driv	en	pipeline	pum
2.	TYPE OF FU	JEL:		GAS							
			x	OIL							
				DIESE	L						
				CONDE	NSATE						
				HYDRA	ULIC						
				OTHER							
3.	FUEL SOURC	CE: pipe	line	e pump	packi	ng g	,lanc	i			
4.	WERE PRECA		_			_			ΙΤ	? YES	
5.	TYPE OF F	IREFIGHTI	NG E	QUIPME	NT UTI	LIZ	ED:	x H	ANI	OHELD	
							[x W	HEE	ELED UNIT	
							[F	IXE	ED CHEMIC	AL
							[F	IXE	ED WATER	
							[N	ONE	<u>c</u>	
							Γ	07	гне	:R	

MMS - FORM 2010 PAGE: 4 OF 8

INJURY/FATALITY/WITNESS ATTACHMENT

x OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER	INJURY FATALITY WITNESS	
NAME: TED BREAUX HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY:	STATE: TOTAL OFFSHORE EXPERIENCE:	YEAR
BUSINESS ADDRESS: CITY: ZIP CODE:	STATE:	
OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER MARTY CHIRPICK	INJURY FATALITY WITNESS	
X CONTRACTOR REPRESENTATIVE	FATALITY	YEAR

MMS - FORM 2010 PAGE: 5 OF 8

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE X CONTRACTOR REPRESENTATIVE	INJURY FATALITY	
NAME: TERRY SEAUX HOME ADDRESS:	X WITNESS STATE:	
CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS:	TOTAL OFFSHORE EXPERIENCE:	YΕ
CITY: ZIP CODE:	STATE:	
OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER CONSTRUCTION PERSONN NAME: JAY WOMACK	X INJURY FATALITY X WITNESS	
CONTRACTOR REPRESENTATIVE X OTHER CONSTRUCTION PERSONN	FATALITY	YE

MMS - FORM 2010 PAGE: 6 OF 8

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE	INJURY
CONTRACTOR REPRESENTATIVE	FATALITY
X OTHER CONSTRUCTION PERSONN	EL WITNESS
NAME: ALFRED BEGNEAUX	
HOME ADDRESS:	
CITY:	STATE:
WORK PHONE:	TOTAL OFFSHORE EXPERIENCE: YEARS
EMPLOYED BY:	
BUSINESS ADDRESS:	
CITY:	STATE:
ZIP CODE:	

MMS - FORM 2010 PAGE: 7 OF 8

POLLUTION ATTACHMENT

1.	VOLUME: 21 GAL BBL	
	YARDS LONG X YARDS WIDE	
	APPEARANCE:	
2.	TYPE OF HYDROCARBON RELEASED: X OIL	
	DIESEL	
	CONDENSATE	
	HYDRAULIC	
	NATURAL GAS	
	OTHER	_
3.	SOURCE OF HYDROCARBON RELEASED:	
4.	WERE SAMPLES TAKEN? NO	
5.	WAS CLEANUP EQUIPMENT ACTIVATED? NO	
	IF SO, TYPE: SKIMMER CONTAINMENT BOOM ABSORPTION EQUIPMENT DISPERSANTS OTHER	
6.	ESTIMATED RECOVERY: GAL BBL	
7.	RESPONSE TIME: HOURS	
8.	IS THE POLLUTION IN THE PROXIMITY OF AN ENVIRONMENTALLY SENSITIVE AREA (CLASS I)? NO	
9.	HAS REGION OIL SPILL TASK FORCE BEEN NOTIFIED? NO	
10.	CONTACTED SHORE: NO IF YES, WHERE:	
11.	WERE ANY LIVE ANIMALS OBSERVED NEAR: NO	
12.	WERE ANY OILED OR DEAD ANIMALS OBSERVED NEAR SPILL: NO	

MMS - FORM 2010 PAGE: 8 OF 8