UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1. OCCURRED DATE: 15-NOV-2007 TIME: 0530 HOURS 2. OPERATOR: Chevron U.S.A. Inc. REPRESENTATIVE: George, Noel TELEPHONE: (504) 592-6542 CONTRACTOR: REPRESENTATIVE: TELEPHONE:	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
4. LEASE: G02185 AREA: SP LATITUDE: BLOCK: 78 LONGITUDE: 5. PLATFORM: RIG NAME:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER
6. ACTIVITY: EXPLORATION(POE)	8. CAUSE:
DEVELOPMENT/PRODUCTION (DOCD/POD) 7. TYPE: HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) RW/JT (>3 days) RW/JT (>3 days)	EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
Other Injury FATALITY	9. WATER DEPTH: FT.
POLLUTION FIRE EXPLOSION	10. DISTANCE FROM SHORE: MI.
LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: SPEED: M.P.H.
SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURE	12. CURRENT DIRECTION: SPEED: M.P.H.
COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: FT.

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On November 15, 2007, at 0530 hours, a crew member was injured while the Motor Vessel (MV) Pope John Paul II was maneuvering and tying-up to Lease OCS-G 2185, South Pass (SP) 78 A Platform. The Injured Person (IP) suffered fractures in both hands and legs when the rope used to tie-up the MV snapped striking both his hands and legs. The IP recovery time is expected to be greater than two months.

Sequence of Events:

The MV Pope John Paul II was trying to tie up to a Marathon platform. After the IP tied the boat up the boat captain tried moving the boat forward to take up the slack out of the rope. The IP tried to stop the captain thinking he was going to fast. The IP thought the captain did not see him because of all the equipment on deck. Before the IP could think about his position the rope snapped in two striking the IP on both legs and hand. Nabors safety coordinator flew with IP to hospital.

Update 1: 11/19/07 - Injured person went through surgery. He did have fractures in both legs and both hands. He was eating regular food and talking. IP currently in ICU and is to be upgraded.

Update 2: 12/4/07 - The injured party will possibly need recovery greater than 2 months.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Human Error:

Lack of communications between crew member and Captain of boat.

- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
- 20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

EV2010R 31-MAR-2008

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None None

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The New Orleans Distrist makes no recommendation to MMS.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

 No onsite investigation. /

 29. ACCIDENT INVESTIGATION PANEL FORMED:

 NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: 28-MAR-2008

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R 31-MAR-2008