UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1.	OCCURRED	8.	CAUSE: EQUIPMENT FAILURE
	DATE: 23-JUN-2005 TIME: 1915 HOURS		X HUMAN ERROR
			EXTERNAL DAMAGE
2.	OPERATOR: Anadarko Petroleum		SLIP/TRIP/FALL
	Corporation		□ □ weather related
			LEAK
	REPRESENTATIVE: Susan Hatchcock		브
	TELEPHONE: (832) 636-8758		UPSET H2O TREATING
3.	LEASE: G21810		OVERBOARD DRILLING FLUID
	AREA: GC LATITUDE: 27.33699401		OTHER
	BLOCK: 652 LONGITUDE: -90.15495779	9.	WATER DEPTH: 4400 FT.
4	PLATFORM:	10.	DISTANCE FROM SHORE: 126 MI.
٠.	LIAITORIT	11.	WIND DIRECTION: E
	RIG NAME ENSCO 7500		SPEED: 16 M.P.H.
5.	ACTIVITY: X EXPLORATION(POE)	12.	CURRENT DIRECTION: SW
	DEVELOPMENT/PRODUCTION		SPEED: 1 M.P.H.
	(DOCD/POD)	1.0	CDA CENTER.
6.	TYPE: FIRE		SEA STATE: 4 FT.
	☐ EXPLOSION	14.	PICTURES TAKEN: NO
	□ □ blowout	15.	STATEMENT TAKEN: YES
	☐ collision	16.	OPERATOR REPRESENTATIVE/
	브		SUPERVISOR ON SITE AT TIME OF INCIDENT:
	INJURY NO		Donnie Soderberg
	FATALITY NO.		CITY: Florin STATE: LA
	X POLLUTION		
	OTHER		TELEPHONE: (337) 735-3544
7.	OPERATION: PRODUCTION		CONTRACTOR: Ensco Offshore Co.
	X DRILLING		
	☐ WORKOVER		CONTRACTOR REPRESENTATIVE/
			SUPERVISOR ON SITE AT TIME OF INCIDENT:
	COMPLETION		Jimmy Pilcher
	MOTOR VESSEL		CITY: Libuse STATE: LA
	PIPELINE SEGMENT NO.		TELEPHONE: (318) 466-9473
	OTHER		

MMS - FORM 2010 PAGE: 1 OF 4

EV2010R * * * * * * * PROPRIETARY * * * * * * 04-JAN-2006

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

In the process of drilling the well, the crew was attempting maintenance on the spare BOP fail safe valve. The main diverter supply valve was closed, resulting in a pressure loss to the slip joint packer. After the loss of pressure occurred, the slip joint packer seal retracted causing 15 barrels of synthetic base mud to spill into the Gulf of Mexico. The Assistant Subsea Engineer failed to execute the scope of the work planned out and discussed by the supervisor during the pre-tour safety meeting. In addition, no permit to work as required by Ensco's Safety System of Work Policy was prepared prior to the operation.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The cause of the spill was an inadvertent loss of pressure on the slip joint packer and was a direct result of human error and failure to follow written procedures.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

none

20. LIST THE ADDITIONAL INFORMATION:

In order to prevent recurrence, Ensco and Anadarko have discussed this matter and Ensco has addressed this issue in safety meetings to raise the level of awareness surrounding these procedures. Ensco has stressed at their pre-tour meetings no changes are to be made without approval from the supervisor. In addition, Ensco modified its preventive maintenance routine for fail safe valves to reflect not only the scenario of Broussard yard maintenance procedures but to apply to maintenance and overhaul on board the rig as well; i.e., not just shore based equipment yard specific but rig specific as well.

MMS - FORM 2010 PAGE: 2 OF 4

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

none

n/a

ESTIMATED AMOUNT (TOTAL):

Ġ

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Due to the specific nature of this incident, the Houma District has nothing to recommend to the Regional Office.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

E-100 for pollution.

25. DATE OF ONSITE INVESTIGATION:

28. ACCIDENT CLASSIFICATION:

MINOR

26. ONSITE TEAM MEMBERS:

Gresham, Amy / Sanchez, Brandon /

Gresnam, Amy / Danchez, Brandon

27. OPERATOR REPORT ON FILE: YES

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Michael J. Saucier

APPROVED

DATE: 22-AUG-2005

MMS - FORM 2010 PAGE: 3 OF 4

POLLUTION ATTACHMENT

1.	VOLUME: GAL 15 BBL
	YARDS LONG X YARDS WIDE
	APPEARANCE: DARK BROWN
2.	TYPE OF HYDROCARBON RELEASED: OIL
	DIESEL
	CONDENSATE
	HYDRAULIC
	NATURAL GAS
	X OTHER Synthetic base mud
3.	SOURCE OF HYDROCARBON RELEASED: Slip Joint Packer
4.	WERE SAMPLES TAKEN? NO
5.	WAS CLEANUP EQUIPMENT ACTIVATED? NO
	IF SO, TYPE: SKIMMER CONTAINMENT BOOM ABSORPTION EQUIPMENT DISPERSANTS OTHER
6.	ESTIMATED RECOVERY: 0 GAL BBL
7.	RESPONSE TIME: HOURS
8.	IS THE POLLUTION IN THE PROXIMITY OF AN ENVIRONMENTALLY SENSITIVE AREA (CLASS I)? NO
9.	HAS REGION OIL SPILL TASK FORCE BEEN NOTIFIED? NO
10.	CONTACTED SHORE: NO IF YES, WHERE:
11.	WERE ANY LIVE ANIMALS OBSERVED NEAR: NO
12.	WERE ANY OILED OR DEAD ANIMALS OBSERVED NEAR SPILL: NO

MMS - FORM 2010 PAGE: 4 OF 4