#### UNITED STATES DEPARTMENT OF THE INTERIOR

# MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

## ACCIDENT INVESTIGATION REPORT

1.	OCCURRED	8.	CAUSE: X EQUIPMENT FAILURE			
	DATE: 02-NOV-2005 TIME: 2330 HOURS		X HUMAN ERROR			
0	OPERATOR: Apache Corporation		EXTERNAL DAMAGE			
۷.			SLIP/TRIP/FALL			
			WEATHER RELATED			
	REPRESENTATIVE: John Garber		LEAK			
	TELEPHONE: (337) 344-9959		UPSET H20 TREATING			
3.	LEASE: <b>G21685</b>	OVERBOARD DRILLING FLUID				
	AREA: ST LATITUDE: 28.161413		OTHER			
	BLOCK: 308 LONGITUDE: -90.227625	9.	WATER DEPTH: 484 FT.			
			DISTANCE FROM SHORE: 66 MI.			
4.	PLAIFORM. A (Tarantula)		WIND DIRECTION: N			
	RIG NAME H&P 107		SPEED: 25 M.P.H.			
5.	ACTIVITY:	12	CURRENT DIRECTION: N			
	_	12.	SPEED: 1 M.P.H.			
	DEVELOPMENT/PRODUCTION (DOCD/POD)					
6.	TYPE:   FIRE	13.	SEA STATE: 6 FT.			
	EXPLOSION					
	BLOWOUT					
			OPERATOR REPRESENTATIVE/			
			SUPERVISOR ON SITE AT TIME OF INCIDENT:			
			John Garber			
	POLLUTION		CITY: Lafayette STATE: LA			
	OTHER		TELEPHONE: (337) 232-2416			
			_			
7.	OPERATION: PRODUCTION		CONTRACTOR: TETRA Technologies, Inc.			
	x DRILLING					
	WORKOVER  COMPLETION  MOTOR VESSEL		CONTRACTOR REPRESENTATIVE/ SUPERVISOR ON SITE AT TIME OF INCIDENT:			
			Eddie Evans			
			CITY: Houma STATE: LA			
			TELEPHONE: (985) 876-7194			
	OTHER					

MMS - FORM 2010 PAGE: 1 OF 4

#### 17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

Upon completion of a frac job, there was approximately 9,500 pounds of pressure on the drill pipe. While pulling on the drill pipe to move the crossover to the reverse position, the hydraulic choke was not completely closed. When the crossover tool hit the reverse position, the 9500 pounds bled to zero within 55 seconds. This caused a tremendous surge of pressure to the overboard line. This is a rubber 2 inch line, which is rated for 10,000 pounds but normally only has 100 to 200 pounds of pressure on it. The line was secured with rope and chains. When the pressure hit the line, it parted the line from a tied down position. The force caused the line to whip around uncontrollably. This line then struck an employee from behind and knocked him into a handrail, causing several injuries. The employee sustained four fractured ribs, a laceration to his calf and brused spleen and kidney. He was treated for a blood clot in his leg, which has not been attributed to the accident.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The manifold choke was left open.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

None

20. LIST THE ADDITIONAL INFORMATION:

n/a

MMS - FORM 2010 PAGE: 2 OF 4

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

VRU panel, panel glass, eyewash station Broken and fiberglass sink.

ESTIMATED AMOUNT (TOTAL):

\$5,300

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Due to the specific nature of this incident, the Houma District has no recommendations to report to the Regional Office.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

On November 4, 2005, an incident of non-compliance G110 was issued for this accident. The leasee did not perform operations in a safe condition. A third party hydraulic choke was not completely closed, and a third party person was injured. The accident occurred on November 2, 2005 at 2310 hours but MMS was not notified until November 3, 2005 at 1430 hours.

25. DATE OF ONSITE INVESTIGATION:

04-NOV-2005

26. ONSITE TEAM MEMBERS:

Sevin, Doug / Gresham, Amy /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Michael J. Saucier

APPROVED

DATE: **12-JAN-2006** 

MMS - FORM 2010 PAGE: 3 OF 4

EV2010R

### INJURY/FATALITY/WITNESS ATTACHMENT

X CONTRACTOR	PRESENTATIVE REPRESENTATIVE	<b>x</b>	INJURY FATALIT				
NAME:		⊔	WITNESS				
CITY:	HOME ADDRESS:  CITY: STATE:  WORK PHONE: (800) 364-7164 TOTAL OFFSHORE EXPERIENCE: YEA						
	TETRA Technologies SS: 25025 I-45 No The Woodlands 77380	orth	2 <b>524</b> STATE:	ТХ			

MMS - FORM 2010 PAGE: 4 OF 4