UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT PACIFIC OCS REGION

ACCIDENT INVESTIGATION REPORT

For Public Release

PAGE: 1 OF 4

18-MAR-2013

1.	OCCURRED DATE: 22-SEP-2012 TIME: 1132 HOURS	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE
2.	OPERATOR: Beta Operating Company, LLC REPRESENTATIVE: TELEPHONE: CONTRACTOR: REPRESENTATIVE: TELEPHONE:	DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE TOTHER ELECTRICAL W/INJURY
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION: X PRODUCTION
4.	LEASE: P00300 AREA: LB LATITUDE: BLOCK: 6438 LONGITUDE:	DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL
5.	PLATFORM: ELLY RIG NAME:	PIPELINE SEGMENT NO. OTHER
	ACTIVITY: EXPLORATION (POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY	8. CAUSE: EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER 9. WATER DEPTH: 265 FT. 10. DISTANCE FROM SHORE: 9 MI. 11. WIND DIRECTION: SPEED: M.P.H. 12. CURRENT DIRECTION: SPEED: M.P.H. 13. SEA STATE: FT.
	CONTINUE TUTSTOKIC T >\$528 T <=\$528	13. SEA STATE: FT. 14. PICTURES TAKEN: YES
		15. STATEMENT TAKEN: YES

MMS - FORM 2010

EV2010R

17. INVESTIGATION FINDINGS:

(cable technician) with 3rd party contractor TDE was performing a Megger (Hi-Pot) test on newly laid sub-sea cable (prior to tie-in). was testing the last conductor when the Megger lead popped off. He walked over to re-attached the Megger lead to the conductor & a loud pop was heard as he received a shock of an estimated 98,000 volts at a low amperage.

- 18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:
 - * Improper PPE: Cable Technician did not utilize (voltage gloves) as required on his JHA (JSA)
 - * A special test procedure was available to the cable technician, however was not available onsite.
- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
 - * Trainning: Although being a level 3 Certified Technician, did the technician need more skill/knowledge to perform the task or to respond to conditions or to understand system response?
 - * Situation not covered on procedure. Did the procedure fail to address all situations that reasonably could have been expected to occur during the completion of the procedure?
 - * No safe work permit issued for the task.
- 20. LIST THE ADDITIONAL INFORMATION:
 - * Policies, Administrative controls, or procedures not used, missing, or in need of improvement? The Supervisor for the area affected by the work (control room operator) should have been notified & received a copy of the JHA (JSA) prior to the contractor starting work. Authorized company personnel should have signed off on the JHA (JSA) prior to starting the task.
 - * further information located under inspections dated 09/24/12 (insp. type "AI"). Photo's of the incident site are also attached under noted inspection record.
 - 21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None

N/A

ESTIMATED AMOUNT (TOTAL):

\$

- 22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:
 - * Adhere to company policy regarding JSA's.
 - * Conduct daily safet meetings to address contractor's activities & their procedures.
 - * Implement safe work or hot work permit as applicable for all non-routine operations.

MMS - FORM 2010

18-MAR-2013

PAGE: 2 OF 4

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
 - * Improper PPE
 - * No procedure onsite for the work being conducted.
- 25. DATE OF ONSITE INVESTIGATION:
- 28. ACCIDENT CLASSIFICATION:

24-SEP-2012

MAJOR

26. ONSITE TEAM MEMBERS:

Bob Borghei / Bobby Fuller /

29. ACCIDENT INVESTIGATION PANEL FORMED:

OCS REPORT:

30. DISTRICT SUPERVISOR:

Mike Mitchell (Acting)

27. OPERATOR REPORT ON FILE: YES

APPROVED

DATE:

12-NOV-2012

MMS - FORM 2010

EV2010R

18-MAR-2013

PAGE: 3 OF 4

MMS - FORM 2010

EV2010R 18-MAR-2013

PAGE: 4 OF 4