

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT  
GULF OF MEXICO REGION

# ACCIDENT INVESTIGATION REPORT

*For Public Release*

1. OCCURRED  
DATE: 17-OCT-2013 TIME: 2130 HOURS

2. OPERATOR: Nexen Petroleum U.S.A. Inc.  
REPRESENTATIVE:  
TELEPHONE:  
CONTRACTOR:  
REPRESENTATIVE:  
TELEPHONE:

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR  
ON SITE AT TIME OF INCIDENT:

4. LEASE: G00985  
AREA: EI LATITUDE:  
BLOCK: 259 LONGITUDE:

5. PLATFORM: B  
RIG NAME:

6. ACTIVITY:  EXPLORATION (POE)  
 DEVELOPMENT/PRODUCTION (DOCD/POD)

7. TYPE:  
 HISTORIC INJURY  
 REQUIRED EVACUATION  
 LTA (1-3 days)  
 LTA (>3 days)  
 RW/JT (1-3 days)  
 RW/JT (>3 days)  
 Other Injury  
 FATALITY  
 POLLUTION  
 FIRE  
 EXPLOSION  
LWC  HISTORIC BLOWOUT  
 UNDERGROUND  
 SURFACE  
 DEVERTER  
 SURFACE EQUIPMENT FAILURE OR PROCEDURES  
COLLISION  HISTORIC  >\$25K  <=\$25K

6. OPERATION:  
 PRODUCTION  
 DRILLING  
 WORKOVER  
 COMPLETION  
 HELICOPTER  
 MOTOR VESSEL  
 PIPELINE SEGMENT NO.  
 OTHER

8. CAUSE:  
 EQUIPMENT FAILURE  
 HUMAN ERROR  
 EXTERNAL DAMAGE  
 SLIP/TRIP/FALL  
 WEATHER RELATED  
 LEAK  
 UPSET H2O TREATING  
 OVERBOARD DRILLING FLUID  
 OTHER

9. WATER DEPTH: 170 FT.

10. DISTANCE FROM SHORE: 51 MI.

11. WIND DIRECTION:  
SPEED: M.P.H.

12. CURRENT DIRECTION:  
SPEED: M.P.H.

13. SEA STATE: FT.

STRUCTURAL DAMAGE  
 CRANE  
 OTHER LIFTING DEVICE  
 DAMAGED/DISABLED SAFETY SYS.  
 INCIDENT >\$25K  
 H2S/15MIN./20PPM  
 REQUIRED MUSTER  
 SHUTDOWN FROM GAS RELEASE  
 OTHER **compressor**

17. INVESTIGATION FINDINGS:-

On 17 October 2013 at approximately 2130 hours, a field boat reported a fire that was the result of a compressor failure.

The compressor was an Ariel JGC-4, Serial number F-11439R, 110,000 lb. rod load with a 1000 rpm compressor frame. The compressor was operating with a suction pressure of 34 psi and the final discharge pressure at 1140 psi.

At approximately 2130 hours, the field boat reported a fire to the main facility that occurred on an unmanned structure. The field boat began to extinguish the fire utilizing the boats fire pump. The field boat actuated the Emergency Shut Down (ESD) at the boat landing but the compressor had shut down due to vibration according to the indication on the compressor panel.

The following morning, an investigation team boarded the facility to determine the cause of the fire. The frame top cover at the rear of the compressor was broken in several pieces. The crosshead shoes were found broken and the wiper packing gland was found in pieces. All of the valves were pulled from the cylinders and were in good condition. The first stage cylinder had a small amount of fluid inside the pockets. The piston was broken and cracked in several places. This is an indication the piston came in contact with an incompressible fluid or object.

The compressor was transported to a third party facility and dismantled to determine the cause of the failure. As the investigation began, the rod bearings apparently had spun and melted to the journal. Also, the connection main journal bearing spun in the saddle. These circumstances caused a loss of lubrication that damaged the connecting rod, wrist pin and crosshead. The loss of lubrication created slack on the journal causing a loss of piston clearance in the cylinder. The piston made contact inside the cylinder resulting in broken con-rod bolts.

Damage to the second stage cylinder was a result of the spun bearings causing a loss of oil.

The third stage cylinder had busted valve plates which placed the cylinder into non-pin reversal causing the wrist pin to seize in the crosshead and destroyed the wrist pin bushing.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

It is believed the failure was due to a liquid carry over in the third stage cylinder that broke the valve plates in the crank and discharge valves. The process gas and lubricating oil was ignited by the hot crankshaft and con rod or by sparks generated from the rotating equipment.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

The failed #3 rod bearing stopped the flow of lubrication to the crosshead pin and bushings. Once these bushings failed, the crosshead became overloaded, causing the Babbitt to de-bond.

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

**Compressor**

NATURE OF DAMAGE:

**Fluid in cylinder resulting in fire**

ESTIMATED AMOUNT (TOTAL): **\$800,000**

22. RECOMMENDATIONS TO PREVENT RECURRENCE NARRATIVE:

**The BSEE Lafayette District office makes no recommendations to the Regional Office of Safety Management (OSM).**

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: **NO**

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

**None**

25. DATE OF ONSITE INVESTIGATION:

**18-OCT-2013**

26. ONSITE TEAM MEMBERS:

**Raymand Johnson / Wade Guillotte /  
Gerald Gonzales /**

29. ACCIDENT INVESTIGATION

PANEL FORMED: **NO**

OCS REPORT:

30. DISTRICT SUPERVISOR:

**Elliott S. Smith**

APPROVED

DATE: **06-FEB-2014**