UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

Ĺ.	OCCURRED	For Public Release					
2.	DATE: 03-MAR-2012 TIME: 2130 HOURS OPERATOR: Murphy Exploration & Production Concepted Representative: TELEPHONE:	6	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K				
	CONTRACTOR: Nabors Drilling Inc. REPRESENTATIVE: TELEPHONE:		H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER Flammable Materials				
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6.	OPERATION:				
1.	LEASE: G21790 AREA: GC LATITUDE: 27.62484093 BLOCK: 338 LONGITUDE: -90.44104746		X PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL				
5.	PLATFORM: A-Front Runner RIG NAME: NABORS MODS 200		PIPELINE SEGMENT NO. OTHER				
	ACTIVITY: EXPLORATION (POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) RW/JT (>3 days)	EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL X WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID X OTHER Prod. SI, Comp. BD					
	Other Injury FATALITY	9	. WATER DEPTH: 3330 FT.				
	POLLUTION FIRE	10	. DISTANCE FROM SHORE: 103 MI.				
	LWC HISTORIC BLOWOUT UNDERGROUND SURFACE		. WIND DIRECTION: NNE SPEED: 53 M.P.H.				
	DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12	. CURRENT DIRECTION: SSW SPEED: 1 M.P.H.				
	COLLISION HISTORIC >\$25K <=\$25K	13	. SEA STATE: 10 FT.				

MMS - FORM 2010 PAGE: 1 OF 5

17. INVESTIGATION FINDINGS:

Murphy Exploration & Production Company had a small fire on GC 338 A (Front Runner platform). The fire occurred in the monkey board area of the derrick on the Nabors Mods 200 platform drilling rig. The rig was warm stacked (idle and ready) and the operation of removing the derrick for onshore inspection was shut down due to high winds and poor weather conditions.

During this time of high winds the platform production system had an upset and the gas in the system blew down through the compressor to the flare (which is continually lit to burn off excess gas). The winds at this time were in excess of 45-53 mph and the direction was out of the north/north east which blew the flare's flames toward the rig. The flames ignited the flammable materials in the monkey board area which consisted of coco mats, rope, and an air-line. No personnel were in the derrick at the time of the fire/compressor blow down and no one was injured.

As a result of this incident, Murphy changed the flare nozzle to direct flow away from the derrick. Murphy conducted a radiation study and with the new nozzle in place, danger exists for the flare to be blown back onto the derrick when winds exceed 45 mph. No personnel would be allowed in the derrick with winds at that level.

- 18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:
 - 1) Production Shut-In
 - 2) Compressor Blow-Down
 - 3) Wind Direction
 - 4) Wind Speed
- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
 - 1) Flammable Materials in Derrick
- 20. LIST THE ADDITIONAL INFORMATION:

The Nabors Mods 200 drilling rig was located in the middle of the production platform to the south of the flare boom. The flare boom was located on the north east corner of the facility and was approximately 208 feet away from the rig derrick.

\$200

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

coco mats, rope, and an air line

burned

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The BSEE Houma District makes no recommendations to the Agency.

MMS - FORM 2010 PAGE: 2 OF 5

EV2010R 28-NOV-2012

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: $_{\mbox{\scriptsize NO}}$
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

n/a

25. DATE OF ONSITE INVESTIGATION:

03-MAR-2012

26. ONSITE TEAM MEMBERS:

Jerry Freeman /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Bryan Domangue

APPROVED DATE: 14-AUG-2012

MMS - FORM 2010 PAGE: 3 OF 5 28-NOV-2012

EV2010R

FIRE/EXPLOSION ATTACHMENT

1.	SOURCE OF IGNITION	1: f]	are boom (constant	fl:	me)				
2.	TYPE OF FUEL:	x	GAS						
			OIL						
		Ш	DIESEL						
			CONDENSATE						
			HYDRAULIC						
			OTHER						
3.	FUEL SOURCE: com	press	sor blow down						
4.	4. WERE PRECAUTIONS OR ACTIONS TAKEN TO ISOLATE KNOWN SOURCES OF IGNITION PRIOR TO THE ACCIDENT ? NO								
5.	TYPE OF FIREFIGHTI	ING E	QUIPMENT UTILIZED:		HANDHELD				
					WHEELED UNIT				
					FIXED CHEMICAL				
					FIXED WATER				
					NONE				
				x	OTHER The wind extinguise before equipment				

MMS - FORM 2010 PAGE: 4 OF 5

MMS - FORM 2010 PAGE: 5 OF 5
EV2010R 28-NOV-2012