UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT
GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

For Public Release

1.	OCCURRED	
	DATE:	STRUCTURAL DAMAGE
	06-AUG-2013 TIME: 1925 HOURS	CRANE
		OTHER LIFTING DEVICE
2.	OPERATOR: Energy XXI GOM, LLC	DAMAGED/DISABLED SAFETY SYS.
	REPRESENTATIVE:	INCIDENT >\$25K
	TELEPHONE:	H2S/15MIN./20PPM
	CONTRACTOR:	REQUIRED MUSTER
	REPRESENTATIVE:	A CONTRACTOR OF THE CONTRACTOR
	TELEPHONE:	SHUTDOWN FROM GAS RELEASE
		OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
		☐ PRODUCTION
		DRILLING
4.	LEASE: 00031	WORKOVER
	AREA: GI LATITUDE: 29.101448	COMPLETION
	BLOCK: 22 LONGITUDE: -89.97855	HELICOPTER
		MOTOR VESSEL
5.	PLATFORM: L-CMP-VALVE	PIPELINE SEGMENT NO.
	RIG NAME:	X OTHER Construction
	REG MILL.	
6.	ACTIVITY: EXPLORATION (POE)	8. CAUSE:
	X DEVELOPMENT/PRODUCTION	
	(DOCD/POD)	EQUIPMENT FAILURE
7.	TYPE:	X HUMAN ERROR EXTERNAL DAMAGE
	HISTORIC INJURY	SLIP/TRIP/FALL
		WEATHER RELATED
	x REQUIRED EVACUATION 1	H LEAK REDATED
	LTA (1-3 days)	UPSET H20 TREATING
	LTA (>3 days	OVERBOARD DRILLING FLUID
	RW/JT (1-3 days)	X OTHER Complacency
	X RW/JT (>3 days)	ii campadono,
	Other Injury	9. WATER DEPTH: 55 FT.
	FATALITY	
	POLLUTION	10. DISTANCE FROM SHORE: 8 MI.
	FIRE	
	EXPLOSION	11. WIND DIRECTION: SE
	LWC HISTORIC BLOWOUT	SPEED: 12 M.P.H.
	UNDERGROUND	SEEED. 12 M.F.A.
	SURFACE	
	DEVERTER	12. CURRENT DIRECTION:
	SURFACE EQUIPMENT FAILURE OR PROCEDURES	SPEED: M.P.H.
	COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: FT.

MMS - FORM 2010 PAGE: 1 OF 5

17. INVESTIGATION FINDINGS:

During construction operations, a FABCON Rigger was caught between a muffler and a handrail scaffold when the muffler suddenly rolled as the butterfly valve was being lifted by the crane. The Injured Person (IP) was flown to Terrebone General where he was examined and released after the CAT scan showed only a hairline fracture of his Scapula (shoulder blade).-

The investigation revealed: -

- 1) Employee complacency. -
- 2) Employee was not aware of the surroundings and was not paying attention to the task at hand.
- 3) The employee placed himself in a potential pinch point. -
- 4) There were only two 3/8" bolts holding the muffler stack to the stand instead of the four (4) required.
- 5) There were slip braces in place instead of welding or bolted bracing to support the muffler stack.-
- 6) The Crane used was on a the Liftboat Ram X. Seas or movement possibly contributed to the force excerted on the butterfly valve mounting bolts.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

- 1) Employee complacency. -
- 2) Employee was not aware of the surroundings and was not paying attention to the task-
- at hand.
- 3) The employee placed himself in a potential pinch point. -

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

- 1) There were only two 3/8" bolts holding the muffler stack to the stand instead of the four (4) required.-
- 2) There were slip braces in place instead of welding or bolted bracing to support the muffler stack.
- 3) The Crane used was on a the Liftboat Ram X. Seas or movement possibly contributed to the force excerted on the butterfly valve mounting bolts.

20. LIST THE ADDITIONAL INFORMATION:

- 1) The Liftboat Ram X was located next to GI 22 Compressor Platform. -
- 2) The crane operation was a blind lift utilizing radio communications, signalmen and riggers.
- 3) The FABCON construction crew previously had replaced two similar butterfly valves on two other compressors (#5 and #7) without incident.-
- 4) Liftboats are under U.S. Coast Guard jurisdiction. No crane form submitted. -

MMS - FORM 2010 PAGE: 2 OF 5

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

Scaffold Legs

Bent

ESTIMATED AMOUNT (TOTAL):

Ġ

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The BSEE New Orleans District makes no recommendations to the Agency.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

G-110 (W) removing butterfly valve in an unsafe manner.

25. DATE OF ONSITE INVESTIGATION:

21-AUG-2013

26. ONSITE TEAM MEMBERS:

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

Gerald Taylor / Greg Johnston Jr. /

OCS REPORT:

30. DISTRICT SUPERVISOR:

David Trocquet

APPROVED

DATE: 10-FEB-2014

MMS - FORM 2010 PAGE: 3 OF 5

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER	x INJURY FATALITY WITNESS
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS:	STATE: TOTAL OFFSHORE EXPERIENCE: 0 YE
CITY: ZIP CODE:	STATE:
OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER	INJURY FATALITY WITNESS
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS:	STATE: TOTAL OFFSHORE EXPERIENCE: 3 YE

MMS - FORM 2010 PAGE: 4 OF 5

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE OTHER	INJURY FATALITY WITNESS	
NAME:		
HOME ADDRESS: CITY:	STATE:	
WORK PHONE:	TOTAL OFFSHORE EXPERIENCE:	YEARS
EMPLOYED BY:		
BUSINESS ADDRESS:		
CITY:	STATE:	
ZIP CODE:		

MMS - FORM 2010 PAGE: 5 OF 5