

UNITED STATES DEPARTMENT OF THE INTERIOR -  
BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT -  
GULF OF MEXICO REGION -

ACCIDENT INVESTIGATION REPORT

For Public Release

1. OCCURRED

DATE: 30-AUG-2014 TIME: 2020 HOURS

2. OPERATOR: Chevron U.S.A. Inc.

REPRESENTATIVE:

TELEPHONE:

CONTRACTOR: Transocean Offshore -

REPRESENTATIVE:

TELEPHONE:

- STRUCTURAL DAMAGE
- CRANE
- OTHER LIFTING DEVICE
- DAMAGED/DISABLED SAFETY SYS.
- INCIDENT >\$25K
- H2S/15MIN./20PPM
- REQUIRED MUSTER
- SHUTDOWN FROM GAS RELEASE
- OTHER

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR  
ON SITE AT TIME OF INCIDENT:

6. OPERATION:

4. LEASE: G25814

AREA: KC LATITUDE: 26.16579874 -  
BLOCK: 829 LONGITUDE: -92.12390483 -

- PRODUCTION
- DRILLING
- WORKOVER
- COMPLETION
- HELICOPTER
- MOTOR VESSEL
- PIPELINE SEGMENT NO.
- OTHER

5. PLATFORM:

RIG NAME: T.O. DISCOVERER CLEAR LEADER

6. ACTIVITY:

- EXPLORATION (POE)
- DEVELOPMENT/PRODUCTION  
(DOCD/POD)

8. CAUSE:

- EQUIPMENT FAILURE
- HUMAN ERROR
- EXTERNAL DAMAGE -  
SLIP/TRIP/FALL
- WEATHER RELATED
- LEAK
- UPSET H2O TREATING
- OVERBOARD DRILLING FLUID
- OTHER \_\_\_\_\_

7. TYPE:

- HISTORIC INJURY -
  - REQUIRED EVACUATION
  - LTA (1-3 days)
  - LTA (>3 days)
  - RW/JT (1-3 days)
  - RW/JT (>3 days)
  - Other Injury -

- FATALITY
- POLLUTION
- FIRE
- EXPLOSION

- LWC -
- HISTORIC BLOWOUT
  - UNDERGROUND
  - SURFACE
  - DEVERTER
  - SURFACE EQUIPMENT FAILURE OR PROCEDURES

9. WATER DEPTH: 6433 FT.

10. DISTANCE FROM SHORE: 192 MI.

11. WIND DIRECTION: SE -  
SPEED: 9 M.P.H.

12. CURRENT DIRECTION: NE  
SPEED: 2 M.P.H.

13. SEA STATE: 3 FT.

COLLISION  HISTORIC  >\$25K  <=\$25K

At 20:20 hours on 30 August 2014, the Transocean Discoverer Clear Leader (DCL) drill ship under contract to Chevron U.S.A. Inc. (Chevron) was conducting drilling operations at Keathley Canyon Block 829 when the Transocean Driller observed a loss of synthetic base mud (SBM) in the Trip Tank from a telescopic slip joint (TSJ) packer failure. At 20:35 hours, Transocean personnel stopped the SBM discharge by manually pressurizing the TSJ lower packer. Chevron estimated that 12 barrels of 14.5 pounds per gallon (ppg) SBM (6.12 gal Synthetic Oil) was spilled from the failed TSJ upper packer into the Gulf of Mexico but was restricted to the moon pool area. Chevron notified the National Response Center (Incident Report #1093959) about the SBM spill incident.

Transocean's investigation findings revealed that a leaking stainless steel Joint Industry Council (JIC) connection for the air hose located at the bottom of the J-plate caused the TSJ upper packer to loose pressure thus allowing the SBM to be discharged in the Gulf of Mexico. In addition, a similar leak was found on secondary packer system that inhibited the automatic engagement of the TSJ lower packer.

Transocean's investigation determined that there were three contributing factors to the SBM spill as follows: 1) the air hoses to the JIC connections on the J-Plate were not properly supported; therefore the weight of the hoses put stress on the JIC connections; 2) the DCL had been experiencing currents from 2 to 3 knots for two weeks prior to the spill and it was speculated that this caused the hoses to vibrate that resulted in the upper and lower TSJ packer connections to loosen; and 3) the hose bundle was submerged below the water line and wave action had transmitted through the hoses to hanging manifold.

## 18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Transocean's investigation findings revealed that a leaking stainless steel Joint Industry Council (JIC) connection for the air hose located at the bottom of the J-plate caused the TSJ upper packer to loose pressure thus allowing the SBM to be discharged in the Gulf of Mexico. In addition, a similar leak was found on secondary packer system that inhibited the automatic engagement of the TSJ lower packer.

## 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Transocean's investigation determined that there were three contributing factors to the SBM spill as follows: 1) the air hoses to the JIC connections on the J-Plate were not properly supported; therefore the weight of the hoses put stress on the JIC connections; 2) the DCL had been experiencing currents from 2 to 3 knots for two weeks prior to the spill and it was speculated that this caused the hoses to vibrate that resulted in the upper and lower TSJ packer connections to loosen; and 3) the hose bundle was submerged below the water line and wave action had transmitted through the hoses to hanging manifold.

## 20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

**For Public Release**

No property was damaged nor did any equipment require replacement. The TSJ upper packer leak was fixed by taking the load off the lines and tighten up the JIC connections. None.

ESTIMATED AMOUNT (TOTAL): \$

22. RECOMMENDATIONS TO PREVENT RECURRENCE NARRATIVE:

**The BSEE Lafayette District makes no recommendations to the Office of Safety Management Regional Office.**

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: **NO**

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

**24-SEP-2014**

26. ONSITE TEAM MEMBERS:

**Johnny Serrette / Troy Naquin /**

29. ACCIDENT INVESTIGATION

PANEL FORMED: **NO**

OCS REPORT:

30. DISTRICT SUPERVISOR:

**Elliott S. Smith**

APPROVED

DATE: **09-OCT-2014**