UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

<u>.</u>		For Public Release
1.	OCCURRED	
	DATE: 13-SEP-2012 TIME: 0430 HOURS	STRUCTURAL DAMAGE
		CRANE OTHER LIFTING DEVICE
2.	OPERATOR: Chevron U.S.A. Inc.	DAMAGED/DISABLED SAFETY SYS.
	REPRESENTATIVE:	INCIDENT >\$25K
	TELEPHONE:	H2S/15MIN./20PPM
	CONTRACTOR:	REQUIRED MUSTER
	REPRESENTATIVE:	SHUTDOWN FROM GAS RELEASE
	TELEPHONE:	X OTHER Foot Injury
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
		PRODUCTION
2		DRILLING
4.	LEASE: G01316 AREA: MP LATITUDE: 29.252824	X WORKOVER
	AREA: MP LATITUDE: 29.252824 BLOCK: 299 LONGITUDE: -88.75746	COMPLETION
	BLOCK: 299 HONGITODE00.75740	HELICOPTER MOTOR VESSEL
5.	PLATFORM: D	PIPELINE SEGMENT NO.
	RIG NAME:	OTHER
		8. CAUSE:
6.	ACTIVITY: EXPLORATION (POE) X DEVELOPMENT/PRODUCTION	o. CAUSE:
	(DOCD/POD)	EQUIPMENT FAILURE
7.	TYPE:	X HUMAN ERROR EXTERNAL DAMAGE
	HISTORIC INJURY	SLIP/TRIP/FALL
	X REQUIRED EVACUATION 1	WEATHER RELATED
	LTA (1-3 days)	LEAK
	LTA (>3 days	UPSET H20 TREATING OVERBOARD DRILLING FLUID
	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	OTHER
	X RW/JT (>3 days) 1 Other Injury	
	T FATALITY	9. WATER DEPTH: 210 FT.
	POLLUTION	10. DISTANCE FROM SHORE: 30 MI.
	FIRE	IU. DISTANCE FROM SHORE. 50 MI.
	EXPLOSION	11. WIND DIRECTION: E
	LWC HISTORIC BLOWOUT	SPEED: M.P.H.
	UNDERGROUND	
	SURFACE	12. CURRENT DIRECTION: E
	DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	SPEED: 23 M.P.H.
	COLLISION HISTORIC >\$25K <- \$25K	13. SEA STATE: FT.

MMS - FORM 2010

17. INVESTIGATION FINDINGS:

On 13 Sep 2012, a worker employed by Coil Tubing Services (CTS) received a minor injury to his foot. At the time of the incident, the CTS crew was in the process of installing a check-valve in the chiksan line. The Injured Person (IP) was standing astride a section of chiksan holding it off the deck while another CTS worker removed a swivel joint. As the CTS worker unscrewed the swivel, water trapped in the line leaked onto the chiksan and the IP's gloves, therefore, creating the slippery conditions that resulted in the IP dropping the chiksan on his left foot behind the steel toe cap of his boot. Lubricators on deck next to chiksan created a very tight working area. The CTS supervisor stated that the workers were unable to use the backsaver because it was too close to the handrail and the pump. The IP was evacuated for medical attention; x-rays revealed no broken bones. The IP was diagnosed with a bruised foot and was released to full duty.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Slippery gloves and standing in an awkward position.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Lubricators on deck next to chiksan created a very tight working area. The CTS supervisor stated that the workers were unable to use the back-saver because it was too close to the handrail and the pump.

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None

ESTIMATED AMOUNT (TOTAL):

\$

None

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The BSEE New Orleans District makes no recommendations to the Agency.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

14-SEP-2012

26. ONSITE TEAM MEMBERS: Earl Roy / 29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

David J. Trocquet

APPROVED DATE: 07-MAY-2013

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE X CONTRACTOR REPRESENTATIVE OTHER	X INJURY FATALITY WITNESS	
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY:	STATE: TOTAL OFFSHORE EXPERIENCE:	YEA
BUSINESS ADDRESS: CITY: ZIP CODE:	STATE:	
 OPERATOR REPRESENTATIVE X CONTRACTOR REPRESENTATIVE OTHER 	INJURY FATALITY X WITNESS	
X CONTRACTOR REPRESENTATIVE	FATALITY	YEA

MMS - FORM 2010 EV2010R