

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT
GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

For Public Release

1. OCCURRED

DATE: 01-NOV-2012 TIME: 2135 HOURS

2. OPERATOR: Apache Corporation

REPRESENTATIVE:

TELEPHONE:

CONTRACTOR: Hercules Offshore Drilling

REPRESENTATIVE:

TELEPHONE:

- STRUCTURAL DAMAGE
- CRANE
- OTHER LIFTING DEVICE
- DAMAGED/DISABLED SAFETY SYS.
- INCIDENT >\$25K
- H2S/15MIN./20PPM
- REQUIRED MUSTER
- SHUTDOWN FROM GAS RELEASE
- OTHER Back Reaming Injury

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR
ON SITE AT TIME OF INCIDENT:

6. OPERATION:

4. LEASE: G01201

AREA: SM LATITUDE:

BLOCK: 69 LONGITUDE:

- PRODUCTION
- DRILLING
- WORKOVER
- COMPLETION
- HELICOPTER
- MOTOR VESSEL
- PIPELINE SEGMENT NO.
- OTHER

5. PLATFORM:

RIG NAME: HERCULES 264

6. ACTIVITY:

- EXPLORATION (POE)
- DEVELOPMENT/PRODUCTION (DOCD/POD)

8. CAUSE:

- EQUIPMENT FAILURE
- HUMAN ERROR
- EXTERNAL DAMAGE
- SLIP/TRIP/FALL
- WEATHER RELATED
- LEAK
- UPSET H2O TREATING
- OVERBOARD DRILLING FLUID
- OTHER

7. TYPE:

HISTORIC INJURY

- REQUIRED EVACUATION 1
- LTA (1-3 days)
- LTA (>3 days) 1
- RW/JT (1-3 days)
- RW/JT (>3 days)
- Other Injury

9. WATER DEPTH: 125 FT.

- FATALITY
- POLLUTION
- FIRE
- EXPLOSION

10. DISTANCE FROM SHORE: 45 MI.

- LWC
- HISTORIC BLOWOUT
 - UNDERGROUND
 - SURFACE
 - DEVERTER
 - SURFACE EQUIPMENT FAILURE OR PROCEDURES

11. WIND DIRECTION: S
SPEED: 8 M.P.H.

12. CURRENT DIRECTION: SW
SPEED: 5 M.P.H.

COLLISION HISTORIC >\$25K <=\$25K

13. SEA STATE: 2 FT.

17. INVESTIGATION FINDINGS:

At approximately 21:30 hours on 01 November 2012, an accident occurred during drilling operations on the Hercules Offshore (Hercules) Rig 264 under contract to Apache Corporation (Apache). The Hercules 264 was situated at the surface location of South Marsh Island (SMI) Block 69; but drilling in subsurface location of SMI Block 58. The accident happened while breaking pipe connections during back reaming operations when a Hercules Floorhand operating the tongs was thrown approximately 8 feet across the rig floor striking the starboard air hoist. The Injured Person (IP) suffered a head laceration, skin abrasions and bruising to the back of his legs. The IP received first-aid care at the rig, but was evacuated for additional medical treatment to Our Lady of Lourdes Hospital located in Lafayette, Louisiana. The IP's head laceration was treated by closing up with surgical staples and he was released from the hospital on 02 November 2012.

Apache and Hercules determined that the primary cause of this incident was slippage of top drive dies that caused the compensator to pick up, turn the stand in the opposite direction with the tongs and throwing the Floorhand approximately 8 feet into the starboard air hoist where he sustained the injuries.

An internal investigation conducted by Hercules identified the following contributing causes: 1) the Driller had assumed that the pipe connection had broken, 2) the Floorhand was unable to see if the saver sub had broken, and 3) the motion compensator picking up the stand prematurely due to reduced weight, spinning the pipe stand two full revolutions, snagging the Floorhand's legs in the snub line, and throwing him approximately 8 feet into the starboard air hoist.

A Job Safety Analysis (JSA) was completed; however, it did not include all job tasks for back reaming nor did it specifically address hazards that may occur if the top drive dies slipped when breaking a pipe connection. Hercules had no written maintenance program in place for inspecting, maintaining, or replacing the top drive dies; however, Hercules had a policy that required the top drive dies to be inspected once per tour. It should be noted that there are no industry standards in place governing top drive die inspection and maintenance.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Apache and Hercules determined that the primary cause of this incident was slippage of top drive dies that caused the compensator to pick up, turn the stand in the opposite direction with the tongs and throwing the Floorhand approximately 8 feet into the starboard air hoist where he sustained the injuries.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

An internal investigation conducted by Hercules identified the following contributing causes: 1) the Driller had assumed that the pipe connection had broken, 2) the Floorhand was unable to see if the saver sub had broken, and 3) the motion compensator picking up the stand prematurely due to reduced weight, spinning the pipe stand two full revolutions, snagging the Floorhand's legs in the snub line, and throwing him approximately 8 feet into the starboard air hoist.

A JSA was completed; however, it did not include all job tasks for back reaming nor did it specifically address hazards that may occur if the top drive dies slipped when breaking a connection. Hercules had no written maintenance program for inspecting, maintaining, or replacing the top drive dies; however, they had a policy that required the top drive dies to be inspected once per tour. It should be noted that currently there are no industry standards for top drive die inspection and maintenance.

20. LIST THE ADDITIONAL INFORMATION:

CORRECTIVE ACTIONS:

The JSA will be revised to address all critical job tasks and identify hazards when conducting back reaming operations. Hercules will implement a maintenance program for inspecting the top drive dies more frequently instead of once per tour. The Driller will visually verify that the saver sub has broken before attempting to back out with the top drive. The Driller will also monitor the weight of the top drive to prevent the compensator from prematurely picking up the stand before the saver sub is broken.

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

No property was damaged during this accident.

None

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The BSEE Lafayette District makes no recommendations for the Agency.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: **NO**

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

02-NOV-2012

26. ONSITE TEAM MEMBERS:

**Jeremy Adams / Ernest Carmouche /
Troy Naquin /**

29. ACCIDENT INVESTIGATION

PANEL FORMED: **NO**

OCS REPORT:

30. DISTRICT SUPERVISOR:

Marty Rinaudo

YES

APPROVED
DATE:

28-DEC-2012

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE

CONTRACTOR REPRESENTATIVE

OTHER _____

INJURY

FATALITY

WITNESS

NAME :

HOME ADDRESS :

CITY :

STATE :

WORK PHONE :

TOTAL OFFSHORE EXPERIENCE :

YEARS

EMPLOYED BY :

BUSINESS ADDRESS :

CITY :

STATE :

ZIP CODE :

OPERATOR REPRESENTATIVE

CONTRACTOR REPRESENTATIVE

OTHER Third Party Contractor

INJURY

FATALITY

WITNESS

NAME :

HOME ADDRESS :

CITY :

STATE :

WORK PHONE :

TOTAL OFFSHORE EXPERIENCE :

YEARS

EMPLOYED BY :

BUSINESS ADDRESS :

CITY :

STATE :

ZIP CODE :

INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE

INJURY

CONTRACTOR REPRESENTATIVE

FATALITY

OTHER _____

WITNESS

NAME :

HOME ADDRESS :

CITY :

STATE :

WORK PHONE :

TOTAL OFFSHORE EXPERIENCE :

YEARS

EMPLOYED BY :

BUSINESS ADDRESS :

CITY :

STATE :

ZIP CODE :

