



# Instrumentation Failure and Embankment Breach Taum Sauk, Missouri

## FERC Pumped Storage Workshop

## FERC Response to the Taum Sauk Embankment Breach



**Daniel J. Mahoney, Deputy Director  
Division of Dam Safety and Inspections**



# Immediate Response

---

---

## FERC Pumped Storage Workshop

- Dispatched FERC Team to the Site
- Focused on Insuring Site Stabilization
- Safety Check on Lower Dam
- Initial Information Collection





# FERC Pumped Storage Workshop



## FERC Action Plan

- Require 12.10 Report – Conditions Affecting the Safety of the Project
- Formed FERC Investigation Team
- Convened an Independent Panel of Consultants
- Coordination with State Dam Safety and Resource Agencies
- Compliance with Project License
- Issue Report with Conclusions



# Independent Panel of Consultants

---

---

## **FERC** **Pumped** **Storage** **Workshop**

- Dr. Alfred J. Hendron, Jr.
- Joseph L. Ehasz
- Kermit Paul





# FERC Pumped Storage Workshop

## Independent Panel of Consultants

---

- Investigation Independent of FERC Team
- Numerous Information and Data Requests
- Site Visits and Interviews with Ameren and FERC Managers and Staff





# FERC Pumped Storage Workshop

## Results of Investigation

---

- 12.10 Report – Rizzo Report
- FERC Investigation Team Report
- IPOC Report
- Information and Conclusions Consistent





# **FERC Pumped Storage Workshop**

## **Project Description**


---

- 100-Foot High Concrete Faced Rock Fill Embankment
- 10-Foot High Parapet Wall
- Operation – 2-Foot of Freeboard





# FERC Pumped Storage Workshop



## Cross Section from Original Design Drawings








# Long Term Settlement of CFRF Dam

## FERC Pumped Storage Workshop



Total History  
Taum Sauk Pin Elevations





**FERC**  
**Pumped**  
**Storage**  
**Workshop**

## Conclusions of IPOC Report

---

- Adopted by FERC
- Primary Cause of Breach
- Primary Root Causes of Breach
- Secondary Root Causes of Breach





# Conclusions of IPOC Report

---

**FERC**  
**Pumped**  
**Storage**  
**Workshop**

**Primary Cause of Breach was**  
**Overtopping of the Parapet Wall**  
**and Embankment**





# Conclusions of IPOC Report

---

## **FERC Pumped Storage Workshop**

**Primary Root Causes of Breach  
Were Those Factors Which  
Caused Overtopping to Occur**

**These were:**





# Conclusions of IPOC Report

## Primary Root Causes of Breach Which Caused Overtopping to Occur

### FERC Pumped Storage Workshop

- The Pressure Transducers that Monitored Reservoir Water Levels Became Unattached From Their Supports Causing Erroneous Water Level Readings





# FERC Pumped Storage Workshop



DEC 15 2005



**FERC  
Pumped  
Storage  
Workshop**

# Conclusions of IPOC Report


## Primary Root Causes of Breach Which Caused Overtopping to Occur

- The Emergency Backup Level Probes Were Set at an Elevation above the Lowest Points Along the Parapet Wall; Thus, They Failed Their Protection Role Because This Enabled Overtopping to Occur Before the Probes Could Trigger Shutdown





# FERC Pumped Storage Workshop



1596.90

1596.75





# FERC Pumped Storage Workshop



Upper Ends of Protective Pipes With Instrument Cables in Enclosure on Parapet

Pressure Transducers Use Left Pipe and Conductivity Probes Use the Second Pipe From Left





# FERC Pumped Storage Workshop



## Conclusions of IPOC Report

### Primary Root Causes of Breach Which Caused Overtopping to Occur

- The Normal Operating High Water Levels of 1 foot Below the Top of the Parapet Wall Was Too Near the Top of the Wall to Allow for any Mistakes of Mis-Operation
- Visual Monitoring of the Upper Reservoir Water was Almost Non-Existent and There was no Systematic “Ground-Proofing” Recorded of the Relationship of the Top of the Wall and Associated Water Levels Actually Being Achieved
- There Was no Overflow Spillway to Safely Carry Accidental Over-Pumped Water Downstream and Below the Dam



# Conclusions of IPOC Report

## Secondary Root Causes

---

### **FERC Pumped Storage Workshop**

Those Factors Which  
Combined to Make This  
Embankment More Vulnerable  
to Failure by Overtopping:





# Conclusions of IPOC Report

## Secondary Root Causes

### FERC Pumped Storage Workshop

The Marginally Stable Dumped “Dirty” Rockfill Constituted An Unforgiving Containment Structure.

It Could Not Tolerate the Additional Pore Pressures and Erosive Effects of the Overtopping Water Plunging Over the Top of the Parapet Wall onto the Narrow Dam Crest and Cascading Down the Steep 1.3:1 Slope







# FERC Pumped Storage Workshop





# FERC Pumped Storage Workshop



Taum Sauk U.R.

## Trends in Type and Height of Rockfill Dams





# **FERC Pumped Storage Workshop**

To View FERC's Incident Description,  
Project Description, Action Plan, Reports  
and Photo Gallery Visit This Link:

<http://www.ferc.gov/industries/hydropower/safety/projects/taum-sauk.asp>





# FERC Pumped Storage Workshop

- Ameren's Dam Safety Program  
Tom Hollenkamp

