| A B C C ORP (Ship per) | Offered sodium hydrosulfite in packages not marked with a proper shipping name; failed to indicate quantity on shipping paper; offered HM in an unauthorized packaging; failed to provide hazard class on the shipping paper; failed to provide shipper's certification. [172.301(a), 172.202(c), 173.204(a), 172.202(a)(1), 172.202(a)(2), 172.204(d)(1), 173.217(a)] Case No. 93-64-SP-WE | \$9,465 |
|--|---|----------|
| A-1 FIRE EQUIPMENT CO INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 94-244-CR-SW | \$4,240 |
| ABCO FIRE PROTECTION INC (Cylinder Retester) | Certified cylinders with equipment not calibrated to 1% accuracy; failed to maintain accurate records; marked cylinders with illegible month and year markings. [173.34(e)(3), 173.34(e)(5), 173.34(e)(6)] Case No. 94-262-CR-CE | \$7,600 |
| ACCURATE BOX CARTON & CONTAINER CORP (Fiberboard Box Manufacturer) | Certified boxes as UN 4G without conducting design qualification tests; failed to properly mark boxes with name and address or registered symbol. [178.601(d), 178.503(a)(7)] Case No. 95-08-BM-WE | \$11,400 |
| ACME BARREL CO INC (Drum Reconditioner) | Certified drums as DOT 17H without conducting periodic drop and hydrostatic tests; failed to mark open-head steel drums as required. [178.118-12(a), 173.28(o)(1)(ii), 173.28(m)(3)(iii)] Case No. 94-19-DR-CE | \$4,700 |
| ADVANCE PACKAGING CORP (Package Certifier) | Certified packagings as UN standard without including the name and address or registered symbol of the approval agency; failed to include required information in the certification marking; failed to keep complete records of design qualification tests. [178.503(a)(8), 178.502(a)(2), 178.516(a), 178.601(k)(1)] Case No. 94-95-PC-CE | \$4,000 |
| AEROJET-GENERAL CORP (Shipper) | Offered Class 1.3 and 1.4 explosives for transportation in exemption packagings after the exemption had expired. [173.62(a), 173.62(b), 173.151] Case No. 94-111-EXR | \$2,610 |
| ALBANY WELDING SUPPLY CO INC (Cylinder Retester) | Filled specification cylinders and offered them for transportation when they were not retested within a five-year period. [173.34(a)(1)] Case No. 95-28-EXR | \$1,500 |
| ALL CHEMICAL CORP (Shipper) | Offered an oxidizer in a packaging not properly certified. [173.212(a)] Case No. 94-193-SP-CE | \$3,250 |
| ALL FIRE EQUIPMENT INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records. [173.34(e)(3), 173.34(e)(5)] Case No. 93-87-CR-CE | \$4,200 |

| ALL FIRE TEST CO INC (Cylinder Retester) | Failed to perform a complete external visual examination. [173.34(e)(1)] Case No. 93-109-CR-CE | \$1,750 |
|--|---|---------|
| ALLIED HASTINGS BARREL & DRUM (Drum Reconditioner) | Failed to properly mark reconditioned drums. [173.28(o)(1)(iii)] Case No. 94-28-DR-CE | \$400 |
| ALOHA FREIGHT FORWARDERS (Shipper) | Offered oxidizing substances, solid, n.o.s. in nonspecification packaging. [173.154(a)] Case No. 94-75-FF-WE | \$2,800 |
| AMERICHEM CORP (Shipper) | Offered flam mable liquid for transportation in DOT 57 portable tanks which had not been retested as required; failed to list a correct emergency response telephone number on shipping papers. [173.32(e)(2)-(4), 173.125(a)(1), 172.201(d), 172.604(b)] Case No. 93-246-SPT-CE | \$6,590 |
| ARCADIAN CORP (Shipper) | Offered HM for transportation in exemption packaging after the exemption had expired. [173.154(a)(17), 173.243] Case No. 94-43-EXR | \$1,950 |
| ASE INDUSTRIES (Cylinder Retester) | Failed to remark exemption aluminum cylinders as specification 3AL; failed to perform a complete visual external examination; failed to maintain accurate records of visual reinspection and retest. [173.23(c), 173.34(e)(1), 173.34(e)(5)] Case No. 95-18-CR-SW | \$4,960 |
| ATLANTIC COAST FIRE EQUIPMENT (Cylinder Retester) | Certified cylinders without performing a complete visual examination; failed to maintain accurate records. [173.34(e)(1), 173.34(e)(5)] Case No. 95-79-CR-HQ | \$4,120 |
| ATLANTIC FIRE EQUIPMENT COMPANY INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-234-CR-EA | \$3,600 |
| ATOMIC FIREWORKS INC OF TENNESSEE (Shipper) | Offered an unapproved explosive device for transportation. [173.54(a)] Case No. 94-66-SE-HQ | \$4,000 |
| AURORA TRI-STATE FIRE PROTECTION (Cylinder Retester) | Failed to condemn a cylinder when permanent expansion exceeded 10%; failed to remark exemption aluminum cylinders as specification 3AL; conducted hydrostatic testing without calibrating test equipment. [171.2(c), 173.34(e)(4), 173.23(c), 173.34(e)(3)] Case No. 94-250-CR-CE | \$6,075 |

| AUTOMATIC FIRE SYSTEMS (Cylinder Retester) | Marked cylinders as meeting the requirements of the HMR without performing the hydrostatic test; failed to conduct a visual examination; failed to condemn a cylinder when permanent expansion exceeded 10%; failed to maintain accurate records; failed to remark an exemption aluminum cylinder as specification 3AL; failed to calculate wall stress before applying the plus mark. [173.34(e)(1), 173.34(e)(4), 173.34(e)(5), 173.23(c), 173.302(c)(3)] Case No. 93-200-CR-EA | \$12,295 |
|--|---|----------|
| B O C IN C (Shipper) | Filled and offered non-liquefied compressed gas without maintaining daily records of pressure verification; failed to provide a proper shipping paper. [173.302(e), 172.202(a)] Case No. 95-149-SC-SW | \$5,345 |
| B-LANN EQUIPMENT COMPANY INC (Cylinder Retester) | Performed hydrostatic testing with inaccurate equipment; conducted a 2nd retest at the same pressure instead of 10% or 100 psi higher, failed to remark exemption aluminum cylinders as 3AL; failed to maintain accurate records; failed to condemn cylinders made to DOT- E7235 when permanent expansion exceeded 5% of total expansion. [173.34(e)(3), 173.23(c), 173.34(e)(5), DOT-E 7235] Case No. 93-43-CR-EA | \$9,385 |
| BADGER WELDING SUPPLIES INC (Cylinder Retester) | Certified cylinders as meeting the requirements of the HMR with equipment not calibrated to an accuracy of 1%; failed to calculate wall stress when marking a cylinder with the "+" sign; failed to maintain accurate records. [173.34(e)(3), 173.302(c)(3), 173.34(e)(5)] Case No. 93-264-CR-CE | \$7,500 |
| BALAZS ANALYTICAL LABORATORY (Shipper) | Offered hydrofluoric acid for transportation in nonspecification packaging; failed to mark packaging containing hydrofluoric acid with a proper shipping name. [173.264(a), 172.301(a)] Case No. 93-53-SB-WE | \$1,900 |
| BARRY WAYNE MACEY (Cylinder Retester) | Certified and marked cylinders as retested without performing retesting; failed to hold a current approval or a retester's identification number (RIN). [173.34(e)(1)(ii), 173.34(e)(1)(i)] Case No. 92-46-CR-HQ | \$7,200 |
| BAXTER DIAGNOSTICS INC (Shipper) | Offered methanol in unauthorized nonspecification packaging. [173.119(b)] Case No. 94-90-SB-SW | \$3,240 |
| BAXTER HEALTH CARE (Fiberboard Box Manufacturer/Shipper) | Certified fiberboard boxes as UN standard 4G without performing design qualification tests and maintaining records of tests; failed to mark UN 4G boxes with the correct year of manufacture. [178.601(d), 178.503(a)(6)] Case No. 94-234-BMS-CE | \$9,240 |

| BAY CORRUGATED CONTAINER INC (Fiberboard Box Manufacturer) | Certified fiberboard boxes as DOT-12B40 that were constructed with fiberboard of insufficient strength and had inner flaps that failed to butt; failed to mark boxes with the name and address or registered symbol of manufacturer. [178.205-14(a), 178.205-18(a)] Case No. 95-02-BM-CE | \$7,000 |
|--|--|----------|
| BEASLEY FIRE EXTINGUISHER SERVICE (Cylinder Retester) | Failed to hold a current approval or R IN; failed to maintain adequate records of reinspection and retest. [173.34(e)(1)(i), 173.34(e)(5)] Case No. 93-164-CR-HQ | \$3,600 |
| BEAUMONT FIRE EXTINGUISHER SERVICE (Cylinder Retester) | Certified cylinders with equipment not calibrated to 1% accuracy. [173.34(e)(3)] Case No. 94-187-CR-SW | \$3,650 |
| BELL CONTAINER CORP (Fiberboard Box Manufacturer) | Certified fiberboard boxes as DOT 12B65 that were not constructed with fiberboard of sufficient strength. [178.205-16(a)] Case No. 95-119-BM-CE | \$4,600 |
| BELL PACKAGING CORP (Fiberboard Box Manufacturer) | Certified fiberboard boxes as DOT12B65 when inner flaps did not meet and fill-in-pieces or pads were not included; failed to use fiberboard of sufficient strength. [178.205-16(a)] Case No. 94-261-BM-CE | \$4,960 |
| BELL PACKAGING CORP (Fiberboard Box Manufacturer) | Certified fiberboard boxes as DOT-12B65 after 9/30/94 that were constructed with fiberboard that did not meet minimum test strength. [171.14(b)(5)(ii)] Case No. 95-106-BM-CE | \$7,190 |
| BENNETT INDU STRIES (Plastic Drum Manufacturer) | Certified plastic drums as UN1H1 without performing and keeping records for periodic drop, leakproofness, and hydrostatic tests; failed to mark year of manufacture in proper sequence; failed to conduct HM training. [178.601(e), 178.503(a), 172.704(d)] Case No. 94-260-PDM-CE | \$10,820 |
| BERGEN BARRELL AND DRUM COMPANY (Plastic Drum Manufacturer) | Certified packagings as UN standard without marking name and address or registered symbol; failed to include required information in the certification marking; failed to mark proper country of manufacture on packaging; failed to keep test records. [178.503(a)(8), 178.502(a)(2)] Case No. 94-95-PC-CE | \$18,163 |
| BEXAR FIRE & SAFETY EQUIPMENT COMPANY INC (Cylinder Retester) | Certified cylinders with equipment not calibrated to 1% accuracy; failed to increase test pressure by 10% or 100 psi on 2nd test; failed to maintain a ccurate records of reinspection and retest. [[173.34(e)(3), 173.34(e)(5)] Case No.94-184-CR-SW | \$9,600 |

| BIG THREE LINCOLN ALASKA INC (Cylinder Retester) | Conducted hydro static testing with inaccurate equipment; failed to determine average minimum wall stress before marking cylinders with a '+'; failed to hold test pressure for at least 30 seconds; failed to use low stress stamps when marking DOT 3HT cylinders; failed to mark cylinders with the proper size markings; failed to check pressure after cool down of cylinders; failed to maintain records. [173.34(e)(3), 173.302(c)(3), 173.34(e)(3), 173.34(e)(13)(iv), 173.34(e)(6), 173.303(d)] Case No. 91-74-CR | \$5,750 |
|---|--|---------|
| BIO-LAB INC (Shipper) | Offered oxidizing substances, solid, N.O.S. for transportation in unauthorized nonspecification packaging. [173.154(a), 173.212(a)] Case No. 94-76-SB-WE | \$5,805 |
| BIRKO CORP (Shipper) | Offered oxidizing substances, solid, in unauthorized packaging. [173.22(a)(2)] Case No. 94-171-SP-CE | \$3,600 |
| BLACKHAWK GASES & SUPPLY COMPANY INC (Cylinder Retester) | Certified cylinders with equipment not calibrated to an accuracy of 1%; failed to increase test pressure by 100 psi or 10% for 2nd test; failed to maintain adequate records. [173.34(e)(3), 173.34(e)(5)] Case no. 93-269-CR-CE | \$6,460 |
| BONAR PACKAGING INC (Plastic Bag Manufacturer) | Certified plastic film bags as UN 5H4 without maintaining design qualification and periodic test records. [178.601(k)] Case No. 94-157-BGM-SW | \$4,100 |
| BOWMAN MELL AND CO INC (Shipper) | Offered paint, flammable liquid for transportation in nonspecification packaging and unauthorized DOT packaging. [173.128(a)] Case No. 92-144-SPB-EA | \$3,360 |
| BOXES INC (Fiberboard Box Manufacturer) | Certified DOT-12B specification boxes after 10/01/94; failed to provide hazmat employee training. [171.14(b)(5), 172.702(a), 172.702(b)] Case No. 95-85-BM-CE | \$5,400 |
| BRANDYWINE VALLEY FIRE & SAFETY (Cylinder Retester) | Failed to have an approval or a current RIN; performed retesting with inaccurate equipment; failed to remark aluminum exemption cylinders with DOT 3AL; failed to maintain adequate records of reinspection and retest. [173.34(e)(1)(i), 173.34(e)(3), 173.23(c), 173.34(e)(5)] Case No. 93-142-CR-EA | \$8,175 |
| BRUIN ENGINEERED PARTS INC (Foreign Cylinder Manufacturer) | Manufactured, marked, and sold DOT 39 cylinders without completing the inspection process. [178.65-3(b), 173.300b] Case No. 90-90-FCM | \$9,396 |
| BRULIN & CO INC (Shipper) | Offered corrosive liquid in nonspecification packaging; offered compound cleaning liquid in nonspecification packaging; failed to properly mark corrosive material with a proper shipping name. [173.245(a), 173.263(a), 173.301(a)] Case No. 93-99-SPB-CE | \$6,760 |

| BURRIS CHEMICAL INC (Shipper) | Offered DOT specification 57 portable tanks without marking the most recent test date; offered HM in unauthorized nonspecification packaging. [173.32(e)(3), 173.163(a), 173.212] Case No. 94-55-SPT-HQ | \$5,228 |
|---|--|----------|
| BWI/IP INTERNATIONAL INC (Cylinder Manufacturer) | Represented and sold DOT-E 10757 exemption cylinders as meeting the requirements of the exemption without performing hydrostatic testing; failed to have testing verified by an approved independent inspection agency; failed to include the exemption number in the shipping description on shipping papers. [178.2(b), 178.65-3(b), 173.203(a)] Case No. 93-168-CM-HQ | \$6,820 |
| CAJUN BAG & SUPPLY CO (Bag Manufacturer) | Represented, marked, and sold exemption bulk bags which were not capable of withstanding a four-foot drop test. [DOT-E 9144, Para. 7] Case No. 93-226-EX-CE | \$4,120 |
| CALGENE CHEMICAL INC (Shipper) | Offered HM for transportation without being registered under RSPA's registration program. [107.608(a)] Case No. 95-70-REG-CE | \$250 |
| CANBERRA CORP (Shipper) | Offering hydrochloric acid, solution, in nonspecification packaging. [173.263(a)] Case No. 93-98-SB-CE | \$3,240 |
| CAPITAL CITY FIRE EXTINGUISHER SERVICE CO (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; exceeded 90% of test pressure prior to performing hydrostatic testing; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(3), 173.34(e)(5)] Case No. 93-57-CR-CE | \$5,100 |
| CAPWELD INC (Cylinder Retester) | Certified cylinders with inaccurate equipment; failed to maintain accurate records; failed to calculate wall stress when marking cylinders with a '+'; failed to remark exemption DOT-E 6498 cylinders with specification 3A L. [173.34(e)(3), 173.34(e)(5), 171.2(c), 173.23(c)] Case No. 94-120-CR-SW | \$10,250 |
| CARLISLE PLASTICS INC D/B/A BERCON PACKAGING (Plastic Bottle Manufacturer) | Manufactured, marked, and sold plastic bottles as DOT specification 2E without conducting periodic drop testing on the top edge or a weaker part; failed to conduct periodic cold drop tests; failed to mark the packaging with the manufacturer name and address or registered symbol. [178.24a-5(d)(1), 178.24a-5(c), 173.24(c)] Case No. 93-193-PBM-EA | \$7,500 |
| CAROLINA SAFETY ASSOCIATES INC (Cylinder Retester) | Failed to condemn cylinders when the permanent expansion exceeded 10%; conducted hydrostatic testing with equipment which could not be verified as accurate to 1%; failed to maintain accurate records. [173.34(e)(4), 173.34(e)(3), 173.34(e)(5)] Case No. 93-197-CR-EA | \$7,530 |

| CAROLINA SOLVENTS INC (Drum Reconditioner/Shipper) | Certified steel drums as DOT-17E without conducting leakage tests; offered methyl propyl ketone in unauthorized nonspecification packaging. [173.28(m)(2), 173.242(c), 173.119(b)] Case No. 94-138-DR-HQ | \$6,500 |
|---|---|----------|
| CHARLES GRATZ FIRE PROTECTION (Cylinder Retester) | Failed to have current approval and RIN; failed to remark exemption aluminum cylinders as DOT specification 3AL; failed to perform a complete visual external examination. [173.34(e)(1)(i), 173.23(c), 173.34(e)(1)] Case No. 93-155-CR-EA | \$3,100 |
| CHEM-BRIGHT INDUSTRIES INC (Shipper) | Offered hydrochloric acid and hypochlorite solution in nonspecification packaging under the authority of an exemption that had expired. [173.263(a), 173.277(a)] Case No. 92-127-EXR | \$5,000 |
| CHEMCENTRAL CORP (Shipper) | Offered acetone, a flammable liquid with a flash point below 20 degrees Fahrenheit, for transportation in unauthorized DOT packaging. [173.119(a)(3)] Case No. 93-47-SD-HQ | \$4,300 |
| CHEMICAL COMMODITIES AGENCIES INC (Shipper) | Allowed an employee to perform a function subject to the HMR, when the employee had not received HM training. [172.702] Case No. 95-71-TRN-W E | \$1,200 |
| CHICAGO STEEL CONTAINER CORP (Steel Drum Manufacturer) | Failed to pass four-foot drop teston DOT 17H drums; failed to conduct periodic drop and hydrostatic tests on DOT 17E drums; failed to conduct periodic drop and hydrostatic tests on DOT 17H drums; failed to conduct design qualification tests for UN 1A1 and UN1A2 drums. [178.118-12(a), 178.116-12(a)(1), 178.116-12(a)(2), 178.118-12(a)(1), 178.118-12(a)(2), 178.601(d)] Case No. 93-32-DM-CE | \$18,000 |
| CHUCK'S FIRE & SAFETY CONTROL (Cylinder Retester) | Represented and marked cylinders as having been retested without holding a current RIN. [173.34(e)(1)(i), 173.34(e)(1)] Case No. 91-04-CR | \$3,000 |
| CITY CHEMICAL CORP (Shipper) | Offered ethyl acetate, flammable liquid, in nonspecification packaging; offered tetrahydrofuran, flammable liquid, in unauthorized inner glass bottles in DOT 12B boxes; failed to mark packages with the UN ID number; failed to label packages as required; failed to indicate RQ in the proper sequence on a shipping paper. [173.119(b), 173.119(a)(7), 172.301(a), 172.400(a), 172.201(a)(4)] Case No. 92-92-SB-EA | \$4,000 |
| CKS PACKAGING INC (Plastic Bottle Manufacturer) | Manufactured plastic bottles as DOT-2E without performing ambient and cold drop tests in outer packaging; manufactured plastic bottles as DOT-2U bottles without performing vibration tests in outer packaging. [178.24-7(a)(1), 178.24-7(a)(3)] Case No. 94-204-PBM-EA | \$8,800 |

| CLAYTON CONTAINER COMPANY INC (Fiberboard Box Manufacturer) | Certified boxes as DOT-12B when inner flaps did not butt and fill-in pieces or pads were not included. [178.205-14(a)] Case No. 94-197-BM-EA | \$5,100 |
|---|--|----------|
| CLEVELAND CONTAINER CORP (Plastic Drum Manufacturer) | Manufactured, marked and sold plastic packagings as DOT specification 35 without drop testing 1 of every 10,000 produced; failed to perform design qualification tests; failed to apply required markings. [178.16-16(a), 178.601(d), 178.603 (e), 178.601(k)(1), 172.2(f), 178.503(a)(6), 178.503(a)(7)] Case No. 94-34-PDM-CE | \$10,600 |
| CLOVER LEASING CO (Cylinder Retester) | Performed hydrostatic testing with in accurate equipment; failed to maintain accurate records; failed to legibly mark cylinders; failed to increase pressure by 10% or 100 psi on 2nd test; failed to properly mark FRP cylinders; failed to properly affix its RIN to FRP cylinders. [173.34(e)(3), 173.34(e)(5), 173.34(c), 173.34(e)(3), 173.34(e)(1), DOT-E 7277, Para. 8f] Case No. 92-64-CR-CE | \$8,500 |
| COFFEYVILLE RE- CON INC (Drum Reconditioner) | Certified, marked, and sold reconditioned steel drums as meeting the DOT17E specification, when they were not authorized for reuse. [173.28(m)] Case No. 94-92-DR-SW | \$4,650 |
| COLLINS FIRE EXTINGUISHER INC (Cylinder Retester) | Certified cylinders without performing retests at the minimum test pressure. [173.34(e)] Case No. 95-167-CR-HQ | \$3,650 |
| COLUMBUS FIRE & SAFETY EQUIPMENT CO INC (Cylinder Retester) | Failed to condemn cylinders when permanent expansion exceeded 10% of total expansion; conducted hydrostatic testing with equipment not calibrated to 1% accuracy; failed to maintain accurate records; failed to conduct employee training. [173.34(e)(4), 173.34(e)(3), 173.34(e)(5), 172.700] Case No. 94-210-CR-EA | \$10,000 |
| CONSOLIDATED CONTAINER CORP (Drum Rec onditioner) | Certified remanufactured steel drums as DOT 17H without conducting drop and hydrostatic testing. [178.116-12(a)] Case No. 94-60-DR-CE | \$4,650 |
| CONSTAR PLASTICS INC (Plastic Bottle Manufacturer) | Represented plastic bottles as DOT specification 2E without conducting the required number of ambient drop tests; failed to conduct drop tests on top edge or weaker part; failed to conduct drop tests on DOT specification 2U plastic bottles. [178.24a-5(b), 178.24a-5(d)(1), 178.0-2(c), 178.24-7(a)(1), 178.24-7(a)(2), 178.0-2(c), 178.24-7(a)(3)] Case No. 93-116-PBM-EA | \$12,042 |
| CONSTAR PLASTICS INC (Plastic Bottle Manufacturer) | Represented plastic bottles as DOT specification 2E without conducting the required number of ambient drop tests. [178.24a-5(b)] Case No. 93-202-PBM-EA | \$8,032 |

| CONSTRUCTION TECHNOLOGY LABORATORIES INC (Package Certifier) | Certified steel drums to a UN standard without properly identifying the package's construction material. [178.502(a)(2)] Case No. 94-130-PC-CE | \$600 |
|---|--|----------|
| CONTAINER CORP OF AMERICA INC (Fiberboard Box Manufacturer) | Certified fiberboard boxes as DOT 12B when inner flaps did not butt and fill-in pieces or pads were not included; failed to properly mark boxes with the name and address or symbol of the manufacturer. [178.0-2, 178.205-14(a), 178.205-18(a)] Case No. 94-25-BM-CE | \$4,000 |
| CONTAINER-QUINN TESTING LABORATORIES INC (Package Certifier) | Issued a UN package certification which failed to include the approval agency's name and ID code; issued a package certification which failed to include a separate 4-digit number for each certified package; issued approval certificates which failed to contain the letter 'S' for UN packages intended to contain inner packagings; failed to maintain complete records of design qualification tests. [107.404(a)(2), 107.404(c), 178.503(a)(5), 178.602(k)(1)] Case No. 94-82-PC-CE | \$3,840 |
| CONTAINER-QUINN TESTING LABORATORIES INC (Package Certifier) | Certified fiberboard boxes as UN 4G without performing design qualification tests. [178.601(d)] Case No. 95-109-PC-CE | \$1,900 |
| CORAL INTERNATIONAL INC (Shipper) | Offered hydrochloric acid solution in unauthorized nonspecification packaging. [173.263(a)] Case No. 94-118-SB-CE | \$3,500 |
| CORRUGATED PAPER PRODUCTS INC (Fiberboard Box Manufacturer) | Certified boxes as DOT-12B with gross weight markings that exceeded the maximum authorized weight; failed to include fill-in pieces or pads when inner flaps did not butt. [178.205(16)(a)] Case No. 94-287-BM-CE | \$7,200 |
| COSTA CHEMICAL CORP (Shipper) | Failed to include the technical name as part of the proper shipping name marking on the packaging. [172.301(c), 173.125(a), 172.202(a)(3), 172.203(k), 173.125(a)] Case No. 91-155-SB. | \$2,450 |
| COTTER & COMPANY (Shipper) | Offered compound cleaning liquid, corrosive material, for transportation in nonspecification packagings. [173.245 (a)] Case No. 93-91-SB-CE | \$3,225 |
| COURTAULDS AEROSPACE (Fiberboard Box Manufacturer/Shipper) | Certified boxes as UN 4G without performing design qualification tests; failed to perform periodic retests; failed to keep complete records of design qualification tests. [178.601(d), 178.601(e), 178.601(d), 178.601(k)(1)] Case No. 95-91-BMS-SW | \$17,895 |

| CRANSTON WELDING SUPPLY COMPANY INC (Cylinder Retester) | Certified cylinders without increasing test pressure by 100 psi or 10% when conducting 2nd test; conducted testing with equipment not calibrated to 1% accuracy. [173.34(e)(3), 173.34(e)(3)] Case No. 95-52-CR-EA | \$5,000 |
|--|---|---------|
| CROSS CONTAINER CORP (Fiberboard Box Manufacturer) | Represented, manufactured, marked, and sold fiberboard boxes as meeting the DOT 12B65 specification, when the boxes were of insufficient strength to meet that specification. [178.205-15(a), 178.205-16(a)] Case No. 93-156-BM-CE | \$3,400 |
| CUSTOM DELIVERIES INC C/O LEASEWAY TRANSPORTATION CORP (Shipper) | Failed to properly mark, label, and package batteries, wet filled with acid, for transportation. [172.301(a), 172.400(a), 173.159(a)] Case No. 93-149-BAT-HQ | \$1,443 |
| CUYAHOGA CHEMICAL COMPANY (Shipper) | Offered acetone, a flammable liquid with a flash point below 20 degrees Fahrenheit, in unauthorized DOT drums. [173.119(a)(3)] Case No. 91-97-SD | \$2,700 |
| CYL-TEC INC (Cylinder Retester) | Performed hydrostatic retesting with equipment which was not accurate to within 1%. [173.34(e)(3)] Case No. 92-62-CR-CE | \$2,500 |
| CYL-TEC INC (Shipper) | Failure to register with RSPA when offering HM of one hazard class in non-bulk packaging in excess of 5000 pounds. [107.608(a)] Case No. 95-112-REG-CE | \$250 |
| DAISY MANUFACTURING COMPANY INC (Shipper) | Offered a new unapproved explosive for transportation. [173.54(a), 173.56(b)(1)] Case No. 94-100-SE-SW. | \$4,000 |
| DAMERON FIRE EQUIPMENT CO (Cylinder Retester) | Failed to hold a current approval and RIN; failed to maintain accurate records of reinspection and retest. [173.34(e)(1)(i), 173.34(e)(5)] Case No. 93-160-CR-HQ | \$2,700 |
| DELTA DRUM INC (Plastic Drum Manufacturer) | Certified UN 1H1 drums without performing the required leakproofn ess testing during production and as part of periodic testing. [178.601(e), 178.604(a), 178.604(b)] Case No. 94-241-PDM-CE | \$4,000 |
| DEPENDABLE CONSTRUCTION SUPPLY INC (Shipper) | Offered corrosive liquid n.o.s. for transportation in nonspecification packaging; failed to mark proper shipping name or ID number on the package; failed to mark "This Side Up or This End Up" on the packaging. [172.301(a), 173.245(a), 172.202(a)(1)-(3), 172.312(a)] Case No. 91-30-SB | \$4,000 |

| DEPENDABLE FIRE EQUIPMENT CO INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; certified exemption aluminum cylinders without remarking them 3AL; failed to maintain accurate records of reinspection and retest; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when the accuracy of the system could not be maintained due to equipment failure. [173.34(e)(3), 173.23(c), 173.34(e)(5), 173.34(e)(3)] Case No. 92-35-CR-EA | \$1,000 |
|---|---|----------|
| DETYANS SHIPYARD INC (Cylinder Retester) | Certified cylinders without increasing test pressure by 100 psi or 10% on 2nd test; failed to insure equipment was accurate to within 1%; failed to mark RIN in clockwise pattern; failed to maintain training records. [173.34(e)(3), 173.34(e)(3), 173.34(e)(6), 172.700] Case No. 94-132-CR-EA | \$7,900 |
| DIGICOURSE INC (Fiberboard Box Manufacturer) | Certified package as UN4G without conducting design qualification tests. [178.603(a), 178.606(a)] Case No. 93-230-BM-CE | \$6,300 |
| DOUGLAS PRODUCTS & PACKAGING CO INC (Shipper) | Offered poison B in nonspecification packagings; failed to properly label a HM package; failed to properly mark a HM package; failed to prepare shipping papers; failed to mark a package for proper container orientation. [173.357(a), 172.400(a), 172.301(a), 172.202(a)(3), 172.312(a)(2)] Case No. 93-69-SB-WE | \$10,300 |
| DOWELL SCHLUMBERGER INC (Shipper) | Offered a corrosive material under the terms of an expired exemption DOT-E 3095 which resulted in the use an unauthorized nonspec ification packaging. [173.245, 173.202] Case No. 94-203-EXR | \$5,000 |
| DPC INDUSTRIES INC (Cylinder Retester) | Certified cylinders without increasing test pressure by 100 psi or 10% when conducting a 2nd test; performed hydrostatic retesting with inaccurate equipment; failed to insure markings were legible. [173.34(e)(3), 173.34(e)(3), 173.34(e)(6)] Case No. 94-192-CR-CE | \$7,350 |
| DURALE PLASTICS INC (Fiberboard Box Manufacturer/Shipper) | Certified boxes as DOT-12B40 when inner flaps did not butt and fill-in pieces and pads were not included; failed to mark boxes with the name and address or registered symbol of the box manufacturer. [178.205-14(a), 178.205-18(a)(2)] Case No. 94-271-BMS-CE | \$3,680 |
| DYMON INC (Shipper) | Offered compound cleaning liquid in unauthorized nonspecification packaging; provided additional information within the HM shipping description on a shipping paper. [173.203(a), 173.245(a), 172.101, 172.201(a)(4)] Case No. 93-134-SP-WE | \$3,200 |
| E G & G IDAHO INC (Cylinder Retester) | Failed to remark exemption aluminum cylinders as DOT 3AL; failed to hold a current approval or RIN. [173.23(c), 173.34(e)(1)(i)] Case No. 93-55-CR-WE | \$4,000 |

| E I DUPONT DE NEMOURS COMPANY (Shipper) | Offered HM under the terms of an expired exemption, DOT-E 10660, which resulted in improper labeling of the material. [172.402(a)(1)] Case No. 94-208-EXR | \$4,700 |
|--|---|---------|
| E P W DISTRIBUTION CENTER INC (Cylinder Retester) | Failed to hold current approval and RIN; failed to maintain accurate records. [173.34(e)(1)(i), 173.34(e)(5)] Case No. 93-03-CR-CE | \$2,410 |
| EAGLE-PICHER INDUSTRIES INC (Shipper) | Offered methanol, a flammable liquid, in a DOT specification 12A box, a nonreusable packaging, which had been previously used. [173.119(b)] Case No. 94-89-SB-SW | \$3,400 |
| EASTERN WELDING SUPPLY CO (Shipper) | Failed to submit a complete and accurate registration statement to RSPA. [107.608(a)] Case No. 94-127-SC-CE | \$250 |
| ELGIN CORRUGATED BOX COMPANY (Fiberboard Box Manufacturer) | Manufactured, marked, and certified fiberboard boxes as DOT 12B when inner flaps did not butt and fill-in pieces or pads were not provided. [178.205-14] Case No. 93-237-BM-CE. | \$3,000 |
| ENGINEERED MATERIALS SYSTEMS INC (Fiberboard Box Manufacturer/Shipper) | Certified boxes as meeting the UN 4G standard with an unauthorized duplicate symbol; failed to perform design qualification testing; failed to mark packages with correct year of manufacture; failed to conduct employee HM training. [178.2(b)(2), 178.503(a)(8), 178.601(d), 178.601(k)(1), 178.503(a)(6), 172.702, 172.704] Case No. 94-36-SMB-CE | \$8,450 |
| ETHOX CHEMICALS INC (Shipper) | Offered corrosive liquids in unauthorized nonspecification packaging; failed to provide a proper shipping description on a shipping paper by using unauthorized abbreviations. [173.245, 173.203, 172.201(a)(3)] Case No. 94-190-SD-HQ | \$5,050 |
| EXIDE CORP (Shipper) | Failed to provide training to HM employees. [172.702(b)] Case No. 95-82-TRN-HQ | \$1,200 |
| EXPLOSIVES TECHNOLOGIES INTERNATIONAL INC (Shipper) | Offered a new explosive for transportation that was forbidden, because it had not been examined, classified, and approved. [173.86(b), 173.51(b)] Case No. 92-105-SE-HQ | \$5,000 |
| FARMINGTON FIRE EQUIPMENT & SAFETY (Cylinder Retester) | Failed to determine average or minimum wall stress for cylinders being marked with '+' marks to indicate 10% overfill authorization; failed to maintain accurate records of reinspection and retest. [173.302(c)(3), 173.302(c)(5), 173.32(e)(5)] Case No. 93-27-CR-WE | \$3,900 |

| FIBERGLASS HAWAII INC (Shipper) | Failed to mark packages of flammable liquid and organic peroxide with the proper shipping name and ID number; offered flammable liquid and organic peroxide in nonspecification packaging; failed to mark proper orientation on packages of HM; provided additional information within the HM shipping description on a shipping paper. [173.301(a), 173.119(a), 173.221(a), 172.312(a)(2), 172.201(a)(4)] Case No. 93-56-SB-WE | \$8,900 |
|--|---|---------|
| FIRE EXTINGUISHER SERVICE (Cylinder Retester) | Performed retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest; failed to remark exemption aluminum cylinders as 3AL; failed to mark cylinders with legible markings. [173.34(e)(3), 173.34(e)(5), 173.23(c), 173.34(c)] Case No. 91-83-CR | \$4,200 |
| FIRE EXTINGUISHER SERVICE CENTER INC (Cylinder Retester) | Performed hydrostatic testing with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5), 173.34(e)(1)(v)] Case No. 91-145-CR | \$4,900 |
| FIRE FIGHTER SALES & SERVICE INC (Cylinder Retester) | Failed to increase test pressure by 100 psi or 10% when retesting the cylinder a second time. [173.34(e)(3)] Case No. 94-38-CR-HQ | \$2,000 |
| FIRE SAFETY SALES & SERVICE INC (Cylinder Retester) | Certified DOT specification cylinders with equipment not calibrated to 1% accuracy. [173.34(e)(3)] Case No. 95-127-CR-SW | \$2,920 |
| FIRELINE CORP (Cylinder Retester) | Failed to increase test pressure by 100 psi or 10% on second test, when the accuracy of the system could not be maintained to due equipment failure; failed to mark cylinders with RIN. [173.34(e)(3), 173.34(e)(6)] Case No. 94-40-CR-HQ | \$3,000 |
| FISHER GLASS D/B/A STOCKTON FIRE EQUIPMENT CO (Cylinder Retester) | Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 92-97-CR-WE | \$1,500 |
| FLORIDA DRUM COMPANY INC (Plastic Drum Manufacturer) | Certified UN 1H1 and 3H1 plastic containers without conducting leakproofness tests. [178.604(e)] Case No. 95-66-PDM-SW | \$5,250 |
| FLUKA CHEMICAL CORP (Shipper) | Offered poisonous liquid, corrosive, n.o.s. for transportation by water, when the exemption under which it was being offered did not authorize transportation by water. [173.3a(a)(3), 173.227] Case No. 93-92-SB-HQ | \$3,600 |

| FRANK POPLA BARREL CO INC (Drum Reconditioner) | Failed to conduct on-line leakage test on drums marked DOT 17E; failed to mark drums with the proper DOT registration number. [173.28(m)(2), 173.28(m)(3)(ii)] Case No. 93-189-DR-EA | \$3,200 |
|--|--|---------|
| FRANK W KERR CHEMICAL COMPANY (Shipper) | Offered denatured alcohol in unauthorized nonspecification packaging; failed to describe a HM with the proper shipping name on a shipping paper; failed to list the shipping description in the proper sequence on the shipping paper; failed to sign the shipper's certification. [173.125(a), 172.202(a)(1), 172.202(b), 172.204(d)(1)] Case No. 91-151-SB | \$3,680 |
| FRANK'S DIVE SHOP INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 91-152-CR | \$3,200 |
| FREMONT INDUSTRIES INC (Shipper) | Offered chromic acid mixture dry, oxidizer, in an unauthorized DOT specification packaging. [173.164(a)] Case No. 93-120-SP-HQ | \$2,900 |
| FRESH PRODUCT INC (Fiberboard Box Manufacturer) | Certified fiberboard boxes as UN4G without conducting the stacking test; failed to maintain complete design qualification test records; failed to mark boxes with the correct year of manufacture. [178.601(d), 178.602(d), 178.601(k)(1), 178.503(a)(7)] Case No. 94-35-BM-CE | \$6,500 |
| FRESNO CAR BONIC INC (Cylinder Retester) | Marked cylinders with the '+' sign without calculating wall stress; failed to maintain accurate records. [173.302(c)(5), 173.34(e)(5)] Case No. 93-127-CR-W E | \$3,800 |
| G & W ELECTRIC COMPANY INC (Shipper) | Offered an unapproved explosive for transportation; failed to fully describe a HM on a shipping paper; failed to provide a monitored 24-hour emergency response telephone number on the shipping paper; failed to provide employees with HM training. [173.51(b), 172.200(a), 172.201(d), 172.604(a)(1), 172.704(a)(2)] Case No. 94-140-SE-CE | \$7,680 |
| G C INDUSTRIES INC (Shipper) | Offered hydrogen sulfide in nonspecification packaging, under the terms of an exemption which had expired. [173.304] Case No. 92-02-EXR | \$3,298 |
| G S PARSONS COMPANY (Cylinder Retester) | Failed to condemn a cylinder with a permanent expansion exceeding 10% of total expansion. [173.34(e)(4)] Case No. 93-04-CR-W E | \$4,788 |
| GADSDEN FIRE EXTINGUISHER & CO2 SERVICE (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to conduct retests at minimum required test pressure; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e), 173.34(e)(5)] Case No.91-62-CR | \$1,800 |

| GAS TECH INC D/B/A ACETYLENE PRODUCTS CO (Cylinder Retester) | Marked cylinders with the '+' sign without calculating wall stress; marked cylinders as successfully retested before retests were conducted; failed to maintain accurate records. [173.302(c)(3), 173.302(c)(5), 173.34(e)(1)(ii), 173.34(e)(5)] Case No.94-01-CR-CE | \$4,950 |
|--|--|----------|
| GAYNES TESTING LABORATORIES LTD (Package Certifier) | Certified a package to a higher gross mass than the weight at which it was tested; assigned an approval certificate and certification number to a package, when that certification number had already been assigned to a different package. [178.503 (a)(4), 178.606(c)(1), 107.404(c), 171.2(f)(1)] Case No. 94-153-PC-CE | \$3,800 |
| GENERAL FIRE & SAFETY EQUIPMENT (Cylinder Retester) | Conducted hydrostatic testing with equipment not calibrated to an accuracy of 1%; failed to increase test pressure by 10% or 100psi, when the first test could not be maintained due to the failure of test equipment. [173.34(e)(3), 171.2(c)] Case No. 93-121-CR-CE | \$3,600 |
| GENERAL FIRE AND SAFETY EQUIP OF DES MOINES INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records. [173.34(e)(3), 173.34(e)(5)] Case No. 93-52-CR-CE | \$3,300 |
| GENERAL STEEL DRUM CORP (Steel Drum Manufacturer) | Failed to conduct drop and hydrostatic testing on drums marked DOT 17E and DOT 17H; failed to conduct design qualification testing on drums certified as UN1A1 and UN1A2 packages. [178.116-12(a), 178.118-8(c)(1)] Case No. 93-219-DM-EA | \$11,600 |
| GETZ FIRE EQUIPMENT COMPANY INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; marked cylinders with a '+'sign without calculating wall stress. [173.34(e)(3), 173.34(e)(5), 173.34(e)(3), 173.302(c)] Case No. 92-130-CR-CE | \$5,625 |
| GFEC INC (Cylinder Manufacturer) | Manufactured, marked, and sold cylinders after physical testing which included a yield strength determination in which the crosshead speed exceeded 1/8 inch per minute; provided a HM shipping description on a shipping paper that was out of sequence; failed to register with RSPA. [178.37-16(c)(4), 172.202(b), 107.608, 107.612] Case No. 94-67-CM-HQ | \$3,950 |
| GOEX INTERNATIONAL INC (Shipper) | Offered class C explosives for transportation in unauthorized nonspecification packaging, under the terms of an exemption which had expired. [173.100(v)] Case No. 94-56-EXR | \$2,610 |
| GOSS BROTHERS WELDING SUPPLY INC (Cylinder Retester) | Marked cylinders with a '+' sign without calculating wall stress; failed to maintain accurate records. [173.302(c)(3), 173.302(c)(5), 173.34(e)(5)] Case No. 93-38-CR-EA | \$4,460 |

| GREAT WESTERN CHEMICAL COMPANY INC (Shipper) | Offered flammab le liquid in unauthorized out-of-test DOT 57 portable tanks; offered hypochlorite solution in nonspecification packaging; failed to mark the proper shipping name and ID number on a package; offered oxidizer n.o.s. in nonspecification packaging; included additional information in the HM shipping description on a shipping paper; failed to indicate a HM shipping description in the proper sequence; failed to indicate the technical name of the material on the shipping paper. [173.32(e)(1)(ii), 173.277(a), 172.301(a), 173.154(a), 172.201(a)(4), 172.202(b), 172.203(k)] Case No. 92-19-SPTB | \$12,000 |
|--|--|----------|
| GREAT WESTERN CHEMICAL COMPANY INC (Shipper) | Offered sulfuric acid in unauthorized nonspecification packaging; failed to mark an exemption number in conjunction with the HM shipping description on a shipping paper. [173.242, DOT-E9052 para. (7)(h), 172.203(a)] Case No. 94-13-SPT-W E | \$10,495 |
| GRECO WELDING SUPPLIES INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; failed to maintain accurate records; failed to mark exemption cylinders with the RIN by stamping or labeling. [173.34(e)(3), 173.34(e)(4), 173.34(e)(5), 173.34(e)(6), DOT-E 7277] Case No. 92-94-CR-EA | \$11,400 |
| GREERS SUPPLY COMPANY INC (Cylinder Retester) | Conducted hydrostatic testing with test equipment not accurate to one percent of test pressure and/or total expansion. [173.34(e)(3)] Case No. 93-126-CR-HQ | \$3,240 |
| GREIF BROS CORP (Fiber Drum Manufacturer) | Manufactured, marked, and sold fiber drums as DOT-21C drums without conditioning drums 48 hours before testing; manufactured, marked and sold drums as meeting the UN 1G standard without conducting drop and stacking tests; failed to mark UN certification information in proper sequence. [178.224-2(a), 178.601(e), 178.503(a)] Case No. 94-21-FDM-CE | \$10,600 |
| GREIF BROS CORP (Fiberboard Box Manufacturer) | Certified fiberboard boxes as DOT 12B, when inner flaps did not butt and fill-in pieces or pads were not included. [178.205-14(a), 178.0-2] Case No. 93-253-BM-CE | \$4,155 |
| GREIF BROS CORP (Plastic Drum Manufacturer) | Manufactured, marked, and sold UN 1H1 drums without conducting and recording periodic drop, leakproofness, hydrostatic, and stacking tests. [178.603, 178.601(f)] Case No. 93-240-PDM-CE | \$10,400 |

| GRIFFIN AND ASSOCIATES (Cylinder Retester) | Failed to condemn cylinders when permanent expansion exceeded 10% of total expansion; represented cylinders as tested without conducting the test; represented cylinders as meeting the requirements of the regulations while marking them with illegible markings. [173.34(e)(4), 173.34(e)(1)(ii), 173.34(c), 173.34(e)(6)] Case No. 93-137-CR-EA | \$5,500 |
|---|---|----------|
| GROW GROUP INC (Shipper) | Offered trichloroisocyanuric acid dry, oxidizer, in nonspecification packaging; failed to sign the shipper's certification on the shipping paper. [173.217(a), 173.212(a), 172.204(d)] Case No. 93-166-SB-EA | \$9,600 |
| H B FULLER COMPANY INC (Shipper) | Offered potassium permanganate for transportation in unauthorized nonspecification packaging. [173.154(a)] Case No. 94-164-SB-CE | \$4,950 |
| HALLIBURTON COMPANY INC (Shipper) | Offered an unapproved explosive for transportation. [173.56(b)] Case No. 94-112-SE-HQ | \$15,400 |
| HAMPTON BAY DIVERS D/B/A PECONIC SCUBA (Cylinder Retester) | Failed to have current RIN; performed retesting with inaccurate equipment; failed to remark exemption aluminum cylinders as DOT specification 3AL; failed to maintain accurate records. [173.34(e)(1)(i), 173.34(e)(3), 173.23(c), 173.34(e)(5)] Case No. 93-14-CR-EA | \$5,000 |
| HARCROS CHEMICALS INC (Cylinder Retester) | Conducted testing with equipment not calibrated to one percent accuracy; offered butyl acetate, a flammable liquid, without a signed shipper's certification on the shipping paper. [173.34(e)(3), 172.204(d)] Case No. 93-256-CR-EA | \$7,840 |
| HARCROS CHEMICALS INC (Shipper) | Offered HM under exemption without noting the exemption on the shipping paper; failed to have a signed shipper's certification on the shipping paper; certified ton tanks as retested without conducting the tests. [172.203(a), 172.204(d), 173.31(d)(3)] Case No. 94-172-STT-SW | \$13,300 |
| HARRISON'S POOL EQUIPMENT INC (Shipper) | Failed to indicate the proper shipping name on the shipping paper. [172.202(a)(1)] Case No. 93-67-SB-WE | \$1,300 |
| HASA INC (Shipper) | Offered hypochlorite solution, a corrosive material, in DOT-E 9052 portable tanks which had not been hydrostatically retested in accordance with the exemption; failed to list the proper exemption number on the shipping paper. [173.32(e)(1)(ii), 173.32(f), DOT-E 9052 para. 7.h., 172.203(a)] Case No. 93-254-SPT-WE | \$4,911 |
| HEDWIN CORP (Plastic Pail Manufacturer) | Certified plastic drums as UN1H1 without maintaining records of periodic retest at each location where those drums were manufactured. [178.601(k)(3), 178.601(k)(1)] Case No. 94-258-PPM-CE | \$3,260 |

| HITECH HOLDINGS INC (Shipper) | Offered ex plosive substances, classed as explosive A, in unauthorized nonspecification packaging. [173.64(a)] Case No. 93-233-SB-CE | \$2,250 |
|--|--|---------|
| HODGDON POWDER COMPANY INC (Shipper) | Offered an unapproved explosive for transportation; offered propellant explosive in previously used packaging without removing or obliterating the old markings. [173.86(b), 173.28(d)] Case No. 93-122-SE-CE | \$8,000 |
| HOLSTON GASES INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to remark exemption aluminum cylinders as DOT 3 AL. [173.34(e)(3), 173.23(c)] Case No. 93-162-CR-HQ | \$4,250 |
| HOOK'S CLEAN CARE INC (Shipper) | Offered hydrochloric acid in unauthorized nonspecification packaging; provided a shipping paper that incorrectly identified the hazard class and volume of the material. [173.263(a), 172.202(a)(2)] Case No. 94-29-SB-CE | \$4,000 |
| HOOKS CLEAN CARE INC (Cylinder Retester) | Certified cylinders with equipment not calibrated to 1% accuracy. [173.34(e)(4)] Case No. 94-107-CR-CE | \$2,500 |
| HOOVER GROUP INC (Plastic Tank Manufacturer) | Manufactured, marked, and sold plastic portable tanks as meeting the requirements of DOT-E 9440, when the tanks could not withstand drop test requirements. [178.19-7(a), DOT-E 9440 para. 7.c.] Case No. 94-58-PTM-CE | \$5,480 |
| HOPRICH COMPANY INC (Cylinder Retester) | Marked cylinders with a "+" mark without calculating average wall stress. [173.302(c)(3), 173.302(c)(5)] Case No. 94-128-CR-CE | \$3,655 |
| HOUGHTON CHEMICAL CORP (Shipper) | Offered flammable liquid in a specification DOT 57 portable tank that had not been properly retested. [173.125(a)(1), 173.242(c)] Case No. 94-93-SPT-HQ | \$3,440 |
| HOUSTON DISTRIBUTING INC (Shipper) | Failed to mark the HM ID number on drums; offered potassium permanganate in nonspecification packaging; provided additional information within the HM shipping description on a shipping paper; offered chromic acid solid in nonspecification packaging; failed to mark the proper shipping name and ID number on packages containing calcium hypochlorite. [172.301(a), 173.154(a), 172.201(a)(4), 173.164(a), 172.201(a)(4), 172.301(a)] Case No. 92-61-SD-HQ | \$5,500 |
| HOWARD TERNES PACKAGING COMPANY (Shipper) | Offered an explosive for transportation under the terms of an exemption that had expired. [172.202(a), 172.301(a), 172.400(a), 173.62] Case No. 95-60-EXR | \$1,750 |

| HUMMEL CROTON INC (Shipper) | Offered flammable solid in unauthorized nonspecification packaging; failed to identify a reportable quantity of HM by marking the letters RQ after the shipping description on the shipping paper. [173.189(a), 173.213(a), 172.203(c)(2)] Case No. 93-174-SD-WE | \$2,000 |
|---|--|----------|
| HUNTER CHEMICAL & FORMULATING CO INC (Shipper) | Offered corrosive liquid in unauthorized nonspecification packaging; failed to properly mark the packages; failed to provide HM training to employees; failed to indicate proper shipping name and ID number on shipping papers. [173.245(a), 172.301(a), 172.702, 172.202(a)] Case No. 94-232-SB-EA | \$11,440 |
| I Q PRODUCTS COMPANY INC (Shipper) | Failed to indicate the proper shipping name and hazard class on a shipping paper; failed to provide HM training. [172.202(a), 172.704] Case No. 95-80-TRN-HQ | \$1,700 |
| IDEAL CHEMICAL & SUPPLY COMPANY INC (Shipper) | Offered so dium hydroxide for transportation in exemption portable tanks that had not been retested as required. [173.32(e)(1)(ii), 173.32(f), DOT-E 9440, para, 7.g.] Case No. 95-53-SPT-SW | \$3,640 |
| ILLINIFIRE EQUIPMENT CO (Cylinder Retester) | Certified cylinders with equipment not calibrated to 1% accuracy; failed to maintain accurate records of rein spection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-249-CR-CE | \$4,825 |
| IMC FERTILIZER GROUP INC (Shipper) | Failed to set brakes and block wheels on all rail tank cars while unloading HM after the expiration of an exemption. [174.67(a)(2)] Case No. 93-61-EXR | \$2,100 |
| IND WELDING SUPPLY OF HATTIESBURG INC D/B/A NORDAN SMITH (Cyl Retester) | Certified cylinders with equipment not calibrated to 1% accuracy; failed to mark cylinders in a legible manner; failed to cover labels on a FRP cylinder with an epoxy coating. [173.34(e)(3), 173.34(e)(1)(ii), DOT-E 7277 para. 8.f.] Case No. 94-121-CR-SW | \$4,650 |
| INDIANA OXYGEN COMPANY INC (Cylinder Retester) | Certified cylinders with equipment that was not calibrated to 1% accuracy; failed to determine the minimum or average wall stress for cylinders marked with a "+" mark to indicate authorization for 10% overfill. [173.34(e)(3), 173.302(c)] Case No. 93-96-CR-CE | \$5,700 |
| INDUSTRIAL CHEMICALS CORP (Shipper) | Offered flammable liquids in unauthorized DOT specification packagings; failed to indicate the technical name of the HM on the shipping paper. [173.119, 172.203(k)] Case No. 93-117-SP-WE | \$5,000 |
| INNERSPACE DIVE SHOP (MR JOHN MAR SHALL) (Cylinder Retester) | Certified cylinders without holding a current approval or RIN. [173.34(e)(1)(i)] Case No. 94-179-CR-HQ | \$2,700 |

| INSTA-FOAM PRODUCTS INC (Shipper) | Offered compressed gas for transportation in nonspecification packaging under the terms of an exemption that had expired. [173.315(a)] Case No. 93-111-EXR | \$2,000 |
|--|--|---------|
| INTERCONTINENTA L CHEMICAL CORP (Shipper) | Offered corrosive liquid in unauthorized nonspecification packaging. [173.245, 173.202(a)] Case No. 94-70-SB-CE | \$4,160 |
| IOWA INTERSTATE RAILROAD (Shipper) | Offered and transported railroad track torpedoes, class B explosives, and railway fusees, flammable solid, in nonspecification packaging under the terms of an exemption which had expired. [173.154a, 173.91(f)] Case No. 91-93-EXR | \$1,350 |
| ISO-SCIENCES LABORATORIES INC (Shipper) | Offered radioactive materials for transportation in a DOT 7A Type A package without having documentation of tests and an engineering evaluation for that package. [173.415(a)] Case No. 94-272-RMS-HQ | \$3,240 |
| J G & J IN C D/B/A ALPENA FIRE EQUIPMENT SALES & SERVICE (Cylinder Retester) | Certified cylinders with equipment not calibrated to 1% accuracy; failed to maintain accurate records of visual reinspection. [173.34(e)(3), 173.34(e)(5)] Case No. 94-249-CR-CE | \$3,320 |
| J N JOHNSON SALES & SERVICE INC (Cylinder Retester) | Certified cylinders with equipment not calibrated to 1% accuracy; failed to conduct employee HM training. [173.34(e)(3), 172.704(a)(1)] Case No. 94-211-CR-CE | \$5,040 |
| JACKSONVILLE WELDING SUPPLY INC (Cylinder Retester) | Certified cylinders with equipment not calibrated to 1% accuracy. [173.34(e)(3)] Case No. 95-173-CR-SW | \$3,650 |
| JEFFERSON SMURFIT AND CONTAINER CORP OF AMERICA (Package Certifier) | Certified fiberboard boxes as UN 4G when boxes did not pass design qualification tests; issued one approval certificate for two different package designs; failed to mark UN4G box with name and address or registered symbol of package certifier. [178.601(d), 178.603(a), 107.404(c), 107.404(a)(3), 178.503(a)(8)] Case No. 94-156-PC-CE | \$4,000 |
| JEFFERSON SMURFIT CORP (Fiberboard Box Manufacturer) | Certified boxes as DOT 12B when inner flaps did not butt and fill-in pieces or pads were not included. [178.205-14(a), 178.205-14(b)] Case No. 94-22-BM-CE | \$3,000 |
| JONES CHEMICALS INC (Cylinder Retester/Shipper) | Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of visual reinspection; certified a 106A500X ton tank without performing the required tests. [173.34(e)(3), 173.34(e)(5), 173.31(d)(3)] Case No. 94-229-CRS-SW | \$6,700 |

| JORGENSEN & COMPANY (Cylinder Retester) | Failed to calculate wall stress when marking a cylinder with a "+" plus sign. [173.302(c)] Case No. 94-02-CR-WE | \$3,600 |
|---|--|----------|
| KEN-MAR FIRE EXTINGUISHER COMPANY INC (Cylinder Retester) | Performed retesting with inaccurate equipment; marked cylinders with "+" mark without determining wall stress. [173.34(e)(3), 173.302(c)(3), 173.302(c)(5)] Case No. 93-17-CR-EA | \$5,800 |
| KENNEL VACCINE SUPPLY INC (Shipper) | Offered flammable liquid in unauthorized nonspecification packaging; affixed warning label to the package that did not comply with size requirements. [173.125(a), 173.202(b) 172.407(c)] Case No. 93-267-SB-CE | \$3,023 |
| KESCO INC (Shipper) | Offered an unapproved explosive for transportation; failed to mark the package with the proper ID number of the material; failed to mark the approval number on the package; failed to include the packing group and ID number on shipping paper. [173.56(b), 172.301(a), 173.320(a), 172.202(a), 172.202(a)(3)] Case No. 93-274-SE-EA | \$11,080 |
| KIRCHNER FIRE EXTINGUISHERS INC (Cylinder Retester) | Retested a cylinder when test pressure and specification marks could not be determined due to illegible markings; failed to maintain accurate records. [173.34(e)(1)(ii), 173.34(c), 173.34(e)(5)] Case No. 92-125-CR-CE | \$3,300 |
| KOCH INDUSTRIES INC (Shipper) | Offered flammable liquid for transportation in nonspecification packagings under the terms of an exemption that had expired. [173.119(a)] Case No. 94-145-EXR. | \$2,900 |
| KUTOL PRODUCTS COMPANY INC (Shipper) | Offered ethanol solutions, flammable liquid, in unauthorized packaging. [173.125(a), 173.202(a)] Case No. 94-49-SB-CE | \$2,900 |
| L H KELLOGG CHEMICAL CO INC D/B/A/KELCO SUPPLY (Shipper) | Offered methanol in nonspecification packaging. [173.119(b)] Case No. 95-164-SB-CE | \$5,540 |
| LANTIS PRODUCTIONS INC (Shipper) | Offered for transportation and transported an unapproved explosive device. [173.51(b), 173.86(b)] Case No. 91-106-SE | \$5,000 |
| LAVERTY SUPPLY INC (Shipper) | Offered and transported blasting agents in nonspecification bulk packagings under the terms of an exemption that had expired. [173.114a(i)] Case No. 91-92-EXR | \$1,200 |

| LEWISBURG CONTAINER CO INC (Fiberboard Box Manufacturer) | Manufactured, marked, and sold fiberboard boxes as meeting the DOT 12B specification which were not of sufficient strength; manufactured, marked and sold fiberboard boxes as meeting the DOT 12B specification when inner flaps did not butt and fill-in pieces or pads were not provided. [178.205-14(b), 178.205-16(a)] Case No. 93-261-BM-EA. | \$4,100 |
|---|--|---------|
| LILLY INDUSTRIES INC (Fiberboard Box Manufacturer/Shipper) | Certified boxes as UN 4G without conducting design qualification testing; failed to mark boxes properly. [178.601(d), 178.503(a)(5)(ii)] Case No. 94-236-BMS-CE | \$7,500 |
| LILYBLAD PETROLEUM INC (Shipper) | Offered gasoline, flammable liquid, in an unauthorized DOT packaging; failed to mark the technical name on the package; included additional unauthorized information in the shipping description on a shipping paper; failed to include the technical name in the shipping description. [173.119(a)(3), 172.301(c), 172.201(a)(4), 172.203(k)] Case No. 92-122-SD-WE | \$7,000 |
| LINCOLN BIG THREE INC (Cylinder Retester) | Failed to condemn a cylinder with permanent expansion exceeding 10% of total expansion. [173.34(e)(4)] Case No. 93-213-CR-HQ. | \$4,500 |
| LINCOLN WELDING SUPPLY INC (Cylinder Retester) | Performed hydrostatic testing with inaccurate equipment. [173.34(e)(3)] Case No. 94-243-CR-SW | \$3,440 |
| LINWELD INC (Cylinder Retester) | Failed to determine the minimum or average wall stress for cylinders marked with a "+" mark to indicate authorization for 10% overfill. [173.302(c)(3), 173.302(c)(5)] Case No. 93-124-CR-CE. | \$3,050 |
| LINWELD INC (Cylinder Retester) | Failed to condemn cylinders with permanent expansions exceeding 10% of total expansion; failed to provide employee function specific HM training. [173.34(e)(4), 172.702(b), 172.704(a)(2)] Case No. 94-53-CR-CE | \$7,125 |
| LIQUID AIR CORP (Cylinder Retester) | Conducted a second retest at the same pressure rather than 10% or 100 psi higher, whichever is lower, when accuracy of the system cannot be maintained due to equipment failure. [173.34(e)(3)] Case No. 93-145-CR-WE. | \$3,870 |
| LIQUID AIR CORP (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-273-CR-WE | \$6,020 |
| LIQUID CONTAINER LP (Plastic B ottle Manufacturer) | Certified DOT 2E bottles without performing required drop tests; failed to conduct required number of 3-per-1000 ambient drop tests on DOT 2E bottles. [178.24a-5(d)(1), 178.24a-5(b)] Case No. 94-78-PBM-CE | \$8,240 |

| LITHO PHOTO INC (Shipper) | Offered so dium hydroxide in nonspecification packaging; failed to mark packages with the proper shipping name and ID number; failed to provide a shipping paper for sodium hydroxide; failed to include orientation marks on package. [172.301(a), 173.249, 172.202(a)(1), 173.312(a)(2)] Case No. 93-65-SB-WE | \$2,500 |
|---|--|---------|
| LND INCORPORATED (Shipper) | Offering HM in unauthorized packaging under the terms of an exemption which had expired. [173.302] Case No. 94-46-EXR | \$2,610 |
| LONDON CHEMICAL COMPANY INC (Shipper) | Offered oxidizer for transportation in nonspecification packaging. [173.154(a)(12)] Case No. 93-90-SB-CE | \$3,825 |
| LONG ISLAND FIRE PREVENTION INC (Cylinder Retester) | Performed hydrostatic testing with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-15-CR-EA. | \$2,425 |
| LOVE BOX COMPANY INC (Fiberboard Box Manufacturer) | Failed to conduct periodic retests, including drop and stack tests on fiberboard boxes marked as UN 4G; failed to maintain test records. [178.601(e), 178.601(k)(2), 178.603, 178.606] Case No. 94-109-BM-CE | \$4,680 |
| LOVE BOX COMPANY INC (Fiberboard Box Manufacturer) | Failed to conduct design qualification tests, and maintain records of the tests on boxes marked UN4G; failed to mark UN4G with proper name and address or symbol. [178.601(d), 178.601(k)(1), 178.503(a)(8)] Case No. 94-31-BM-CE | \$7,320 |
| LOVE BOX COMPANY INC (Fiberboard Box Manufacturer) | Certified boxes as DOT-12B when inner flaps did not butt and fill-in-pieces or pads were not provided. [178.205-14(a)] Case No. 95-103-BM-CE | \$3,600 |
| LUND FIRE PRODUCTS COMPANY INC (Cylinder Retester) | Failed to hold current approval or RIN; performed hydrostatic retesting with inaccurate equipment; conducted a second test at the same pressure instead of 10% or 100 psi higher, whichever is lower, when the accuracy of the system could not be maintained due to equipment failure; failed to remark exemption aluminum cylinders as DOT 3AL; failed to properly mark RIN on cylinders; failed to include evidence of visual inspection on records. [173.34(e)(1)(i), 173.34(e)(3), 173.34(e)(3), 173.23(c), 173.34(e)(6), 173.34(e)(1)(ii), 173.34(e)(5)] Case No. 93-12-CR-EA. | \$7,000 |
| LYNCH'S FIRE PROTECTION INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuarcy of the system could not be maintained due to equipment failure. [173.34(e)(3), 173.34(e)(3)] Case No. 93-138-CR-CE | \$4,815 |

| M & S FIRE AND SAFETY EQUIPMENT CO INC (Cylinder Retester) | Performed hydrostatic retesting on DOT cylinders with inaccurate equipment. [173.34(e)(3)] Case No. 94-154-CR-CE | \$3,900 |
|---|---|----------|
| MADISON RECHARGING SERVICE INC (Cylinder Retester) | Failed to hold an approval or current RIN (RIN); failed to condemn cylinders with permanent expansion exceeding 10% of total expansion. [173.34(e)(1)(i), 173.34(e)(4)] Case No. 93-263-CR-CE | \$7,225 |
| MAINE OXY- ACETYLENE SUPPLY COMPANY INC (Cylinder Retester) | Failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; failed to maintain test pressure for 30 seconds to secure complete expansion of the cylinder; performed hydrostatic retesting with inaccurate equipment; failed to determine the minimum or average wall stress for cylinders marked with"+" to indicate authorization of 10% overfill; failed to remark exemption aluminum cylinders 3AL; failed to maintain accurate records of reinspection and retest. [173.34(e)(4), 173.34(e)(3), 173.34(e)(3), 173.302(c)(3), 173.302(c)(5) 173.23(c), 173.34(e)(5)] Case No. 93-80-CR-EA | \$16,110 |
| MALLINCKRODT MEDICAL INC (Shipper) | Failed to provide employee HM training. [172.702] Case No. 95-140-TRN-HQ | \$2,400 |
| MARATHON CARBONIC DIVISION OF GENERAL PARTS INC (Cylinder Retester) | Certified cylinders with inaccurate equipment; failed to hold test pressure for at least 30 seconds to secure complete expansion of the cylinder. [173.34(e)(3), 173.34(e)(3)] Case No. 94-87-CR-CE | \$6,640 |
| MARK PACKAGING INC (Fiberboard Box Manufacturer) | Certified boxes as DOT-12B when inner flaps did not butt and fill-in pieces or pads were not included; certified boxes as DOT12B which were constructed of fiberboard of insufficient strength; failed to mark boxes with name and address or registered symbol. [178.205-14, 178.205-18(a)(2)] Case No. 94-282-BM-CE | \$6,150 |
| MARTEL L GUAY & SONS INC (Cylinder Retester) | Failed to condemn DOT-E 7277 cylinders when permanent expansion exceeded maximum allowable limits; failed to conduct a complete visual examination; conducted testing with equipment not calibrated to 1% accuracy; failed to maintain accurate records of reinspection and retest. [173.34(e)(4), 173.34(e)(1), 173.34(e)(3), 173.34(e)(5)] Case No. 93-115-CR-EA | \$11,750 |
| MARYLAND FIRE EQUIPMENT CORP (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-112-CR-HQ. | \$3,600 |

| MARYLAND STATE MANUFACTURING COMPANY INC (Shipper) | Offered unapproved explosive devices for transportation. [173.86(b), 173.86(b), 173.86(j)(3)] Case No. 92-76-SE-HQ | \$6,000 |
|--|---|----------|
| MASTER INDUSTRIES INC (Fiber Drum Manufacturer) | Failed to mark UN1G package with the address of the manufacturer or registered symbol; failed to train HM employees. [178.503(a)(8), 172.702(a)] Case No. 95-117-FDM-CE | \$2,030 |
| MASTER PROTECTION CORP (Cylinder Retester) | Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 94-06-CR-WE | \$8,625 |
| MATHESON GAS PRODUCTS INC (Cylinder Retester) | Certified cylinders without performing test at minimum test pressure; failed to maintain accurate records of reinspection; failed to maintain a record of average daily compression for filling helium; failed to include the proper shipping name on a shipping paper for class 2.1 material. [173.34(e), 173.34(e)(10), 173.302(e), 172.202(a)(1)] Case No. 94-242-CR-SW | \$11,450 |
| MAX BURTON ENTERPRISES INC (Shipper) | Offered butane in nonspecification packagings; failed to provide the HM shipping description first, in contrasting color, or in conjunction with an "X" in an HM column on the shipping paper; failed to include the proper shipping name on the shipping paper; failed to provide a 24-hour emergency response telephone number on the shipping paper. [173.304(d)(3), 172.201(a)(1), 172.202(a), 172.604(a)] Case No. 93-123-SC-W E | \$5,400 |
| MCCANN BARREL COMPANY INC (Drum Reconditioner) | Failed to conduct periodic drop and hydrostatic tests on remanufactured DOT 17E drums. [178.116-12(a)] Case No. 94-50-DR-CE | \$4,635 |
| MCCOOK DRUM AND BARREL COMPANY INC (Drum Reconditioner) | Failed to conduct periodic drop and hydrostatic tests on remanufactured DOT 17E drums; failed to properly mark reconditioned DOT17H drums. [178.116-12(a)(1), 173.28(m)(3)] Case No. 94-27-DR-CE | \$5,485 |
| MESSER GRESHEIM INDUSTRIES INC D/B/A MG INDUSTRIES (Cylinder Retester) | Failed to determine the minimum or average wall stress for cylinders marked with "+" mark to indicate authorization for 10% overfill. [171.2(c)] Case No. 93-150-CR-HQ | \$2,500 |

| MEYER STEEL DRUM INC (Drum Manufacturer) | Failed to conduct periodic drop and hydro static tests on drums marked DOT 17E and DOT 17H; failed to conduct design qualification tests for UN1A1 and UN1A2 drums; failed to conduct on-line leakage tests for DOT17E and 17H drums; failed to properly mark UN1A1 and 1A2 drums. [178.116-12(a)(1), 178.116-12(a)(2), 178.118-12(a)(1), 178.118-12(a)(2), 178.601(d), 178.116-13(a), 178.118-13(a), 178.503(a)(6), 178.503(a)(8)] Case No. 93-33-DM-CE | \$9,000 |
|---|---|---------|
| MEYER STEEL DRUM INC (Drum Reconditioner) | Certified nonspecification steel drums as reconditioned DOT17E/17H; failed to test DOT 17C drums to a minimum air pressure of 15 psi. [173.28(o), 173.28(m)(2)] Case No. 94-03-DR-CE | \$4,500 |
| MID-AMERICA STEEL DRUM COMPANY INC (Drum Rec onditioner) | Failed to conduct periodic drop and hydrostatic tests on remanufactured DOT 17H drums. [178.118-12(a)] Case No. 94-51-DR-CE | \$2,500 |
| MIDLAND CONTAINER CORP (Fiberboard Box Manufacturer) | Certified fiberboard boxes as DOT12B when inner flaps did not butt and fill-in pieces or pads were not included; certified boxes as DOT 12B when constructed of fiberboard of insufficient strength; failed to conduct design qualification tests and maintain records of the tests on UN4G packages; failed to conduct training for HM employees. [178.205-14(a), 178.205-16(a), 178.601(d), 172.702] Case No. 94-79-BM-CE | \$9,600 |
| MILWAUKEE SOLVENTS & CHEMICALS CORP (Shipper) | Offered hexane, a flammable liquid with a flash point below 20 degrees Fahrenheit, in unauthorized DOT packaging. [173.119(a)(3)] Case No. 90-157-SD | \$1,800 |
| MINERAL RESEARCH & DEVELOPMENT CORP (Shipper) | Offered zinc chloride solution, corrosive, in nonspecification packaging; failed to mark package with proper shipping name and ID number. [172.301(a), 173.245(a)] Case No. 93-05-SP-HQ | \$4,800 |
| MINNESOTA MINING & MANUFACTURING COMPANY (Box Manufacturer/Shipper) | Certified boxes as UN 4G without conditioning them be fore conducting design qualification tests; failed to maintain records of periodic testing. [178.601(d), 178.602(d), 178.601(e), 178.601(k)(2)] Case No. 94-161-BM-CE | \$8,880 |
| MINNTECH CORP (Shipper) | Offered HM without marking the proper shipping name and ID number on the package; offered oxidizer, corrosive liquid nos in DOT specification packaging not authorized for air transportation and in nonspecification inner packages; failed to include the proper shipping description on the shipping paper; failed to provide a shipper's certification on a shipping paper. [172.301(a), 173.245(a)(12), 172.202(a)(1)-(3), 172.204(a)] Case No. 92-83-SB | \$6,000 |

| MINNTECH CORP (Shipper) | Failed to register with RSPA after offering for transportation 5,000 lbs or more of HM of 1 hazard class in non-bulk packaging in a single shipment requiring placarding. [107.601(e)] Case No. 95-158-REG-CE | \$315 |
|---|---|----------|
| MOORE DRUMS INC (Drum Reconditioner) | Failed to conduct required drop and hydrostatic tests on remanufactured steel drums marked DOT 17H. [178.118-12(a)] Case No. 94-54-DR-HQ | \$3,800 |
| MORTON INTERNATIONAL INC (Fiberboard Box Manufacturer/Shipper) | Certified fiberboard boxes as UN 4G without conducting design qualification tests; failed to conduct periodic retests on UN 4G packages. [178.601(d), 178.601(e)] Case No. 94-104-BMS-CE | \$11,000 |
| MORTON INTERNATIONAL INC (Shipper) | Offered boxes of Class C power devices in nonspecification packaging; failed to properly described HM on the shipping papers. [173.102, 172.202(a)(1), 172.202(a)(2)] Case No. 90-82-SB | \$1,500 |
| MYERS CONTAINER CORP (Drum Manufacturer) | Manufactured, marked, certified, and sold drums as meeting the UN1A2/Y1.4/260 standard without performing design qualification tests. [178.601(d)] Case No. 93-225-DM-WE | \$7,900 |
| MYERS CONTAINER CORP (Drum Reconditioner) | Failed to conduct periodic drop and hydrostatic tests on remanufactured DOT 17H drums. [178.118-12(a)] Case No. 93-182-DR-W E | \$3,440 |
| NATIONAL FIRE EXTINGUISHER CO INC (Cylinder Retester) | Performed retesting with inaccurate equipment; failed to remark aluminum exemption cylinders as DOT 3AL; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.23(c), 173.34(e)(5)] Case No. 93-151-CR-EA | \$5,425 |
| NATIONAL FIRE PROTECTION COMPANY (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to perform external visual inspection; failed to remark exemption aluminum cylinders as 3AL. [173.34(e)(3), 173.34(e)(1), 173.23(c)] Case No. 93-198-CR-EA | \$7,450 |
| NATIONAL WELDERS SUPPLY COMPANY INC (Cylinder Retester/Shipper) | Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to determine the minimum or average wall stress for cylinders marked with "+" mark to indicate authorization for 10% overfill; offered oxygen/nitrogen without verifying daily compression. [173.34(e)(3), 173.302(c)(3), 173.302(e)] Case No. 93-196-CR-EA | \$6,900 |
| NFC CO INC D/B/A/ SUBURBAN CARBONIC INC (Shipper) | Failed to register with RSPA after offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding. [107.601(e)] Case No. 95-110-REG-CE | \$1,000 |

| NILES CHEMICAL PAINT COMPANY (Box Manufacturer/Shipper) | Certified boxes as UN 4G when periodic drop and stacking tests were not conducted and records were not maintained; failed to mark UN 4G boxes with the date of manufacture. [178.601(e), 178.601(k)(2), 178.503(a)(6)] Case No. 94-259-BMS-CE | \$6,510 |
|--|--|----------|
| NORAC COMPANY THE INC (Shipper) | Offered organic peroxide in unauthorized packagings. [173.225(d)(2), 173.22(a)(2)] Case No. 93-251-SP-CE | \$4,120 |
| NORTHEAST AIRGAS INC (Cylinder Retester) | Certified cylinders as retested without holding an approval or current RIN; failed to maintain accurate records of reinspection and retest; performed hydrostatic retesting with in accurate equipment. [173.34(e)(1)(i), 173.34(e)(5), 173.34(e)(3)] Case No.93-186-CR-EA | \$5,500 |
| NORTHEAST BOX COMPANY (Fiberboard Box Manufacturer) | Certified boxes as DOT 12H when the minimum strength requirement was not met; failed to perform required testing on boxes marked DOT 12H. [178.209-11(a), 178.209-14, 178.209-15, 178.209-16] Case No. 93-191-BM-EA. | \$6,900 |
| NOSTALGIA PYROTECHNICS (Shipper) | Offered new explosive which had not been examined, classed, and approved for transportation; offered Class B and C explosives in nonspecification packaging; offered a leaking explosive for transportation. [173.51(b), 173.86(b), 173.91, 173.108, 173.51(e)] Case No. 92-68-SE-CE | \$9,360 |
| NUCLETRON CORP (Shipper) | Provided an emergency response phone number for which the answering person was not knowledgeable regarding the material being offered. [172.604(a)(3)] Case No. 94-74-RMS-HQ. | \$3,600 |
| O'TOOLE AND NAPIER COURIERS INC (Shipper) | Accepted radioactive materials for transportation, when separation distances could not be met by driver; failed to maintain training records for HM employees; failed to provide emergency response information; failed to affix the proper hazard class label to the package. [177.842(b), 172.702(b), 172.602(c), 172.400] Case No. 94-98-RMS-HQ | \$11,750 |
| OFFICIAL FIRE EQUIPMENT INC (Cylinder Retester) | Failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; conducted a second retest at the same pressure instead of 10% or 100 psi, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to maintain accurate records or reinspection and retest. [173.34(e)(4), 173.34(e)(3), 173.34(e)(5)] Case No. 93-79-CR-EA | \$7,560 |
| P B & S CHEMICAL COMPANY INC (Cylinder Retester) | Failed to conduct hydrostatic retesting at minimum test pressure. [173.34(e)] Case No. 94-115-CR-CE | \$2,420 |

| P B & S CHEMICAL COMPANY INC (Shipper) | Offered flammable liquid in out-of-test DOT 57 portable tanks; offered oxidizing material in nonspecifiction packaging; failed to identify a hazardous substance on the shipping paper with the letters RQ; failed to include the proper shipping name on the shipping paper. [173.32(e)(1)(ii), 173.154(a)(9), 172.203(c)(2), 172.200(a)] Case No. 93-157-SPTD-CE | \$6,800 |
|--|---|---------|
| PACIFIC FIRE PROTECTION INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-220-CR-WE | \$3,655 |
| PACIFIC SCIENCES CORP (Shipper) | Offered ammonium hydroxide for transportation in nonspecification packaging. [173.245(a)] Case No. 92-102-SB-WE | \$2,200 |
| PAN-AM PLASTICS CORP (Plastic Bottle Manufacturer) | Failed to conduct periodic vibration testing on bottles marked DOT 2U; failed to properly mark DOT 2U bottles. [178.24-7(a)(3), 178.24-5(a)] Case No. 91-55-PLM | \$2,700 |
| PARAGON PACKAGING INC (Plastic Bottle Manufacturer) | Failed to conduct cold drop testing on DOT 2E bottles; failed to properly mark DOT 2E bottles. [178.24a-5(d)(2), 178.24a-5(c), 178.24a-6(a)] Case No. 91-138-PBM | \$2,500 |
| PARKS CORP (Shipper) | Offered acetone, naphtha, and denatured alcohol in quantities which exceeded the gross weight limit of the packaging; offered paint related material without marking the proper shipping name and ID number on the package. [173.119(a)(7), 178.205-16(a), 172.301(a)] Case No. 92-57-SB-HQ | \$5,500 |
| PENN PLASTIC INCORPORATED (Plastic Bottle Manufacturer) | Failed to conduct cold drop tests on DOT 2E bottles; failed to conduct drop tests on bottles marked DOT 2U in the outer specification packaging; Failed to conduct ambient drop tests on DOT 2E bottles from the required height; failed to mark DOT 2E bottles with the minimum wall thickness. [178.24a-5(c), 178.0-2(c), 178.24a-5(d)(1), 178.24a-6(a)(1)] Case No. 94-77-PBM-EA | \$1,000 |
| PERFORMANCE COATINGS INC (Shipper) | Offered flammable liquid in nonspecifiction packaging. [173.119(b), 173.202(a)] Case No. 93-247-SB-CE | \$3,450 |
| PHOENIX FIRE & SAFETY EQUIPMENT (Cylinder Retester) | Failed to hold an approval or current RIN. [173.34(e)(1)(i)] Case No. 93-169-CR-WE | \$2,500 |
| PIPE RECOVERY SYSTEMS INC (Cylinder Manufacturer) | Manufactured, represented, certified and sold cylinders as meeting the terms of an exemption, which were not manufactured in accordance with the requirements of the exemption. [DOT-E 7774 para. 7.a.] Case No. 94-178-CM-HQ | \$4,960 |

| PLASTIPAK PACKAGING INC (Plastic Bottle Manufacturer) | Failed to conduct periodic ambient and cold drop tests on exemption plastic bottles in the outer package. [178.19-7, DOT-E 6614 para. 7.a.iii.) Case No. 94-16-PBM-CE | \$4,300 |
|---|--|----------|
| PLYMOUTH PACKAGING INC (Fiberboard Box Manufacturer) | Certified boxes as DOT 12B when inner flaps did not butt and fill-in pieces or pads were not included. [178.205-14] Case No. 93-211-BM-CE. | \$6,000 |
| PRATT & LAMBERT INC (Shipper) | Offered paint for transportation in unauthorized nonspecification packaging. [173.242(c)] Case No. 94-105-SPT-CE | \$3,700 |
| PRESSURE PRODUCTS INTERNATIONAL (Cylinder Manufacturer) | Manufactured, marked, certified, and sold cylinders as meeting DOT specifications, when required test reports were not reviewed and signed by an independent inspection agency. [178.45-3, 178.45-17(e)] Case No. 93-104-CM-HQ | \$1,163 |
| PRESTON TRUCKING COMPANY INC (Nonvessel Operating Common Carrier) | Accepted poisonous liquid, corrosive, n.o.s. for water-borne transportation when the exemption under which it was being transported did not authorize transportation by water. [173.3(a)(3), 173.227] Case No. 93-93-NVO-HQ | \$2,700 |
| PRILLAMAN CHEMICAL CORP (Cylinder Retester) | Failed to condemn a cylinder with a permanent expansion exceeding 10% of total expansion; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to mark the RIN in square pattern; failed to test DOT cylinders to the minimum test pressure. [173.34(e)(4), 173.34(e)(3), 173.34(e)(1)(ii), 173.32(f)] Case No. 94-99-CR-EA | \$16,000 |
| PURITAN-BENNET CORP (Cylinder Retester) | Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when the accuracy of the system could not be maintained due to equipment failure; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-223-CR-EA | \$4,115 |
| QUEEN CITY FIRE EQUIPMENT INC (Cylinder Retester) | Marked a DOT 3HT cylinder without using low stress steel stamps; failed to mark DOT-E 7277 cylinders with the proper date and RIN; failed to maintain records of employee's HM training. [173.34(e)(13)(iv), 173.34(e)(6), 172.702(a)] Case No. 94-238-CR-EA | \$6,480 |
| QUINCY FIRE HEATING COMPANY (Cylinder Retester) | Failed to hold an approval or current RIN; failed to maintain records of reinspection and retest. [173.34(e)(1)(i), 173.34(e)(5)] Case No. 90-25-CR | \$2,500 |

| RED BALL OXYGEN COMPANY INC (Cylinder Retester/Shipper) | Performed hydrostatic retesting on inaccurate equipment; failed to mark DOT 3HT cylinders with low stress steel stamps; failed to record and maintain a 30-day verification of container pressure. [173.34(e)(3), 173.34(e)(13)(iv), 173.303(d)] Case No. 95-43-CRS-SW | \$7,700 |
|--|---|----------|
| REESE MEDICAL OXYGEN SUPPLY INC (Cylinder Retester) | Marked and certified cylinders as retested without actually performing the tests; failed to have a current approval and RIN. [173.34(e)(1)(ii), 173.34(e)(1)(i)] Case No. 92-36-CR-HQ | \$10,000 |
| RELIABLE CONTAINER INC (Fiberboard Box Manufacturer) | Certified packages as UN4G without conducting design qualification tests; certified fiberboard boxes as DOT 12A without conducting the required drop tests; failed to properly mark DOT 12A fiberboard boxes; failed to provide training for HM employees. [178.603, 178.210-10(a), 178.210-12(a)(1), 172.702(a)] Case No. 94-116-BM-CE | \$10,000 |
| REMEL LIMITED PARTN ERSHIP D/B/A/ REMEL (Box Manufacturer/Shipper) | Failed to mark UN packages with the proper UN certification number. [178.2(b), 178.2(d), 178.3(b)(3)] Case No. 94-102-BMS-CE | \$800 |
| RHEE BROS INC (Shipper) | Offered HM for transportation without a HM shipping paper; failed to mark the outer package with the proper shipping name and ID number; failed to provide training to HM employees. [172.200(a), 172.301(a)(1), 172.702(b)] Case No. 94-217-SC-HQ | \$8,425 |
| RICE WELDING SUPPLY COMPANY INC (Cylinder Retester) | Failed to determine average or maximum wall stress for cylinders being marked with a "+" sign to indicate 10% overfill authorization; failed to properly mark cylinders with the RIN. [173.302(c)(3), 173.34(e)(1)(ii), 173.34(e)(6)] Case No. 94-136-CR-SW | \$5,800 |
| RING CAN CORP (Plastic Bottle Manufacturer) | Failed to conduct ambient and cold drop tests on DOT 2U plastic containers inside prescribed outer containers. [178.24-7(a)(1), 178.24-7(a)(2)] Case No. 94-94-PLM-CE | \$6,400 |
| RIVIANA FOODS D/B/A RVR PACKAGE TESTING CENTER (Package Certifier) | Certified UN standard fiberboard boxes with a four-digit certification number which had already been assigned to a different packaging. [171.2(e), SA-890504]. Case No. 93-183-PC-CE. | \$1,200 |
| RIVIANA FOODS D/B/A RVR PACKAGE TESTING CENTER (Package Certifier) | Certified boxes as UN4GV when proper design qualification tests were not performed. [178.503(a)(2)] Case No. 95-96-PC-CE | \$3,500 |

| ROBERTS CHEMICAL COMPANY INC (Shipper) | Offered sodium cyanide in UN standard packaging which did not meet the packaging criteria for the material being shipped; failed to legibly sign the shipper's certification on a shipping paper. [173.211, 172.204(d)] Case No. 95-51-SP-EA | \$3,500 |
|---|--|----------|
| ROUSSEL BIO CORP D/B/A/ FOR D'S CHEMICAL INC (Shipper) | Offered poison B in nonspecification packaging; failed to mark package with upward orientation arrows; offered flammable liquid in nonspecification packaging; failed to establish that boxes marked DOT 12 A met test requirements. [173.346(a), 172.312(a)(2), 173.119(b), 173.346(a)(26)] Case No. 92-101-SB-WE | \$9,500 |
| ROYAL CARBO CORP (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to perform complete internal and external inspection; failed to maintain accurate records of retest and reinspection; failed to remark exemption aluminum cylinders as DOT 3AL. [173.34(e)(3), 173.34(e)(1), 173.34(e)(5), 173.23(c)] Case No. 92-124-CR-EA | \$7,150 |
| ROYAL CONTINENTAL BOX CO D/B/A ABC SHIPPING SUPPLY (Box Manufacturer) | Certified boxes as UN4M without performing design qualification tests; failed to properly mark packages to indicate construction material; failed to mark year of manufacture. [178.601(d), 178.503(a)(2)] Case No. 94-73-BM-CE | \$6,720 |
| RUSSELL-STANLEY CORP (Plastic Drum Manufacturer) | Failed to maintain test records for drums marked DOT 34; failed to conduct the production leakproofness tests on UN1H1 drums. [178.19-7(d), 178.604(e)] Case No. 94-18-DM-EA | \$4,000 |
| RUSSELL-STANLEY CORP (Steel Drum Manufacturer) | Failed to conduct periodic drop and hydrostatic tests on drums marked 5B, 17H, 17C; failed to conduct design qualification tests on drums marked UN 1A1 and 1A2; certified an open head drum as a UN1A1. [178.82-13(a)(1), 178.82-13(a)(2), 178.118-12(a)(1), 178.118-12(a)(2), 178.115-12(a)(1), 178.115-12(a)(2), 178.603, 604, 178.605, 178.606, 178.503(a)(2), 178.504(a)(2)] Case No. 93-10-DM-CE | \$18,850 |
| SAFEGUARD FIRE AND SAFETY EQUIPMENT COMPANY INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to test cylinders to minimum test pressure; failed to hold an approval or current RIN. [173.34(e)(1), 173.34(e), 173.34(e)(1)(i)] Case No. 94-12-CR-EA | \$6,000 |
| SAVAGE INDUSTRIES INC (Shipper) | Offered explosives for transportation under the terms of an exemption that had expired. [173.62(a)] Case No. 94-273-EXR | \$2,900 |
| SAVOLITE CORP (Shipper) | Provided unauthorized additional information in the basic HM shipping descriptions on shipping papers; offered flammable liquid in unauthorized DOT specification packaging; offered hypochlorite solution in nonspecification packaging. [172.201(a)(4), 173.119(c), 173.203(a)] Case No. 94-14-SP-WE | \$6,900 |

| SCHUTZ CONTAINER SYSTEMS INC (Plastic Drum Manufacturer) | Certified plastic drums as UN1H1 without performing leakproofness tests. [178.604] Case No. 95-27-PDM-CE | \$3,700 |
|--|---|---------|
| SCHWEIZER FIRE PROTECTION COMPANY INC (Cylinder Retester) | Failed to condemn cylinders with permanent expansion exceeding 10% of total expansion. [173.34(e)(4)] Case No. 93-201-CR-EA | \$3,000 |
| SCOTT SPECIALTY GASES INC (Cylinder Manufacturer/Shipper) | Certified cylinders as DO T-39 and DO T-E 8990, when the cylinders did not meet those requirements; failed to include the exemption number on the shipping paper; failed to provide training to HM employees. [178.65-14(b), 172.203(a), 172.702(a), 172.702(b)] Case No. 95-35-CM-HQ | \$7,350 |
| SCOTT SPECIALTY GASES INC (Shipper) | Offered compressed gas under the terms of an expired exemption. [DOT-E 7835, 177.848] Case No. 94-146-EXR | \$1,600 |
| SCRANTON COOPERAGE INC (Drum Reconditioner) | Certified intermediate bulk containers without performing requalification tests at minimum test pressure. [173.32(f), DOT-E 9051] Case No. 94-85-DR-EA | \$4,000 |
| SEAMLESS CYLINDER INTERNATIONAL INC (Cylinder Manufacturer) | Certified 4B cylinders without conducting the hydrostatic, flattening, and physical tests. [178.50-14, 178.50-15, 178.50-16] Case No. 93-89-FCM-HQ | \$6,400 |
| SHEEHAN'S BOISE INC (Cylinder Retester) | Performed hydrostatic retesting on inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-244-CR-WE | \$4,000 |
| SHELL OIL COMPANY D/B/A SHELL CHEMICAL CO (Box Manufacturer/Shipper) | Represented and marked fiberboard boxes as meeting UN4G without conducting design qualification tests. [178.601(d), 178.2(b)] Case No. 93-207-SBM-CE | \$6,000 |
| SHELTON FIREWORKS INC (Shipper) | Failed to register with RSPA when offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding. [107.601(e)] Case No. 93-16-SE-CE | \$250 |
| SIERRA MONITOR CORP (Cylinder Manufacturer) | Failed to maintain inspectors reports for three years on cylinders marked DOT 39; failed to provide 24-hour emergency response telephone number on shipping paper. [178.65-15(a), 172.604(a)] Case No. 93-235-CM-HQ | \$4,100 |

| SLO AIR PRODUCTS INC (Cylinder Manufacturer) | Certified and offered cylinders as meeting DOT-E 6563 that were not manufactured in accordance with the exemption. [DOT-E 6563, Para. 7] Case No. 92-56-EX-HQ | \$3,000 |
|---|--|----------|
| SMURFIT PACKAGING CORP (Fiber Drum Manufacturer) | Manufactured, marked, certified, and sold drums as specification DOT-21 C fiber drums after October 1, 1994. [171.14(a)(6)] Case No. 95-120-FDM-CE | \$1,600 |
| SMURFIT PLASTIC PACKAGING INC (Plastic Drum Manufacturer) | Manufactured, marked and certified nonspecification polyethylene containers as meeting the requirements of an expired exemption. [171.2(c), DOT-E 8780] Case No. 93-140-EX-EA | \$2,900 |
| SOMMERFIELD WELDERS SUPPLY COMPANY INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to remark exemption aluminum cylinders as DOT 3AL. [173.34(e)(3), 173.34(e)(5), 173.23(c)] Case No. 93-139-CR-CE | \$8,000 |
| SONOCO PRODUCTS CO D/B/A SONOCO PLASTICS DRUM (Plastic Drum Manufacturer) | Certified drums as UN 1H1 without performing periodic testing; failed to perform production leakproofness tests at the required test pressure. [178.601(e), 178.604(b)(1), 178.604(e)(2)] Case No. 94-32-PDM-HQ | \$5,175 |
| SOUTH SHORE FIRE & SAFETY (Cylinder Retester) | Failed to retest cylinders at a minimum test pressure; performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest; failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; failed to meet the terms of DOT-E 7235. [173.34(e), 173.34(e)(3), 173.34(e)(5), 173.34(e)(4), DOT-E 7235] Case No. 93-113-CR-EA | \$18,300 |
| SOUTHWESTERN WELDING SUPPLY COMPANY INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; failed to maintain accurate records of reinspection and retest; charged and offered cylinders without verifying pressure. [173.34(e)(3), 173.34(e)(4), 173.34(e)(5), 173.302(e)] Case No. 95-159-CR-SW | \$13,365 |
| SPACE AGE MANUFACTURING COMPANY INC (Shipper) | Offered an unapproved explosive device for transportation. [173.56(b)] Case No. 94-37-SE-HQ | \$7,000 |

| SPARTAN CHEMICAL COMPANY INC (Shipper) | Offered sodium hydroxide in nonspecification packaging; offered corrosive liquid in nonspecification packaging. [173.245(a), 173.249(a)] Case No. 94-48-SB-CE | \$4,500 |
|---|---|----------|
| SPARTENBURG STEEL PRODUCTS INC (Steel Drum Manufacturer) | Failed to retain periodic test samples for DOT 5C; failed to conduct design qualification testing on the required number of UN1A1 drums; manufactured DOT 5C drums without the required rolling hoops; marked DOT 5C drums with an incorrect gauge marking. [178.83-13(a), 178.601(c)(1), 178.83-7(a), 178.83-11(a)(4)] Case No. 93-227-DM-EA | \$12,500 |
| SPECTROWAX CORP (Shipper) | Offered compound cleaning liquid in nonspecification packaging; failed to mark the proper shipping name and ID number on the package; failed to sign the shipper's certification on the shipping paper. [173.245(a), 173.203(a), 172.301(a), 172.204(d)] Case No. 93-188-SB-EA | \$6,600 |
| STANDARD COATING CORP (Shipper) | Offered flammable liquids in unauthorized DOT packaging; offered a flammable liquid with a flash point above 73 degrees Fahrenheit in nonspecification packaging without marking the package with an indication of the flash point; provided additional unauthorized information in the HM shipping description on a shipping paper. [173.119(b), 173.118(b), 172.201(a)(4)] Case No. 93-09-SP-EA | \$5,600 |
| STARLIGHT NAIL SUPPLIES INC (Shipper) | Offered acetone, flammable liquid, in nonspecifiction packaging; failed to mark packages with the proper shipping name and ID number. [173.119(a), 172.301(a)] Case No. 93-272-SB-WE | \$5,400 |
| STATE LINE FIRE & SAFETY INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest; failed to condemn cylinders with permanent expansion exceeding 5% and 10% of total expansion. [173.34(e)(3), 173.34(e)(5), 173.34(e)(4)] Case No. 93-114-CR-EA | \$10,600 |
| STEELCRETE COMPANY INC (Plastic Bottle Manufacturer) | Failed to conduct drop tests in outside containers on exemption plastic bottles every four months after start of production; failed to drop test exemption bottles every two hours or every 2,500 bottles; failed to include the exemption number on the shipping paper. [178.19-7, DOT-E 6614 para. 7.a., 172.203(a)] Case No. 94-15-PBM-CE | \$12,530 |
| SUMMIT SCREEN INKS C/O FLINT INK CORP (Box Manufacturer/Shipper) | Failed to conduct periodic requalification tests and maintain records on boxes marked UN 4G; marked UN 4G boxes with the incorrect year of manufacture. [178.601(k)(2), 178.601(e), 178.503(a)(6)] Case No. 94-106-BMS-CE | \$5,700 |

| SUPERIOR WELDING SUPPLY COMPANY INC (Cylinder Retester) | Performed hydrostatic retests on inaccurate equipment. [173.34(e)(3)] Case No. 94-108-CR-CE | \$4,000 |
|--|---|----------|
| SUSPA INC (Shipper) | Offered HM for transportation under the terms of an expired exemption. [173.306(f)(2)(iii)] Case No. 95-72-EXR | \$2,900 |
| SYFLO COMPANY (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment; failed to determine the minimum or average wall stress for cylinders marked with "+" mark to indicate authorization for 10% overfill; marked RIN in the improper sequence; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.302(c)(3), 173.34(e)(6), 173.34(e)(6)] Case No. 93-45-CR-CE | \$6,580 |
| SYNDER INDUSTRIES INC (Portable Tank/Drum Manufacturer) | Certified plastic DOT-E 10918 exemption portable tanks when periodic drop tests were not conducted; failed to conduct design qualification tests and periodic requalification tests on various UN 1H1 drums; failed to maintain records of design qualification tests; failed to train to HM employees. [DOT-E 10918 para. 7.b., 178.601(d), 178.603(a), 178.601(k)(1), 178.601(k)(2), 172.702(b)] Case No. 94-223-PTDM-CE | \$10,550 |
| SYSTRON-DONNER CORP (Exemption Cylinder Manufacturer/Shipper) | Manufactured DOT-E 7477 cylinders with unauthorized parts; offered bromotrifluoromethane for transportation in unauthorized cylinders; failed to maintain reports on DOT-E 7477 cylinders; failed to indicate the exemption number on the shipping paper; failed to describe a HM with its proper shipping name on a shipping paper. [Exemption DOT-E 7477, para. 7.a.4., 173.304(a), Exemption DOT-E 7477, para. 8.e., 172.203(a), 172.202(a), 173.306(c)] Case No. 93-36-ECM-HQ | \$10,540 |
| T H COCHRANE LABORATORIES INC (Independent Inspection Agency) | Certified and marked DOT-E 7277 cylinders with additional information affecting the required service pressure markings. [173.34(c)(1)] Case No. 94-142-IIA-HQ | \$2,500 |
| TAYLOR'S FIRE CONTROL (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-106-CR-HQ | \$2,900 |
| TEXBERRY CONTAINER CORP (Plastic Bottle Manufacturer) | Failed to perform periodic ambient, cold drop, and vibration testing on DOT 2U containers in prescribed outer packagings; failed to mark rated capacity on DOT 2U containers. [178.24-7(a)(1)-(3), 178.24-5(a)(4)] Case No. 93-13-PLM-CE | \$7,960 |

| THATCHER COMPANY INC (Shipper) | Offered compound cleaning liquid in nonspecification packaging; failed to include the proper shipping name on the shipping paper; offered a corrosive liquid in nonspecification packaging; failed to mark the technical name of a HM on the package. [173.249, 172.202(a)(1)-(3), 173.245(a), 172.301(c), 172.203(k)(3)] Case No. 93-173-SP-WE | \$7,100 |
|---|--|---------|
| THE NDL ORGANIZATION INC (Shipper) | Failed to mark packages of radioactive materials with the proper shipping name. [173.301(a)] Case No. 94-97-RMS-HQ | \$800 |
| THEOCHEM LABORATORIES (Shipper) | Offered compound cleaning liquid, corrosive material, in nonspecification packaging. [173.256] Case No. 93-07-SP-HQ | \$2,850 |
| THEOCHEM LABORATORIES INC (Shipper) | Offered compound cleaning liquid in nonspecification packaging; failed to sign shipper's certification on shipping paper. [173.256, 172.204(d)(1)] Case No. 91-144-SB | \$3,200 |
| THEOCHEM LABORATORIES INC (Shipper) | Offered flammable liquid in nonspecification packaging; offered a corrosive, poisonous material without removing the hazard class from subsidiary hazard label. [173.119(b), 172.402(b)] Case No. 94-231-SP-EA | \$5,520 |
| TIOGA COATINGS CORP (Shipper) | Offered paint in nonspecification and out-of-test DOT 57 portable tanks. [173.128(a)(3), 173.242(c)] Case No. 94-71-SPT-CE | \$2,250 |
| TOMCO CHEMICALS (Shipper) | Offered acetone and acetic acid in nonspecification packaging; failed to provide employee HM training; failed to include a 24-hour emergency response telephone number on the shipping paper; included additional unauthorized information before the basic HM shipping description on the shipping paper; failed to sign the shipper's certification. [173.119(a), 172.702(b), 172.604(a)(2), 172.201(a)(4), 172.204(d)] Case No. 95-135-SBP-SW | \$8,170 |
| TRAK AUTO CORP (Shipper) | Offered batteries, wet, filled with acid, without labeling, marking, and in nonspecification packaging. [172.301(a), 172.400(a), 173.159(a)] Case No. 93-147-BAT-HQ | \$7,000 |
| TRANS GULF INDUSTRIES INC (Shipper) | Offered xylene in unauthorized DOT packaging; included additional unauthorized information in the HM shipping description on a shipping paper; failed to provide a 24-hour emergency response telephone number on a shipping paper. [173.119(c), 173.119(d), 172.201(a)(4), 172.201(d)] Case No. 92-129-SP-WE | \$3,200 |

| TRI CONTAINERS INC (Steel Drum Manufacturer) | Failed to conduct drop and hydrostatic tests on drums marked DOT 17E and 17H; failed to conduct the proper on-line leakage test; failed to mark drums with proper gauge markings; failed to mark drums with the name and address or registered symbol of the manufacturer. [178.116-12(a)(1), 178.116-12(a)(2), 178.118-12(a)(1), 178.118-12(a)(2), 178.116-13, 178.116-10(a)(4), 178.116-10(a)(3), 178.116-6] Case No. 90-109-DM | \$9,100 |
|--|---|----------|
| UNION CAMP CORP (Bag Manufacturer) | Manufactured, marked, certified, and sold bags as meeting the UN 5M2 standard without conducting design qualification tests; failed to properly mark UN 5M2 bags with the correct performance standard. [178.601, 178.503(a)(3)] Case No. 94-84-BGM-EA | \$7,600 |
| UNITED INDUSTRIES INC (Cylinder Retester) | Failed to perform hydrostatic retest at minimum test pressure; failed to properly mark RIN on cylinders; performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e), 173.34(e)(6), 173.34(e)(3), 173.34(e)(5)] Case No. 91-134-CR | \$2,500 |
| UNITED STATES WELDING INC (Cylinder Retester) | Performed hydrostatic retests with inaccurate equipment; failed to determine the minimum or average wall stress for cylinders marked with "+" mark to indicate authorization for 10% overfill; failed to maintain adequate records of reinspection and retest; failed to properly mark RIN on cylinders. [173.34(e)(3), 173.302(c)(5), 173.34(e)(5), 173.34(e)(6)] Case No. 92-13-CR | \$6,570 |
| UNITED WAREHOUSE INC (Shipper) | Offered bromotrifluoromethane in DOT 110A800W ton tanks which had not been visually inspected within five years as required; provided unauthorized additional information in the HM shipping description on a shipping paper. [173.31(d)(9), 173.314(c), 172.201(a)(4)] Case No. 93-30-STT-WE | \$3,500 |
| UNIVERSITY OF NORTH CAROLINA (Shipper) | Offered radioactive material in nonspecification packaging; failed to mark the proper shipping name and ID number on the package; failed to properly label a package of radioactive material; failed to provide the proper shipping name and ID number on shipping papers. [173.415(a), 172.202(a), 172.301(a)(1), 172.400(a)(1)] Case No. 95-09-RMS-HQ | \$5,920 |
| VAN LEER CONTAINERS INC (Steel Drum Manufacturer) | Failed to conduct periodic drop and hydrostatic tests on DOT 17E and DOT17H drums; certified steel drums as UN1A1 and UN1A2 when design qualification tests were not conducted. [178.116-12(a), 178.118-12(a), 178.601(d)] Case No. 94-158-DM-CE | \$12,500 |
| VAN WATERS & ROGERS INC (Shipper) | Offered toluene in non specification packaging. [173.119(b)] Case No. 93-208-SB-WE | \$8,100 |

| VAN WATERS & ROGERS INC (Shipper) | Offered chloropicrin liquid in nonspecification packaging; failed to label packages of HM; failed to mark packages for proper orientation; failed to mark the proper shipping name and ID number on packages of HM. [173.357(a), 172.400(a), 172.312(a)(2), 172.301(a)] Case No. 93-68-SB-WE | \$15,175 |
|---|---|----------|
| VARNCO HOLDINGS INC (Shipper) | Failed to register with RSPA after offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding; failed to provide the proper shipping description on a shipping papers. [107.608(a)(2), 107.620, 172.202(a), 172.203(k)(3)] Case No. 94-166-SB-CE | \$1,050 |
| VIDEOJET SYSTEMS INTERNATIONAL INC (Fiberboard Box Manufacturer/Shipper) | Certified UN 4G boxes when design qualification tests were not conducted. [178.601(d)] Case No. 94-110-BMS-CE | \$6,885 |
| WAXIE SANITARY SUPPLY (Shipper) | Offered corrosive material in nonspecification packaging. [173.245(a), 173.203(a)] Case No. 93-229-SP-WE | \$1,825 |
| WELDERS SUPPLY CO - BELOIT INC (Cylinder Retester) | Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-270-CR-CE. | \$3,225 |
| WELDERS SUPPLY CO OF LOUISVILLE INC (Shipper) | Failed to register with RSPA after offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding. [107.608(a)] Case No. 95-142-REG-CE | \$250 |
| WESCHEM INC (Shipper) | Offered potassium hydroxide solution for transportation in nonspecification packaging; failed to mark the proper shipping name on the package. [173.249(a), 172.301(a)] Case No. 92-104-SB-WE | \$1,500 |
| WEST AGRO INC (Shipper) | Offered hydriodic acid, solution in DOT-E10090 containers that have not been retested as specified in the exemption; failed to indicate exemption number on the shipping paper. [173.32(f), DOT-E10090 para. 7.g., 172.203(a)] Case No. 93-232-SPT-CE | \$4,160 |
| WESTAR CORP (Carrier) | Failed to submit a DOT 5800.1 report within 15 days following an unintentional release of a HM. [171.16] Case No. 89-52-HMI | \$1,264 |
| WESTERN AUTO SUPPLY COMPANY (Shipper) | Failed to mark, label, and properly package batteries, wet filled with acid. [172.301(a), 172.400(a), 173.159(a)] Case No. 93-148-BAT-HQ | \$6,600 |

| WESTERN DRUM INC (Drum Manufacturer) | Manufactured, marked, certified, and sold open-head steel drums as meeting DOT 17H that could not pass the hydrostatic test; failed to conduct periodic drop and hydrostatic tests on DOT 17C, 17E and 17H drums; failed to mark the registration number on rings and closures of DOT 17H 55-gallon 18-gauge drums; failed to properly mark the gauge on DOT 17H drums. [178.118-12(a)(2), 178.115-12(a)(1), 178.115-12(a)(2), 178.118-6(a), 178.118-10(a)(4), 178.116-12(a)(1), 178.116-12(a)(2), 178.118-12(a)(1), 178.118-12(a)(2)] Case No. 91-102-DM | \$11,856 |
|--|---|----------|
| WESTERN FIRE & SAFETY COMPANY (Cylinder Retester) | Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure. [173.34(e)(3)] Case No. 92-27-CR | \$1,100 |
| WESTERN ZINC CORP (Shipper) | Offered water reactive solid n.o.s., a flammable solid, in unauthorized packaging, under the terms of an exemption which had expired. [173.154(a)] Case No. 92-132-EXR | \$3,031 |
| WESTVACO CORP (Fiberboard Box Manufacturer) | Failed to conduct drop tests on box es marked DOT 12A prior to initial use. [178.210-10(a), 178.210-10(b)] Case No. 94-42-BM-CE | \$4,000 |
| WEYERHAUSER PAPER COMPANY INC (Fiber Box Manufacturer) | Certified boxes as meeting DOT 12B when inner flaps did not butt and fill-in pieces or pads were not included; failed to mark the name and address or registered symbol of the manufacturer on DOT 12B boxes. [178.205-14(a), 178.0-2(a)-(c), 178.205-18(a)(2)] Case No. 94-163-BM-CE | \$5,280 |
| WICHITA FIRE EQUIPMENT (Cylinder Retester) | Failed to hold an approval or current RIN; conducted second retest at same pressure instead of 10% or 100 psi higher, which ever is lower, when accuracy of the system could not be maintained due to equipment failure.[173.34(e)(1)(i), 173.34(e)(3)]Case No. 91-32-CR | \$2,700 |
| WILSON PRODUCTS COMPRESSED GAS CO INC (Cylinder Retester) | Failed to remark exemption aluminum cylinders as DOT 3AL; failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; performed retesting with inaccurate equipment. [173.23(c), 173.34(e)(4), 173.34(e)(3)] Case No. 92-32-CR-EA | \$3,200 |
| WORLD LABORATORIES LTD (Shipp er) | Offered hydrochloric acid in non specification packaging; failed to mark package with the proper shipping name; failed to include the proper shipping name on the shipping paper, failed to provide a shipper's certification on the shipping paper; included additional unauthorized information in a HM shipping description on the shipping paper. [173.263(a), 173.202(a), 172.301(a), 172.202(a), 172.204(a), 172.201(a)(4)] Case No. 93-175-SB-WE | \$5,000 |

| WRIG (Ship | CO CORP per) | Offered corrosive materials in nonspecifiction packaging; failed to include the hazard class and ID number on the shipping paper; failed to provide a shipper's certification on the shipping paper; failed to include a 24-hour emergency response telephone number on the shipping paper; provided an incomplete hazard class on the shipping paper; provided the shipping description on the shipping paper in the wrong sequence. [173.245(a), 172.202(a)(2), 172.204(d), 172.201(d), 172.202(b)] Case No. 92-85-SB-HQ | \$4,600 |
|---------------|------------------------------|--|---------|
| | GHT BROTHERS (Shipper) | Failed to provide employee HM training; failed to register with RSPA when offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding; failed to provide the HM shipping description in the proper sequence on a shipping paper. [172.702, 107.608, 172.202(b)] Case No. 94-162-SC-CE | \$2,700 |
| | NG LOSIVES CORP orter) | Failed to inform a foreign shipper of the requirements of the HM Regulations that would apply to a shipment of HM imported into the United States. [171.12(a)] Case No. 92-09-IMP | \$2,700 |