

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II SAM NUNN ATLANTA FEDERAL CENTER 61 FORSYTH STREET SW SUITE 23T85 ATLANTA, GEORGIA 30303-8931

June 2, 2003

SAFEGUARDS INFORMATION

Mr. Dale E. Young, Vice President Crystal River Nuclear Plant (NA1B) Supervisor, Licensing & Regulatory Programs 15760 West Power Line Street Crystal River, FL 34428-6708 SAFEGUARDS INFORMATION REMOVED

SUBJECT: CRYSTAL RIVER UNIT 3 - NRC SAFEGUARDS INSPECTION REPORT 50-302/03-07

Dear Mr. Young:

On April 18, 2003, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at your Crystal River Nuclear Plant. The enclosed inspection report documents the inspection findings, which were discussed on April 18, 2003, with Mr. D. Roderick and other members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with an Order issued on February 25, 2002, which required your site to implement specific measures related to security of your facility. The inspection used Temporary Instruction 2515/148, "Inspection of Nuclear Reactor Safeguards Interim Compensatory Measures," to verify implementation of the Order as clarified in your response dated March 14, 2002. The inspection also reviewed other selected areas of the security program including performance indicators and behavioral observation/access authorization. Within these areas, the inspection consisted of selected examination of procedures and records, observation of activities, and interviews with personnel.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, without the enclosed Safeguards Information, will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

Should you have any questions concerning this letter, please contact us.

Sincerely,

2

/RA/

Anne T. Boland, Chief Plant Support Branch Division of Reactor Safety

Docket No. 50-302 License No. DPR-72

Enclosure: NRC Inspection Report 50-302/03-07

cc w/encl: See Page 3

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

cc w/Safeguards Information:

Daniel L. Roderick Director Site Operations Crystal River Nuclear Plant (NA2C) 15760 West Power Line Street Crystal River, FL 34428-6708

Jon A. Franke Plant General Manager Crystal River Nuclear Plant (NA2C) 15760 West Power Line Street Crystal River, FL 34428-6708

cc w/o Safeguards Information:

Richard L. Warden Manager Nuclear Assessment Crystal River Nuclear Plant (NA2C) 15760 West Power Line Street Crystal River, FL 34428-6708

Donald L. Taylor Manager Support Services Crystal River Nuclear Plant (NA2C) 15760 W. Power Line Street Crystal River, FL 34428-6708

R. Alexander Glenn
Associate General Counsel (MAC - BT15A)
Florida Power Corporation
P. O. Box 14042
St. Petersburg, FL 33733-4042

(Continued on Page 4)

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

FPC

<u>cc w/o Safeguards Information</u>: (continued) Attorney General Department of Legal Affairs The Capitol Tallahassee, FL 32304

William A. Passetti Bureau of Radiation Control Department of Health 2020 Capital Circle, SE, Bin #C21 Tallahassee, FL 32399-1741

Craig Fugate, Director Division of Emergency Preparedness Department of Community Affairs 2740 Centerview Drive Tallahassee, FL 32399-2100

Chairman Board of County Commissioners Citrus County 110 N. Apopka Avenue Inverness, FL 36250

Jim Mallay Framatome ANP 1911 North Ft. Myer Drive, Suite 705 Rosslyn, VA 22209

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

Distribution w/o Safeguards Information: J. Peralta, NSIR (encrypted copy w/SGI) B. Mozafari, NRR C. Evans (Part 72 Only) L. Slack, RII EICS RIDSNRRDIPMLIPB PUBLIC

OFFICE	RII:DRS		RII:DRS		RII:DRS		RII:DRS		NSIR		RII:DRP		RII:DRS	
SIGNATURE	JW		KD		LM		ATB for WS		BH for		JM		ATB	
NAME	WALLO		DAVIS		MILLER		SARTOR		PERALTA		MUNDAY		BOLAND	
DATE	06/02/03		05/30/03		05/30/03		06/02/03		06/02/03		05/30/03		06/02/03	
E-MAIL COPY?	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO
PUBLIC DOCUMENT	YES	NO												

OFFICIAL RECORD COPY DOCUMENT NAME: C:\ORPCheckout\FileNET\ML031540097.wpd

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

ENCLOSURE

U.S. NUCLEAR REGULATORY COMMISSION

REGION II

- Docket No.: 50-302
- License No.: DPR-72
- Report No.: 50-302/03-07
- Licensee: Florida Power Corporation
- Facility: Crystal River Unit 3
- Location: 15760 West Power Line Street Crystal River, FL 34428-6708
- Dates: April 14 -18, 2003
- Inspectors: Jon H. Wallo, Senior Physical Security Inspector Kenneth Davis, Physical Security Inspector William M. Sartor, Senior Emergency Preparedness Inspector Lee Miller, Senior Operator Licensing Examiner
- Approved By: Anne T. Boland, Chief Plant Support Branch Division of Reactor Safety

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

SUMMARY OF FINDINGS

IR 05000302/2003-003; Florida Power Corporation; 4/14-18/2003; Crystal River Unit 3; Temporary Instruction (TI) 2515/148; Verification of Compliance with Interim Compensatory Measures Order, IP 71130.02 Access Control and 71130.03 Response to Contingency Events.

The report covered an announced inspection by two regional physical security inspectors, an emergency preparedness inspector, and an operator licensing examiner. Two issues, the significance of which are to be determined, were identified. Pending further review, these issues are characterized as unresolved items. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 3, dated July 2000.

A. Inspector-Identified and Self-Revealing Findings

Cornerstone: Physical Security

- The inspectors identified an unresolved item concerning the licensee's implementation of Interim Compensatory Measure B.4.b of the February 25, 2002 Order. (Section V.B)
- The inspectors identified an unresolved item concerning the licensee's implementation of Interim Compensatory Measure B.5.b of the February 25, 2002 Order. (Section VI.B)
- B. <u>Licensee-Identified Violations</u>

None

DOCUMENT CONTAINS SAFEGUARDS INFORMATION