

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II

SAM NUNN ATLANTA FEDERAL CENTER 61 FORSYTH STREET SW SUITE 23T85 ATLANTA, GEORGIA 30303-8931

May 19, 2003

SAFEGUARDS INFORMATION

Florida Power and Light Company
ATTN: Mr. J. A. Stall, Senior Vice President
Nuclear and Chief Nuclear Officer
P. O. Box 14000
Juno Beach, FL 33408-0420

SAFEGUARDS INFORMATION REMOVED

SUBJECT:

TURKEY POINT NUCLEAR STATION SPECIAL INSPECTION

REPORT 50-250/2003-06 AND 50-251/2003-06

Dear Mr. Stall:

On April 4, 2003, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at your Turkey Point facility. The enclosed inspection report documents the inspection findings, which were discussed on April 4, 2003, with Mr. T. Jones and other members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with an Order issued on February 25, 2002, which required your site to implement specific measures related to security of your facility. The inspection used Temporary Instruction 2515/148, "Inspection of Nuclear Reactor Safeguards Interim Compensatory Measures," to verify implementation of the Order as clarified in your responses dated March 15, 2002; June 24, 2002; and September 3, 2002. Within these areas, the inspection consisted of selected examination of procedures and records, observation of activities, and interviews with personnel.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, without the enclosed Safeguards Information, will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

2

Should you have any questions concerning this letter, please contact us.

Sincerely,

/RA/

Anne T. Boland, Chief Plant Support Branch Division of Reactor Safety

Docket No. 50-250 and 50-251 License No. DPR-31 and DPR-41

Enclosure: NRC Inspection Report

50-250 and 50-251/2003-06

cc w/encl: See Page 3

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

cc w/Safeguards Information:

T. O. Jones Site Vice President Turkey Point Nuclear Plant Florida Power and Light Company 9760 SW 344th Street Florida City, FL 33035

cc w/o Safeguards Information:

Walter Parker Licensing Manager Turkey Point Nuclear Plant Florida Power and Light Company 9760 SW 344th Street Florida City, FL 33035

Don Mothena, Manager Nuclear Plant Support Services Florida Power & Light Company P. O. Box 14000 Juno Beach, FL 33408-0420

Rajiv S. Kundalkar Vice President - Nuclear Engineering Florida Power & Light Company P. O. Box 14000 Juno Beach, FL 33408-0420

M. S. Ross, Attorney Florida Power & Light P. O. Box 14000 Juno Beach, FL 33408-0420

Jim Reed Document Control Supervisor Florida Power & Light Company 9760 SW 344th Street Florida City, FL 33035

continued on Page 4

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

cc w/o Safeguards Information: (continued)

Attorney General
Department of Legal Affairs
The Capitol
Tallahassee, FL 32304

William A. Passetti Bureau of Radiation Control Department of Health 2020 Capital Circle SE, Bin #C21 Tallahassee, FL 32399-1741

County Manager Metropolitan Dade County 111 NW 1st Street, 29th Floor Miami, FL 33128

Craig Fugate, Director Division of Emergency Preparedness Department of Community Affairs 2740 Centerview Drive Tallahassee, FL 32399-2100

Curtis Ivy
City Manager of Homestead
Electronic Mail Distribution

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

Distribution w/o Safeguards Information:

E. Brown, NRR C. Evans (Part 72 Only) L. Slack, RII EICS RIDSNRRDIPMLIPB PUBLIC

OFFICE	RII:DRS		RII:DRS		RII:DRS		RII:DRP		NSIR		RII:DRP		RII:DRS	
SIGNATURE	ATB for JW		ATB for JE		ATB for KD		СР		BH for jp		JM		ATB	
NAME	WALLO		ENNIS		DAVIS		PATTERSON		PERALTA		MUNDAY		BOLAND	
DATE	5/15/03		5/15/03		5/15/03		5/19/03		5/15/03		5/15/03		5/19/03	
E-MAIL COPY?	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO
PUBLIC DOCUMENT	YES	NO												

5

OFFICIAL RECORD COPY DOCUMENT NAME: C:\ORPCheckout\FileNET\ML031390407.wpd

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

ENCLOSURE

U.S. NUCLEAR REGULATORY COMMISSION

REGION II

Docket No.: 50-250 and 50-251

License No.: DPR-31 and DPR-41

Report No.: 50-250 and 50-251/2003-06

Licensee: Florida Power and Light Company

Facility: Turkey Point Nuclear Station

Location: Florida City, FL

Dates: March 31 - April 4, 2003

Inspectors: Jon H. Wallo, Senior Physical Security Inspector

Jerry D. Ennis, Physical Security Inspector Kenneth Davis, Physical Security Inspector

James L. Kreh, Senior Emergency Preparedness Inspector

Charles S. Patterson, Senior Resident Inspector

Approved by: Anne T. Boland, Chief

Plant Support Branch Division of Reactor Safety

SAFEGUARDS INFORMATION

SUMMARY OF FINDINGS

IR 05000250/2003-006; IR 05000251/2003-006: Florida Power and Light Corporation; 3/31-4/4/2003; Turkey Point Nuclear Station, Units 3 and 4; Temporary Instruction (TI) 2515/148, Verification of Compliance with Interim Compensatory Measures Order.

The report covered an announced inspection by three regional physical security inspectors, an emergency preparedness inspector, and the Senior Resident Inspector. Three ICM-related unresolved items remain open pending further NRC review. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 3, dated July 2000.

A. <u>Inspector-Identified and Self-Revealing Findings</u>

Cornerstone: Physical Security

- An unresolved item concerning the licensee's implementation of Interim Compensatory Measure B.3.b of the February 25, 2002, Order was identified (Section IV.B).
- An unresolved item concerning the licensee's implementation of Interim Compensatory Measure B.3.d of the February 25, 2002, Order was identified (Section IV.D).
- An unresolved item concerning the licensee's implementation of Interim Compensatory Measure B.5.b of the February 25, 2002, Order was identified (Section VI.B).

B. Licensee Identified Violations

None

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION REMOVED