

# UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA, SUITE 400 ARLINGTON, TEXAS 76011-4005

### DOCUMENT CONTAINS SAFEGUARD INFORMATION

April 14, 2003

Mr. J. V. Parrish Chief Executive Officer Energy Northwest P.O. Box 968; MD 1023 Richland, Washington 99352-0968

SUBJECT: COLUMBIA GENERATING STATION NRC SAFEGUARDS INSPECTION OF

COMPLIANCE WITH ORDER INSPECTION REPORT 50-397/03-03

Dear Mr. Parish:

On March 7, 2003, the NRC completed an inspection at your Columbia Generating Station. The enclosed report documents the inspection findings that were discussed on March 7, 2003, with you and other members of your staff. Additionally, on April 3, 2003, the inspectors conducted a final exit meeting with Mr. Steve Scammon, Resource Protection Manager, and other members of your staff.

This inspection examined activities conducted under your license as they relate to safety and compliance with an Order issued on February 25, 2002, which required your site to implement specific measures related to the security of your facility. The inspection utilized Temporary Instruction 2515/148, "Inspection of Nuclear Reactor Safeguards Interim Compensatory Measures," to verify implementation of the Order as clarified in your responses dated March 18, and September 6, 2002. Within these areas, the inspection consisted of selected examination of procedures and representative records, observations of activities, and interviews with personnel.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will <u>not</u> be placed in the Public Document Room.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

-2-

NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a> (the Public Electronic Reading Room). Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

#### //RA//

Troy W. Pruett, Chief Plant Support Branch Division of Reactor Safety

Docket: 50-397 License: NPF-21

Enclosure: NRC Inspection Report 50-397/03-03

### cc without safeguards enclosure:

Rodney Webring (Mail Drop PE04) Vice President, Nuclear Generation Energy Northwest P.O. Box 968 Richland, Washington 99352-0968

Albert E. Mouncer (Mail Drop PE01) Vice President, Corporate Services/ General Counsel/CFO Energy Northwest P.O. Box 968 Richland, Washington 99352-0968

Chairman
Energy Facility Site Evaluation Council
P.O. Box 43172
Olympia, Washington 98504-3172

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

DOCUMENT CONTAINS SAFEGUARD INFORMATION

Douglas W. Coleman (Mail Drop PE20) Manager, Performance Assessment and Regulatory Programs Energy Northwest P.O. Box 968

Richland, Washington 99352-0968

Christina L. Perino (Mail Drop PE20) Manager, Licensing Energy Northwest P.O. Box 968 Richland, Washington 99352-0968

Chairman
Benton County Board of Commissioners
P.O. Box 190
Prosser, Washington 99350-0190

Dale K. Atkinson (Mail Drop PE08) Vice President, Technical Services Energy Northwest P.O. Box 968 Richland, Washington 99352-0968

Thomas C. Poindexter, Esq. Winston & Strawn 1400 L Street, N.W. Washington, D.C. 20005-3502

Bob Nichols
Executive Policy Division
Office of the Governor
P.O. Box 43113
Olympia, Washington 98504-3113

Lynn Albin Washington State Department of Health P.O. Box 7827 Olympia, WA 98504-7827

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

#### cc with safeguards enclosure:

Vonna Ordaz (NSIR/DNS/RSS) (MS T4D8) Juan Peralta (NSIR/DNS/SOS) (MS T4D8) Elaine McNeil (NSIR/DNS/RSS) (MS T4D8) RIV Docket File - File Room Custodian Security Inspector (Pick) Senior Resident Inspector (Replogle)

Electronic distribution by RIV without safeguards enclosure:

Regional Administrator (EWM)

DRP Director (ATH)
DRS Director (DDC)

Branch Chief, DRP/B (WBJ)

Senior Project Engineer, DRP/B (VGG)

Staff Chief, DRP/TSS (PHH)

RITS Coordinator (NBH)

Brian McDermott (BJM)

Site Secretary (LEF1)

Dale Thatcher (DFT)

W. A. Maier, RSLO (WAM)

DOCUMENT: R:\CGS2003-03gapSGI.wpd

RIV:PSB	DRP/A	DRP/B	NSIR/DNS/SOS	DRP/E
GAPick	GLGuerra	FLBrush	JDPeralta	WBJones
/RA/	via T	via T	via T	/RA/
4/ 01 /03	4/ 01 /03	4/ 01 /03	4/ 01 /03	4/ 03 /03
C:PSB				
C:PSB TWPruett				

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

### DOCUMENT CONTAINS SAFEGUARD INFORMATION

#### **ENCLOSURE**

### U.S. NUCLEAR REGULATORY COMMISSION REGION IV

Dockets: 50-397

Licenses: NPF-21

Report No.: 50-397/03-03

Licensee: Energy Northwest

Facility: Columbia Generating Station

Location: Richland, Washington

Dates: March 3 - 7, 2003

Inspectors: Gregory A. Pick, Senior Physical Security Inspector

Frank L. Brush, Senior Resident Inspector Gilbert L. Guerra, Resident Inspector

Accompanying

Personnel:

James Buchanon, Reactor Inspector

Approved By: Troy W. Pruett, Chief, Plant Support Branch

Attachment: Supplemental Information

### DOCUMENT CONTAINS SAFEGUARD INFORMATION

#### SUMMARY OF FINDINGS

IR 05000397-03-03, Energy Northwest; 03/03 - 07/2003; Columbia Generating Station; TI 2515/148, Verification of Compliance With Interim Compensatory Measures Order.

The inspection was conducted by one senior physical security inspector, one senior resident inspector, and one resident inspector.

#### **Cornerstone: Physical Security**

- On February 25, 2002, the NRC imposed by Order, Interim Compensatory Measures to
  enhance physical security. The inspectors determined that, overall, the licensee appropriately
  incorporated the Interim Compensatory Measures into the site protective strategy and access
  authorization program; developed and implemented relevant procedures; ensured that the
  emergency plan could be implemented; and established and effectively coordinated interface
  agreements with offsite organizations.
- The inspectors identified an unresolved item for failure to analyze the effects of the vehicle bomb on security monitoring equipment and two security structures, as required by Item B.2.(a).1 of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section III.A.2).
- The inspectors identified an unresolved item because the licensee may have failed to train appropriate personnel on hostage and duress situations, as required by Item B.3.e of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section IV.E.2).
- The inspectors identified an unresolved item for failure to maintain owner controlled area
  patrols random and continuous as required by Item B.4.e of the Order. This item remains
  open pending review by the Office of Nuclear Security and Incident Response
  (Section V.E.2).
- The inspectors identified an unresolved item regarding availability of supplementary equipment, as required by Item B.4.f of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section V.F.2).
- The inspectors identified an unresolved item regarding an evaluation of hazardous material as specified in Item B.5.c of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section VI.C.2).

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

## -2- DOCUMENT CONTAINS SAFEGUARD INFORMATION

•	The inspectors identified an unresolved item for failure to control generic use of passwords as
	required by Item B.5.f of the Order. This item remains open pending review by the Office of
	Nuclear Security and Incident Response (Section VI.F.2).