

UNITED STATES DEPARTMENT OF THE INTERIOR
 MINERALS MANAGEMENT SERVICE
 GULF OF MEXICO REGION
ACCIDENT INVESTIGATION REPORT

1. OCCURRED

DATE: **25-APR-2008** TIME: **0300** HOURS

2. OPERATOR:

Chevron U.S.A. Inc.

REPRESENTATIVE: **George, Noel**

TELEPHONE: **(985) 773-6542**

CONTRACTOR:

REPRESENTATIVE:

TELEPHONE:

- STRUCTURAL DAMAGE
- CRANE
- OTHER LIFTING DEVICE
- DAMAGED/DISABLED SAFETY SYS.
- INCIDENT >\$25K
- H2S/15MIN./20PPM
- REQUIRED MUSTER
- SHUTDOWN FROM GAS RELEASE
- OTHER

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR
ON SITE AT TIME OF INCIDENT:

6. OPERATION:

4. LEASE:

G02937

AREA:

WD

LATITUDE:

BLOCK:

109

LONGITUDE:

- PRODUCTION
- DRILLING
- WORKOVER
- COMPLETION
- HELICOPTER
- MOTOR VESSEL
- PIPELINE SEGMENT NO.
- OTHER

5. PLATFORM:

A

RIG NAME:

6. ACTIVITY:

EXPLORATION(POE)

DEVELOPMENT/PRODUCTION
(DOCD/POD)

8. CAUSE:

7. TYPE:

HISTORIC INJURY

REQUIRED EVACUATION

LTA (1-3 days)

LTA (>3 days)

RW/JT (1-3 days)

RW/JT (>3 days)

Other Injury

- EQUIPMENT FAILURE
- HUMAN ERROR
- EXTERNAL DAMAGE
- SLIP/TRIP/FALL
- WEATHER RELATED
- LEAK
- UPSET H2O TREATING
- OVERBOARD DRILLING FLUID
- OTHER _____

FATALITY

POLLUTION

FIRE

EXPLOSION

9. WATER DEPTH: **184** FT.

LWC HISTORIC BLOWOUT

UNDERGROUND

SURFACE

DEVERTER

SURFACE EQUIPMENT FAILURE OR PROCEDURES

10. DISTANCE FROM SHORE: **12** MI.

11. WIND DIRECTION:

SPEED: M.P.H.

12. CURRENT DIRECTION:

SPEED: M.P.H.

COLLISION

HISTORIC

>\$25K

<=\$25K

13. SEA STATE: FT.

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On April 25, 2008, at 0300 hours the Motor Vessel (M/V) Veritas, was approaching Chevron U.S.A. Inc's, OCS-G 02937, West Delta (WD) Block 109 A Platform, when it collided with the Platform. The M/V Veritas was to start dive work at the platform. The M/V Veritas' life raft was destroyed and there was damage to the communications dome and railings. The Platform's overhang was damaged, no structural damage.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Human Error:
The pilot inattention to steering the boat.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED: NATURE OF DAMAGE:
M/V Veritas' life raft, communications Collision
dome and railings.
Platform's overhang damaged.

ESTIMATED AMOUNT (TOTAL): \$

22. RECOMMENDATIONS TO PREVENT RECURRENCE NARRATIVE:
The New Orleans Distict makes no recommendations to MMS.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: **NO**

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

26. ONSITE TEAM MEMBERS:
No onsite investigation /

29. ACCIDENT INVESTIGATION
PANEL FORMED: **NO**

OCS REPORT:

30. DISTRICT SUPERVISOR:
Troy Trosclair

APPROVED

DATE: **04-JUN-2008**